

**HASKELL AND BARKER CAR COMPANY  
MICHIGAN CITY, INDIANA  
PHOTOGRAPHIC COLLECTION**



**WOMEN WORKERS INSTALL WINDOW SHADES IN TROOP SLEEPER**


**10-8-45**

**NEG # 4708**

**VIDEO DISC # 45082**

**SMITHSONIAN INSTITUTION  
NATIONAL MUSEUM OF AMERICAN HISTORY  
DIVISION OF TRANSPORTATION  
ROOM 5010 M 628  
WASHINGTON, DC  
20560**







HASKELL AND BARKER CAR COMPANY PHOTOGRAPHS  
MICHIGAN CITY, INDIANA  
Active 1852-1971  
(Pullman Subsidiary 1922)

Smithsonian Institution  
National Museum of American History  
Division of Transportation  
Washington, D.C.

Catalog prepared by John N. Stine  
Typed by Mary E. Braunagel  
1991



HASKELL AND BARKER CAR COMPANY  
MICHIGAN CITY, INDIANA  
Active 1852-1971  
(Pullman Subsidiary 1922)

This collection is a partial photographic record of the Haskell and Barker Car Company's activities from 1926 to 1949.

The gaps between negative numbers assigned by Haskell and Barker indicate that a portion were either discarded by the photographer or removed from the file and not replaced. Although the car building operation at Michigan City, Indiana began in 1852, the photos listed in this catalog represent the complete holdings of the Division of Transportation.

A great deal of attention has been directed at the operation of the plant. Shop scenes recording special tooling, testing of car components and the construction or upgrading of the car building plant are plentiful. In some instances a car is photographed during each step of construction, others only after completion. Occasionally a car was returned to the plant for a rebuild either due to its becoming obsolete or due to major damage. In any case, these repairs are well documented.

Scenes showing shop personnel operating car building equipment or engaged in the assembly of rolling stock are abundant.

This is a very fine collection in that it deviates from the standard practice of recording finished cars and concentrates on the daily operation of the building plant. Except for some World War II troop sleeper views, all of the pictures are of railroad freight stock: box, hopper, refrigerator, tank, flat, and cabooses.

The photos themselves range in quality from fair to excellent. We cannot, however, guarantee the quality of the prints, that is under the control of the Office of Printing & Photographic Services.

Division of Transportation  
National Museum of American History  
Smithsonian Institution  
1991



INDEX  
HASKELL AND BARKER CAR COMPANY PHOTOGRAPHS

<u>Railroad or Company</u>	<u>Pages</u>	<u>Railroad or Company</u>	<u>Pages</u>
Acme Fast Freight	1	Columbus & Greenville	43
Akron Canton & Youngstown	1	Commonwealth Cast Steel	43
American Car & Foundry	1	Copper Range	43
American Refrigerator Transit Co.	1-2	Delaware & Hudson	43-44
American Smelting & Refining Co.	1	Delaware Lackawanna & Western	44
Ann Arbor	3	Denver & Rio Grande Western	44
Apalachicola & Northern	3	Detroit & Mackinac	44
APX	3	Detroit Toledo & Ironton	45
ARMCO	3	Duluth Missabe & Iron Range	45-47
Atchison Topeka & Santa Fe	3-10	Duluth Missabe & Northern	48
Atlanta & West Point	10-11	Duluth South Shore & Atlantic	48
Atlantic Coast Line	11-12	E.F. Amapa	48
Bangor & Aroostook	12	E.M. Co.	48
Bessemer & Lake Erie	13-14	Equitable Life Assurance Society	49
Birmingham Slag Co.	14	Electro Metallurgical Co. (see Union Carbide)	
Birmingham Southern	15-17	Elgin Joliet & Eastern	49
Boston & Maine	18	Erie	49
Buffalo Creek	18	EsCANABA & Lake Superior	49
Buffalo Creek & Gauley	18	Export	50-53
Burlington Refrigerator Express	18	F.C. del Pacifico	53
Canadian Pacific	19	Florida East Coast	53
Central of Georgia	19-20	Fort Dodge Des Moines & Southern	53
Chesapeake & Ohio	21-26	Georgia (RR. & Banking Co.)	54
Chicago & Alton	26	GOC	54
Chicago & Eastern Illinois	27	Grand Trunk Western	54
Chicago & Illinois Midland	27-28	Great Northern	54-55
Chicago & North Western	28-35	Green Bay & Western	55
Chicago Burlington & Quincy	35	Gulf Mobile & Ohio	56
Chicago Great Western	36-37	Illinois Central	56-59
Chicago Indianapolis & Louisville (MONON)	37-39	International Minerals & Chemical Corp.	59
Chicago Milwaukee St. Paul & Pacific	39-40	Kansas City Southern	59-60
Chicago Rock Island & Pacific	40-41	Kewaunee Green Bay & Western	60
Chicago St. Paul Minneapolis & Omaha	41-42	La Salle & Bureau County	60
Cleveland Cincinnati Chicago & St. Louis	42	Lake Superior & Ishpeming	61
Clinchfield	42	Lancaster & Chester	61



<u>Railroad or Company</u>	<u>Pages</u>	<u>Railroad or Company</u>	<u>Pages</u>
Lehigh & New England	61	Pennsylvania Railroad	87
Lehigh Valley	61	Pere Marquette	88
Louisiana & Arkansas	62	Pittsburgh & Lake Erie	88-89
Louisville & Nashville	62-66	Pittsburgh & West Virginia	89
Maine Central	67	Pressed Steel Car Co.	89
McMillen Feed Mills	67	Pullman	90-109
Merchants Despatch Refrigerator Line	67	PS2-2	92
Merchants Despatch Transportation Corp.	67-68	PS-3 (PSX-44)	92-93
Michigan Central	68	PSX (Exhibition Car)	93-94
Minneapolis & St. Louis	68	PSX-1	94-95
Minneapolis Northfield & Southern	69	PSX-2	96
Minneapolis St. Paul & Sault Ste. Marie (SOO)	69-70	PSX-3 (Exhibition Car)	96
Mississippi Central	70	X-P5 & P5	97
Missouri Kansas & Texas	71-72	PSX-12	97
Missouri Pacific	72	PSX-19	97-98
MONON (See Chicago Indianapolis & Louisville)		PSX-24	98
Nacionales de Mexico	72-73	PSX-34	99
Nashville Chattanooga & St. Louis	73	PSX-35	99-100
National Coil Spring	73	PSX-53	100
National Steel Car Corp.	74	Trailmobile	101
New York Central	74-75	Troop Sleepers	101-106
New York Chicago & St. Louis (Nickel Plate)	75-79	XYZ Railroad	106-107
New York Despatch Refrigerator Lines	79	Pullman Railroad Co.	107-109
New York New Haven & Hartford	80	Richmond Fredericksburg & Potomac	109
New York Susquehanna & Western	80	Rutland	109
Newburgh & South Shore	80	Sacramento Northern	110
NMSX	80	St. Louis & San Francisco	110-111
Norfolk & Western	81-82	St. Louis Brownsville & Mexico	112
Norfolk Southern	82	St. Louis Southwestern	112
North American Car Corp.	82	Santa Fe Refrigerated Dispatch	113
Northern Pacific	83-84	Savannah & Atlanta	113
Northern Refrigerator Car Co.	84	Seaboard Air Line	114-116
Northern Refrigerator Line	85	Southern Pacific	116-118
Olympic Portland Cement	85	Southern Railway System	119-121
Orinoco Mining Co.	85	Spokane Portland & Seattle	121
Pacific Fruit Express (U.P.-S.P.)	86-87	Tennessee Central	121

INDEX--p.3

<u>Railroad or Company</u>	<u>Pages</u>
Tennessee Coal Iron & RR. Co.	121-122
Texas & New Orleans (S.P.)	122
Texas & Pacific	123
Texas Mexican Rly. Co.	123
Tidewater Southern	123
Toledo Peoria & Western	123
Union Carbide	123
Union Pacific	124-129
Union Railroad	129
United States Air Force	129-130
United States Army	130-131
United States Army (Export)	131-134
United States Marine Corps	134
United States Navy	134-135
USCC	136
U.S. Steel Corp	136
Virginian	136
Western Pacific	136-141
Western Ry. of Alabama	141
Wheeling & Lake Erie	142
Woodward	142
Haskell & Barker Car Co.	142-195
Portraits	195
Lot List	i-xviii





HASKELL AND BARKER CAR COMPANY  
MICHIGAN CITY, INDIANA  
Active 1852-1971  
(Pullman Subsidiary 1922)

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
ACME FAST FREIGHT						
5436	Container Flat	1002	1929	Ext. end	8996	48926
5436	Container Flat	1002	1929	Ext. 3/4 end	8997	48927
5436	Container Flat	1002	1929	Ext. side	8998	48928
5436	Container Flat	1002	1929	Ext. hand brake end	8999	48929
5436	Container Flat	1002	1929	Ext. 3/4 end	9000	48930
AKRON CANTON & YOUNGSTOWN						
8004	Box	750	1951	Ext. 3/4 side	7065	47279
8004	Box	750	1951	Ext. hand brake end	7066	47280
8245	Box	3600	1955	Ext. 3/4 side	8812	48766
8245	Box	3600	1955	Ext. hand brake end	8813	48767
8245	Box		1955	Int.	8814	48768
AMERICAN CAR & FOUNDRY						
	Trailer Flat		1956	End only; trailer support retracted	9181	49108
	Trailer Flat		1956	Three views of trailer support, diff. positions	9182	49109
	Trailer Flat		1956	3/4 front	9183	49110
AMERICAN REFRIGERATOR TRANSIT CO.						
5878	Refrigerator		1947	Shop scene insulating car, no roof; 5593-5604 series	5593	45849
5878	Refrigerator		1947	See 5593	5594	45850
5878	Refrigerator		1947	Moving car to insulation shop; see 5593	5595	45851
5878	Refrigerator		1947	See 5593	5596	45852



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
AMERICAN REFRIGERATOR TRANSIT CO. (continued)						
5878	Refrigerator		1947	See 5593; roof on car	5597	45853
5878	Refrigerator		1947	Int. insulation process beginning; see 5593	5598	45854
5878	Refrigerator		1947	Int. insulation step 2	5599	45855
5878	Refrigerator		1947	Int. insulation step 3; see 5593	5600	45856
5878	Refrigerator		1947	Int.; see 5593 (same as 5598)	5601	45857
5878	Refrigerator		1947	Int.; see 5593 (same as 5600)	5602	45858
5878	Refrigerator		1947	Int. insulation step 3; see 5593	5603	45859
5878	Refrigerator		1947	Ext. roof framing installed; see 5593	5604	45860
5878	Refrigerator	28136	1947	Ext. 3/4 side	5605	45861
5878	Refrigerator	28430	1947	Int. floor raised	5693	45952
5878	Refrigerator	28430	1947	Int. floor in place	5694	45953
5878	Refrigerator	28430	1947	Int. half floor raised	5695	45954
5878	Refrigerator		1947	Int. insulating car; 5721-5724 a series	5721	45981
5878	Refrigerator		1947	See 5721	5722	45982
5878	Refrigerator		1947	See 5721	5723	45893
5878	Refrigerator		1947	See 5721	5724	45984
5878	Refrigerator	28368	1947	Ext. hand brake end	5729	45987
5878	Refrigerator		1947	Ext. roof hatch open	5759	46017
5878	Refrigerator		1947	Ext. roof hatch closed	5760	46018
5878	Refrigerator	28795	1947	Ext. roof	5761	46019
5878	Refrigerator	28795	1947	Ext. roof hatch closed	5762	46020
5878	Refrigerator		1947	Frame 3/4 front	5827B	46086
5878	Refrigerator		1946	Frame 3/4 front inverted	5828B	46088

## AMERICAN SMELTING &amp; REFINING CO.

8069	Box	768	1952	Int. floor at side doors	7534	47721
8069	Box	768	1952	Ext. 3/4 side	7535	47722
8069	Box	768	1952	Ext. hand brake end	7536	47723

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
ANN ARBOR						
8282	Box	371	1956	Ext. 3/4 side	9069	48998
8282	Box	371	1956	Ext. hand brake end	9070	48999
APALACHICOLA & NORTHERN						
8111	Pulp Wood Car	AN117	1953	Ext. 3/4 side	8069	48110
8111	Pulp Wood Car	AN117	1953	Ext. hand brake end	8070	48111
APX						
5918A	Hopper	57	1949	Ext. 3/4 side	6280	46455
5918A	Hopper	57	1949	Ext. hand brake end	6281	46456
8040	Hopper	69	1953	Ext. 3/4 side	7982	48075
8040	Hopper	69	1953	Ext. hand brake end	7983	48076
ARMCO						
8123	Gondola	2205	1953	Ext. 3/4 side	7992	48085
8123	Gondola	2205	1953	Ext. hand brake end	7993	48086
ATCHISON TOPEKA & SANTA FE						
5547			1937	Side view double truss truck	2152	43600
5547			1937	3/4 front double truss truck	2153	43601
5585	Refrigerator		1938	3/4 front flat car w/car frames	2406	43739
5652	Box		1941	3/4 end inverted frfame S/S	3053	44268
5652	Box		1941	Int. no floor or sheathing	3054	44269
5652	Box		1941	3/4 side frame	3055	44270
5675	Box	143510	1941	Ext. side	3201	44289



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
ATCHISON TOPEKA & SANTA FE (continued)						
5675	Box	143701	1941	Ext. 3/4 side	3202	44290
5675	Box	144028	1941	Ext. 3/4 side	3308	44387
5675	Box	144137	1941	Ext. 3/4 side	3309	44388
5675	Box	143780	1941	Ext. 3/4 side	3310	44389
5675	Box	143798	1941	Ext. 3/4 side	3311	44390
5676	Box		1941	3/4 front, truck	3283	44370
5676	Box		1941	Truck side	3284	44371
5676	Box		1942	Coupler	3305	44384
5676	Box		1942	Coupler, opp. of 3305	3306	44385
5676	Box	10440	1942	Ext. 3/4 side	3307	44386
5696	Box		1941c.	Ajax hand brake winch	3207	44295
5696	Box		1941	Ajax hand brake winch	3208	44295
5696	Box		1941	Ajax hand brake winch back plate	3209	44297
5696	Box		1941	Ajax hand brake gears, etc.	3210	44298
5696	Box		1941	Ajax hand brake winch parts	3211	44299
5696	Box		1941	Ajax hand brake winch	3212	44300
5696			1941	Truck, 3/4 side	3284	44371
5696			1941	Truck 3/4 side	3285	44372
5696	Box		1941	Truck, front	3286	44373
5696	Box	146500	1941	Ext. 3/4 side	3312	44391
5696	Box	145798	1941		3313	44392
5696	Box	145798	1941	Ext. 3/4 side	3314	44393
5696	Box	146963	1942	Ext. 3/4 side	3315	44394
5696	Box	146757	1942	Ext. hand brake end	3316	44396
5696	Box	140079	1942	Ext. end	3317	44396
5696	Box	146979	1942	Int.	3318	44397
5696	Box		1942	Coupler and under frame	3319	44398
5696	Box		1942	Opp. of 3319	3320	44399
5696	Box	147343	1942	Ext. 3/4 side	3331	44417
5696	Box	146223	1942	Ext. 3/4 side	3332	44418
5764	Box		1944	3/4 front frame	4268	44837
5764	Box	151191	1944	Ext. 3/4 side	4272	44838
5799			1945	Coupler pocket	4582	44987
5799			1945	Different view of 4582	4583	44988

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
ATCHISON TOPEKA & SANTA FE (continued)						
5799			1945	Another view of 4582	4584	44989
5799			1945	Another view of 4582?	4585	44990
5799			1945	Shop scene welding center sill	4587	44991
5799			1945	Coupling pocket	4588	44992
5799			1945	Different view of 4588	4589	44993
5799			1945	Another view of 4588	4590	44994
5799			1945	Another view of 4588	4591	44995
5799			1945	Another view of 4588	4592	44996
5799	Box	64500 ser.	1945	Coupler pocket ends	4601	45005
5799	Box	64500 ser.	1945	Center plates	4603	45006
5799	Box	64500 ser.	1945	3/4 l.s. frame	4604	45007
5799	Box		1945	Frame 3/4 side inverted	4605	45008
5799	Box	64500 ser.	1945	Ext. 3/4 side line of cars fire damaged 6-7-45	4624	45012
5799	Box		1945	Train of cars fire damaged	4625	45013
5799	Box	64386	1945	Ext. 3/4 side	4634	45022
5799	Box	64619	1945	Ext. side	4635	45023
5799	Box	64494	1945	Ext. 3/4 side	4636	45024
5799	Box	64545	1945	Ext. 3/4 side	4637	45025
5799	Box		1945	Worker electric welding frame	6379	46554
5879	Box	276749	1947	Ext. 3/4 side	5734	45992
5879	Box	276749	1947	Ext. end	5735	45993
5879	Box	276749	1947	Ext. hand brake end	5736	45994
5879	Box	276749	1947	Ext. 3/4 side	5737	45995
5964	Box	31740	1950	Ext. 3/4 front from above	6701	46926
5964	Box		1950	Ext. roof 3/4 side	6702	46927
5964	Box		1950	Ext. roof end only 3/4 side	6710	46935
5964	Box		1950	Ext. roof 3/4 end	6711	46936
5964	Box		1950	Frame 3/4 front	6730	46955
5964	Box		1950	Frame 3/4 front inverted	6731	46956
5964	Box		1950	Frame center section inverted	6732	46957
5964	Box		1950	Frame inverted from above	6733	46958
5964	Box		1950	Frame inverted	6734	46959
5964	Box		1950	Frame 3/4 side	6735	46960
5964	Box		1950	Frame 3/4 rear end only	6736	46961



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
ATCHISON TOPEKA & SANTA FE (continued)						
5964	Box		1950	Frame 3/4 side end only	6737	46962
5964	Box		1950	Frame 3/4 side end only	6738	46963
5964	Box		1950	Coupler pocket 3/4 front	6739	46965
5964	Box		1950	Frame 3/4 side	6740	46966
5964	Box		1950	Frame 3/4 side inverted	6741	46967
5964	Box		1950	Interior	6742	46968
5964	Box		1950	Ext. side door open	6743	46969
5964	Box		1950	Ext. side door open	6744	46970
5964	Box		1950	Underside of car electrical sensors attached	6745	46971
5964	Box		1950	See 6745	6746	46972
5964	Box		1950	Ext. interior sheathing at side door	6747	46973
5964	Box		1950	Int. side wall no sheathing	6748	46975
5964	Box		1950	Air brake tank side	6749	46976
5964	Box		1950	Air brake tank side	6750	46977
5964	Box		1950	Air brake cylinder end view	6751	46978
5964	Box		1950	Air brake cylinder from top	6752	46979
5964	Box		1950	Air brake cylinder side	6753	46980
5964	Box		1950	Westinghouse brake valve AB	6754	46981
5964	Box		1950	Frame cross members	6755	46982
5964	Box		1950	Frame cross members	6756	46983
5964	Box		1950	Int. corner no sheathing	6757	46984
5964	Box		1950	Shop scene body erection shop	6758	46985
5964	Box		1950	Frame center member	6759	46986
5964	Box		1950	Int. no floor or sheathing	6760	46987
5964	Box		1950	Int. finished car	6761	46988
5964	Box		1950	Int. end	6762	46989
5964	Box		1950	Ext. 3/4 end coupler	6763	46990
5964	Box		1950	Ext. 3/4 side closeup of truck	6764	46991
5964	Box		1950	3/4 side closeup of coupler	6765	46992
5964	Box		1950	Ext. hand brake end	6766	46993
5964	Box		1950	Ext. 3/4 end	6767	46994
5964	Box		1950	Ext. end	6768	46995
5964	Box		1950	Ext. 3/4 end	6769	46996
5964	Box		1950	Ext. 3/4 side no lettering	6770	46997

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
ATCHISON TOPEKA & SANTA FE (continued)						
5964	Box		1950	Ext. 3/4 side no lettering	6771	46998
5964	Box		1950	Int. corner unfinished	6772	46999
5964	Box		1950	Underside of car	6773	47000
5964	Box		1950	Roof from end	6775	47001
5964	Box	31374	1950	3/4 side	6777	47003
5964	Box		1950	Closeup of car frame at sill	6780	47006
5964	Box		1950	Int. detail of car framing	6806	47032
8218	Box Compart.	11434	1955	Ext. 3/4 side	8656	48611
8218	Box Compart.	11434	1955	Ext. hand brake end	8657	48612
8218	Box Compart.		1955	Int.	8658	48613
8218	Box Compart.		1955	Int.	8671	48625
8218	Box Compart.		1955	Int.	8672	48626
8218	Box Compart.	11445	1955	Ext. 3/4 side	8675	48629
8218	Box Compart.	11431	1955	Ext. 3/4 side	8676	48630
8219	Refrigerator		1955	Int. no sheathing or floor	8673	48627
8219	Refrigerator		1955	Int. no sheathing	8674	48628
8219	Refrigerator		1955	Ext. side door	8722	48676
8219	Refrigerator		1955	Ext. side door	8723	48677
8219	Refrigerator		1955	Ext. side door	8724	48678
8219	Refrigerator		1955	Ext. side door	8725	48679
8219	Refrigerator		1955	Ext. side door	8726	48680
8219	Refrigerator		1955	Ext. side door	8727	48681
8219	Refrigerator		1955	Ext. side door	8728	48682
8219	Refrigerator		1955	Ext. side door open	8729	48683
8219	Refrigerator		1955	Ext. side door open	8730	48684
8219	Refrigerator	6047	1955	Ext. 3/4 side	8731	48685
8219	Refrigerator	6057	1955	Ext. 3/4 side	8732	48686
8219	Refrigerator	6193	1955	Ext. hand brake end	8733	48687
8219	Refrigerator		1955	Ext. closeup of side door; 8754-8765 a series	8754	48708
8219	Refrigerator		1955	Ext. closeup of side door locks	8755	48709
8219	Refrigerator		1955	Ext. closeup of door lock	8756	48710
8219	Refrigerator		1955	Ext. closeup of door hinges	8757	48711
8219	Refrigerator		1955	Ext. closeup of door latch	8758	48712
8219	Refrigerator		1955	Ext. closeup of door roller	8759	48713



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
ATCHISON TOPEKA & SANTA FE (continued)						
8219	Refrigerator		1955	Ext. side door & roller	8760	48714
8219	Refrigerator		1955	Ext. side door latch	8761	48715
8219	Refrigerator		1955	Ext. door lock	8762	48716
8219	Refrigerator		1955	Ext. closeup of door latch pivot	8763	48717
8219	Refrigerator		1955	Ext. closeup of side door	8764	48718
8219	Refrigerator		1955	Ext. closeup of door latch pivot	8765	48719
8219	Refrigerator		1955	Top view of couplers on 154' R.damage to air line	8782	48736
8219	Refrigerator		1955	See 8782	8783	48737
8219	Box Compart.		1955	Int.	8797	48751
8219	Box Compart.		1955	Int.	8798	48752
JO9408	Refrigerator		1938	3/4 side, car sides in gondola car 170573 for shipment	2405	43738
JO24999	Box		1946	Car side repair job; note 5037-5040 a series	5037	45352
JO24999	Box		1946	See 5037	5038	45353
JO24999	Box		1946	See 5037	5039	45354
JO24999	Box		1946	See 5037	5040	45355
	Box (repair)	300000	1948	Blt. 1941, ext. side; note 5994-6061 series; see 6077-6085 for finished car	5994	46174
	Box (repair)	300000	1948	Ext. 3/4 end closeup; see 5994	5995	46175
	Box (repair)	300000	1948	Ext. side; see 5994	5996	46176
	Box (repair)	300000	1948	Ext. 3/4 side; see 5994	5997	46177
	Box (repair)	300000	1948	Ext. end; see 5994	5998	46178
	Box (repair)	300000	1948	Ext. hand brake end; see 5994	5999	46179
	Box (repair)	300000	1948	Ext. roof; see 5994	6000	46180
	Box (repair)	300000	1948	Ext. roof; see 5994	6001	46181
	Box (repair)	300000	1948	Int. before rebuild; see 5994	6002	46182
	Box (repair)	300000	1948	Int. before rebuild; see 5994	6003	46183
	Box (repair)	300000	1948	Underside closeup truck bolster; see 5994	6004	46184
	Box (repair)	300000	1948	Ext. closeup of brake cylinder; see 5994	6005	46185
	Box (repair)	300000	1948	Air brake control; see 5994	6006	46186
	Box (repair)	300000	1948	Int. frame detail; see 5994	6007	46187
	Box (repair)	300000	1948	Int. construction detail; see 5994	6008	46188
	Box (repair)	300000	1948	Int. construction detail; see 5994	6009	46189
	Box (repair)	300000	1948	Int. construction detail; see 5994	6010	46190
	Box (repair)	300000	1948	Ext. underside frame detail; see 5994	6011	46191



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
ATCHISON TOPEKA & SANTA FE (continued)						
	Box (repair)	300000	1948	Ext. ladder; see 5994	6012	46192
	Box (repair)	300000	1948	Int. no floor; see 5994	6013	46193
	Box (repair)	300000	1948	Int. no floor; see 5994	6014	46194
	Box (repair)	300000	1948	Int. side wall; see 5994	6015	46195
	Box (repair)	300000	1948	Int. side wall; see 5994	6016	46196
	Box (repair)	300000	1948	Int. side wall; see 5994	6017	46197
	Box (repair)	300000	1948	Int. side wall; see 5994	6018	46198
	Box (repair)	300000	1948	Ext. underside frame detail; see 5994	6019	46199
	Box (repair)	300000	1948	Ext. underside frame detail; see 5994	6020	46200
	Box (repair)	300000	1948	Ext. underside frame detail; see 5994	6021	46201
	Box (repair)	300000	1948	Ext. underside frame detail; see 5994	6022	46202
	Box (repair)	300000	1948	Ext. underside sill detail; see 5994	6023	46203
	Box (repair)	300000	1948	Ext. frame inverted; see 5994	6024	46204
	Box (repair)	300000	1948	Ext. frame detail; see 5994	6025	46205
	Box (repair)	300000	1948	Ext. brake rod detail; see 5994	6026	46206
	Box (repair)	300000	1948	Ext. underside frame detail; see 5994	6027	46207
	Box (repair)	300000	1948	Frame detail; see 5994	6028	46208
	Box (repair)	300000	1948	Underside frame detail; see 5994	6029	46209
	Box (repair)	300000	1948	Frame detail; see 5994	6030	46210
	Box (repair)	300000	1948	Int. corner frame detail; see 5994	6031	46211
	Box (repair)	300000	1948	Int. lower side frame detail; see 5994	6032	46212
	Box (repair)	300000	1948	Int. lower side frame detail; see 5994	6033	46213
	Box (repair)	300000	1948	Int. lower corner frame detail; see 5994	6034	46214
	Box (repair)	300000	1948	Int. frame detail at bolster; see 5994	6035	46215
	Box (repair)	300000	1948	Int. frame & side sill detail; see 5994	6036	46216
	Box (repair)	300000	1948	Frame detail; see 5994	6037	46217
	Box (repair)	300000	1948	Int. new reinforcements at door opening; see 5994	6038	46218
	Box (repair)	300000	1948	See 6038	6039	46219
	Box (repair)	300000	1948	Ext. closeup of coupler; see 5994	6040	46220
	Box (repair)	300000	1948	Air tank; see 5994	6041	46221
	Box (repair)	300000	1948	Ext. hole cut to expose post in side; see 5994	6042	46222
	Box (repair)	300000	1948	Similar to 6042; see 5994	6043	46223
	Box (repair)	300000	1948	Ext. hole cut to expose beam in roof; see 5994	6044	46224
	Box (repair)	300000	1948	Similar to 6044; see 5994	6045	46225



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
ATCHISON TOPEKA & SANTA FE (continued)						
	Box (repair)	300000	1948	Similar to 6045	6046	46226
	Box (repair)	300000	1948	Ext. cutting instruction on car side; see 5994	6047	46227
	Box (repair)	300000	1948	Similar to 6047; see 5994	6048	46228
	Box (repair)	300000	1948	Similar to 6048; see 5994	6049	46229
	Box (repair)	300000	1948	Int. side frame detail at sill; see 5994	6050	46230
	Box (repair)	300000	1948	Int. reinforcement to upper side panel at door	6051	46231
	Box (repair)	300000	1948	Int. opposite of 6051; see 5994	6052	46232
	Box (repair)	300000	1948	Int. reinforcement at both upper side panels	6053	46233
	Box (repair)	300000	1948	Int. upper side frame detail; see 5994	6054	46234
	Box (repair)	300000	1948	Int. similar to 6051; see 5994	6055	46235
	Box (repair)	300000	1948	Int. side panel at sill; see 5994	6056	46236
	Box (repair)	300000	1948	Int. similar to 6056; see 5994	6057	46237
	Box (repair)	300000	1948	Int. side panel at roof line; see 5994	6058	46238
	Box (repair)	300000	1948	Int. similar to 6051; see 5994	6059	46239
	Box (repair)	300000	1948	Int. similar to 6058; see 5994	6060	46240
	Box (repair)	300000	1948	Ext. detail of side door pivot; see 5994	6061	46241
	Box (repair)	300000	1948	Ext. hand brake end; 6077-6085 series as reb.	6077	46257
	Box (repair)	300000	1948	Ext. 3/4 side; see 6077	6078	46258
	Box (repair)	300000	1948	Ext. opposite of 6078; see 6077	6079	46259
	Box (repair)	300000	1948	Int.; see 6077	6080	46260
	Box (repair)	300000	1948	Int.; see 6077	6081	46261
	Box (repair)	300000	1948	Int. upper side door detail; see 6077	6082	46262
	Box (repair)	300000	1948	Ext. 3/4 side; see 6077	6083	46263
	Box (repair)	300000	1948	Ext. 3/4 end; see 6077	6085	46264
			1949c.	Truck 3/4 side	9309	49187
ATLANTA & WEST POINT						
5685	Box	37300	1941	Ext. side	3291	44376
5685	Box	37300	1941	Ext. hand brake end	3292	44377
5753	Box	37459	1944	Ext. side	4116	44786
5753	Box	37459	1944	Ext. hand brake end	4117	44787
5783A	Box	37500	1945	Ext. 3/4 side	4566	44980

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
ATLANTA & WEST POINT (continued)						
5783A	Box	37500	1945	Ext. hand brake end	4567	44979
8039	Box	37989	1952	Ext. 3/4 side	7674	47850
8039	Box	37989	1952	Ext. hand brake end	7675	47851
8283	Box	39004	1956	Ext. 3/4 side	9102	49029
8283	Box	39004	1956	Ext. hand brake end	9103	49030
8284C	Box	38009	1956	Ext. 3/4 side	9137	49064
8284C	Box	38009	1956	Ext. hand brake end	9138	49065
ATLANTIC COAST LINE						
5641			1940	Body bolster	2890	44119
5641			1940	Body bolster	2891	44120
5641			1940	Coupler pocket	2892	44121
5641			1940	Draft gear part	2893	44122
5641			1940	Draft gear part	2894	44123
5641			1940	Draft gear part	2894	44124
5641			1940	Draft gear part	2896	44125
5641			1940	Draft gear part	2897	44126
5641	Box Auto	51637	1941	Ext. side	2958	44183
5641	Box Auto	51637	1941	Ext. hand brake end	2959	44184
5641	Box Auto	51637	1941	Ext. double side doors	2960	44185
5641	Box Auto	51637	1941	Int. double side doors	2961	44186
5687	Box	21011	1942	Ext. side	3321	44400
5687	Box	21011	1942	Ext. hand brake end	3322	44401
5719	Box Automobile	53450	1944	Ext. side	4370	44884
5719	Box Automobile	53450	1944	Ext. hand brake end	4371	44885
5971	Hopper Covered	85346	1950	Ext. 3/4 side	6925	47139
5971	Hopper Covered	85346	1940	Ext. hand brake end	6926	47140
8013	Pulp Wood	72899	1952	Ext. hand brake end	7409	47598
8132	Hopper		1953	Series (8078-8106) showing assembly of a wheel set from bare axle to journal box	8078	48119
8132	Hopper		1953	See 8078	8079	48120
8132	Hopper		1953	See 8078	8080	48121



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
ATLANTIC COAST LINE(continued)						
8132	Hopper		1953	See 8078	8081	48122
8132	Hopper		1953	See 8078	8082	48123
8132	Hopper		1953	See 8078	8083	48124
8132	Hopper		1953	See 8078	8084	48125
8132	Hopper		1953	See 8078	8085	48126
8132	Hopper		1953	See 8078	8086	48127
8132	Hopper		1953	See 8078	8087	48128
8132	Hopper		1953	See 8078	8088	48129
8132	Hopper		1953	See 8078	8089	48130
8132	Hopper		1953	See 8078	8090	48131
8132	Hopper		1953	See 8078	8091	48132
8132	Hopper		1953	See 8078	8092	48133
8132	Hopper		1953	See 8078	8093	48134
8132	Hopper		1953	See 8078	8094	48135
8132	Hopper		1953	See 8078	8095	48136
8132	Hopper		1953	See 8078	8096	48137
8132	Hopper		1953	See 8078	8097	48138
8132	Hopper		1953	See 8078	8098	48139
8132	Hopper		1953	See 8078	8099	48140
8132	Hopper		1953	See 8078	8100	48141
8132	Hopper		1953	See 8078	8101	48142
8132	Hopper		1953	See 8078	8102	48143
8132	Hopper		1953	See 8078	8103	48144
8132	Hopper		1953	See 8078	8104	48145
8132	Hopper		1953	See 8078	8105	48146
8132	Hopper		1953	See 8078	8106	48147
8132	Hopper Covered	86329	1953	Ext. 3/4 side	8137	48176
8132	Hopper Covered	86329	1953	Ext. hand brake end	8138	48177
BANGOR & AROOSTOOK						
8160	Box	4500	1954	Ext. 3/4 side	8292	48325
8160	Box	4500	1954	Ext. hand brake end	8293	48326

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
BESSEMER & LAKE ERIE						
	Box		1940	Gauging door lock castings	2617	43915
	Box		1940	Pile of door panels	2618	43916
5584	Box		1938	Interior	2392	43726
5584	Box	90171	1938	Exterior end	2393	43727
5584	Box	90171	1938	Exterior hand brake end	2394	43728
5584	Box		1939	Interior from end (note: 2515-2523 all one car from a series of light weight cars built in 1938)	2515	43829
5584	Box		1939	Side door damaged	2516	43830
5584	Box		1939	Close up of side door damage	2517	43831
5584	Box		1939	3/4 end damaged side door	2518	43832
5584	Box		1939	Ext. top corner damage	2519	43833
5584	Box		1939	Ext. end damage	2520	43834
5584	Box		1939	Interior from end	2521	43835
5584	Box		1939	Exterior end damage	2522	43836
5584	Box		1939	Ext. end damage from above	2523	43837
5584	Box		1939	Int. closeup of damage; see 2515	2530	43844
5584	Box		1939	Int. end damage; see 2515	2531	43845
5584	Box		1939	Int. closeup of damage; see 2515	2532	43846
5584	Box	90101	1939	Ext. 3/4 side no trucks under repair	2564	43874
5584	Box	90101	1939	Int. end from center	2565	43875
5584	Box	90101	1939	Ext. 3/4 end under repair	2566	43876
5584	Box	90101	1939	Ext. 3/4 side end under repair	2567	43877
5584	Box	90101	1939	Ext. 3/4 end top under repair	2568	43878
5584	Box		1939	Int. end under repair	2569	43879
5584	Box	90101	1939	Ext. 3/4 end no trucks, under repair	2570	43880
5584	Box	90101	1939	Ext. roof under repair	2571	43881
5584	Box	90101	1939	Ext. closeup damage to side sheet	2572	43882
5584	Box	90101	1939	Ext. closeup lower sill repaired	2573	43883
5584	Box	90101	1939	Int. worker straightening roof arch bars	2574	43884
5584	Box	90101	1939	Int. repairs complete	2575	43885
5584	Box	90101	1939	Ext. 3/4 side closeup of end repair	2576	43886
5584	Box	90101	1939	Int. repair tools display	2577	43887
5584	Box	90101	1939	Ext. car top	2578	43888



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
BESSEMER & LAKE ERIE (continued)						
5584	Box	90101	1939	Int. roof trusses repaired	2579	43889
5584	Box		1940	Side door testing for rigidity	2611	43911
5584	Box	90101	1939	Ext. side	2681	43964
5584	Box	90101	1940	Ext. side	2682	43965
5584	Box	90101	1940	Ext. end	2683	43966
5584	Box	90101	1940	Ext. hand brake end	2684	43967
5584	Box	90101	1940	Ext. roof and end	2685	43968
5584	Box		1940	Frame from below repair work	2717	43999
5584	Box		1940	Int. floor removed for repair	2718	44000
5584	Box		1940	End coupler pocket repair	2748	44023
5584	Box		1940	End coupler pocket repair	2749	44024
5584	Box		1940	Coupler pocket	2758	44033
5584	Box		1940	Coupler pocket	2759	44034
5584	Box	90199	1946	Frame detail	4885	45260
5584	Box	90199	1946	Frame detail	4886	45261
5584	Box		1946	Int. floor (in for repair)	4984	45300
5584	Box		1946	Closeup of frame repair	4985	45301
5584	Box		1946	Closeup of frame repair	4986	45302
5584	Box		1946	Ext. damage to end	4987	45303
5584	Box		1946	Ext. door damaged	4988	45304
5584	Box		1946	Damaged door	4989	45305
5584	Box		1946	Damaged door; see 4989	4990	45306
5584	Box		1946	Int. of door; see 4989	4991	45307
5584	Box		1946	Worker with door; see 4989	4992	45308
BIRMINGHAM SLAG CO.						
5844A	Hopper	OD-1	1946	Ext. 3/4 side	5252	45518
5844A	Hopper	OD-1	1946	Ext. hand brake end	5253	45519
5927A	Hopper	OD101	1949	Ext. 3/4 side	6422	46597
5927A	Hopper	OD101	1949	Ext. hand brake end	6423	46598

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
BIRMINGHAM SOUTHERN						
5541 & 5544	Steel Sheathed Box		1936	Lower part of door inside cover removed, closed and open position	2116	43576
5541 & 5544	Steel Sheathed Box		1936	Door roller assembly in open and closed position, cover removed	2117	43577
5541 & 5544	Steel Sheathed Box		1936	Exterior lower door sheet bearings for roller assembly	2118	43578
5541 & 5544	Steel Sheathed Box		1936	Interior and exterior lower door sht. handle in open position	2119	43579
5541 & 5544	Steel Sheathed Box		1936	Exterior lower door sht. with and without lever	2120	43580
5541	Steel Sheathed Box		1936	Electric welded draft sill	2121	43581
5541	Steel Sheathed Box		1936	Electric welded center sill	2122	43582
5541	Steel Sheathed Box		1936	Electric welded center sill	2123	43583
5541	Steel Sheathed Box		1936	Electric welded draft sill	2124	43584
5541	Steel Sheathed Box		1936	Center filler and back stop plates	2125	43585
5544			1937	Electric welded draft sill	2141	43592
5544			1937	Electric welded draft sill	2142	43593
5544			1937	Exterior spot-welded side door	2144	43594
5544			1937	Same as 2144	2145	43595
5544			1937	Exterior spot-welded side door, door partially open	2146	43596
5544			1937	Exterior side door details	2147	43597
5544			1937	Exterior side door detail	2148	43598
5544			1937	Exterior side door details	2149	43599
5541	Steel Sheathed Box	320	1937	Exterior end (hand brake)	2201	43612
5541	Steel Sheathed Box	320	1937	Exterior side	2202	43613
5541	Box	320	1942	Cracks in casting coupler pocket (44584-44590 ser.)	3508	44584
5541	Box	320	1942	(Blt. 1936) 3/4 frt. cracks in coupler pocket	3509	44585
5541	Box	320	1942	Ext. 3/4 side	3510	44586
5541	Box	320	1942	Closeup of cracks	3511	44587
5541	Box	320	1942	Closeup of cracks	3512	44588
5541	Box	320	1942	Closeup of cracks	3513	44589
5541	Box	320	1942	Closeup of cracks	3514	44590
5541	Box		1946	Top of frame at axle	4875	45250



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
BIRMINGHAM SOUTHERN (continued)						
5541	Box		1946	See 4875	4876	45251
5541	Box		1946	Ext. side door	4877	45252
5541	Box		1946	Ext. 3/4 side	4887	45262
5541	Box		1946	Damaged door int.; note 4935-4938 a series	4935	46835
5541	Box		1946	Damaged door ext.; see 4935	4936	46836
5541	Box		1946	Damaged door; see 4935	4937	46837
5541	Box		1946	Damaged door; see 4935	4938	46838
5541	Box		1946	Damaged door parts	5201	45468
5541	Box		1946	Damaged door parts	5202	45469
5541	Box		1946	Damaged door parts	5203	45470
5541	Box		1946	Damaged door parts	5204	45471
5595	Hopper		1939	Coupler pocket	2513	43829
5595	Hopper	1912	1939	Exterior side	2538	43850
5595	Hopper	1912	1939	Ext. hand brake end	2539	43851
5595	Hopper	1912	1939	Int. from above	2540	43852
5595	Hopper	1912	1939	Ext. on side showing bottom (note: 2541-2546 are construction photos of car #1912)	2541	43853
5595	Hopper	1912	1939	3/4 side in shop	2542	43854
5595	Hopper	1912	1939	Upside down, welders working	2543	43855
5595	Hopper	1912	1939	Ext. car bottom & ends, no sides	2544	43856
5595	Hopper	1912	1939	3/4 side frame	2545	43857
5595	Hopper	1912	1939	Frame cross member	2546	43858
5595	Hopper		1946	Line of hoppers for scrap; blt. 1912	4878	45253
5595	Hopper		1946	Int. of car; see 4878	4879	45254
5595	Hopper		1946	Ext. 3/4 side; see 4878	4880	45255
5595	Hopper		1946	Ext. closeup; see 4878	4881	45256
5595	Hopper		1946	Ext. end; see 4878	4882	45257
5595	Hopper		1946	Ext. end; see 4878	4883	45258
5595	Hopper		1946	Axle & coupler; see 4878	4884	45259
5595	Hopper		1946	Machining body bolster; note, 4939-4945 a series	4939	46839
5595	Hopper		1946	See 4939	4940	46840
5595	Hopper		1946	See 4939	4941	46841
5595	Hopper		1946	See 4939	4942	46842
5595	Hopper		1946	See 4939	4943	46843

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
BIRMINGHAM SOUTHERN (continued)						
5595	Hopper		1946	See 4939	4944	46844
5595	Hopper		1946	See 4939	4945	46845
5596	Flat	254	1939	Exterior side	2524	43838
5596	Flat	254	1939	Exterior hand brake end	2525	43839
5596	Flat	254	1939	3/4 end from under frame	2526	43840
5596	Flat	254	1939	Different view of 2526	2527	43841
5596	Flat	254	1939	End view from top, frame	2528	43842
5596	Flat	254	1939	3/4 front from above, frame	2529	43843
5710	Gondola Steel	5500	1942	Ext. side	3614	44629
5710	Gondola Steel	5500	1942	Ext. hand brake end	3615	44630
5710	Gondola Steel	5500	1942	Int. end dropped, no floor	3616	44631
5710	Gondola Steel	5500	1942	Int. end dropped, no floor	3617	44632
5710	Gondola Steel	5500	1942	Frame only 3/4 front	3618	44633
5710	Gondola Steel	5500	1942	Frame underside	3619	44634
5710	Gondola Steel	5500	1942	Frame under construction	3620	44635
5710	Gondola Steel		1942	Int. end dropped with floor	3621	44636
5710	Gondola Steel		1942	Int. line of car ends dropped	3622	44637
5754	Box	6599	1944	Ext. side	4118	44788
5754	Box	6599	1944	Ext. hand brake end	4119	44789
5905	Hopper	7050	1948	Ext. 3/4 side	6119	46296
5905	Hopper	7050	1948	Ext. hand brake end	6120	46297
5905	Hopper	7050	1948	Int. from above	6121	46298
8009	Box	6799	1952	Ext. 3/4 side	7376	47568
8009	Box	6799	1952	Ext. hand brake end	7377	47569
8009	Box		1952	Int. door	7378	47570
8009	Box		1952	Ext. door	7379	47571
8009	Box		1952	Ext. door	7380	47572
8165	Hopper Covered	6010	1953	Ext. 3/4 side	8196	48233
8165	Hopper Covered	6010	1953	Ext. hand brake end	8197	48234



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
BOSTON & MAINE						
5877	Box	74305	1947	Ext. 3/4 side	5644	45900
5877	Box	74305	1947	Ext. 3/4 side	5645	45901
5877	Box	74305	1947	Ext. hand brake end	5646	45902
5877	Box	74262	1947	Interior	5719	45978
5999	Box	75249	1951	Ext. 3/4 side	6981	47195
5999	Box	75249	1951	Ext. hand brake end	6982	47196
8288	Box		1956	Car step	9130	49057
8288	Box		1956	Car step	9131	49058
8288	Box		1956	Car step	9132	49059
8288	Box		1956	Car step	9133	49060
8288	Box		1956	Car step	9134	49061
8288	Box		1956	Car step	9135	49062
8288	Box		1956	Car step	9136	49063
8288	Box	77399	1956	Ext. 3/4 side	9145	49072
8288	Box	77399	1956	Ext. hand brake end	9146	49073
BUFFALO CREEK						
8292	Box	2170	1956	Ext. 3/4 side	9199	49126
8292	Box	2170	1956	Ext. hand brake end	9200	49127
BUFFALO CREEK & GAULEY						
8038	Box	1001	1952	Ext. 3/4 side	7547	47735
8038	Box	1001	1952	Ext. hand brake end	7548	47736
8038	Box	1001	1952	Int. floor at side door	7558	47740
BURLINGTON REFRIGERATOR EXPRESS						
5820	Refrigerator	75276	1945	Ext. 3/4 side	4658	45044

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
CANADIAN PACIFIC						
5950	Box	269960	1949	Ext. 3/4 side	6476	46642
5950	Box	269960	1949	Ext. hand brake end	6477	46643
8036C	Box	268899	1952	Ext. 3/4 side	7549	47737
8036C	Box	268899	1952	Ext. hand brake end	7550	47738
8087	Box	269349	1953	Ext. 3/4 side	7706	47883
8087	Box	269349	1953	Ext. hand brake end	7707	47884
	Refrigerator	281282	1949	Int.; 6486-6498 copies of competitors photos, various cars	6486	46649
	Refrigerator	281282				
	Refrigerator		1949	See 6486	6487	46650
	Refrigerator		1949	Roof ext. see 6486	6488	46651
	Refrigerator		1949	Shop scene car side frame	6489	46652
	Refrigerator		1949	Shop scene erecting side; see 6486	6490	46653
	Refrigerator	281212	1949	Ext. hand brake end	6491	46654
	Refrigerator		1949	Ext. 3/4 front; see 6486	6492	46655
	Refrigerator		1949	Int. car frame only	6493	46656
	Refrigerator		1949	Shop scene fabricating roof; see 6486	6494	46657
	Refrigerator		1949	Shop scene frame inverted; see 6486	6495	46658
	Refrigerator		1949	Shop scene frame front view; see 6486	6496	46659
	Refrigerator		1949	Ext. side no sheathing; see 6486	6497	46660
	Refrigerator		1949	Ext. 3/4 end only; see 6486	6498	46661
CENTRAL OF GEORGIA						
5501	Hopper Steel-Triple	732	1934	Exterior, 3/4 side	1937	43470
5501	Hopper Steel-Triple	732	1934	Exterior end	1938	43471
5540	Steel Double Hopper	21640	1936	Exterior 3/4 side	2112	43572
5540	Steel Double Hopper	21640	1936	Exterior end hand brake	2113	43573
5568	Box, Steel 40'	4254	1937	Exterior side	2282	43650
5568	Box, Steel 40'	4254	1937	Exterior end (hand brake)	2283	43651
5626	Hopper, Cement	1314	1940	Ext. side	2843	44103
5626	Hopper, Cement	1314	1940	Ext. hand brake end	2844	44104
5699	Box	1649	1942	Ext. side	3342	44421



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
CENTRAL OF GEORGIA (continued)						
5699	Box	1649	1942	Ext. hand brake end	3343	44422
5736A	Hopper	21700	1943	Ext. side	3923	44673
5736A	Hopper	21700	1943	Ext. hand brake end	3924	44674
5761	Box	41193	1944	Ext. side	4273	44839
5761	Box	41193	1944	Ext. hand brake end	4274	44840
5777	Box	4560	1945	Ext. 3/4 side	4562	44976
5777	Box	4560	1945	Ext. hand brake end	4563	44977
5778	Box	6670	1945	Ext. 3/4 side	4502	44948
5778	Box	6670	1945	Ext. hand brake end	4503	44949
5779	Hopper	21899	1945	Ext. 3/4 side	4490	44942
5779	Hopper	21899	1945	Ext. hand brake end	4491	44943
5783	Box	19950	1945	Ext. 3/4 side	4564	44978
5783	Box	19950	1945	Ext. hand brake end	4565	44981
8030	Box	7086	1952	Ext. 3/4 side	7492	47679
8030	Box	7086	1952	Ext. hand brake end	7493	47680
8031	Gondola	18572	1952	Ext. 3/4 side	7372	47564
8031	Gondola	18572	1952	Ext. hand brake end	7373	47565
8134	Hopper Covered	1444	1953	Ext. 3/4 side	8206	48243
8134	Hopper Covered	1444	1953	Ext. hand brake end	8207	48244
8150	Box	8199	1953	Ext. 3/4 side	8221	48258
8150	Box	8199	1953	Ext. hand brake end	8222	48259
8198	Box	5751	1954	Ext. 3/4 side	8482	48440
8198	Box	5751	1954	Ext. hand brake end	8483	48441
8207A	Box Compartmentizer	6200	1954	Ext. 3/4 side	8504	48462
8207A	Box Compartmentizer	6200	1954	Ext. hand brake end	8505	48463
8207A	Box Compartmentizer	6200	1954	Int.	8506	48464
8207A	Box Compartmentizer	6200	1954	Int.	8507	48465
8207A	Box Compartmentizer	6200	1954	Int.	8508	48466
8216A	Box	6208	1954	Ext. 3/4 side	8614	48571
8216A	Box	6208	1954	Ext. hand brake end	8615	48572
8283	Box	1781	1956	Ext. 3/4 side	9061	48990
8283	Box	1781	1956	Ext. hand brake end	9062	48991

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
CHESAPEAKE & OHIO						
5499	Box	7299	1934	Exterior, side	1901	43445
5499	Box, Flour/Grain	7625	1934	Interior roof and side wall	1907	43448
5499	Plankless truck	7625	1934	3/4 front	1914	43447
5499	Box, Flour/Grain	7625	1934	Interior side door and wall	1915	43449
5499	Box, Flour/Grain	7625	1934	Interior, side door open	1916	43449
5499	Box, Flour/Grain	7625	1934	3/4 front, ARA "Z" center sill frame	1917	43450
5499	Box, Flour/Grain	7625	1934	Front view ARA "Z" center sill frame	1918	43451
5499	Box, Flour/Grain		1934	3/4 front ARA old style frame	1919	43452
5499	Plankless truck		1934	Side view	1920	43453
5499	Box, Flour/Grain		1934	Interior, side view side wall	1921	43454
5499	Box, Flour/Grain		1934	Interior, end view, no floor or sheathing	1922	43455
5499	Box, Flour/Grain		1934	Interior, end view, no side sheathing	1923	43456
5499	Box, Flour/Grain		1934	Interior, end view	1924	43457
5499	Truck coil spring		1934	Truck side view	1925	43458
5499	Truck coil spring		1934	End view	1926	43459
5499	Truck coil elliptic		1934	Side view	1927	43460
5499	Truck coil elliptic		1934	End view	1928	43461
5499	Box, Flour/Grain	7299	1934	Exterior, side	1933	43466
5499	Box, Flour/Grain	7299	1934	Exterior end (hand brake)	1934	43467
5499	Box, Flour/Grain	7299	1934	Exterior, end	1935	43468
5499	Box, Flour/Grain	7299	1934	Exterior end, same as 1934	1936	43469
5514	Auto Box	6407	1936	Exterior side	2032	43524
5514	Auto Box	6407	1936	Exterior end	2033	43525
5514	Auto Box	6407	1936	Exterior end (hand brake)	2034	43526
5514	Auto Box	6407	1936	Exterior, 3/4 side	2035	43527
5514	Auto Box	6407	1936	Dalman Patent Truck 3/4 side	2036	43528
5514	Auto Box	6407	1936	Dalman Patent Truck front view	2037	43529
5514	Auto Box	6407	1936	3/4 side frame	2038	43530
5514	Auto Box	6407	1936	Interior	2039	43521
5514	Auto Box	6407	1936	Interior end with floor frame exposed	2040	43532
5531	Steel Box	4526	1936	Exterior 3/4 side	2109	43569
5531	Steel Box	4526	1936	Exterior 3/4 side	2110	43570
5532	Automobile Box	6284	1936	Exterior end	2083	43556



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
CHESAPEAKE & OHIO (continued)						
5532	Automobile Box	6284	1936	Exterior hand brake end	2084	43557
5532	Automobile Box	6284	1936	Exterior side view	2085	43558
5532	Automobile Box	6250	1936	Ext. 3/4 side	9303	49177
5601	Hopper	134299	1939	Ext. 3/.4 side	2556	43867
5601	Hopper	134299	1939	Int. end from above	2557	43868
5601	Hopper	134299	1939	Ext. end	2558	43869
5601	Hopper	134299	1939	Ext. hand brake end	2559	43870
5601	Hopper	134299	1939	Ext. side	2560	43871
5601	Hopper	134299	1939	3/4 side frame, under construction	2561	43872
5601	Hopper	134299	1939	3/4 side bottom & end under construction	2562	43873
5627	Flat		1940	Section of frame	2707	43990
5627	Flat		1940	Interior	2708A	43992
5627	Flat	80497	1940	3/4 side frame underside	2774	44048
5627	Flat	80497	1940	3/4 side frame partial	2775	44049
5627	Flat	80497	1940	3/4 rear end of frame from above	2776	44050
5627	Flat	80497	1940	3/4 end from above, frame	2777	44051
5627	Flat	80497	1940	3/4 view side rails	2778	44052
5627	Flat	80497	1940	3/4 side frame end	2779	44053
5627	Flat	80497	1940	3/4 end frame	2780	44054
5627	Flat	80497	1940	Ext. side	2783	44055
5627	Flat	80497	1940	Ext. side	2784	44056
5627	Flat	80497	1940	Ext. end	2785	44057
5627	Flat	80497	1940	3/4 front frame and trucks	2789	44058
5635	Box	3542	1940	Ext. 3/4 side	2828	44089
5635	Box	3542	1940	Interior	2829	44090
5635	Box	3542	1940	Ext. 3/4 side	2830	44091
5635	Box	3542	1940	3/4 front frame on trucks	2831	44092
5781	Hopper		1944	Ext. 3/4 side	4419	44902
5781	Hopper		1944	Center sill, shop scene	4423	44906
5781	Hopper		1944	Frame inverted, shop scene	4424	44907
5781	Hopper		1944	Different view of 4424	4425	44908
5781	Hopper		1944	Frame and bottom, shop scene	4426	44909
5781	Hopper		1944	Frame, shop scene	4427	44910
5781	Hopper		1944	Frame and bottom, shop scene	4428	44911

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
CHESAPEAKE & OHIO (continued)						
5781	Hopper		1944	Frame and bottom, shop scene	4434	44915
5781	Hopper		1944	Frame and bottom, shop scene	4436	44916
5781	Hopper		1944	Shop scene, car end	4437	44917
5781	Hopper		1944	Interior from above	4447	44924
5781	Hopper	49099	1944	Ext. 3/4 side	4448	44925
5781	Hopper	49099	1944	Ext. end	4449	44926
5781	Hopper	49099	1944	Ext. hand brake end	4450	44927
5781	Hopper		1944	Construction scene	4468	44935
5781	Hopper		1944	Doors and frames	4469	44936
5801	Box	14111	1945	Frame 3/4 front	4628	45017
5801	Box		1945	Frame end only inverted	4629	45016
5801	Box	14111	1945	Ext. 3/4 side	4630	45018
5801	Box		1945	Truck side	4638	45026
5801	Box		1945	Trucks front view	4639	45027
5801	Box	14111	1945	Ext. hand brake end	4640	45028
5801	Box	14111	1945	Ext. end	4641	45029
5801	Box	14111	1945	Ext. 3/4 side	4642	45030
5801	Box	14047	1945	Interior	4643	45031
5801	Box		1945	Int. no floor or sheathing	4644	45032
5801	Box		1945	Frame 3/4 end	4645	45033
5801	Box		1945	Frame 3/4 front inverted	4646	45034
5801	Box		1946	Truck, side view	4903	45278
5801	Box		1946	Truck, 3/4 front	4904	45279
5886	Box	15000	1947	Ext. side	5752	46010
5886	Box	15000	1947	Ext. hand brake end	5753	46011
5886	Box	15000	1947	Ext. side	5754	46012
5886	Box	15000	1947	Ext. 3/4 end	5755	46013
5886	Box	15000	1947	Ext. 3/4 side	5756	46014
5886	Box	15000	1947	Ext. opposite of 5755	5757	46015
5886	Box	15000	1948	3/4 side (night photo)	5827A	46085
5886	Box	15000	1948	Ext. side	5828A	46087
5886	Box	15000	1948	Ext. 3/4 side	5829	46089
5886	Box	15370	1948	Ext. 3/4 side	5839	46099
5886	Box	15563	1948	Ext. 3/4 side in train; see 5856	5850	46110



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
CHESAPEAKE & OHIO (continued)						
5886	Box	15564	1948	3/4 side in train; see 5856	5851	46111
5886	Box	15565	1948	Ext. 3/4 side in train; see 5856	5852	46112
5886	Box	15563	1948	Ext. 3/4 side in train; see 5856	5853	46113
5886	Box	15564	1948	Ext. side in train; see 5856	5854	46114
5886	Box	15564	1948	3/4 side in train; see 5856	5855	46115
5886	Box		1948	Train of cars for delivery	5856	46116
5983	Box	16249	1950	Ext. 3/4 side	6900	47113
5983	Box	16249	1950	Ext. 3/4 side	6901	47114
5983	Box	16249	1950	Ext. end	6902	47115
5983	Box	16249	1950	Ext. hand brake end	6903	47116
5983	Box		1950	Frame 3/4 front	6904	47117
5983	Box		1950	Frame 3/4 front inverted	6905	47118
5983	Box		1950	Int. no floor or sheathing	6906	47119
5983	Box	16545	1950	Int.	6907	47120
5983	Box		1950	Truck side	6908	47121
5983	Box		1950	Truck 3/4 front	6909	47122
5983	Box		1950	Frame part sectioned for test; 6917-6920 series	6917	47130
5983	Box		1950	See 6917	6918	47131
5983	Box		1951	See 6917	6919	47132
5983	Box		1950	See 6917	6920	47133
8017	Box	17246	1951	Int.	7140	47340
8017	Box	17099	1951	Ext. 3/4 side	7141	47341
8017	Box	17099	1951	Ext. 3/4 side	7142	47342
8017	Box	17099	1951	Ext. end	7143	47343
8017	Box	17099	1951	Ext. hand brake end	7144	47344
8017	Box	17919	1951	Int. load level markings	7195	47395
8017	Box	17919	1951	Int. load level marks	7196	47396
8017	Box	17919	1951	Int.	7197	47397
8017	Box		1951	Frame 3/4 front inverted	7242	47442
8037	Box	18499	1952	Frame 3/4 front	7500	47687
8037	Box	18499	1952	Frame 3/4 front inverted	7501	47688
8037	Box	18499	1952	Truck, side view	7502	47689
8037	Box	18499	1952	Truck, front view	7503	47690
8037	Box	18499	1952	Ext. 3/4 side	7504	47691

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
CHESAPEAKE & OHIO (continued)						
8037	Box	18499	1952	Ext. 3/4 side	7505	47692
8037	Box	18499	1952	Ext. end	7506	47693
8037	Box	18499	1952	Ext. hand brake end	7507	47694
8037	Box		1952	Int. no floor or sheathing	7508	47695
8037	Box		1952	Int. finished car	7509	47696
8160	Box		1954	Frame 3/4 front	8241	48275
8160	Box		1954	Frane 3/4 front inverted	8242	48276
8160	Box		1954	Frame 3/4 side	8243	48277
8160	Box		1954	Frame 3/4 side inverted	8244	48278
8160	Box		1954	Different view of 8244	8245	48279
8160	Box		1954	Int. no floor or sheathing	8246	48280
8160	Box	2990	1954	Ext. 3/4 side	8257	48291
8160	Box	2990	1954	Ext. hand brake end	8258	48292
8160	Box		1954	Underside of car	8429	48395
8160	Box		1954	Underside of car	8430	48396
8247	Box	28199	1955	Truck front view	8894	48827
8247	Box	28199	1955	Frame 3/4 front	8895	48828
8247	Box	28199	1955	Frame 3/4 front inverted	8896	48829
8247	Box	28199	1955	Int. no floor or sheathing	8897	48830
8247	Box	28199	1955	Int.	8898	48831
8247	Box	28199	1955	Ext. 3/4 side	8899	48832
8247	Box	28199	1955	Ext. 3/4 side opposite of 8899	8900	48833
8247	Box	28199	1955	Ext. end	8901	48834
8247	Box	28199	1955	Ext. hand brake end	8902	48835
8289	Box	21142	1956	Ext. 3/4 side	9106	49033
8289	Box	21142	1956	Ext. opposite of 9106	9107	49034
8289	Box	21142	1956	Ext. end	9108	49035
8289	Box	21142	1956	Ext. hand brake end	9109	49036
8289	Box	21142	1956	Int. no floor or sheathing	9110	49037
8289	Box	21142	1956	Int.	9111	49038
8289	Box		1956	Truck side	9112	49039
8289	Box		1956	Truck 3/4 front	9113	49040
8289	Box		1956	9123-9129 a series	9123	49050
8289	Box		1956	See 9123	9124	49051



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
CHESAPEAKE & OHIO (continued)						
8289	Box		1956	See 9123	9125	49052
8289	Box		1956	See 9123	9126	49053
8289	Box		1956	See 9123	9127	49054
8289	Box		1956	See 9123	9128	49055
8289	Box		1956	See 9123	9129	49056
		254075	1940	Interior from above, loaded	2902	44131
	Box		1956	Ext. closeup of bldrs. plate, blt. American Car; 9001-9006 a series	8001	48931
	Box		1956	Ext. closeup of damage; see 9001	9002	48932
	Box		1956	Same as 9002; see 9001	9003	48933
	Box		1956	Ext. closeup of damage; see 9001	9004	48934
	Box		1956	Different view of 9004; see 9001	9005	48935
	Box		1956	Int. closeup of damage; see 9001	9006	48936
	Flat	80553	1940	Ext. side	9306	49183
CHICAGO & ALTON						
5756	Box	51000	1944	Ext. 3/4 side	4104	44775
5756	Box	51000	1944	Ext. end	4105	44776
5756	Box	51000	1944	Ext. hand brake end	4106	44777
5756	Box	51000	1944	Interior	4107	44778
5756	Box	51000	1944	Ext. 3/4 side	4112	44782
5756	Box	51390	1944	Ext. side	4195	44813
5756	Box	51390	1944	Ext. opposite of 4195	4196	44814
5756	Box		1944	Truck 3/4 side	4197	44815
5756	Box		1944	Truck 3/4 front	4198	44816
5756	Box		1944	Ext. closeup of center door	4199	44817
5756	Box		1944	Similar to 4199	4200	44818
5793	Box	52147	1945	Ext. end	4568	44982
5793	Box	52111	1945	Ext. hand brake end	4569	44983
5793	Box	52161	1945	Interior	4570	44984
5793	Box	52384	1945	Ext. 3/4 side	4571	44985
5793	Box	52384	1945	Ext. 3/4 side, door open	4572	44986

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
CHICAGO & EASTERN ILLINOIS						
5802	Hopper	97622	1945	Ext. 3/4 side	4835	45205
5802	Hopper	97622	1945	Ext. hand brake end	4836	45206
5802	Hopper		1946	Ext. 3/4 side frame & hopper doors only	4866	45241
5802	Hopper		1946	Ext. similar to 4866 but one side up	4867	45242
5802	Hopper	97790	1946	Ext. 3/4 side	4868	45243
5802	Hopper	97790	1946	Ext. 3/4 side	4869	45244
5802	Hopper	97790	1946	Ext. end	4870	45245
5802	Hopper	97790	1946	Ext. hand brake end	4871	45246
5802	Hopper		1946	Int. from above	4872	45247
5802	Hopper		1946	Truck side view	4873	45248
5802	Hopper		1946	Truck front view	4874	45249
5808	Box	1	1945	Ext. 3/4 side	4717	45091
5808	Box	5	1945	Ext. 3/4 side	4718	45092
5808	Box	4	1945	Ext. 3/4 side	4719	45093
5808	Box	3	1945	Ext. 3/4 side	4720	45094
5808	Box	2	1945	Ext. 3/4 side	4721	45095
5808	Box	5	1945	Ext. hand brake end	4722	45096
5808	Box	1	1945	Ext. side	4728	45102
5808	Box		1945	Closeup of car lettering	4729	45103
5962B	Hopper Covered	80025	1950	Ext. hand brake end	6686	46913
5962B	Hopper Covered	80025	1950	Ext. 3/4 side	6687	46912
5996	Box	65596	1951	Ext. 3/4 side	6943	47157
5996	Box	65596	1951	Ext. 3/4 end only	6944	47158
8192	Box	3734	1954	Ext. 3/4 side	8389	48360
8192	Box	3734	1954	Ext. hand brake end	8390	48361
CHICAGO & ILLINOIS MIDLAND						
5490	Caboose	68	1931	Exterior 3/4 side	1849	43429
5490	Caboose	68	1931	Exterior 3/4 end only	1850	43430
5490	Caboose	68	1931	Exterior, car top, 3/4	1851	43431
5490	Caboose	68	1931	Exterior car roof, opposite of 43431	1852	43432



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
CHICAGO & ILLINOIS MIDLAND (continued)						
5490	Caboose	68	1931	Interior	1855	43433
5490	Caboose	68	1931	Interior, opposite of 43433	1856	43434
5562	Gondola	7410	1937	Ext. 3/4 side	2180A	49154
5563	Hopper	6300	1937	Ext. 3/4 side	2175	49152
8191	Box	16100	1954	Int. no floor or sheathing	8428	48394
8191	Box	16100	1954	Ext. 3/4 side	8431	48397
8191	Box	16100	1954	Ext. 3/4 side	8434	48398
8191	Box	16100	1954	Ext. hand brake end	8435	48399
CHICAGO & NORTH WESTERN						
5446	Auto/Furniture, single sheathed		1929	Interior, end view	1703	43374
5446	Auto/Furniture		1929	Frame inverted, end view	1704	43375
5446	Auto/Furniture		1929	Frame inverted, 3/4 side (orig. neg. badly stained)	1705	43376
5446	Auto/Furniture 40'6"		1929	Side view, no sheathing	1706	43377
5446	Auto/Furniture		1929	End door open, exterior	1707	43378
5446	Auto/Furniture		1929	Exterior end doors	1708	43379
5446	Auto/Furniture		1929	Interior end	1712	43380
5447	Gondola 44'3" 1.s	93799	1929	Frame under construction, side view	1674	43357
5447	Gondola 44'3" 1.s	93799	1929	Frame under construction, side view	1675	43358
5447	Gondola 44'3" 1.s	93799	1929	End view (hand brake)	1676	43359
5447	Gondola 44'3" 1.s	93799	1929	End view	1677	43360
5447	Gondola 44'3" 1.s.		1929	Side view	1678	43361
5481	Box	85000-85998	1931	Interior side door detail (even nos. only)	1778	43400
5481	Box	85000-85998	1931	Interior detail of frame welding (even nos. only)	1780	43401
5481	Box	85000-85998	1931	Exterior side door (even nos. only)	1781	43402
5481	Box	85000-85998	1931	Interior side door (even nos. only)	1782	43403
5481	Box	85000-85998	1931	Exterior side door (even nos. only)	1783	43404
5481	Box	85000-85998	1931	Exterior side door (even nos. only)	1784	43405
5481	Box	85000-85998	1931	Exterior door track detail (even nos. only)	1785	43406
5481	Box	85000-85998	1931	Interior side door (even nos. only)	1786	43407

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
CHICAGO & NORTH WESTERN (continued)						
5608	Hopper	64345	1940	Ext. 3/4 side	2601	43904
5608	Hopper	64347	1940	Ext. 3/4 side	2602	43905
5608	Hopper	64261	1940	Ext. end	2603	43906
5608	Hopper	64205	1940	Ext. hand brake end	2604	43907
5608	Hopper		1940	Side under construction, no sides	2606	43908
5608	Hopper		1940	2 views frame only	2607	43909
5691	Box	71028	1941	Ext. 3/4 side	3216	44304
5691	Box	71028	1941	Int. no floor or sheathing	3217	44305
5691	Box	71988	1941	Interior	3218	44306
5691	Box	71342	1941	Ext. side	3219	44307
5691	Box	71512	1941	Ext. hand brake end	3220	44308
5691	Box	71310	1941	Ext. end	3221	44309
5691	Box	71626	1941	Ext. roof from end	3222	44310
5691	Box		1941	3/4 front, frame	3223	44311
5691	Box		1941	3/4 front, frame inverted	3224	44312
5691	Box		1941	3/4 side, truck	3225	44313
5691	Box		1941	3/4 front, truck	3226	44314
5691	Box		1941	3/4 front, frame	3227	44315
5704			1942	Truck underside	3418	44494
5704			1942	Truck, center	3419	44495
5704	Box	77382	1942	Ext. 3/4 side	3457	44534
5704	Box	77382	1942	Ext. 3/4 end	3458	44535
5704	Box	77400	1942	Int.	3459	44536
5720	Flat	45865	1942	Ext. 3/4 side	3623	44638
5785	Box	80606	1945	Ext. 3/4 side	4504	44950
5785	Box	80606	1945	Ext. opposite of 4504	4505	44951
5785	Box		1945	Int. no floor or sheathing	4506	44952
5785	Box	80606	1945	Ext. hand brake end	4507	44953
5785	Box	80606	1945	Ext. end	4508	44954
5785	Box	80606	1945	Int.	4509	44955
5785	Box	81176	1945	Ext. roof	4510	44956
5800	Hopper	65215	1945	Ext. 3/4 side	4684	45064
5800	Hopper	65215	1945	Ext. 3/4 side	4685	45065
5800	Hopper	65215	1945	Ext. end	4686	45066



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
CHICAGO & NORTH WESTERN (continued)						
5800	Hopper	65215	1945	Ext. hand brake end	4687	45067
5800	Hopper	65215	1945	Int. from above	4688	45068
5800	Hopper		1945	Shop scene hopper doors installed	4712	45086
5800	Hopper		1945	Shop scene frame inverted; 4713-4715 a series	4713	45087
5800	Hopper		1945	Shop scene end sheets in place; see 4713	4714	45088
5800	Hopper		1945	See 4713	4715	45089
5800	Hopper		1945	Shop scene frame on side	4716	45090
5837	Box		1946	Structural layout for cutting; note 5019-5021 series	5019	45334
5837	Box		1946	See 5019	5020	45335
5837	Box		1946	See 5019	5021	45336
5837	Box		1946	Structural steel laid out for cutting; see 5030	5029	45344
5837	Box		1946	See 5029	5030	45345
5837	Box		1946	Bulb angles laid out for cutting; note 5042-5045 ser.	5042	45357
5837	Box		1946	See 5042	5043	45358
5837	Box		1946	See 5042	5044	45359
5837	Box		1946	See 5042	5045	45360
5837	Box		1946	Attaching fixture to frame members prior to welding; note 5046-5053 a series	5046	45361
5837	Box		1946	See 5046	5047	45361
5837	Box		1946	See 5046	5048	45363
5837	Box		1946	See 5046	5049	45364
5837	Box		1946	See 5046	5050	45365
5837	Box		1946	See 5046	5051	45366
5837	Box		1946	See 5046	5052	45367
5837	Box		1946	See 5046	5053	45368
5837	Box	105758	1946	Ext. 3/4 side	5054	45369
5837	Box		1946	Ext. roof front view	5055	45370
5837	Box	105758	1946	Ext. end	5056	45371
5837	Box	105758	1946	Ext. hand brake end	5057	45372
5837	Box	105758	1946	Ext. 3/4 side	5058	45373
5837	Box		1947	Frame, top from end	5059	45374
5837	Box		1946	Frame 3/4 front inverted	5060	45375
5837	Box		1946	Int. no floor or sheathing	5061	45376
5837	Box		1946	Truck, 3/4 front	5062	45377

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
CHICAGO & NORTH WESTERN (continued)						
5837	Box		1947	Truck, side view	5063	45378
5837	Box		1946	Test weld; note 5064-5067 a series	5064	45379
5837	Box		1946	See 5064	5065	45380
5837	Box		1946	See 5064	5066	45381
5837	Box		1946	See 5064	5067	45382
5837	Box		1946	Car side 3/4 end	5071	45385
5837	Box	105758	1946	Int.	5072	45386
5919A	Box	88364	1948	Ext. 3/4 side	6256	46431
5919A	Box	88364	1948	Opposite of 6256	6257	46432
5919A	Box	88364	1948	Ext. hand brake end	6258	46433
5920	Box	86390	1948	Ext. 3/4 front roof	6075	46256
5920	Box	86942	1948	Ext. 3/4 front roof	6087	46267
5920	Box	87238	1948	Ext. 3/4 side	6103	46280
5920	Box	87238	1948	Ext. opposite of 6103	6104	46281
5920	Box	87682	1949	Ext. side	6129	46306
5920	Box	87238	1948	Ext. hand brake end	6200	46376
5920	Box	87238	1948	Ext. end	6201	46377
5925	Hopper	67655	1948	Ext. 3/4 side	6225	46401
5925	Hopper	67655	1948	Ext. 3/4 side	6232	46407
5925	Hopper	67655	1948	Ext. end	6233	46408
5925	Hopper	67655	1948	Ext. hand brake end	6234	46409
5925			1948	Workers removing bad rivets	6249	46424
5925	Hopper	49703	1949	Ext. 3/4 side	6408	46583
5925	Hopper	49703	1949	Ext./ hand brake end	6409	46584
5955	Box	106982	1949	Ext. 3/4 side	6508	46671
5955	Box	106982	1949	Ext. end	6509	46672
5955	Box	106982	1949	Ext. hand brake end	6510	46673
5955	Box	106982	1949	Ext. 3/4 end only	6511	46674
5955	Box	106982	1949	Ext. 3/4 side opposite of 6508	6512	46675
5955	Box	108104	1949	Ext. 3/4 side	6513	46676
5955	Box		1949	Ext. closeup of truck	6514	46677
5955	Box		1949	Shop scene fabricating frame; see 6516	6515	46678
5955	Box		1949	Shop scene see 6515	6516	46679
5957	Box		1949	Side sill	6564	46726



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
CHICAGO & NORTH WESTERN (continued)						
5957	Box		1949	Int. no floor or sheathing	6565	46727
5957	Box		1949	Int. side door	6566	46728
5957	Box		1949	Int. unfinished	6567	46729
5957	Box		1949	Int. unfinished	6568	46730
5957	Box	57694	1949	Ext. 3/4 side	6569	46731
5957	Box	57694	1949	Ext/ 3/4 side; opposite of 6569	6570	46732
5957	Box	57694	1949	Ext. end	6571	46733
5957	Box	57694	1949	Ext. hand brake end	6572	46734
5957	Box	57800	1949	Int.	6573	46735
5957	Box	57800	1949	Int.	6574	46736
5957	Box	57800	1949	Int.	6575	46737
5957	Box		1949	Ext. side end only at ladder; 6587-6594 a series	6587	46749
5957	Box		1949	See 6587	6588	46750
5957	Box		1949	See 6587	6589	46751
5957	Box		1949	See 6587	6590	46752
5957	Box		1949	See 6587	6591	46753
5957	Box		1949	See 6587	6592	46754
5957	Box		1949	See 6587	6593	46755
5957	Box		1949	See 6587	6594	46756
5957			1949	Frame 3/4 front inverted; 6629-6635 a series of frame construction	6629	46796
5957			1949	See 6629	6630	46797
5957			1949	See 6629	6631	46798
5957			1949	See 6629	6632	46799
5957			1949	See 6629	6633	46800
5957			1949	See 6629	6634	46801
5957			1949	See 6629	6635	46802
5979C	Hopper Covered	69467	1951	Ext. 3/4 side	6975	47189
5979C	Hopper Covered	69467	1951	Ext. hand brake end	6976	47190
8007	Box	6838	1951	Ext. 3/4 side; see 7108	7106	47313
8007	Box	6838	1951	Ext. 3/4 side; same as 7106 but different lettering	7108	47314
8007	Box	6838	1951	Ext. end	7110	47315
8007	Box	6838	1951	Ext. hand b rake end	7111	47316
8007	Box		1951	Int. no floor or sheathing	7112	47317

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
CHICAGO & NORTH WESTERN (continued)						
8007	Box	7990	1951	Int. finished car	7113	47318
8007	Box		1951	A ser.(7156-7161) of assemb. insulated car side sects.	7156	47356
8007	Box		1951	See 7156	7157	47357
8007	Box		1951	See 7156	7158	47358
8007	Box		1951	See 7156	7159	47359
8007	Box		1951	See 7156	7160	47360
8007	Box		1951	See 7156	7161	47361
8007	Box		1951	Int. installing car end; 7162-7168 a series	7162	47362
8007	Box		1951	See 7162	7163	47363
8007	Box		1951	See 7162	7164	47364
8007	Box		1951	See 7162	7165	47365
8007	Box		1951	See 7162	7166	47366
8007	Box		1951	See 7162	7167	47367
8007	Box		1951	See 7162	7168	47368
8016	Box	5000 ser.	1951	Train of cars in yard for delivery; see 7063	7062	47276
8016	Box	5000 ser.	1951	Same as 7062	7063	47277
8016	Box		1951	Same as 7062	7064	47278
8016	Box		1951	Train of cars for delivery	7098	47305
8105	Box	84288	1953	Ext. 3/4 side	8127	48166
8105	Box	84288	1953	Ext. 3/4 side opposite of 8127	8128	48167
8105	Box	84288	1953	Ext. hand brake end	8129	48168
8144	Box	1	1953	Ext. 3/4 side	8141	48180
8144	Box	1	1953	Ext. hand brake end	8142	48181
8144	Box	1	1953	Int.	8143	48182
8144	Box		1953	Int. no floor or sheathing	8158	48197
8144	Box		1953	int. similar to 8158	8159	48198
8144	Box		1953	Int. side wall	8162	48201
8144	Box		1953	Similar to 8162	8163	48202
8144	Box	275	1953	Ext. 3/4 side	8164	48203
8144	Box	275	1953	Ext. 3/4 side	8165	48204
8144	Box	275	1953	Ext. end	8166	48205
8144	Box	275	1953	Ext. hand brake end	8167	48206
8144	Box	625	1953	Int.	8186	48225
8177	Box	1555	1954	Ext. 3/4 side	8365	48336



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
CHICAGO & NORTH WESTERN (continued)						
8177	Box	1555	1954	Ext. 3/4 side different paint scheme	8366	48337
8177	Box	1555	1954	Ext. end	8367	47338
8177	Box	1555	1954	Ext. hand brake end	8368	48339
8177	Box		1954	Int.	8369	48340
8177	Box		1954	Int. corner	8370	48341
8202 & 8175A	Box		1954	Ext. 3 cars in line	8436	48400
8216B	Box	2256	1955	Ext. 3/4 side	8611	48568
8216B	Box	2256	1955	Ext. 3/4 side; opposite of 8611	8612	48569
8216B	Box	2256	1955	Ext. hand brake end	8613	48570
8228	Box	3109	1955	Ext. 3/4 side	8778	48732
8228	Box	3109	1955	Ext. 3/4 side; opposite of 8778	8779	48733
8228	Box	3109	1955	Ext. end	8780	48734
8228	Box	3109	1955	Ext. hand brake end	8781	48735
8262	Box	4516	1955	Ext. 3/4 side	8945	48875
8262	Box	4516	1955	Ext. 3/4 side; opposite of 8945	8946	48876
8262	Box	4516	1955	Ext. end	8947	48877
8262	Box	4516	1955	Ext. hand brake end	8948	48878
8280	Box		1955	Train of cars for delivery; 8990-8995 a series	8990	48920
8280	Box		1955	Train of cars for delivery	8991	48921
8280	Box		1955	Train of cars for delivery	8992	48922
8280	Box		1955	Train of cars for delivery; see 8990	8993	48923
8280	Box		1955	Train of cars for delivery; see 8990	8994	48924
8280	Box		1955	Train of cars for delivery; see 8990	8995	48925
8280	Box		1956	Paint shop cutting stencils and applying letters; 9016-9022 a series	9016	48946
8280	Box		1956	See 9016	9017	48947
8280	Box		1956	See 9016	9018	48948
8280	Box		1956	See 9016	9019	48949
8280	Box		1956	See 9016	9020	48950
8280	Box		1956	See 9016	9021	48951
8280	Box		1956	See 9016	9022	48952
8280	Box	7851	1956	Ext. 3/4 side	9024	48954
8280	Box	7851	1956	Ext. opposite of 9024	9025	48955

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
CHICAGO & NORTH WESTERN (continued)						
8280	Box	7851	1956	Ext. end	9026	48956
8280	Box	7851	1956	Ext. hand brake end	9027	48957
8280	Box		1956	Int. installing strap anchors; 9039-9044 a series	9039	48969
8280	Box		1956	See 9039	9040	48970
8280	Box		1956	See 9039	9041	48971
8280	Box		1956	See 9039	9042	48972
8280	Box		1956	See 9039	9043	48973
8280	Box		1956	See 9039	9044	48974
8280	Box	9643	1956	Int.	9051	48980
8280	Box	9643	1956	Int.	9052	48981
8280	Box		1956	Ext. floor & frame from below	9053	48982
8280	Box		1956	Different view of 9053	9054	48983
8280	Box		1956	Different view of 9053	9055	48984
8307	Box	23099	1956	Underside of frame, closeup of floor clamps	9206	49128
8307	Box	23099	1956	Ext. 3/4 side	9211	49133
8307	Box	23099	1956	Ext. 3/4 side; opposite of 9211	9212	49134
8307	Box	23099	1956	Ext. end	9213	49135
8307	Box	23099	1956	Ext. hand brake end	9214	49136
	Box	1491	1955	Coupler pocket; 8793-8796 a series	8793	48747
		1491	1955	Coupler pocket	8794	48748
	Box	1491	1955	Coupler pocket	8795	48749
	Box	1491	1955	Coupler pocket	8796	48750
CHICAGO BURLINGTON & QUINCY						
	Box	41999		Hand brake end	1371	43301
	Box	41999		Opposite end	1373	43302
	Box	45899	1928c.	End	1376	43303
	Box	45899	1928c.	Hand brake end	1375	43304
	Steel box	16899	1926	Hand brake end	1446	43315
	Steel box	16899	1926	End view	1447	43316
	Box Automobile	45899	1925	Ext. 3/4 side	5388	49167
	Box Automobile	45899	1925	Ext. side (duplicate of 49167)	5388	49168



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
CHICAGO GREAT WESTERN						
5483	Hopper, 140,000	67591	1931	Pressed steel main frame	1790	43408
5483	Hopper, 140,000	67591	1931	Worker welding panel	1792	43409
5483	Hopper, 140,000	67591	1931	Worker welding tubular framing	1793	43416
5483	Hopper, 140,000	67591	1931	Worker welding tubular framing	1793A	43411
5483	Hopper, 140,000	67591	1931	Worker welding side sheet	1794	43412
5483	Hopper, 140,000	67591	1931	Worker welding in bolster area	1795	43413
5483	Hopper, 140,000	67591	1931	Exterior 3/4 end frame and truck	1801	43414
5483	Hopper, 140,000	67591	1931	3/4 view truck and end of frame	1802	43415
5483	Hopper, 140,000	67591	1931	Exterior end	1803	43416
5483	Hopper, 140,000	67591	1931	Exterior 3/4 end frame and coupler	1809	43417
5483	Hopper, 140,000	67591	1931	Exterior end, same as 43415	1810	43418
5483	Hopper, 140,000	67591	1931	Exterior 3/4 end frame and center support	1811	43419
5483	Hopper, 140,000	67591	1931	Exterior 3/4 end (half car)	1812	43420
5483	Hopper, 140,000	67591	1931	Exterior 3/4 end (opposite of 43420)	1813	43421
5483	Hopper, 140,000	67591	1931	Door drop hinge	1815	43422
5483	Hopper, 140,000	67599	1931	Exterior end	1819	43423
5483	Hopper, 140,000	67599	1931	Exterior 3/4 end (half car)	1827	43424
5498	Grain/Flour Box	87886	1933	Exterior 3/4 side	1876	43440
5498	Grain/Flour Box	87886	1933	Exterior side	1877	43441
5528	Flat 52'		1936	Exterior, 3/4 side	2131	43591
5584	Box		1938	Interior end finished car	2388	43725
5708	Box	52183	1942	Ext. 3/4 side	3328	44412
5708	Box	52189	1942	Ext. hand brake end	3329	44415
5708	Box	52189	1942	Int.	3330	44416
5771	Box	91900	1944	Ext. side	4430	44913
5771	Box	91900	1944	Ext. hand brake end	4431	44914
5772	Hopper	69049	1944	Ext. 3/4 side	4457	44932
5772	Hopper	69049	1944	Ext. hand brake end	4458	44933
5805	Box	92000	1945	Ext. 3/4 side	4691	45071
5805	Box	92000	1945	Ext. hand brake end	4692	45072
5853	Hopper Covered	70025	1947	Ext. 3/4 side	5366	
5853	Hopper Covered	70025	1947	Ext. hand brake end	5367	
5853	Hopper Covered	70025	1947	Ext. roof doors open	5368	

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
CHICAGO GREAT WESTERN (continued)						
5853	Hopper Covered	70025	1947	Ext. roof doors closed	5369	
5875	Box	93251	1947	Ext. 3/4 side	5587	45844
5875	Box	93251	1947	Ext. hand brake end	5588	45845
5875	Box	93251	1947	Ext. 3/4 side	5662	45918
8016	Box	5000 ser.	1951	Train of cars in yard for delivery	7067	47281
8016	Box	5000 ser.	1951	Same as 7067	7068	47282
8016	Box	5200	1951	Ext. 3/4 side	7069	47283
8016	Box	5200	1951	Ext. hand brake end	7070	47284
CHICAGO INDIANAPOLIS & LOUISVILLE (MONON)						
5707	Box	9427	1942	Ext. 3/4 underside	3420	44496
5707	Box	9427	1942	Interior	3421	44497
5707	Box	9427	1942	Ext. 3/4 end only	3422	44498
5707	Box	9426	1942	Ext. 3/4 hand brake end	3423	44499
5860	Box	1	1947	Ext. side	5454	45707
5860	Box	1	1947	Ext. 3/4 side	5455	45708
5860	Box	1	1947	Ext. 3/4 side	5456	45709
5860	Box	1	1947	Ext. 3/4 side	5458	45710
5860	Box	1	1947	Ext. 3/4 side	5459	45711
5860	Box	1	1947	Ext. hand brake end	5460	45712
5860	Box		1947	Ext. coupler and truck	5460A	45713
5860	Box	1	1947	Ext. hand brake end	5461	45714
5860	Box	1	1947	Int.	5462	45715
5860	Box	1	1947	Ext. closeup of air hose connection	5463	45716
5860	Box	1	1947	Same as 5463	5464	45717
5860	Box	227	1947	Ext. 3/4 end only	5556B	45813
5860	Box	470	1947	Ext. 3/4 side	5557	45815
5942A	Box	502	1949	Ext. 3/4 side	6440	46615
5942A	Box		1949	Posts and side sheet samples	6450	46625
5942A	Box	502	1949	Ext. side	6451	46626
5942A	Box		1949	Similar to 6450	6452	46627
5942A	Box	511	1949	Ext. side	6453	46628



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
CHICAGO INDIANAPOLIS & LOUISVILLE (MONON) (continued)						
5942A	Box		1949	Side sheet tests	6454	46629
5942A	Box	521	1949	Ext. side	6455	46630
5942A	Box	521	1949	Ext. 3/4 side	6462	46637
5942A	Box	521	1949	Ext. hand brake end	6363	46638
8060	Box	726	1952	Ext. 3/4 side	7663	47839
8060	Box	726	1952	Ext. hand brake end	7664	47840
8105	Box	861	1953	Ext. 3/4 side	8119	48160
8105	Box	861	1953	Ext. hand brake end	8120	48161
8108	Hopper Covered	4331	1953	Ext. 3/4 side	8115	48156
8108	Hopper Covered	4331	1953	Ext. hand brake end	8116	48157
8129	Box	1481	1953	Ext. 3/4 side	8130	48169
8129	Box	1481	1953	Ext. hand brake end	8131	48170
8168	Tank (CI&L-Monon)		1954	Parts for tank car door	8228	48262
8168	Tank		1954	Tank car door	8229	48263
8168	Tank		1954	Tank car door	8230	48264
8168	Tank		1954	Tank car door	8231	48265
8168	Tank		1954	Tank car door	8232	48266
8168	Tank		1954	Tank car door	8233	48267
8168	Hopper	4001	1954	Ext. 3/4 side	8380	48351
8168	Hopper	4001	1954	Ext. end	8381	48352
JO33991	Box	533	1950	Ext. 3/4 side; 6876-6877 a series	6876	47093
JO33991	Box	533	1950	Ext. 3/4 end; see 6876	6877	47094
	Gondola	32447	1938	(New in 1926) interior end (for repair)	2439	43762
	Gondola	32447	1938	(New 1926) ext. 3/4 end (in for repair)	2440	43763
	Gondola	33286	1938	Ext. 3/4 front	2441	43764
	Gondola		1938	(New 1926) ext. 3/4 side end only	2442	43765
	Gondola		1939	(New 1926) ext. drop door open	2442X	43766
	Gondola		1939	(New 1926) opposite of 2442X	2443	43767
	Box	532	1949	Ext. 3/4 side	6585	46747
	Hopper Covered	4270	1953	Ext. worker opening roof hatches; note 7945-7959 and 7971-7972 a series. This car apparently used as a model for Lot 8094	7945	48037
	Hopper Covered	4270	1953	Ext. worker opening roof hatches; see 7945	7946	48038
	Hopper Covered	4270	1953	Ext. roof only; see ;7945	7947	48039

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.	
CHICAGO INDIANAPOLIS & LOUISVILLE (MONON) (continued)							
	Hopper Covered	4270	1953	Ext. worker on roof; see 7945	7948	48040	
	Hopper Covered	4270	1953	Ext. end; see 7945	7949	48041	
	Hopper Covered	4270	1953	Ext. measuring hopper doors; see 7945	7953A	48042	
	Hopper Covered	4270	1953	Ext. side & roof; see 7945	7951	48043	
	Hopper Covered	4270	1953	Ext. worker on roof; see 7945	7952	48044	
	Hopper Covered	4270	1953	Ext. closeup of side; see 7945	7953	48045	
	Hopper Covered	4270	1953	Ext. 3/4 side end only; see ;7945	7956	48046	
	Hopper Covered	4270	1953	Ext. roof; see 7945	7955	48047	
	Hopper Covered	4270	1953	Ext. roof; see 7945	7956	48048	
	Hopper Covered	4270	1953	Ext. 3/4 side; see 7945	7957	48049	
	Hopper Covered	4270	1953	Ext. worker opening roof hatch; see 7945	7950	48050	
	Hopper Covered		1953	Ext. 3/4 roof only (not Pullman-built)	7971	48064	
	Hopper Covered		1953	Ext. roof only (not Pullman-built)	7972	48065	
	Hopper Covered		1953	Top view of roof doors (not Pullman-built)	7974	48067	
	Hopper Covered		1953	Ext. 3/4 side (not Pullman-built)	7975	48068	
	Hopper Covered		1953	Ext. end (not Pullman-built)	7976	48069	
CHICAGO MILWAUKEE ST. PAUL & PACIFIC							
	Box	50286	1949	3/4 end	6385	46560	
	Box	50286	1949	Ext. hand brake end	6386	46561	
8025	Box	35003	1951	Ext. 3/4 side	7189	47389	
8025	Box	35003	1951	Ext. hand brake end	7190	47390	
8105	Box	35061	1953	Ext. 3/4 side	8109	48150	
8105	Box	35061	1953	Ext. hand brake end	8110	48151	
8224	Box	8741	1955	Ext. hand brake end	8653	48608	
8224	Box	Compartmentized	1955	Int. compartmentizer doors; 8659-8661 a series	8659	48614	
8224	Box	Compartmentized	1955	See ;8659	8660	48615	
8224	Box	Compartmentized	1955	See 8659	8661	48616	
8224	Box	Compartmentized	8741	1955	Ext. 3/4 side	8662	48617
8224	Box	Compartmentized	1955	Int. gates backside	8719	48673	
8224	Box	Compartmentized	1955	Int. gates back side	8720	48674	
8224	Box	Compartmentized	1955	Int. gates locking side	8721	48675	



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
CHICAGO MILWAUKEE ST. PAUL & PACIFIC (continued)						
8295B	Box	Compartmentized 39050	1956	Ext. 3/4 side	9187	49114
8295B	Box	Compartmentized 39050	1956	Ext. hand brake end	9188	49115
CHICAGO ROCK ISLAND & PACIFIC						
5817	Box		1946	Frame, 3/4 front	4837	45207
5817	Box		1946	Frame, 3/4 front inverted	4838	45208
5817			1946	3/4 end coupler	4839	45214
5817			1946	3/4 rear, frame	4840	45215
5817			1946	3/4 rear, frame	4841	45216
5817			1946	3/4 side, frame	4842	45217
5817			1946	3/4 side, frame	4843	45218
5817			1946	Closeup of frame	4844	45219
5817			1946	Coupler and frame	4845	45220
5817			1946	3/4 front, frame	4846	45221
5817			1946	Frame w/air tank	4847	45222
5817			1946	Frame, 3/4 side	4848	45223
5817	Box	25000	1946	Ext. roof front view	4864	45239
5817	Box	25000	1946	Ext. 3/4 side	4865	45240
5817	Box		1946	Section of frame in welding fixture	4950	45283
5817	Box		1946	Section of frame in welding fixture; see 4950	4951	45284
5817			1946	Shop scene welding fixture, steps in fabricating frame section; note 4952-4956 a series	4952	46850
5817			1946	See 4952	4953	46851
5817			1946	See 4952	4955	46852
5817	Box		1946	Section of frame in welding fixture; see 4950	4954	45285
5817	Box		1946	See 4952	4955	46852
5817	Box		1946	Shop scene building frame	4956	45286
5817	Box		1946	Shop scene building frame; see 4956	4957	45287
5817	Box		1946	See 4952	4958	46853
5817	Box		1946	Ext. 3/4 side	4972	45288
5817	Box	25120	1946	Ext. hand brake end	4973	45289
5817	Box		1946	Shop scene frame inverted	4974	45290

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
CHICAGO ROCK ISLAND & PACIFIC (continued)						
5817	Box	25324	1946	Ext. 3/4 side	4980	45296
5817	Box		1946	Truck bolster inverted	4981	45297
5817	Box		1946	Different view of 4981	4982	45298
5817	Box		1946	Different view of 4981	4983	45299
5919	Box	25688	1948	Ext. 3/4 side	6062	46242
5919	Box	25688	1948	Ext. hand brake end	6063	46243
5919	Box	26304	1948	Ext. side	6088	46268
5919	Box	26393	1948	Ext. side	6131	46308
8028	Box	21499	1951	Ext. 3/4 side	7268	47458
8028	Box	21499	1951	Ext. hand brake end	7269	47469
8028	Box	22621	1952	Ext. 3/4 side	7279	47473
8028	Box	22621	1952	Ext. 3/4 side (3/4 of car)	7280	47474
8081	Hopper Covered	100	1953	Group of men posing with car	7666	47842
8081	Hopper Covered	100	1953	Same as 7666	7667	47843
8081	Hopper Covered	165	1953	Ext. 3/4 side	7716	47893
8081	Hopper Covered	165	1953	Ext. hand brake end	7717	47894
8081	Hopper Covered	165	1953	Ext. roof front view hatches open	7718	47895
8081	Hopper Covered	165	1953	Ext. roof front view hatches closed	7719	47896
8210	Box	5159	1954	Ext. 3/4 side	8492	48450
8210	Box	5159	1954	Ext. hand brake end	8493	48451
	Box	21000	1951	Ext. group of men posing by CRI&P box car; note 7216-7218 a series	7216	47416
	Box	21000	1951	See 7216	7217	47417
	Box	21000	1951	See 7216	7218	47418
CHICAGO ST. PAUL MINNEAPOLIS & OMAHA						
5434	Flat Car 46'0"		1928	Car truck, end view	1580	43342
5434	Flat Car 46'0"		1928	Car truck, Dalman One Level, side	1587	43344
5434	Flat Car 46'0", 100,000#		1929	3/4 end, frame inverted on truck	1589	43345
5434	Flat Car 46'0"		1928	Frame, under construction, 3 views	1590	43346
5434	Flat Car 46'0"		1928	A		43347
5434	Flat Car 46'0"		1928	B		43348



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
CHICAGO ST. PAUL MINNEAPOLIS & OMAHA (continued)						
5434	Flat Car	46'0"	1928	End view	1591	43349
5434	Flat Car	46'0"	1928	End view	1592	43350
5434	Flat Car	46'0", 100,000#	1928	Side	1593	43351
5434	Flat Car	46'0"	1928	Side frame w/truck under construction	1594	43352
5434	Flat Car	46'0"	1928	Side view truck	1599	43353
5434	Flat Car	46'0"	1928	End view truck	1600	43354
5919A	Box	39302	1948	Ext. 3/4 side (incorrect lot no. on negative0	6268	46443
5919A	Box	39304	1948	Ext. 3/4 side	6291	46466
5919A	Box	39304	1948	Ext. hand brake end	6292	46467
8105	Box	22440	1953	Ext. 3/4 side	8121	48162
8105	Box	22440	1953	Ext. hand brake end	8122	48163
8109	Box	22418	1953	Ext. 3/4 side	8113	48154
8109	Box	22418	1953	Ext. hand brake end	8114	48155
CLEVELAND, CINCINNATI, CHICAGO & ST. LOUIS						
	Steel hopper	87599	1926	Hand brake end	1426	43312
	Steel hopper	87599	1926	Side view	1427	43313
	Steel hopper	87599	1926	3/4 end from above	1428	43314
CLINCHFIELD RR.						
8055	Hopper	52499	1953	Ext. 3/4 side	7798	47972
8055	Hopper	52499	1953	Ext. hand brake end	7799	47973
8295A	Box	5655	1956	Ext. 3/4 side	9176	49103
8295A	Box	5655	1956	Ext. hand brake end	9177	49104

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
COLUMBUS & GREENVILLE						
8032	Gondola	9336	1952	Ext. 3/4 side	7473	47660
8032	Gondola	9336	1952	Ext. hand brake end	7474	47661
COMMONWEALTH CAST STEEL						
5497	Hopper	P65X1000	1933	Commonwealth Cast Steel Underframe, ext. hopper hinge (note--1870-1875 same car)	1870	43435
5497	Hopper	P65X1000	1933	Commonwealth Cast Steel Underframe, ext. 3/4 side	1872	43436
5497	Hopper	P65X1000	1933	CCS Underframe, ext. 3/4 side	1873	43437
5497	Hopper	P65X1000	1933	CCS Underframe, ext. side	1874	43438
5497	Hopper	P65X1000	1933	CCS Underframe, 3/4 side	1875	43439
COPPER RANGE						
5662A	Box	4001	1941	Ext. 3/4 side	3037	44252
5908A	Box	4010	1948	Ext. opposite of 6074	6073	46255
5908A	Box	4010	1948	Ext. 3/4 side	6074	46253
5908A	Box	4010	1948	Ext. end	6076	46254
5919A	Box	4025	1948	Ext. 3/4 side	6290	46465
5919A	Box	4025	1948	Ext. hand brake end	6293	46468
DELAWARE & HUDSON						
5973	Box		1950	Int. floor at side door	6878	47095
5973	Box	18570	1950	Ext. 3/4 side	6879	47096
5973	Box	18570	1950	Ext. 3/4 hand brake end	6880	47097
5998	Box	19099	1951	Ext. 3/4 side	6953	47167
5998	Box	19099	1951	Ext. hand brake end	6954	47168
8049	Box	19600	1952	Ext. 3/4 side	7615	47796
8049	Box	19600	1952	Ext. hand brake end	7616	47797



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
DELAWARE & HUDSON (continued)						
8139	Hopper Covered	2935	1953	Ext. 3/4 side	8170	48209
8139	Hopper Covered	2935	1953	Ext. hand brake end	8171	48210
8161	Hopper Covered	2900	1953	Ext. 3/4 side	8172	48211
8161	Hopper Covered	2900	1953	Ext. hand brake end	8173	48212
8294	Box	20010	1956	Ext. 3/4 side	9174	49101
8294	Box	20010	1956	Ext. hand brake end	9175	49102
8295	Box	22164	1956	Ext. 3/4 side	9157	49084
8295	Box	22164	1956	Ext. hand brake end	9158	49085
DELAWARE LACKAWANNA & WESTERN						
5936	Box	35139	1948	Ext. hand brake end	6202	46378
5936	Box	35139	1948	Ext. 3/4 side	6250	46425
5936	Box	35139	1948	Ext. hand brake end	6251	46426
DENVER & RIO GRANDE WESTERN						
8145	Hopper Covered	18450	1953	Ext. 3/4 side	8204	48241
8145	Hopper Covered	18450	1953	Ext. hand brake end	8205	48242
8214	Box	60500	1954	Ext. 3/4 side	8494	48452
8214	Box	60500	1954	Ext. hand brake end	8495	48453
DETROIT & MACKINAC						
5621A	Box	2700	1940	Ext. side	2731	44007

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
DETROIT TOLEDO & IRONTON						
8112	Box	15299	1953	Ext. 3/4 side	8002	48095
8112	Box	15299	1953	Ext. hand brake end	8003	48096
8112	Box	15299	1953	Int.	8004	48097
8112	Box	15299	1953	Int.	8005	48098
DULUTH MISSABE & IRON RANGE						
5723	Hopper Ore	25561	1942	Ext. opposite of 3585	3584	44605
5723	Hopper Ore	25561	1942	Ext. hand brake end	3585	44606
5723	Hopper Ore	25561	1942	Ext. end	3586	44607
5723	Hopper Ore	25561	1942	Int.	3587	44608
5723	Hopper Ore	25561	1942	Ext. end under construction	3588	44609
5723	Hopper Ore		1942	Trucks 3/4 front	3589	44610
5723	Hopper Ore		1942	Truck 3/4 side	3590	44611
5723	Hopper Ore		1942	Truck 3/4 side	3591	44612
5723	Hopper Ore		1942	Int. end sheet	3592	44613
5723	Hopper Ore		1942	Shop scene frame under const. (3593-3600 car body under construction)	3593	44614
5723	Hopper Ore		1942	Frame 3/4 end under construction	3594	44615
5723	Hopper Ore		1942	Floor & frame 3/4 end under construction	3595	44616
5723	Hopper Ore		1942	3/4 side frame under construction	3596	44617
5723	Hopper Ore		1942	Continuation of 3593	3597	44618
5723	Hopper Ore		1942	Cont. of 3593	3598	44619
5723	Hopper Ore		1942	Cont. of 3593	3599	44620
5723	Hopper Ore		1942	Cont. of 3593	3600	44621
5723	Hopper Ore		1942	Closeup of dump mech.	3601	44622
5723	Hopper Ore		1942	Different view of 3601	3604	44623
5723	Hopper Ore		1942	Closeup of air brake line	3605	44624
5723	Hopper Ore		1942	Closeup of dump mech.	3606	44625
5723	Hopper Ore		1942	Ext. 3/4 side	3611	44626
8041	Hopper Ore	31016	1952	Ext. 3/4 side	7282	47475
8041	Hopper Ore	31016	1952	Ext. 3/4 side opposite of 7282	7283	47476



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
DULUTH MISSABE & IRON RANGE (continued)						
8041	Hopper Ore	31016	1952	Ext. 3/4 side	7284	47477
8041	Hopper Ore	31016	1952	Ext. end	7285	47478
8041	Hopper Ore	31016	1952	Ext. hand brake end	7286	47479
8041	Hopper Ore		1952	Truck side	7287	47480
8041	Hopper Ore		1952	Truck front view	7288	47481
8041	Hopper Ore		1952	Truck closeup at brake beam	7289	47482
8041	Hopper Ore		1952	Int. hopper from above	7290	47483
8041	Hopper Ore		1952	Int. from above	7291	47484
8041	Hopper		1952	Shop scene fabricating hopper car lot 8041; shop "B"; 7338-7362 a series	7338	47530
8041	Hopper		1952	See 7338	7339	47531
8041	Hopper		1952	See 7338	7340	47532
8041	Hopper		1952	See 7338	7341	47523
8041	Hopper		1952	See 7338	7342	47534
8041	Hopper		1952	See 7338	7343	47535
8041	Hopper		1952	Frames being placed on trucks; see 7338	7344	47536
8041	Hopper		1952	Body placed on frame; see 7338	7345	47537
8041	Hopper		1952	Body on frame; see 7338	7346	47538
8041	Hopper		1952	Frames shop "B"; see 7338	7347	47539
8041	Hopper		1952	Forge shop looking west; see 7338	7348	47540
8041	Hopper		1952	Shop "B" looking s.e. frame fabricating; see 7338	7349	47541
8041	Hopper		1952	Shop "B" frame fabricating; see ;7338	7350	47542
8041	Hopper		1952	Shop "B" frame fabricating; see 7338	7351	47543
8041	Hopper		1952	Shop "B" looking west body frame mounted; see 7338	7352	47544
8041	Hopper		1952	Similar to 7352; see 7338	7352	47544
8041	Hopper		1952	Workers hanging hopper doors; see 7338	7354	47546
8041	Hopper		1952	Similar to 7354; see 7338	7355	47547
8041	Hopper		1952	Similar to 7354; see 7338	7356	47548
8041	Hopper		1952	Shop "B"; see 7338	7357	47549
8041	Hopper		1952	Shop "B" hopper body floor; see 7338	7358	47550
8041	Hopper		1952	Shop "B" frames on truck; see 7338	7359	47551
8041	Hopper		1952	Frame inverted; see 7338	7360	47552
8041	Hopper		1952	Closeup of car side; see 7338	7361	47553
8041	Hopper		1952	Winch, door opener; see 7338	7362	47554

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
DULUTH MISSABE & IRON RANGE (continued)						
8041	Hopper Ore		1952	Frame coupler pocket	7446	47635
8041	Hopper Ore		1952	Frame end section	7447	47636
8041	Hopper Ore		1952	Frame section from rear	7448	47637
8041	Hopper Ore		1952	Frame coupler pocket from rear	7449	47638
8041	Hopper Ore		1952	Frame bolster	7450	47639
8041	Hopper Ore		1952	Frame coupler pocket front	7451	47640
8125	Hopper Ore		1953	3 men posing by Missabe ore car; see 8007	8006	48099
8125	Hopper Ore		1953	Group of men posing by Missabe ore car; see 8006	8007	48100
8125	Hopper Ore		1953	Parts in spot weld shop; 8060-8068 a series	8060	48101
8125	Hopper Ore		1953	Similar to 8060	8061	48102
8125	Hopper Ore		1953	See 8060	8062	48103
8125	Hopper Ore		1953	See 8060	8063	48104
8125	Hopper Ore		1953	See 8060	8064	48105
8125	Hopper Ore		1953	See 8060	8065	48106
8125	Hopper Ore		1953	See 8060	8066	48107
8125	Hopper Ore		1953	See 8060	8067	48108
8125	Hopper Ore		1953	See 8060	8068	48109
JO36209	Hopper Ore	32499	1952	A complete rebuild; 7475-7487 a series	7475	47662
JO36209	Hopper Ore	32499	1952	Ext. hand brake end; see 7475	7476	47663
JO36209	Hopper Ore	32499	1952	Ext. 3/4 side in primer paint; see 7475	7477	47664
JO36209	Hopper Ore	32499	1952	Ext. 3/4 end lower half; see 7475	7478	47665
JO36209	Hopper Ore	32499	1952	Ext. 3/4 side; see 7475	7479	47666
JO36209	Hopper Ore	32499	1952	Ext. 3/4 end only; see 7475	7480	47667
JO36209	Hopper Ore	32499	1952	Ext. 3/4 end; see 7475	7481	47668
JO36209	Hopper Ore	32499	1952	Ext. side at ladder; see 7475	7482	47669
JO36209	Hopper Ore	32499	1952	Ext. closeup of hopper end; see 7475	7483	47670
JO36209	Hopper Ore	32499	1952	Ext. body detail; see 7475	7484	47671
JO36209	Hopper Ore	32499	1952	Ext. 3/4 side completed car; see 7475	7485	47672
JO36209	Hopper Ore	32499	1952	Ext. side completed car; see 7475	7486	47673
JO36209	Hopper Ore	32499	1952	Ext. hand brake end; see 7475	7487	47674



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
DULUTH MISSABE & NORTHERN						
5554	Hopper Steel Ore	24711	1937	Exterior brake mechanism	2185	43604
5554	Hopper Steel Ore	24711	1937	Exterior end closeup	2186	43605
5554	Hopper Steel Ore	24711	1937	3/4 front truck	2190	43606
5554	Hopper Steel Ore	24711	1937	Exterior side/end brake mechanism	2191	43607
5554	Hopper Steel Ore	24711	1937	Exterior side/end only closeup	2192	43608
5554	Hopper Steel Ore	24711	1937	Exterior closeup brake mechanism	2193	43609
5554	Hopper Steel Ore	24711	1937	Exterior side/end only dumping mechanism	2194	43610
5554	Hopper Steel Ore	24711	1937	Exterior end	2917	43611
DULUTH SOUTH SHORE & ATLANTIC						
5645	Box	17077	1940	Ext. 3/4 side	2920	44149
5919A	Box	15052	1948	Ext. 3/4 side	6248	46423
5939	Gondola	4099	1949	Ext. 3/4 side	6418	46593
5939	Gondola	4099	1949	Ext. hand brake end	6419	46594
8143	Box	15186	1953	Ext. 3/4 side	8144	48183
8143	Box	15186	1953	Ext. hand brake end	8145	48184
E.F. AMAPA						
8232	Box	216	1955	Ext. 3/4 side	8752	48706
8232	Box	216	1955	Ext. hand brake end	8753	48707
E.M. CO.						
5728	Hopper	No. 1	1942	Ext. side (Plancor No. 571)	3612	44627
5728	Hopper	No. 1	1942	Ext. hand brake end (Plancor No. 571)	3613	44628

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
EQUITABLE LIFE ASSURANCE SOCIETY						
			1950	Owners plate	6778	47004
ELECTRO METALLURGICAL CO. (See: UNION CARBIDE)						
ELGIN JOLIET & EASTERN						
8166	Hopper Self Clearing	70988	1953	Ext. 3/4 side	8208	48245
8166	Hopper Self Clearing	70988	1953	Ext. hand brake end	8212	48249
ERIE						
	Box	79134	1940	Ext. hand brake end	2676A	43959
	Box	71363	1950	Ext. end; not Pullman-built	6700	46925
8160	Box	84009	1954	Ext. 3/4 side	8282	48315
8160	Box	84009	1954	Ext. hand brake end	8283	48316
8175	Box	86767	1954	Frame 3/4 front	8235	48269
8175	Box	86767	1954	Ext. 3/4 front, roof	8236	48270
8175	Box	86767	1954	Int.	8237	48271
8175	Box	86749	1954	Ext. end	8238	48273
8175	Box	86749	1954	Ext. hand brake end	8239	
8175	Box	86749	1954	Ext. 3/4 side	8240	48274
ESCANABA & LAKE SUPERIOR						
5938B	Hopper	4035	1949	Ext. 3/4 side	6458	46633
5938B	Hopper	4035	1949	Ext. hand brake end	6459	46634
5939A	Gondola	5033	1949	Ext. 3/4 side	6416	46591
5939A	Gondola	5033	1949	Ext. hand brake end	6417	46592



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
EXPORT (buyers not identified)						
5714	Gondola High Side		1942	Ext. 3/4 side. Note: frames 44541-44566 same car	3464	44541
5714	Gondola High Side		1942	Ext. side doors open	3465	44542
5714	Gondola High Side		1942	Ext. closeup of side doors	3466	44543
5714	Gondola High Side		1942	Ext. side doors open	3467	44544
5714	Gondola High Side		1942	Same as 3467	3468	44545
5714	Gondola High Side		1942	Ext. end	3469	44546
5714	Gondola High Side		1942	Ext. 3/4 end	3470	44547
5714	Gondola High Side		1942	Interior	3471	44548
5714	Gondola High Side		1942	Interior side doors open	3472	44549
5714	Gondola High Side		1942	Interior	3473	44550
5714	Gondola High Side		1942	Ext. end	3474	44551
5714	Gondola High Side		1942	Interior corner closeup	3475	44552
5714	Gondola High Side		1942	Same as 3475, closer view	3476	44553
5714	Gondola High Side		1942	Sides packed in car	3477	44554
5714	Gondola High Side		1942	Sides crated	3478	44555
5714	Gondola High Side		1942	Side in drilling jig	3479	44556
5714	Gondola High Side		1942	Side	3480	44557
5714	Gondola High Side		1942	Different view of 3480	3481	44558
5714	Gondola High Side		1942	Safety chains, truck	3482	44559
5714	Gondola High Side		1942	Doors crated	3483	44560
5714	Gondola High Side		1942	Doors crated	3484	44561
5714	Gondola High Side		1942	Ends crated	3485	44562
5714	Gondola High Side		1942	Carload of misc. parts	3486	44563
5714	Gondola High Side		1942	Buffer stem before welding	3487	44564
5714	Gondola High Side		1942	Different view of 3487	3488	44565
5714	Gondola High Side		1942	Buffer stem heat treating	3489	44566
5715	Gondola D/S		1942	3/4 end; 3359-3407 same lot. Car pictured in 3384 frame 44460	3358	44437
5715	Gondola D/S		1942	Ext. 3/4 end	3360	44438
5715	Gondola D/S		1942	Ext. 3/4 end	3361	44439
5715	Gondola D/S		1942	Ext. opposite end	3362	44440
5715	Gondola D/S		1942	Ext. under frame	3363	44441
5715	Gondola D/S		1942	Ext. under side	3364	44442

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
EXPORT (continued)						
5715	Gondola D/S		1942	Ext. dump machinery	3365	44443
5715	Gondola D/S		1942	Ext. under side	3366	44444
5715	Gondola D/S		1942	3/4 side hand brake	3369	44445
5715	Gondola D/S		1942	Partial frame	3370	44446
5715	Gondola D/S		1942	Frame from top	3371	44447
5715	Gondola D/S		1942	Partial frame	3372	44448
5715	Gondola D/S		1942	Partial frame	3373	44449
5715	Gondola D/S		1942	3/4 end	3374	44450
5715	Gondola D/S		1942	3/4 end underside	3375	44451
5715	Gondola D/S		1942	Opposite of 3375	3376	44452
5715	Gondola D/S		1942	3/4 end closeup	3377	44453
5715	Gondola D/S		1942	3/4 frame top	3380	44454
5715	Gondola D/S		1942	3/4 frame top	3381	44455
5715	Gondola D/S		1942	Section of frame	3382	44456
Frames 44457-44459 are duplicates of 44454-44456						
5715	Drop Side Gondola		1942	Ext. 3/4 side	3384	44460
5715	Gondola D/S		1942	Body side bearings	3385	44461
5715	Gondola D/S		1942	Parts crated for shipment aboard Monon car	3386	44462
5715	Gondola D/S		1942	Inverted frame	3387	44463
5715	Gondola D/S		1942	Brake rods packed for shipment	3388	44464
5715	Gondola D/S		1942	Couplers	3389	44465
5715	Gondola D/S		1942	Brake bell crank	3390	44466
5715	Gondola D/S		1942	End doors	3391	44467
5715	Gondola D/S		1942	Carload of trucks	3392	44468
5715	Gondola D/S		1942	Shop scene frames without end sill	3393	44469
5715	Gondola D/S		1942	3/4 front, frame	3394	44470
5715	Gondola D/S		1942	Frame, can of grease attached	3395	44471
5715	Gondola D/S		1942	Center sill bottom	3396	44472
5715	Gondola D/S		1942	Sub center sill, top	3397	44473
5715	Gondola D/S		1942	End door latch	3398	44474
5715	Gondola D/S		1942	End sill inside	3399	44475
5715	Gondola D/S		1942	End sill outside	3400	44476
5715	Gondola D/S		1942	Body bolster	3401	44477
5715	Gondola D/S		1942	Body bolster assembly	3402	44478



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
EXPORT (continued)						
5715	Gondola D/S		1942	Buffer stems	3403	44479
5715	Gondola D/S		1942	Truck journal box inside	3404	44480
5715	Gondola D/S		1942	Trucks packed iin car for shipment	3405	44481
5715	Gondola D/S		1942	Brake parts packed for shipment	3406	44482
5715	Gondola D/S		1942	Vacuum lines packet for shipment	3407	44483
5715	Gondola D/S		1942	Side planks packed	3425	44501
5715	Gondola D/S		1942	Journal box packing	3426	44502
5715	Gondola D/S		1942	Side planks packed	3427	44503
5715	Gondola D/S		1942	Barrel of field rivets	3428	44504
5715	Gondola D/S		1942	Brake bell cranks packed	3429	44505
5715			1942	Barrels of journal box oil	3430	44506
5715			1942	Hand brake shafts packed	3431	44507
5715			1942	Misc. material	3432	44508
5715			1942	Trucks in car	3433	44509
5715			1942	Vacuum brakes packed	3434	44510
5715			1942	Trucks in car	3435	44511
5715			1942	End doors new packing style	3435	44512
5715			1942	End doors old packing	3436	44513
5715			1942	Car loaded with misc. parts	3437	44514
5715			1942	Buffer stems crated	3438	44515
5715			1942	Buffer stems crated	3439	44516
5715			1942	Journal bearing crated	3440	44517
5715			1942	Vacuum lines crated	3441	44518
5715			1942	Side top angles crated	3442	44519
5715			1942	J. frames crated	3443	44520
5715			1942	Brake bell cranks crated	3444	44521
5715			1942	Car load of misc. parts	3445	44522
5715			1942	Body bolster assembly	3446	44523
5715			1942	Air lines crated	3447	44524
5715			1942	Air lines crated	3448	44525
5715			1942	Air line fittings crated	3449	44526
5715			1942	Air line fittings crated	3450	44527
5814	Flat Dropside		1945	Export to Russia? Ext. 3/4 side	4667	45047
5814	Flat		1945	Export to Russia; ext. hand brake end	4668	45048

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
EXPORT (continued)						
5846	Box		1946	Export to France; ext. side	5129	45435
5846	Box		1946	Export to France; ext. end	5130	45436
5846	Box		1946	Export to France; int.	5131	45437
FERROCARRIL DEL PACIFICO						
8105	Box	3300	1953	Ext. 3/4 side	8111	48152
8105	Box	3300	1953	Ext. hand brake end	8112	48153
8142	Box	3319	1953	Ext. 3/4 side	8107	48148
8142	Box	3319	1953	Ext. hand brake end	8108	48149
8156	Box	3557	1953	Ext. 3/4 side	8193	48230
8156	Box	3599	1953	Ext. 3/4 side	8194	48231
8156	Box	3599	1953	Ext. hand brake end	8194	48232
8156	Box	3599	1953	Ext. 3/4 side	8227	48261
FLORIDA EAST COAST						
8089	Gondola	12200	1953	Ext. 3/4 side	7984	48077
8089	Gondola	12200	1953	Ext. hand brake end	7985	48078
FORT DODGE DES MOINES & SOUTHERN						
8036B	Box	12300	1952	Ext. 3/4 side	7545	47732
8036B	Box	12300	1952	Ext. hand brake end	7546	47733



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
GEORGIA (RR. & BANKING CO.)						
5753	Box	19899	1944	Ext. side	4113	44783
5753	Box	19899	1944	Ext. hand brake end	4114	44784
5784	Hopper	21151	1945	Ext. 3/4 side	4492	44944
5784	Hopper	21151	1945	Ext. hand brake end	4493	44945
5869	Box	29049	1947	Ext. 3/4 side	5710	45970
5869	Box	29049	1947	Ext. hand brake end	5711	45971
5902A	Hopper	21200	1948	Ext. 3/4 side	5964	46143
5902A	Hopper	21200	1948	Ext. hand brake end	5965	46144
8021	Box	39518	1952	Ext. 3/4 side	7368	47560
8021	Box	39518	1952	Ext. hand brake end	7369	47561
8040	Hopper	21350	1953	Ext. 3/4 side	7980	48073
8040	Hopper	21350	1953	Ext. hand brake end	7981	48074
GOC						
5876	Box	222	1947	Ext. 3/4 side	5714	45974
5876	Box	222	1947	Ext. hand brake end	5715	45975
GRAND TRUNK WESTERN						
5931	Box	595519	1948	Ext. 3/4 side	6252	46427
5931	Box	595519	1948	Ext. hand brake end	6253	46428
GREAT NORTHERN						
5565	Box		1937	Ext. 3/4 side	2179	49153
5565	Box	50499	1937	Ext. 3/4 side, no sides	2195	49156
5650	Box, Steel Frame	47648	1941	Ext.	2982	44207
5650	Box	47648	1941	Int.	2983	44208

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
GREAT NORTHERN (continued)						
5697	Box		1942	Series showing construction inner and outer sheathing 3325-3341	3325	44404
5697	Box		1942	See 3325	3326	44405
5697	Box		1942	See 3325	3327	44406
5697	Box		1942	See 3325	3333	44407
5697	Box		1942	See 3325	3336	44408
5697	Box		1942	See 3325	3337	44409
5697	Box		1942	See 3325	3338	44410
5697	Box		1942	See 3325	3339	44411
5697	Box		1942	See 3325	3340	44412
5697	Box		1942	See 3325	3341	44413
5697	Box	46477	1942	Ext. 3/4 side	3347	44426
5697	Box	46515	1942	Ext. 3/4 side	3348	44427
5697	Box	46515	1942	Duplicate of 3348	3349	44428
5697	Box	46515	1942	Ext. 3/4 car end	3350	44429
5697	Box	46977	1942	Interior	3357	44436
7764	Hopper Covered	71188	1953	Ext. side	7764	47941
7764	Hopper Covered	71188	1953	Ext. 3/4 side	7765	47942
7764	Hopper Covered	71188	1953	Ext. hand brake end	7766	47943
8160	Box	21961	1954	Ext. 3/4 side	8284	48317
8160	Box	21961	1954	Ext. hand brake end	8285	48318
	Box	11854	1948	Ext. 3/4 end; built by Great Northern; see 6072	6071	46251
	Box	11854	1948	Ext. opposite of 6071; blt. by Great Northern	6072	46252
	Box	52765	1940	Ext. side	9308	49185
GREEN BAY & WESTERN						
5977	Box	799	1950	Ext. 3/4 side	6889	47102
5977	Box	799	1950	Ext. 3/4 end	6890	47103
5977	Box	799	1950	Ext. hand brake end	6891	47104



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
GULF MOBILE & OHIO						
5633	Hopper, Coal	32000	1940	Ext. hand brake end	2832	44093
5633	Hopper, Coal	32000	1940	Ext. side	2833	44094
5851	Hopper Covered	80003	1947	Ext. 3/4 side	5321	45580
5851	Hopper Covered	80003	1947	Ext. hand brake end	5322	45581
5851	Hopper Covered	80003	1947	Ext. roof doors open	5323	45582
5851	Hopper Covered	80003	1947	Ext. roof doors closed	5324	45583
5932	Hopper	32633	1949	Ext. 3/4 side	6456	46631
5932	Hopper	32633	1949	Ext. hand brake end	6457	46632
	Box	26071	1949	Ext. 3/4 side	6604	46770
	Box	26071	1949	Exact opposite of 6604	6605	46771
	Box	26071	1949	Ext. end	6606	46772
	Box	26071	1949	Ext. 3/4 side end only	6608	46775
	Box	26071	1949	Ext. 3/4 end	6607	46776
8032	Gondola	14145	1951	Ext. 3/4 side	7496	47683
8032	Gondola	14145	1951	Ext. hand brake end	7497	47684
8135	Hopper Covered	80121	1953	Ext. 3/4 side	8168	48207
8135	Hopper Covered	80121	1953	Ext. hand brake end	8169	48208
ILLINOIS CENTRAL						
	Box, automobile	155799	1926	Side view	1414	43305
	Box, automobile	155799	1926	Side	1415	43306
	Box, automobile	155799	1926	3/4 end	1416	43307
	Car truck, 4-wh.	155799	1926	3/4 front	1417	43308
	Car truck, 4 wh.	155799	1926	Side	1418	43309
	Box, automobile	155799	1926	End	1419	43310
	Box, automobile	155799	1926	Hand brake end	1420	43311
5411	Hopper	401299	1926	Interior of car body, end view, doors open	1457	43317
5411	Hopper	401299	1926	Interior of car body, end view, doors closed	1458	43318
5411	Hopper, side dump	401299	1926	3/4 side	1459	43319
5411	Hopper	401299	1926	Side view	1460	43320
5411	Hopper	401299	1926	End view, hand brake	1461	43321

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
ILLINOIS CENTRAL (continued)						
5411	Steel/wood gondola	401435	1926	End	1462	43322
5411	Steel/wood gondola	401452	1929	Side	1463	43323
5411	Car truck		1926	Dalman One Level, 3/4 front	1464	43324
5411	Car truck		1926	Dalman One Level, Side	1465	43325
5413	Auto/Furniture	162885	1926	Wood/steel, pressed steel end	1500	43326
5413	Auto/Furniture	162386	1926	Wood/steel, pressed steel end (hand brake)	1501	43327
5413	Auto/Furniture	162386	1926	Wood/steel, 3/4 exterior	1502	43328
5413	Auto/Furniture	162390	1926	Composite; side, exterior	1503	43329
5413	Auto/Furniture	163050	1926	Composite; pressed steel end	1504	43330
5413	Auto/Furniture	163048	1926	Composite; pressed steel end (hand brake)	1505	43331
5413	Auto/Furniture	163048	1926	Composite; exterior, side	1506	43332
5413	Auto/Furniture	163048	1926	Composite; exterior, side	1507	43333
5413	Auto/Furniture	163048	1926	Composite; exterior, 3/4 end roof	1508	43334
5413	Auto/Furniture	163150	1926	Composite; end, Murphy doors	1509	43336
5413	Auto/Furniture	163150	1926	Composite; exterior end (hand brake)	1510	43337
5413	Auto/Furniture	163119	1926	Composite; exterior, side	1511	43338
5413	Auto/Furniture	163150	1926	Composite; exterior, side	1512	43339
5413	Auto/Furniture	163150	1926	Composite; exterior, end, doors open	1513	43340
5413	Auto/Furniture	163150	1926	Composite; exterior, 3/4 end, doors open	1514	43341
5560	Automobile Box	166199	1937	Exterior side	2249	43631
5560	Automobile Box	166199	1937	Exterior 3/4 side	2250	43632
5560	Automobile Box	166199	1937	Exterior side	2251	43633
5560	Automobile Box	166199	1937	Exterior end	2252	43634
5560	Automobile Box	166199	1937	Exterior hand brake end	2253	43635
5560	Automobile Box	166199	1937	Truck side	2254	43636
5560	Automobile Box	166199	1937	Truck front view	2255	43637
5607	Hopper	71675	1940	Ext. side	2766	44040
5607	Hopper	71675	1940	Ext. opposite of 2766	2767	44041
5607	Hopper	71675	1940	Ext. end	2768	44042
5607	Hopper	71675	1940	Ext. hand brake end	2769	44043
5607	Hopper	71675	1940	Interior from abovew	2770	44044
5607	Hopper	71675	1940	3/4 front, truck	2771	44045
5607	Hopper	71675	1940	Front, truck	2772	44046
5607	Hopper	71675	1940	Closeup side of dump door	2773	44047



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
ILLINOIS CENTRAL (continued)						
5636	Box	20300	1940	Ext. side	2911	44140
5636	Box	20300	1940	Ext. opposite of 2911	2912	44141
5636	Box	20300	1940	Ext. end	2913	44142
5636	Box	20300	1940	Ext. hand brake end	2914	44143
5636	Box	20300	1940	Interior	2915	44144
5636	Box	20300	1940	Ext. roof from end	2916	44145
5636	Box	20300	1940	3/4 side, truck	2917	44146
5636	Box	20300	1940	Front view truck	2918	44147
5850	Hopper Covered	79795	1947	Ext. 3/4 side	5352	45611
5850	Hopper Covered	79795	1947	Ext. 3/4 side	5353	45612
5850	Hopper Covered	79795	1947	Ext. end	5354	45613
5850	Hopper Covered	79795	1947	Ext. hand brake end	5355	45614
5850	Hopper Covered	79795	1947	Ext. roof doors open	5356	45615
5850	Hopper Covered	79795	1947	Ext. roof doors closed	5357	45616
5850	Hopper Covered		1947	Shop scene car body incomplete	5358	45617
5850	Hopper Covered		1947	Shop scene car body on side	5359	45618
5850	Hopper Covered		1947	Truck side view	5360	45619
5850	Hopper Covered		1947	Truck 3/4 front	5361	45620
5918	Hopper	90999	1949	Ext. 3/4 side	6282	46457
5918	Hopper	90999	1949	Duplicate of 6282	6283	46458
5918	Hopper	90999	1949	Ext. end	6284	46459
5918	Hopper	90999	1949	Ext. hand brake end	6285	46460
5918	Hopper	90999	1949	Int. from above	6286	46461
5918	Hopper		1949	Truck side view	6287	46462
5918	Hopper		1949	Truck front view	6288	46463
5918	Hopper		1949	Closeup of hopper doors	6289	46464
5938	Hopper	92142	1949	Ext. 3/4 side	6298	46474
5938	Hopper	92142	1949	Ext. 3/4 side	6299	46475
5938	Hopper	92142	1949	Ext. end	6300	46476
5938	Hopper	92142	1949	Ext. hand brake end	6301	46477
5938	Hopper	92142	1949	Closeup of hopper doors	6302	46478
5938	Hopper	92142	1949	Int. from above	6303	46479
5938	Hopper		1949	Truck 3/4 side	6304	46480
5938	Hopper		1949	Truck front view	6305	46481

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
ILLINOIS CENTRAL (continued)						
8072	Hopper Covered		1953	Ext. 3/4 side roof	7708	47885
8072	Hopper Covered		1953	Ext. roof hatch open	7709	47886
8072	Hopper Covered		1953	Ext. roof hatch open	7710	47887
8072	Hopper Covered		1953	Ext. roof hatch closed	7711	47888
8072	Hopper Covered		1953	Ext. 3/4 side roof	7712	47889
8072	Hopper Covered	79010	1953	Ext. 3/4 side	7732	47909
8072	Hopper Covered		1953	Body detail	7733	47910
8072	Hopper Covered	79345	1953	Ext. 3/4 side	7745	47922
8072	Hopper Covered	79345	1953	Ext. hand brake end	7746	47923
8122	Hopper Covered	79373	1953	Ext. 3/4 side	7942	48035
8122	Hopper Covered	79373	1953	Ext. hand brake end	7943	48036
INTERNATIONAL MINERALS & CHEMICAL CORP.						
8091	Hopper Covered	30098	1953	Ext. 3/4 side	7758	47935
8091	Hopper Covered	30098	1953	Ext. hand brake end	7749	47936
KANSAS CITY SOUTHERN						
5682	Auto Box	30899	1941	Ext. side	3253	
5682	Auto Box	30899	1941	Ext. hand brake end	3254	
5682	Auto Box		1941	Int. from end	3255	
5682	Auto Box	30899	1941	Int. car carrier down	3256	
5815	Hopper		1946	Mis-shaped Z bar; note 4915-4924 a series	4915	46816
5815	Hopper		1946	Draft gear lugs; see 4915	4916	46817
5815	Hopper		1946	Draft gear lugs on center sill; see 4915	4917	46818
5815	Hopper		1946	See 4915	4918	46819
5815	Hopper		1946	See 4915	4919	46820
5815			1946	Closeup of weld	4920	45282
5815	Hopper		1946	See 4915	4921	46821
5815	Hopper		1946	See 4915	4922	46822
5815	Hopper		1946	See 4915	4923	46823



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
KANSAS CITY SOUTHERN (continued)						
5815	Hopper		1946	Ext. 3/4 front unfinished car	4924	46824
5815	Hopper	29240	1946	Int. from above	4975	45291
5815	Hopper	29237	1946	Ext. 3/4 side	4976	45292
5815	Hopper	29237	1946	Ext. 3/4 front	4977	45293
5815	Hopper	29240	1946	Int. from above	4975	45291
5815	Hopper	29237	1946	Ext. 3/4 side	4976	45292
5815	Hopper	29237	1946	Ext. 3/4 front	4977	45293
5818	Hopper, Covered	29621	1946	Ext. 3/4 side	4905	45280
5818	Hopper, Covered	29621	1946	Ext. hand brake end	4906	45281
5818	Hopper, Covered	29621	1946	Ext. roof from above, hatches closed	4907	46808
5818	Hopper, Covered	29621	1946	Ext. roof from above, hatches open	4908	46809
5818	Hopper, Covered		1946	Shop scene Kansas City Southern under construction; note: 4909-4912 a series	4909	46810
5818	Hopper, Covered		1946	See 4909	4910	46811
5818	Hopper, Covered		1946	See 4909	4911	46812
5818	Hopper, Covered		1946	See 4909	4912	46813
5885	Box	18549	1948	Ext. 3/4 side	5835	46095
5885	Box	18549	1948	Ext. hand brake end	5836	46096
8196	Pulp Wood Car	24269	1954	Ext. 3/4 side	8441	48405
8196	Pulp Wood Car	24269	1954	Ext. hand brake end	8442	48406
KEWAUNEE GREEN BAY & WESTERN						
5938A	Hopper	406	1949	Ext. side	6460	46635
5938A	Hopper	406	1949	Ext. hand brake end	6461	46636
LA SALLE & BUREAU COUNTY						
5950	Box	1105	1949	Ext. 3/4 side	6478	46644

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
LAKE SUPERIOR & ISHPEMING						
5965A	Box	2266	1950	Ext. 3/4 side	6853	47070
5965A	Box	2266	1950	Ext. hand brake end	6854	47071
8047	Box	2422	1952	Ext. 3/4 side	7587	47768
8047	Box	2422	1952	Ext. hand brake end	7588	47769
LANCASTER & CHESTER						
8003A	Box	1019	1952	Ext. 3/4 side	7295	47488
8003A	Box	1019	1952	Ext. hand brake end	7296	47489
LEHIGH & NEW ENGLAND						
8287	Box	8927	1956	Ext. 3/4 side	9099	49026
8287	Box	8927	1956	Ext. hand brake end	9100	49027
LEHIGH VALLEY						
5873	Box	62000	1947	Ext. 3/4 side	5539	45794
5873	Box	62000	1947	Duplicate of 5539; appears twice on disc	5539	45795
5873	Box	62000	1947	Ext. 3/4 end only	5556A	45812
5970	Box	62738	1950	Ext. 3/4 end	5556C	45813
5970	Box	62738	1950	Ext. 3/4 side	6857	47074
5970	Box	62738	1950	Ext. hand brake end	6858	47075
5970	Box	62738	1950	Ext. 3/4 front, end only	6859	47076



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
LOUISIANA & ARKANSAS						
5551	Box Steel Sheathed	15073	1937	Exterior 3/4 side	2173	43602
5551	Box Steel Sheathed	15073	1937	Exterior end hand brake	2174	43603
5680	Hopper	3954	1941	Ext. hand brake end	3267	44369
5680	Hopper	3954	1941	Ext. side	3266	44368
5681	Box	36158	1941	Ext. side	3192	44280
5681	Box	36158	1941	Ext. hand brake end	3193	44281
5681	Box	25124	1941	Ext. side	3194	44282
5681	Box	25124	1941	Ext. hand brake end	3195	44283
5913	Gondola	9000	1948	Ext. 3/4 side	6122	46299
5913	Gondola	9000	1948	Ext. hand brake end	6123	46300
5913	Gondola	9000	1948	Int. from above	6124	46301
LOUISVILLE & NASHVILLE						
5564	Hopper Steel Coal	61654	1937	Exterior hand brake end	2207	43618
5564	Hopper Steel Coal	61654	1937	Exterior, 3/4 side	2208	43619
5616	Hopper	63360	1940	Ext. side	2763	44038
5616	Hopper	63360	1940	Ext. hand brake end	2764	44039
5626	Hopper, Cement	38297	1940	Ext. side	2820	44081
5626	Hopper, Cement	39297	1940	Ext. hand brake end	2821	44082
5639	Box (End Doors)	99935	1940	Exterior side	2906	44135
5639	Box (End Doors)	99935	1940	Ext. end w/doors	2907	44136
5639	Box (End Doors)	99935	1940	Ext. end, doors open	2908	44137
5639	Box (End Doors)	99935	1940	Ext. hand brake end	2909	44138
5639	Box (End Doors)	99935	1940	Ext. roof from end	2910	44139
5656	Hopper, Coal	64535	1941	Ext. side	3024	44241
5656	Hopper, Coal	64535	1941	Ext. hand brake end	3025	44242
5657	Box	99815	1941	Ext. side	2986	44211
5657	Box	99815	1941	Ext. hand brake end	2987	44212
5657	Box	99815	1941	Ext. door opening end	2988	44213
5657	Box		1955	Blt. 1941; closeup of door frame cracks; 8977-79 ser.	8977	48908
5657	Box		1955	See 8977	8978	48909

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
LOUISVILLE & NASHVILLE (continued)						
5657	Box		1955	See 8977	8979	48910
5684	Box, Stagger Door	99138	1941	Ext. side	3241	
5684	Box	99138	1941	Ext. hand brake end	3252	
5685	Box	90350	1941	Ext. side	3264	44366
5685	Box	90350	1941	Ext. hand brake end	3265	44367
5686	Hopper	67200	1941	Ext. side	3293	44378
5686	Hopper	67200	1941	Ext. hand brake end	3294	44379
5717	Box	91046	1942	Ext. side	3455	44532
5717	Box	91046	1942	Ext. hand brake end	3456	44533
5742	Hopper	31472	1943	Ext. side	3921	44671
5742	Hopper	31472	1943	Ext. hand brake end	3922	44672
5833	Hopper	68599	1946	Ext. 3/4 side	5017	45332
5833	Hopper	68599	1946	Ext. hand brake end	5018	45333
5858	Hopper	69250	1947	Ext. 3/4 side	5585	45842
5858	Hopper	69250	1947	Ext. hand brake end	5586	45843
5883	Hopper	80350	1947	Ext. 3/4 side	5706	45966
5883	Hopper	80350	1947	Ext. hand brake end	5707	45967
5926	Hopper		1948	Lugs welded to beam; see 6158	6157	46334
5926	Hopper		1948	See 6157	6158	46335
5926	Hopper	34000	1948	Group posing beside car	6160	46337
5926	Hopper		1948	Int. from above	6161	46338
5926	Hopper	34000	1948	Int. from above	6164	46341
5926	Hopper	34000	1948	Ext. end	6166	46343
5926	Hopper	34000	1948	Ext. hand brake end	6167	46344
5926	Hopper	34000	1948	Ext. 3/4 front, end only	6168	46345
5926	Hopper	34000	1948	Opposite of 6168	6169	46346
5926	Hopper	34000	1948	Ext. 3/4 front hand brake end only	6170	46347
5926	Hopper	34000	1948	Opposite of 6170	6171	46348
5926	Hopper		1948	6172-6182 a series welds are marked in white	6172	46349
5926	Hopper		1948	See 6172	6173	46350
5926	Hopper		1948	See 6172	6174	46351
5926	Hopper		1948	See 6172	6175	46352
5926	Hopper		1948	See 6172	6176	46353
5926	Hopper		1948	See 6172	6177	46354



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
LOUISVILLE & NASHVILLE (continued)						
5926	Hopper		1948	See 6172	6178	46355
5926	Hopper		1948	See 6172	6179	46356
5926	Hopper		1948	See 6172	6180	46357
5926	Hopper		1948	See 6172	6181	46358
5926	Hopper		1948	See 6172	6182	46359
5926	Hopper		1948	Riveted body detail; see 6187	6186	46362
5926	Hopper		1948	See 6186	6187	46363
5926	Hopper		1948	Int. welds marked in white	6188	46364
5926	Hopper	34000	1948	Ext. 3/4 side	6211	46387
5926	Hopper		1949	Section of center sill	6275	46450
5926	Hopper	34270	1949	Ext. 3/4 side	6306	46482
5926	Hopper	34270	1949	Ext. hand brake end	6307	46483
5926	Hopper		1949	Int. from above	6308	46484
5926			1949	Shop scene "B" shop forge; see 6324	6331	46506
5926			1949	Shop scene "B" shop; see 6324	6332	46507
5926			1949	Shop scene hoppers; see 6339	6340	46515
5926			1949	Shop scene hoppers; see 6339	6341	46516
5926			1949	Shop scene frame welding fixture; see 6339	6342	46517
5926			1949	Shop scene building car side; see 6339	6343	46518
5926			1949	Shop scene building car side; see 6339	6344	46519
5926			1949	Shop scene installing hopper on frame; see 6339	6345	46520
5926			1949	Shop scene car body welding fixture; see 6339	6346	46521
5926			1949	Shop scene car frame on side; see 6339	6347	46522
5926			1949	Shop scene frame with hoppers; see 6339	6348	46523
5926			1949	Shop scene car side; see 6339	6349	46524
5926			1949	Shop scene car parts; see 6339	6350	46525
5926			1949	Shop scene car parts; see 6339	6351	46526
5926			1949	Shop scene installing hoppers; see 6339	6352	46527
5926			1949	Shop scene frame with hoppers; see 6339	6353	46528
5926			1949	Shop scene car parts; see 6339	6354	46529
5926			1949	Shop scene car side welding fixture; see 6339	6355	46530
5926			1949	Closeup of hoppers in car; see 6339	6356	46531
5926			1949	Shop scene car body on side; see 6339	6357	46532
5926			1949	Ext. car end; see 6339	6358	46533

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
LOUISVILLE & NASHVILLE (continued)						
5926			1949	Spot welder on car side; see 6339	6359	46534
5926			1949	Spot welder on car side; see 6339	6360	46535
5926			1949	Shop scn. car body on side welders at work; see 6339	6361	46536
5926			1949	Shop scene car body; see 6339	6362	46537
5926			1949	Shop scene spot welders on car body; see 6339	6363	46538
5926			1949	Shop scene installing ends; see 6339	6364	46539
5926			1949	Shop scene erecting car sides; see 6339	6365	46540
5926			1949	Int. closeup of hopper; see 6339	6366	46541
5926			1949	Int. welding hopper sheets; see 6339	6367	46542
5926			1949	Ext. closeup of hopper doors; see 6339	6368	46543
5926			1949	Shop scene general view frame shop; see 6339	6369	46544
5926			1949	Shop scn. car body on side welders at work; see 6339	6370	46545
5926			1949	Similar to 6370; see 6339	6371	46546
5926			1949	Similar to 6370; see 6339	6372	46547
5926			1949	Ext. car end; see 6339	6373	46548
5926			1949	Similar to 6373	6374	46549
5926			1949	Int. elec. welders at work; see 6339	6375	46550
5926			1949	Similar to 6375; see 6339	6376	46551
5926			1949	Shop scene car body; see 6339	6377	46552
5926			1949	Shop scene car nearly complete; see 6339	6378	46553
5926			1949	Ext. car end; see 6339	6387	46562
5926			1949	Breaking a temporary weld; see 6339	6388	46563
5926	Hopper	35499	1949	Ext. 3/4 side w/posing group	6390	46565
5926	Hopper	35499	1949	Ext. side	6391	46566
5926			1949	Car side straightener on crane; see 6339	6392	46567
5926			1949	Car side straightener in operation; see 6339	6393	46568
5926			1949	Closeup of car end; see 6339	6394	46564
5926			1949	Shop scene car body; see 6339	6395	46570
5926			1949	Shop scene shear for cutting hopper chutes; see 6339	6396	46571
5926			1949	First operation in shearing hopper chute; see 6339	6397	46572
5926			1949	Second operation in sheating hopper chute; see 6339	6398	46573
5926			1949	Third operation shearing hopper chutes; see 6339	6399	46574
5926			1949	Closeup of underside at truck; see 6339	6400	46575
5926			1949	Ext. closeup of OK frame section; see 6339	6401	46576



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
LOUISVILLE & NASHVILLE (continued)						
5926			1949	Ext. closeup of hopper door; see 6339	6402	46577
5926			1949	Ext. 3/4 end corner only; see 6339	6403	46578
5926			1949	Ext. end; see 6339	6404	46579
5926			1949	Ext. closeup of frame at truck; see 6339	6405	46580
5926			1949	Closeup of frame detail; see 6339	6406	46581
5926			1949	Closeup of hopper door hinge; see 6339	6407	46582
5927	Hopper	33199	1949	Ext. 3/4 side	6310	46486
5927	Hopper	33199	1949	Ext. hand brake end	6311	46487
5961	Hopper Covered	38174	1940	Ext. 3/4 side	6681	46906
5961	Hopper Covered	38174	1950	Ext. hand brake end	6682	46907
5966	Box	16938	1950	Ext. side	6797	47023
5966	Box	16938	1950	Ext. 3/4 side	6798	47024
5966	Box	16938	1950	Ext. end	6799	47025
5966	Box	16938	1950	Ext. hand brake end	6800	47026
5966	Box	17041	1950	Int.	6801	47027
5966	Box		1950	Int. no floor or sheathing	6802	47028
5966	Box		1950	3/4 front roof	6803	47029
5966	Box	17575	1940	Ext. side	6819	47044
5966	Box	17575	1940	Ext. 3/4 side	6820	47045
5966	Box	17575	1940	Ext. hand brake end	6821	47046
5988	Box	17946	1951	Ext. 3/4 side	7238	47438
5988	Box	17946	1951	Ext. hand brake end	7239	47439
8039	Box	5000	1952	Ext. 3/4 side	7498	47685
8039	Box	5000	1952	Ext. hand brake end	7499	47686
8039	Box	7199	1952	Int. end	7672	47848
8039	Box	7199	1952	Int.	7673	47849
8040	Hopper	82200	1952	Ext. 3/4 side	7471	47658
8040	Hopper	82200	1952	Ext. hand brake end	7472	47659

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
MAINE CENTRAL						
5877	Box		1947	Ext. closeup of damaged area	5687	45946
5877	Box	6730	1947	Ext. 3/4 side	5690	45949
5877	Box	6730	1947	Ext. side	5691	45950
5877	Box	6730	1947	Ext. hand brake end	5692	45951
5999	Box	8199	1951	Ext. 3/4 side	7041	47255
5999	Box	8199	1951	Ext. hand brake end	7042	47256
McMILLEN FEED MILLS						
8072	Hopper Covered	CSX136	1953	Ext. 3/4 side	7756	47933
8072	Hopper Covered	CSX136	1953	Ext. hand brake end	7757	47934
MERCHANTS DESPATCH REFRIGERATOR LINE						
5507	Exp. Reefer	2000	1942	Ext. 3/4 side	3564	44601
5507	Exp. Reefer	2000	1942	Ext. 3/4 side	3565	44602
MERCHANTS DESPATCH TRANSPORTATION CORP.						
5798	Refrigerator		1945	Train of cars for delivery	4500	44946
5798	Refrigerator		1945	Closeup of 4500	4501	44947
5798	Refrigerator		1945	3/4 end wood framing (frames 44957-44961 series0	4511	44957
5798	Refrigerator		1945	Ext. 3/4 side showing wood framing	4516	44958
5798	Refrigerator		1945	Ext. 3/4 side no doors	4522	44959
5798	Refrigerator		1945	3/4 end insulation being installed	4523	44960
5798	Refrigerator		1945	Ext. 3/4 side showing insulation	4524	44961
5798	Refrigerator	23014	1945	Ext. 3/4 side	4525	44962
5798	Refrigerator		1945	Drip pans	4526	44963
5798	Refrigerator		1945	Int. car floor during construction	4527	44964
5798	Refrigerator		1945	Ext. 3/4 end w/damage	4535	44966



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
MERCHANTS DESPATCH TRANSPORTATION CORP. (continued)						
5798	Refrigerator		1945	3/4 end w/damage	4536	44967
5798	Refrigerator	16876	1945	Ext. 3/4 end	4539	44968
5798	Refrigerator		1945	Ext. 3/4 end insulation in place	4550	44969
5798	Refrigerator		1945	Ext. 3/4 end framing only	4552	44970
5798	Refrigerator		1945	Int.	4554	44971
5798	Refrigerator	23030	1945	Ext. 3/4 side	4555	44975
5798	Refrigerator		1945	Train of cars damaged by fire	4593	44997
5798?	Refrigerator		1945	Ext. end; see 4633	4632	45020
5798?	Refrigerator		1945	Ext. hand brake end; see 4632	4633	45021
MICHIGAN CENTRAL						
5459	Auto/Furniture	S-89999	1929	Interior end view doors open	1729	43388
5459	Auto/Furniture	S-89999	1929	Exterior door end	1730	43389
5459	Auto/Furniture	S-89150	1929	Exterior end doors open	1737	43392
5459	Auto/Furniture	S-89150	1929	Exterior end with doors closed	1738	43393
5459	Auto/Furniture	S-89150	1929	End view closed end	1739	43394
5459	Box Automobile	S-89150	1929	Ext. side	9299	49173
5459	Box Automobile	S-89999	1929	Ext. 3/4 side from above	9300	49174
MINNEAPOLIS & ST. LOUIS						
5847	Hopper Covered	70131	1947	Ext. 3/4 side	5300	45561
5847	Hopper Covered	70131	1947	Ext. hand b rake end	5301	45562
5847	Hopper Covered	70131	1947	Ext. roof doors open	5302	45563
5847	Hopper Covered	70131	1947	Ext. roof doors closed	5303	45564

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
MINNEAPOLIS NORTHFIELD & SOUTHERN						
8050	Box	1050	1952	Ext. 3/4 side	7621	47802
8050	Box	1050	1952	Ext. side	7622	47803
8050	Box	1050	1952	Ext. hand brake end	7623	47804
8180	Box	1103	1954	Ext. 3/4 side	8443	48407
8180	Box	1103	1954	Ext. hand brake end	8444	48408
MINNEAPOLIS ST. PAUL & SAULT STE. MARIE (SOO LINE)						
5536	Box		1936	Exterior end	2097	43563
5536	Box		1936	Exterior 3/4 side closeup	2098	43564
5536	Box	136200	1936	Ext. side	9304	49178
5536	Box	136200	1936	Ext. 3/4 side group posing	9305	49179
5569	Box Automobile	175098	1937	Ext. 3/4 side	2199	49158
5570	Gondola	66999	1937	Ext. 3/4 side	2243	49163
5570	Gondola	66999	1937	Ext. 3/4 end	2245	49164
5599	Auto		1939	Coupler pocket	2590	43895
5599	Auto		1939	Coupler pocket	2591	43896
5599	Auto		1939	Coupler pocket	2592	43897
5599	Auto		1939	Coupler pocket	2593	43898
5599	Auto		1939	Coupler pocket	2594	43899
5599	Auto		1939	Welded cross members	2595	43900
5600	Flat		1939	Ext. 3/4 front frame only	2580	43890
5600	Flat		1939	Ext. 3/4 front deck laid	2583	43891
5600	Flat		1939	Frame inverted in shop	2584	43892
5600	Flat		1939	Draft gear, coupling pocket	2585	43893
5600	Flat		1939	Cross member	2587	43894
5645	Box	43980	1940	Floor beams	2900	44129
5645	Box	43980	1940	Same as 2900, different view	2901	44130
5645	Box	43980	1940	Ext. side	2919	44148
5645	Box	136362	1940	Ext. 3/4 side	2921	44150
5645	Box	175712	1940	Ext. 3/4 side	2922	44151
5668	Flat	5225	1941	Ext. side	2998	44217



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
MINNEAPOLIS ST. PAUL & SAULT STE. MARIE [SOO LINE] (continued)						
5688	Box	44134	1941	Ext. 3/4 side	3196	44284
5689	Auto Box	176480	1942	Ext. 3/4 side	3323	44402
5689	Auto Box	176072	1942	Ext. hand brake end	3324	44403
MISSISSIPPI CENTRAL						
5942	Box		1949	Closeup of riveted section	6389	46564
5942	Box		1943	Ext. closeup of car lettering; 6410-6413 a series	6410	46585
5942	Box		1943	See 6410	6411	46586
5942	Box		1943	See 6410	6412	46587
5942	Box		1943	See 6410	6413	46588
5942	Box		1949	Frame inverted	6431	46606
5942	Box		1949	Frame and section inverted	6432	46607
5942	Box		1949	Ext. car end panel	6433	46608
5942	Box		1949	Shop scene frame welding fixture	6434	46609
5942	Box		1949	Ext. car end panel	6434	46610
5942	Box		1949	Same as 6435	6436	46611
5942	Box		1949	Similar to 6436	6437	46612
5942	Box	5038	1949	Ext. 3/4 side	6438	46613
5942	Box	5038	1949	Ext. hand brake end	6439	46614
5942	Box		1949	Frame 3/4 front	6441	46616
5942	Box		1949	Frame 3/4 front inverted	6442	46617
5942	Box		1949	Frame 3/4 front inverted	6443	46618
5942	Box	5020	1949	Ext. side	6444	46619
5942	Box	5020	1949	Ext. side posts	6445	46620
5942	Box		1949	Same as 6445	6446	46621
5942	Box	5020	1949	Ext. side	6447	46622
5942	Box	5000	1949	Several side sheets for sample car	6448	46623
5942	Box	5000	1949	Ext. side (sample car)	6449	46624

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
MISSOURI KANSAS & TEXAS						
5950	Box	90052	1949	Ext. 3/4 side	6580	46742
5950	Box	90050	1949	Ext. 3/4 side	6581	46743
5950	Box	90051	1949	Ext. 3/4 side	6582	46744
5950	Box	90025	1949	Ext. 3/4 side	6583	46745
5950	Box	90024	1949	Ext. 3/4 side	6584	46746
5950	Box (JO33080)	90080	1949	Ext. 3/4 side	6627	46794
5950	Box	90024	1949	Ext. hand brake end	6628	46795
8215	Box	99371	1954	Ext. 3/4 side	8531	48488
8215	Box	99371	1954	Ext. hand brake end	8532	48489
8215	Box	99342	1954	Ext. car marking	8545	48502
8215	Box	99322	1954	Ext. car marking	8546	48503
8215	Box	99357	1954	Ext. car marking	8547	48504
8215	Box	99417	1954	Ext. car marking	8548	48505
8215	Box	99453	1954	Ext. car marking	8549	48506
8215	Box	99486	1954	Ext. car marking	8550	48507
8215	Box	99459	1954	Ext. car marking	8551	48508
8216	Box	97741	1955	Ext. car markings	8583	48540
8216	Box	97732	1955	Ext. car markings	8584	48541
8216	Box	97758	1955	Ext. car markings	8585	48542
8216	Box	97759	1955	Ext. car markings	8586	48543
8216	Box	97617	1955	Ext. car markings	8587	48544
8216	Box	97773	1955	Ext. car markings	8588	48545
8216	Box	97793	1955	Ext. car markings	8589	48546
8216	Box	97772	1955	Ext. 3/4 side	8590	48547
8216	Box	97772	1955	Ext. hand brake end	8591	48548
8216	Box		1955	Car door	8592	48549
8273	Box	99530	1955	Ext. 3/4 side	8943	48873
8273	Box	99530	1955	Ext. hand brake end	8944	48874
8273	Box	99641	1955	Closeup of car lettering	8952	48883
8274	Box	92002	1955	Ext. 3/4 side	8957	48888
8274	Box	92002	1955	Ext. hand brake end	8958	48889
8274	Box	92058	1955	Int.	8959	48890
8274	Box	92002	1955	Ext. closeup of lettering	8960	48891



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
MISSOURI KANSAS & TEXAS (continued)						
8275	Box		1955	Unloading floor sections; 8961-8971 a series	8961	48892
8275	Box		1955	Floor section; see 8961	8962	48893
8275	Box		1955	Similar to 8962; see 8961	8963	48894
8275	Box		1955	Int.; see 8961	8964	48895
8275	Box		1955	Int. subfloor; see 8961	8965	48896
8275	Box		1955	Int. finished floor partially installed; see 8961	8966	48897
8275	Box		1955	Int. similar to 8966; see 8961	8967	48898
8275	Box		1955	Int. diff. view of 8966; see 8961	8968	48899
8275	Box		1955	Int. diff. view of 8966; see 8961	8969	48900
8275	Box		1955	Int.; see 8961	8970	48901
8275	Box		1955	Int. closeup of floor; see 8961	8971	48902
8275	Box	90135	1955	Ext. 3/4 side	8972	48903
8275	Box	90142	1955	Ext. hand b rake end	8973	48904
8275	Box	90135	1955	Ext. closeup of lettering	8974	48905
MISSOURI PACIFIC						
5823	Box	18899	1946	Ext. 3/4 side	4913	46814
5823	Box	18899	1946	Ext. hand brake end	4914	46815
	Box	47693	1950	Ext. hand brake end	6704	46929
MONON (See: CHICAGO INDIANAPOLIS & LOUISVILLE)						
NACIONALES DE MEXICO						
5453	Auto/Furniture	48496	1926	Exterior side door	1726	43386
5453	Auto/Furniture	48496	1926	Exterior side door	1727	43387
5453	Auto/Furniture	48458	1929	Exterior closed end	1732	43390
5453	Auto/Furniture	48460	1929	Exterior closed end	1733	43391
5505	Box	60276	1935	Exterior side	2314	43674
5505	Box	60276	1935	Exterior side door	2315	43675

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
NACIONALES DE MEXICO (continued)						
5505	Box	60276	1935	Interior side door	2316	43676
5505	Box	60276	1935	Door only, interior side	2317	43677
5505	Box		1935	Door only, interior side	2318	43678
5572	Box, Steel	60891	1937	Exterior Side	2284	43652
5572	Box, Steel	60891	1937	Exterior hand brake end	2285	43653
NASHVILLE CHATTANOOGA & ST. LOUIS						
5561	Box Car, Steel	18300	1937	Exterior hand brake end	2205	43616
5561	Box Car, Steel	18300	1937	Exterior side	2206	43617
5626	Hopper, Cement	49000	1940	Ext. side	2816	44077
5626	Hopper, Cement	49000	1940	Ext. hand brake end	2817	44078
5626	Hopper, Cement	49000	1940	Ext. roof from end	2818	44079
5626	Hopper, Cement	49000	1940	Same as 2818 except doors closed	2819	44080
5694	Box	18850	1942	Ext. side	3334	44419
5694	Box	18850	1942	Ext. hand brake end	3335	44420
	Hopper	48000	1947?	Ext. 3/4 side	5452A	49172
5776	Hopper	48498	1944	Ext. 3/4 side	4486	44940
5776	Hopper	48498	1944	Ext. hand brake end	4487	44941
5866	Box	19399	1947	Ext. 3/4 side	5665	45921
5866	Box	19399	1947	Ext. hand brake end	5666	45922
5868	Hopper	48500	1947	Ext. 3/4 side	5663	45919
5868	Hopper	48500	1947	Ext. hand brake end	5664	45920
8006	Hopper Covered	49111	1950	Ext. 3/4 side	6927	47141
8006	Hopper Covered	49111	1950	Ext. hand brake end	6928	47142
8095	Hopper	46699	1953	Ext. 3/4 side	7986	48079
8095	Hopper	46699	1953	Ext. hand brake end	7987	48080
NATIONAL COIL SPRING						
	Journal Box		1928		1620	43355
	Journal Box		1928	Open	1621	43356



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
NATIONAL STEEL CAR CORP.						
			1947	Canadian National car with Pressed Steel end; note 5553-5555 a series	5553	45809
			1947	Part of Pressed Steel end; see 5553	5554	45810
			1947	Part of Presed Steel end; see 5553	5555	45811
NEW YORK CENTRAL						
	Standard ARA #1 Box		1936	Built 1933; exterior side	1999	43502
	Box	100000	1936	Interior with cargo	2029	43521
	Box	100000	1936	Same as 2029	2030	43522
	Box	100000	1936	Same as 2030	2031	43523
	Box	123528	1950	Ext. hand brake end; not Pullman-built	6676	46901
	Box	111146	1950	Ext. hand brake end	6703	46928
	Box		1950	Roof and side 3/4 end	6776	47002
	Gondola	619200	1946	Load of side doors	4830	45132
5965	Box	169000	1950	Ext. 3/4 side	6811	47037
5965	Box		1950	Int. center floor	6812	47038
5965	Box	169664	1940	Ext. 3/4 side	6835	47052
5965	Box	169664	1950	Ext. 3/4 end front only	6836	47053
5965	Box	169664	1950	Ext. hand brake end	6837	47054
5965	Box	169664	1950	Roof front view	6838	47055
5965	Box	169664	1940	Ext. 3/4 front roof	6839	47056
5965	Box	170481	1950	Ext. 3/4 side	6855	47072
5965B	Box	169982	1950	Int.	6842	47059
5993	Box		1951	Int. door frame	6946	47160
5993	Box	170750	1951	Ext. 3/4 side	6947	47161
5993	Box	170750	1951	Ext. hand brake end	6948	47162
5993	Box	170933	1951	Ext. 3/4 end roof	6973	47187
5993	Box	170933	1951	Int.	6974	47188
5997	Box	171799	1951	Ext. 3/4 side	7029	47243
5997	Box	171799	1951	Ext. hand brake end	7030	47244
5997	Box	172387	1951	Ext. 3/4 front roof	7059	47273

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
NEW YORK CENTRAL (continued)						
5997	Box	172387	1951	Int.	7060	47274
8036A	Box	180199	1952	Ext. 3/4 side	7514	47701
8036A	Box	180199	1952	Ext. hand brake end	7515	47702
8094	Hopper Covered	81230	1953	Ext. 3/4 side	7958	48051
8094	Hopper Covered	81230	1953	Ext. roof only	7959	48052
8094	Hopper Covered	882050	1953	Worker inspecting roof doors	7960	48053
8094	Hopper Covered	882050	1953	Similar to 7960	7961	48054
8094	Hopper Covered	882050	1953	Ext. workman inspecting open roof doors	7962	48055
8094	Hopper Covered	882050	1953	Ext. 3/4 side roof	7963	48056
8094	Hopper Covered	882050	1953	Ext. hopper doors	7964	48057
8094	Hopper Covered	882050	1953	Ext. 3/4 end only	7965	48058
8094	Hopper Covered	882050	1953	Top view of roof with diff. type doors	7973	48066
8094	Hopper Covered	882050	1953	Top view of roof doors	7974	48067
8094	Hopper Covered	882050	1953	Ext. 3/4 side	7975	48068
8094	Hopper Covered	882050	1953	Ext. end	7976	48069
8160	Box	175008	1954	Ext. 3/4 side	8290	48323
8160	Box	175008	1954	Ext. hand brake end	8291	48324

## NEW YORK CHICAGO &amp; ST. LOUIS (NICKEL PLATE)

5499	Box	13399	1934	Exterior, side	1900	43444
5499	Box, Flour/Grain	13399	1934	Exterior side	1929	43462
5499	Box, Flour/Grain	13399	1934	Exterior, 3/4 side	1930	43463
5499	Box, Flour/Grain	13399	1934	Exterior, end	1931	43464
5499	Box, Flour/Grain	13399	1934	Exterior end (hand brake)	1932	43465
5598	Gondola	76007	1939	Ext. 3/4 side loaded w/containers	2533	43847
5598	Gondola, Container	76007	1939	Int. end	2535	43848
5598	Gondola, Container	76007	1939	Ext. 3/4 end	2537	43849
5604			1940	3/4 end frame	2599	43903
5604	Box		1940	Ext. side door	2621	43917
5604	Box		1940	Ext. side door	2622	43918
5604	Box		1940	3/4 end center sill	2624	43919
5604	Box		1940	3/4 center sill	2625	43920
5604	Box		1940	Body bolster diaphragm	2633	43927



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
NEW YORK CHICAGO & ST. LOUIS (continued)						
5604	Box		1940	Cross bearer	2634	43928
5604	Box		1940	Running board bracket	2635	43929
5604	Box		1940	Misc. body parts	2636	43930
5604	Box		1940	Interior no sheathing	2639	43931
5604	Box		1940	Interior corner no sheathing	2640	43932
5604	Box		1940	Interior sheathing in place	2641	43933
5604	Box	20148	1940	Int. end wrecked car; see 2834	2794	44063
5604	Box	20148	1940	Ext. end wrecked car	2795	44064
5604	Box	20148	1940	Ext. end wrecked car	2796	44065
5604	Box	20148	1940	Ext. end from above wrecked car	2797	44066
5604	Box	20097	1941	3/4 end, wrecked, 3001-3008 series	3001	44219
5604	Box	20097	1941	Ext. side, wrecked	3002	44220
5604	Box	20097	1941	Ext. 3/4 end, wrecked	3003	44221
5604	Box	20097	1941	Int., wrecked	3004	44222
5604	Box	20097	1941	Ext. end, wrecked	3005	44223
5604	Box	20097	1941	Ext. side, wrecked	3006	44224
5604	Box	20097	1941	Int., wrecked	3007	44225
5604	Box	20097	1941	Ext. side, wrecked	3008	44226
5604	Box	20110	1941	Ext. 3/4 end, damaged end	3009	44227
5604	Box	20110	1941	Ext. 3/4 end, damaged	3010	44228
5604	Box	20070	1941	Ext. 3/4 side, damaged car	3011	44229
5604	Box		1941	Ext. side damaged car	3012	44230
5604	Box	20097	1941	Ext. side door damaged	3012	44231
5604	Box	20097	1941	Ext. lower corner damage	3014	44232
5604	Box	20097	1941	Ext. damage at coupler	3015	44233
5604	Box	20097	1941	Ext. corner damage	3016	44234
5604	Box	20097	1941	Ext. roof corner damage	3017	44235
5604	Box		1940	Ext. side door	2621	43917
5604	Box		1940	Ext. side door	2622	43918
5604	Box		1940	3/4 end center sill	2625	43919
5604	Box		1940	Ext. side door	2621	43917
5604	Box		1940	Ext. side door	2622	43918
5604	Box		1940	3/4 end center sill	2625	43919
5604	Box		1940	3/4 center sill	2625	43920

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
NEW YORK CHICAGO & ST. LOUIS (continued)						
5604	Box		1940	3/4 center sill	2625	43920
5604A	Box		1940	3/4 side group of cars for delivery	2616	43914
5604A	Box	20000	1940	Ext. end	2627	43921
5604A	Box	20000	1940	Ext. hand brake end	2628	43922
5604A	Box		1940	Int. after repairs; see 2794-97	2834	44095
5604A	Box	20148	1940	Ext. 3/4 side after repair	2835	44096
5604A	Box	20148	1940	Ext. 3/4 front after repairs	2836	44097
5604A	Box	20000	1940	Ext. 3/4 side	9294	49180
JO13773	Box	20081	1940	Ext. 3/4 side	2677	43960
JO13773	Box	20081	1940	3/4 front	2678	43961
JO13773	Box	20081	1940	Int. end	2679	43962
JO13773	Box	20081	1940	Int. end	2680	43963
JO13773	Box	20081	1940	Underside before repair; see 2686-2695 series of repairs same car	2686	43969
JO13773	Box	20081	1940	See 2686	2687	43970
JO13773	Box	20081	1940	See 2686	2688	43971
JO13773	Box	20081	1940	See 2686	2689	43972
JO13773	Box	20081	1940	See 2686	2690	43973
JO13773	Box	20081	1940	See 2686	2691	43974
JO13773	Box	20081	1940	See 2686	2692	43975
JO13773	Box	20081	1940	See 2686	2693	43976
JO13773	Box	20081	1940	See 2686	2694	43977
JO13773	Box	20081	1940	See 2686	2695	43978
			1940	Fixture	2696	43979
5624	Gondola	76010	1940	3/4 front frame	2736	44012
5624	Gondola	76010	1940	3/4 side, frame	2737	44013
5624	Gondola	76010	1940	Truck side	2738	44014
5624	Gondola	76010	1940	Truck front	2739	44015
5624	Gondola	76010	1940	Int. from above	2742	44018
5624	Gondola	76010	1940	Ext. side	2743	44019
5624	Gondola	76011	1940	Ext. 3/4 side	2744	44020
5624	Gondola	76011	1940	Ext. end	2745	44021
5624	Gondola	76011	1940	Ext. hand brake end	2746	44022
5634	Gondola	72483	1940	Ext. side	2846	44106



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
NEW YORK CHICAGO & ST. LOUIS (continued)						
5634	Gondola	72484	1940	Ext. 3/4 side	2847	44107
5634	Gondola	72381	1940	Ext. end	2848	44108
5634	Gondola	72381	1940	Ext. hand brake end	2849	44109
5634	Gondola	72381	1940	Ext. end drop end removed	2850	44110
5634	Gondola	72481	1940	3/4 side frame in shop	2851	44111
5634	Gondola	72481	1940	3/4 front trucks	2853	44112
5720A	Flat	8008	1942	ext. 3/4 side	3624	44639
5766	Box	8006	1944	Ext. end	4201	44819
5766	Box	8006	1944	Int.	4202	44820
5766	Box		1944	Int. no floor or sheathing	4203	44821
5766	Box		1944	Ext. car frame exposed	4204	44822
5766	Box	8026	1944	Ext. hand brake end	4205	44823
5766	Box		1944	Truck 3/4 side	4206	44824
5766	Box		1944	Truck 3/4 front	4207	44825
5766	Box	8026	1944	Ext. 3/4 side	4208	44826
5766	Box	8004	1944	Ext. side	4209	44827
5766	Box		1944	Int. sidewall	4256	44831
5766	Box		1944	Int. at side door	4257	44832
5840	Box		1945	Ext. closeup underside air brake	5091	45400
5840	Box		1946	See 5091	5092	45401
5840	Box	5151	1946	Ext. 3/4 side	5103	45411
5840	Box	5151	1946	Ext. 3/4 side	5104	45412
5840	Box	5151	1946	Ext. hand brake end	5105	45413
5840	Box	5151	1946	Ext. hand brake end	5106	45414
5840	Box		1946	Shop scene, frame 3/4 end	5107	45415
5840	Box		1946	Shop scene, frame 3/4 end inverted	5108	45416
5840	Box	5000	1946	Interior	5109	45417
5840	Box		1946	Int. no floor or sheathing	5110	45418
5840	Box		1946	Truck, side view	5111	45419
5840	Box		1946	Truck, 3/4 front	5112	45420
5840	Box	5292	1946	Ext. 3/4 side	5113	45421
5887	Box	6251	1948	Ext. 3/4 side	5869	46129
5887	Box	6251	1948	Ext. hand brake end	5870	46130
JO30777			1948	Piece of board?	5977	46156

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
NEW YORK CHICAGO & ST. LOUIS (continued)						
JO30777	Box (repair)		1948	Ext. 3/4 side closeup; 5978-5982 a series	5978	46157
JO30777	Box (repair)		1948	Ext. side closeup; see 5978	5979	46158
JO30777	Box (repair)		1948	Ext. 3/4 end closeup; see 5978	5980	46159
JO30777	Box (repair)		1948	Ext. 3/4 side closeup; see 5978	5981	46160
JO30777	Box (repair)		1948	Ext. 3/4 side closeup; see 5978	5982	46161
5929	Hopper	47541	1949	Ext. 3/4 side	6420	46595
5929	Hopper	47541	1949	Ext. hand brake end	6421	46596
5930	Gondola	44275	1949	Ext. 3/4 side	6380	46555
5930	Gondola	44275	1949	Ext. hand brake end	6371	46556
5962A	Hopper Covered	49083	1950	Ext. 3/4 side	6689	46914
5962A	Hopper Covered		1950	Ext. hand brake end	6690	46915
	Box	26064	1950	Ext. end	6673	46898
	Box	27376	1950	Ext. end; not Pullman-built	6699	46924
8015	Box	22145	1952	Ext. 3/4 side	7410	47599
8015	Box	22145	1952	Ext. hand brake end	7411	47600

## NEW YORK DESPATCH REFRIGERATOR LINES

5567	Refrigerator, Ice Bunker	8050	1937	Truck front view	2216	43620
5567	Refrigerator	8050	1937	Truck, 3/4 side	2217	43621
5567	Refrigerator		1937	Interior from end	2224	43622
5567	Refrigerator	8050	1937	Ice bunker doors	2225	43623
5567	Refrigerator	8050	1937	Ice bunker doors	2226	43624
5567	Refrigerator	8050	1937	Drip pan/ice tank	2227	43625
5567	Refrigerator	8050	1937	Drip pan/ice tank	2228	43626
5567	Refrigerator	8050	1937	Interior from end	2235	43627
5567	Refrigerator	8050	1937	Liquid meter	2236	43628
5567	Refrigerator	8050	1937	Interior from end	2238	43629
5567	Refrigerator	8050	1937	Exterior hand brake end	2239	43630



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
NEW YORK NEW HAVEN & HARTFORD						
5780	Box		1944	3/4 front frame	4372	44886
5780	Box		1944	Frame details	4373	44887
5780	Box	31700	1944	Ext. 3/4 side	4429	44912
5780	Box	31323	1944	Ext. 3/4 side	4438	44918
5882	Box		1947	Ext. closeup of locking device; 5746-5751 a ser.	5746	46004
5882	Box		1947	See 5746	5747	46005
5882	Box		1947	See 5746	5748	46006
5882	Box		1947	See 5746	5749	46007
5882	Box		1947	See 5746	5750	46008
5882	Box		1947	See 5746	5751	46009
5882	Box	33870	1947	Ext. 3/4 side	5765	46023
5882	Box	33870	1947	Ext. hand brake end	5766	46024
8340	Box	40506	1956	Ext. 3/4 side	9209	49131
8340	Box	40506	1956	Ext. hand brake end	9210	49132
NEW YORK SUSQUEHANNA & WESTERN						
8080	Box		1952	Train of cars for delivery	7627	47808
8080	Box	414	1952	Ext. 3/4 side	7628	47809
8080	Box	414	1952	Ext. hand brake end	7629	47810
NEWBURGH & SOUTH SHORE						
	Hopper	2410	1940	Ext. 3/4 side	9307	49184
NMSX?						
8115	Box	5201	1952	Ext. 3/4 side	7714	47891
8115	Box	5201	1952	Ext. hand brake end	7715	47892

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
NORFOLK & WESTERN						
8002	Box	44324	1951	Ext. 3/4 side	7057	47271
8002	Box	44324	1951	Ext. hand brake end	7058	47272
8035	Box	44500	1952	Ext. 3/4 side	7300	47493
8035	Box	44500	1952	Ext. hand brake end	7301	47494
8035	Box	44500	1952	Ext. 3/4 side	7331	47523
8035	Box	44500	1952	Ext. side	7332	47524
8035	Box	44500	1952	Ext. hand brake end	7333	47525
8100	Box	53124	1953	Ext. 3/4 side	7760	47937
8100	Box	53124	1953	Ext. hand brake end	7761	47938
8100	Box		1953	Int.	7762	47939
8100	Box		1953	Int. worker installing loading straps	7763	47940
8100	Box	53495	1953	Floor framing; 7821-7841 a series	7821	47995
8100	Box	53495	1953	Int. floor framing; see 7821	7822	47996
8100	Box	53495	1953	Int. no floor or sheathing; see 7821	7823	47997
8100	Box	53495	1953	Int. floor framing; see 7821	7824	47998
8100	Box		1953	Int. floor framing; see 7821	7825	47999
8100	Box		1953	Floor members; see 7821	7826	48000
8100	Box		1953	Floor members; see 7821	7827	48001
8100	Box		1953	Floor framing closeup; see 7821	7828	48002
8100	Box		1953	Similar to 7828; see 7821	7829	48003
8100	Box		1953	Similar to 7828; see 7821	7830	48004
8100	Box		1953	Int. floor const.; see 7821	7831	48005
8100	Box		1953	Int. closeup of floor; see 7821	7832	48006
8100	Box		1953	Similar to 7832; see 7821	7833	48007
8100	Box		1953	Similar to 7832; see 7821	7834	48008
8100	Box		1953	Int. floor closeup; see 7821	7835	48009
8100	Box		1953	Int. floor; see 7821	7836	48010
8100	Box		1953	Int. from end; see 7821	7837	48011
8100	Box	53495	1953	Int. ; see 7821	7838	48012
8100	Box	53495	1953	Int. ; see 7821	7839	48013
8100	Box	53495	1953	Int.; see 7821	7840	48014
8100	Box	53495	1953	Int.; see 7821	7841	48015
8159	Box		1953	Group inspecting car (8200-8203 a series)	8200	48237



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
NORFOLK & WESTERN (continued)						
8159	Box		1953	See 8200	8201	48238
8159	Box	53542	1953	See ;8200	8202	48239
8159	Box		1953	See 8200	8203	48240
8159	Box		1954	120 car train of cars being delivered; 8213-15 ser.	8213	48250
8159	Box		1954	See 8213	8214	48251
8159	Box		1954	See 8213	8215	48252
8159	Box	53749	1954	Ext. 3/4 side	8217	48254
8159	Box	53749	1954	Ext. hand brake end	8218	48255
8159	Box	53749	1954	Ext. 3/4 side	8226	48260
8160	Box	53996	1954	Ext. 3/4 side	8294	48327
8160	Box	53996	1954	Ext. hand brake end	8295	48328
8260	Box	52749	1955	Ext. 3/4 side	8911	48842
8260	Box	52749	1955	Ext. hand brake end	8912	48843
8261	Box	42099	1955	Ext. 3/4 side	8909	48840
8261	Box	42099	1955	Ext. hand brake end	8910	48841
8305	Box	52799	1956	Ext. 3/4 side	9218	49140
8305	Box	52799	1956	Ext. hand brake end	9219	49141
NORFOLK SOUTHERN						
5513	Box	25246	1935	Exterior side	1993	43496
5513	Box	25246	1935	Exterior, 3/4 end	1994	43497
5513	Box	25246	1935	Exterior end (hand brake)	1995	43498
5871	Box	27000	1947	Ext. 3/4 side	5647	45903
5871	Box	27000	1947	Ext. hand brake end	5648	45904
NORTH AMERICAN CAR CORP.						
5979C	Hopper Covered	30030	1951	Ext. 3/4 side	6977	47191
5979C	Hopper Covered	30030	1951	Ext. hand brake end	6978	47192

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
NORTHERN PACIFIC						
5386	Arch Bar Truck		1926	Side view	1369	43300
5621	Truck Double Truss	15108	1940	Side	2698	43980
5621	Truck Double Truss	15108	1940	Front	2699	43981
5621	Truck Double Truss	15108	1940	3/4 front from above	2700	43982
5621	Box	15108	1940	3/4 front frame	2701	43983
5621	Box	15108	1940	3/4 front frame inverted	2702	43984
5621	Box	15108	1940	Ext. side	2703	43985
5621	Box	15108	1940	Ext. side	2704	43986
5621	Box	15108	1940	Ext. end	2705	43987
5621	Box	15108	1940	Ext. hand brake end	2706	43988
5621	Box	15108	1940	Int. no floor frame exposed	2707	43989
5621	Box	15137	1940	Interior	2708	43991
5621	Box	15137	1940	Duplicate of 2708	2708A	43992
5662	Box	17177	1941	Ext. 3/4 side	3026	44243
5662	Box	17672	1941	Ext. side	3027	44244
5662	Box	17177	1941	Ext. end	3028	44245
5662	Box	17177	1941	Ext. hand brake end	3029	44246
5662	Box	17502	1941	Int. from end	3030	44247
5662	Box	17633	1941	Ext. roof from end	3031	44248
5662	Box		1941	Truck, 3/4 side	3032	44249
5662	Box		1941	3/4 side frame, shop scene	3035	44250
5662	Box		1941	3/4 side frame shop scene	3036	44251
5698	Box	27635	1942	Ext. 3/4 side	3351	44430
5698	Box	27635	1942	Ext. 3/4 car end	3352	44431
5770	Box	28023	1944	Ext. 3/4 side	4318	44848
5770	Box		1944	Ext. 3/4 side car frame exposed	4319	44849
5770	Box	28023	1944	Ext. hand brake end	4320	44850
5770	Box	28021	1944	Ext. end	4321	44851
5770	Box	28464	1944	Ext. 3/4 side	4322	44852
5770	Box	28014	1944	Int.	4323	44853
5770	Box	28022	1944	Ext. roof	4324	44854
5770	Box		1944	Truck side view	4325	44855
5770	Box		1944	Truck 3/4 front	4326	44856



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
NORTHERN PACIFIC (continued)						
5770	Box		1944	Truck top view	4327	44857
5770	Box		1944	Similar to 4327	4328	44858
5770	Box		1944	3/4 front frame	4329	44859
5770	Box		1944	3/4 front frame inverted	4330	44860
5807	Box		1945	Truck front view	4647	45035
5807	Box		1945	Truck 3/4 side	4648	45036
5807	Box		1945	Truck 3/4 side	4649	45037
5807	Box		1945	Truck 3/4 front	4650	45038
5807	Box		1945	Truck 3/4 front	4651	45039
5807	Box		1945	Truck 3/4 side	4652	45040
5807	Box		1945	Truck 3/4 side	4653	45041
5807	Box	29168	1945	Ext. 3/4 side	4659	45045
5807	Box	29168	1945	Ext. 3/4 side	4669	45049
5807	Box	29168	1945	Ext. end	4670	45050
5807	Box	29168	1945	Ext. hand brake end	4671	45051
5807	Box	29168	1945	Ext. roof from end	4672	45042
5807	Box	29168	1945	Int. no floor or sheathing	4673	45053
5807	Box	29070	1945	Int. finished	4674	45054
5807	Box		1945	Trucks, side	4675	45055
5807	Box		1945	Truck 3/4 front	4676	45056
5807	Box		1945	Truck top	4677	45057
5807	Box		1945	Truck top, no bolster	4678	45058
5807	Box		1945	Frame 3/4 front	4679	45059
5807	Box		1945	Frame 3/4 front inverted	4680	45060
	Box	12786	1950	Ext. end; not Pullman-built	6675	46900

## NORTHERN REFRIGERATOR CAR CO.

5438	Refrigerator	120	1929	Exterior end	1740	43395
5438	Refrigerator	120	1929	Exterior, 3/4 end	1741	43396
5468	Refrigerator	471	1929	End view trucks and partial frame	1744	43397
5468	Refrigerator	471	1929	3/4 view truck	1745	43398
5468	Refrigerator	471	1929	Exterior, 3/4 end view	1749	43399

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
NORTHERN REFRIGERATOR LINE						
5550	Express Reefer	779	1942	Ext. side	3502	44579
5550	Express Reefer	727	1942	Ext. side	3503	44580
5550	Express Reefer		1942	Interior repair to floor	3504	44581
5550	Express Reefer		1942	3/4 end ext.	3518	44592
5550	Express Reefer	763	1942	Ext. 3/4 side	3519	44593
5550	Express Reefer		1942	Ext. roof doors	3532	44594
5550	Express Reefer		1942	Workman welding car center plate	3551	44595
5550	Express Reefer		1942	Closeup of truck brake and journal	3554	44596
5550	Express Reefer	709	1942	Ext. side	3560	44598
5550	Express Reefer	709	1942	Ext. 3/4 side	3561	44597
5550	Express Reefer		1942	Ext. 3/4 hand brake end	3562	44599
5550	Express Reefer	707	1942	Ext. 3/4 side	3563	44600
5550	Express Reefer		1942	Ext. closeup of side	3575	44603
OLYMPIC PORTLAND CEMENT CO. LTD.						
8152	Hopper Covered	H4	1953	Ext. 3/4 side	8191	48228
8152	Hopper Covered	H4	1953	Ext. hand brake end	8192	48229
ORINOCO MINING CO.						
	Hopper	OMC2-1	1953	Ext. 3/4 front (note car blt. by Magor Car Corp.)	8209	48246
	Hopper	OMC2-1	1953	Ext. side; note car built by Magor Car Corp.)	8210	48247
	Hopper	OMC2-1	1953	Ext. hand brake end; car built by Magor Car Corp.	8211	48248



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
PACIFIC FRUIT EXPRESS (U.P.-S.P.)						
5431	Refrigerator	37034		End (hand brake)	1582	43343
5526	Wheel, 700#		1936	Inside and outside	2070	43555
5526	Refrigerator	41950	1936	Ext. side	9301	49175
5526	Refrigerator	41950	1936	Dup. negative	9302	49176
5857	Refrigerator		1947	Frame 3/4 front	5387	45640
5857	Refrigerator		1947	Frame inverted	5388	45641
5857	Refrigerator		1947	Frame 3/4 front	5389	45643
5857	Refrigerator		1947	Ext. installing side door	5401	45655
5857	Refrigerator		1947	Ext. similar to 5401	5402	45656
5857	Refrigerator		1947	Installing roof	5403	45657
5857	Refrigerator		1947	Installing roof	5404	45658
5857	Refrigerator		1947	Installing roof	5405	45659
5857	Refrigerator		1947	Int. no roof	5406	45650
5857	Refrigerator		1947	No roof installing side wall insulation	5407	45661
5857	Refrigerator		1947	Ext. 3/4 end roof off installing insulation	5408	45662
5857	Refrigerator		1947	Similar to 5409	5410	45663
5857	Refrigerator		1947	Train of cars for delivery	5434	45687
5857	Refrigerator	47754	1947	Ext. 3/4 side	5436	45689
5857	Refrigerator	47779	1947	Int.	5437	45690
5857	Refrigerator	47779	1947	Int.	5438	45691
5857	Refrigerator	47784	1947	Ext. 3/4 side	5445	45698
5857	Refrigerator	47784	1947	Ext. end	5446	45699
5857	Refrigerator	47784	1947	Ext. hand brake end	5447	45700
5857	Refrigerator		1947	Int. from above no roof	5448	45701
5857	Refrigerator		1947	Int. end gates; see 5478	5477	45730
5857	Refrigerator		1947	Int. worker moving gate; see 5477	5478	45731
5857	Refrigerator		1947	Int. gate latch	5479	45732
5857	Refrigerator		1947	Truck, side view	5484	45736
5857	Refrigerator		1947	Truck, 3/4 front	5485	45737
5857	Refrigerator	47839	1947	Ext. 3/4 end	5486	45738
5857	Refrigerator		1947	Int. no floor or sheathing	5488	45740
5857	Refrigerator		1949	Train of cars for delivery; 5512-5514 a series	5512	45767
5857	Refrigerator		1949	See 5512	5513	45768

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
PACIFIC FRUIT EXPRESS (continued)						
5857	Refrigerator		1949	See 5512	5514	45769
5857	Refrigerator	17859	1947	Ext. side	5517	45772
5857	Refrigerator		1947	Train of cars for delivery	5518	45773
5857	Refrigerator		1947	Similar to 5518	5519	45774
PENNSYLVANIA RAILROAD						
			1940	Door section, repair work	2730	44006
	Box		1940	Int. Creco side door	2799	44067
	Box		1940	Int. Creco door	2800	44068
	Box	120330	1950	Ext. end; not Pullman-built	6674	46899
	Gondola	364255	1950	6781-6796 a series of details of PRR gondola in H&B yard	6781	47007
	Gondola	364255	1950	3/4 end view yard; see 6781	6782	47008
	Gondola	364255	1950	End view; see 6781	6783	47009
	Gondola	364255	1950	See 6781	6784	47010
	Gondola	364255	1950	See 6781	6785	47011
	Gondola	364255	1950	See 6781	6786	47012
	Gondola	364255	1950	See 6781	6787	47013
	Gondola	364255	1950	See 6781	6788	47014
	Gondola	364255	1950	See 6781	6789	47015
	Gondola	364255	1950	See 6781	6790	47016
	Gondola	364255	1950	See 6781	6791	47017
	Gondola	364255	1950	See 6781	6792	47018
	Gondola	364255	1950	See 6781	6793	47019
	Gondola	364255	1950	See 6781	6794	47020
	Gondola	364255	1950	See 6781	6795	47021
	Gondola	364255	1950	See 6781	6796	47022
8160	Box	47009	1954	Ext. 3/4 side	8288	48321
8160	Box	47009	1954	Ext. hand brake end	8289	48322



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
PERE MARQUETTE						
5478	Auto/Furniture	90991	1930	Exterior end (hand brake)	1951	43481
5604B	Box	84000	1940	Ext. end	2629	43923
5604B	Box	84000	1940	Ext. hand brake end	2630	43924
5604B	Box	84020	1948	Closeup of draft gear lugs	6218	46394
5604B	Box	84020	1948	See 6218	6219	46395
5604B	Box	84020	1948	Closeup of coupler	6220	46396
5604B	Box	84000	1940	Ext. side	9295	49181
5647	Box	83735	1941	Int. door panel	2935	44160
5647	Box	83735	1941	Int. door	2936	44161
5647	Box	83735	1941	Ext. side door	2937	44162
5647	Box	83735	1941	Ext. side door	2938	44163
5647	Box	83735	1941	Ext. side door	2939	44164
5647	Box	83690	1941	Ext. 3/4 side	2946	44171
5647	Box	83760	1941	Ext. end	2947	44172
5647	Box	83760	1941	Int. end	2948	44173
5647	Box	83760	1941	Opp. of 2948	2949	44174
5647	Box	83760	1941	Int. end from side door	2950	44175
5647	Box	83760	1941	Ext. roof from end	2951	44176
PITTSBURGH & LAKE ERIE						
	Box	21568	1951	Closeup of center of frame; see 7188; 7169-7188 ser.	7169	47369
	Box		1951	Center of frame; see 7188	7170	47370
	Box		1951	Closeup of center of frame; see 7188	7171	47371
	Box		1951	Closeup of frame at side sill; see 7188	7172	47372
	Box		1951	Closeup of roof at side sill; see 7188	7173	47373
	Box		1951	Int. frame at bolster; see 7188	7174	47374
	Box		1951	Int. roof at side sill; see 7188	7175	47375
	Box		1951	Int. closeup of frame; see ;7188	7176	47376
	Box		1951	Int. closeup of frame; see 7188	7178	47378
	Box		1951	Int. closeup of frame; see 7188	7179	47379
	Box		1951	Ext. coupler; see 7188	7180	47380

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
PITTSBURGH & LAKE ERIE (continued)						
	Box		1951	Ext. coupler; see 7188	7181	47381
	Box		1951	Int. no floor; see 7188	7182	47382
	Box		1951	Int. no floor; see 7188	7183	47383
	Box		1951	Int. frame at bolster; see 7188	7184	47384
	Box	21568	1951	Ext. hand brake end; not Pullman, blt. D&S	7185	47385
	Box	21568	1951	Ext. hand brake end; not Pullman, blt. D&S	7186	47386
	Box	21568	1951	Ext. side; not Pullman, blt. D&S	7187	47387
	Box	21568	1951	Ext. side; not Pullman, blt. D&S	7188	47388
PITTSBURGH & WEST VIRGINIA						
5919A	Box	1310	1948	Ext. 3/4 side	6185	46361
5919A	Box	1310	1948	Ext. hand brake end	6206	46382
PRESSED STEEL CAR CO.						
				Center Bearing Plate	2129	43589



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
PULLMAN						
	Journal Boxes		1929	National Malleable & Steel Casting Co. Pat. 1914 (marked "Pullman")	1682	43362
	Journal Boxes		1929	National Malleable & Steel Casting Co. Pat. 1914	1683	43363
	Journal Box			Bearing wedges	1684	43364
	Journal Box			Frnt. vw. Nat. Malleable & Steel Casting Co. Pat. 1914	1685	43365
	Journal Boxes			2 views National Malleable & Steel Casting Co.	1686	43366
	Journal Box			Front view closed, Nat. Malleable & Steel Casting Co.	1687	43367
	Journal Box			Same as 43367 except open	1688	43368
	Journal Boxes		1929	2 types, 2 views each	1720	43385
	750# Steel Wheel			Both sides	2130	43590
	Wheels		1937	Both sides 695# car wheels	2341	43696
			1937c.	Welded bolster	2343	43697
	Truck trailer		1940	Int. single axle	2658	43944
	Truck trailer		1940	Ext. 3/4 frt. under side	2659	43945
	Truck trailer		1940	Int. front end	2660	43946
	Truck trailer		1940	Ext. rear door and & roof?	2661	43947
	Truck trailer		1940	Interior	2662	43948
	Truck trailer		1940	Ext. rear frame	2663	43949
	Truck trailer		1940	Ext. axle & brakes, 3/4 front	2664	43950
	Truck trailer		1940	Front view axle, brakes	2665	43951
	Truck trailer		1940	Ext. frame	2666	43952
	Truck trailer		1940	Ext. 3/4 front	2667	43953
	Truck trailer		1940	Ext. 3/4 rear	2668	43954
	Truck trailer		1940	Ext. side	2669	43955
	Truck trailer		1939	3/4 front underside	2670	43956
	Truck trailer		1940	3/4 rear under side	2671	43957
			1952	100th anniversary car label	7624	47805
	Box		1947	Shop scene building car doors; 5523-5528 a series	5523	45778
	Box		1947	See 5523	5524	45779
	Box		1947	Cleaning door prior to painting; see 5523	5525	45780
	Box		1947	Similar to 5525; see 5523	5526	45781
	Box		1947	Painting door; see 5523	5527	45782
	Box		1947	Similar to 5527; see 5523	5528	45783

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
PULLMAN (continued)						
	Box		1947	Ext. 3/4 side painting car	5529	45784
	Box		1947	Ext. side adjusting door latch	5530	45785
	Box		1947	Ext. hand brake end	5531	45786
	Box		1947	Ext. closeup of coupler	5532	45787
	Box		1947	Bolster section of frame inverted; cutaway showing draft gear lugs; 5533-5538 a series	5533	45788
	Box		1947	Frame bolster section, side; see 5533	5534	45789
	Box		1947	Similar to 5533	5535	45790
	Box		1947	Frame bolster section 3/4 rear; see 5533	5536	45791
	Box		1947	Frame bolster section 3/4 rear; see 5533	5537	45792
	Box		1947	Frame bolster section 3/4 side; cutaway showing draft gear lugs; see 5533	5538	45793
	Box	PS 1-3	1951	Car ladders closeup; see 6937	6936	47150
	Box	PS 1-3	1951	See 6936	6937	47151
			1951	Closeup of brake gear & coupler; see 6942	6941	47155
			1951	See 6941	6942	47156
	Box		1951	Pressed Steel car roof; 7092-7097 a series	7092	47299
	Box		1951	See 7092	7093	47300
	Box		1951	See 7092	7094	47301
	Box		1951	See 7092	7095	47302
	Box		1951	See 7092	7096	47303
	Box		1951	See 7092	7097	47304
			1951	Ext. roof 3/4 front Pressed Steel; see 7103	7102	47309
			1951	See 7102	7103	47310
			1952	Worker with stencil after spray painting car ("Pullman 100th Year")	7278	47472
	Box		1956	Ext. 3/4 side; special color scheme, car marked "Body by Fisher"; 9046-9049 a series	9046	48976
	Box		1956	Ext. 3/4 side; see 9046	9047	48977
	Box		1956	Ext. 3/4 side; see 9046	9048	48978
	Box		1956	Ext. 3/4 side; see 9046	9049	48979



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
PULLMAN (continued)						
JO36209	Hopper		1952	Frame & floor with coupler pocket inverted	7434	47623
JO36209	Hopper		1952	Frame & floor inverted from rear	7435	47624
JO36209	Hopper		1952	Frame & floor inverted 3/4 rear	7436	47625
JO36209	Hopper		1952	Similar to 7438 closeup	7437	47626
JO36209	Hopper		1952	Similar to 7439	7438	47627
JO36209	Hopper		1952	Floor & frame inverted	7439	47628
JO36209	Hopper		1952	Frame & floor 3/4 rear	7440	47629
JO36209	Hopper		1952	Frame & floor side view	7441	47630
JO36209	Hopper		1952	Hopper doors from above	7442	47631
JO36209	Hopper		1952	Coupler pocket top view	7443	47632
JO36209	Hopper		1952	Hopper door	7444	47633
JO36209	Hopper		1952	Hopper door	7445	47634
JO36209	Hopper		1952	Car end panel	7452	47641
JO36209	Hopper		1952	Side frame	7453	47642
JO36209	Hopper		1952	Similar to 7453	7454	47643
JO36209	Hopper		1952	Int. from front above doors closed	7457	47644
JO36209	Hopper		1952	Int. from front above doors open	7458	47645
JO36209	Hopper		1952	Ext. 3/4 side (in primer paint)	7459	47646
PULLMAN PS2-2						
			1949	Side sheet; 6576-6577 a series	6576	46738
			1949	Side sheet; see 6576	6577	46739
			1949	Side sheet; see 6576	6578	46740
			1949	Frame 3/4 front; see 6639	6638	46805
			1950	Frame 3/4 front inverted; see 6638	6639	46806
PULLMAN PS-3 (PSX-44)						
	Hopper 70-ton		1954	Ext. side; 8391-8400 same car	8391	48362
	Hopper 70-ton		1954	Ext. hand brake end; see 8391	8392	48363
	Hopper 70-ton		1954	Ext. 3/4 end; see 8391	8393	48364

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
PULLMAN PS-3 (continued)						
	Hopper 70-ton		1954	Ext. hand brake end; see 8391	8394	48365
	Hopper 70-ton		1954	Int. from end; see 8391	8395	48366
	Hopper 70-ton		1954	Ext. 3/4 side; see 8391	8396	48367
	Hopper 70-ton		1954	Ext. side; see 8391	8397	48368
	Hopper 70-ton		1954	Ext. 3/4 front; see 8391	8398	48369
	Hopper 70-ton		1954	Ext. closeup of hopper doors; see 8391	8399	48370
	Hopper 70-ton		1954	Int. from end; see 8391	8400	48371
PULLMAN PSX (Exhibition Car)						
JO34869	Compartmentizer	171400	1951	Int. ceiling; 6983-7018 a series	6983	47197
	Compartmentizer	171400	1951	Int. no floor or sheathing; see 6983	6984	47198
	Compartmentizer	171400	1951	Int. no floor or sheathing; see 6983	6985	47199
	Compartmentizer	171400	1951	Int. no floor or sheathing; see 6983	6986	47200
	Compartmentizer	171400	1951	Int. ceiling; see 6983	6987	47201
	Compartmentizer	171400	1951	Int. ceiling; see 6983	6988	47202
	Compartmentizer	171400	1951	Int. ceiling; see 6983	6989	47203
	Compartmentizer	171400	1951	Int. partially finished; see 6983	6990	47204
	Compartmentizer	171400	1951	Int. opposite of 6990; see 6983	6991	47205
JO34869	Compartmentizer	171400	1951	Int. partially finished; see 6983	6992	47206
	Compartmentizer	171400	1951	Int. ceiling & end closeup; see 6983	6993	47207
	Compartmentizer	171400	1951	Int. closeup of compartment floor anchor; see 6983	6994	47208
	Compartmentizer	171400	1951	Int. closeup of corner; see 6983	6995	47209
	Compartmentizer	171400	1951	Int. closeup of compartment door & hinge; see 6983	6996	47210
	Compartmentizer	171400	1951	Int. compartment door lower hinge; see 6983	6997	47211
	Compartmentizer	171400	1951	Int. compartment door upper hinge; see 6983	6998	47212
	Compartmentizer	171400	1951	Int. compartment door lower hinge; see 6983	6999	47213
	Compartmentizer	171400	1951	Int. compartment door upper brace; see 6983	7000	47214
	Compartmentizer	171400	1951	Int. compartment doors center lock; see 6983	7001	47215
	Compartmentizer	171400	1951	Int. colmpartment door upper brace; see 6983	7002	47216
	Compartmentizer	171400	1951	Int. upper section compartment door; see 6983	7003	47217
	Compartmentizer	171400	1951	Int. upper compartment door traveler; see 6983	7004	47218
	Compartmentizer	171400	1951	Int. compartment door traveler; see 6983	7005	47219



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
PULLMAN PSX (continued)						
	Compartmentizer	171400	1951	Int. compart. door lock; see 6983	7006	47220
	Compartmentizer	171400	1951	Int. compart. door locks; see 6983	7007	47221
	Compartmentizer	171400	1951	Int. compart. door lower hinge; see 6983	7008	47222
	Compartmentizer	171400	1951	Int. end compart. doors; see 6983	7009	47223
	Compartmentizer	171400	1951	Int. end compart. doors; see 6983	7010	47224
	Compartmentizer	171400	1951	Int. side; see 6983	7011	47225
	Compartmentizer	171400	1951	Int. end compart. doors; see 6983	7012	47226
	Compartmentizer	171400	1951	Int. end compart. doors; see 6983	7013	47227
	Compartmentizer	171400	1951	Int. end compart. doors; see 6983	7014	47228
	Compartmentizer	171400	1951	Int. end compart. doors; see 6983	7015	47229
	Compartmentizer	171400	1951	Int. end compart. doors; see 6983	7016	47230
	Compartmentizer	171400	1951	Int. compart. door; see 6983	7017	47231
	Compartmentizer	171400	1951	Ext. 3/4 side	7018	47232
	Compartmentizer	171400	1951	Int. damaged caused by shifted load; 7031-7036 ser.	7031	47245
	Compartmentizer	171400	1951	See 7031	7032	47246
	Compartmentizer	171400	1951	See 7031	7033	47247
	Compartmentizer	171400	1951	See 7031	7034	47248
	Compartmentizer	171400	1951	See 7031	7035	47249
	Compartmentizer	171400	1951	See 7031	7036	47250
	Compartmentizer	171400	1951	Int. compartment load; 7037-7040 a series	7037	47251
	Compartmentizer	171400	1951	See 7037	7038	47252
	Compartmentizer	171400	1951	See 7037	7039	47253
	Compartmentizer	171400	1951	See 7037	7040	47254

## PULLMAN PSX-1

JO27406	Box		1947	Ext. 3/4 side	5540	45796
JO27406	Box		1947	Ext. side	5541	45797
JO27406	Box		1947	Ext. opposite of 5541	5542	45798
JO27406	Box		1947	Int. car side	5489	45741
JO27406	Box		1947	Dup. of frame 45741	5490	45742
JO27406	Box		1947	Frame 3/4 front	5490	45743
JO27406	Box		1947	Dup. of frame 45743	5490	45744

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
PULLMAN PSX-1 (continued)						
JO27406	Box		1947	Frame 3/4 side inverted	5491	45745
JO27406	Box		1947	Dup. of frame 45745	5491	45746
JO27406	Box		1947	Frame end only inverted	5492	45747
JO27406	Box		1947	Same as 5492 frame right side up	5493	45748
JO27406	Box		1947	Coupler pocket	5494	45749
JO27406	Box		1947	Frame, side end only	5495	45750
JO27406	Box		1947	Frame 3/4 side end only	5496	45751
JO27406	Box		1947	Frame inverted (center section)	5497	45752
JO27406	Box		1947	Frame at bolster	5498	45753
JO27406	Box		1947	Frame inverted center section	5499	45754
JO27406	Box		1947	Int. car end sheet	5506	45761
JO27406	Box		1947	Int. corner	5507	45762
JO27406	Box		1947	Ext. end	5508	45763
JO27406	Box		1947	Ext. 3/4 side from above	5509	45764
JO36935	Box 50,000th		1953	Frame end, bolster for exhibit; 7784-7789 series	7784	47959
JO36935	Box		1953	See 7784	7785	47960
JO36935	Box		1953	See 7784	7787	47961
JO36935	Box		1953	See 7784	7788	47962
JO36935	Box		1953	See 7784	7789	47963
	Box 50,000th	PSX-1	1953	Ext. 3/4 side; 7790-7797 a series	7790	47964
	Box 50,000th	PSX-1	1953	Ext. end; see 7790	7791	47965
	Box 50,000th	PSX-1	1953	Ext. hand brake end; see 7790	7792	47966
	Box 50,000th	PSX-1	1953	Int.; see 7790	7793	47967
	Box 50,000th	PSX-1	1953	Int.	7794	47968
	Box 50,000th	PSX-1	1953	See 7790	7795	47969
	Box 50,000th	PSX-1	1953	Int.; see 7790	7796	47970
	Box 50,000th	PSX-1	1953	Int. no floor or sheathing; see 7790	7797	47971



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
PULLMAN (continued)						
PULLMAN PSX-2						
	Hopper Covered		1953	Ext. hand brake end	7966	48059
	Hopper Covered		1953	Ext. end	7967	48060
	Hopper Covered		1953	Ext. 3/4 end; see 7966	7968	48061
	Hopper Covered		1953	Ext. hopper doors	7969	48062
	Hopper Covered		1953	Ext. 3/4 end only	7970	48063
	Hopper Covered		1953	Top view of roof with diff. type doors	7973	48066
	Hopper Covered		1953	Ext. end	7976	48069
PULLMAN PSX-3 (exhibition car)						
J014852	Hopper	PS-3	1953	Ext. 3/4 side; 7853-7869 a series	7853	48019
J014852	Hopper	PS-3	1953	Ext. 3/4 side; see 7853	7854	48020
J014852	Hopper	PS-3	1953	3/4 end from above; see 7853	7855	48021
J014852	Hopper	PS-3	1953	Int. car body only; see 7853	7856	48022
J014852	Hopper	PS-3	1953	Ext. end; see 7853	7857	48023
J014852	Hopper	PS-3	1953	Ext. hand brake end; see 7853	7858	48024
J014852	Hopper	PS-3	1953	Builders plate; see 7853	7859	48025
J014852	Hopper	PS-3	1953	Closeup of welded joint; see 7853	7860	48026
J014852	Hopper	PS-3	1953	Closeup of car body frame; see 7853	7861	48027
J014852	Hopper	PS-3	1953	Int. of body closeup; see 7853	7862	48028
J014852	Hopper	PS-3	1953	Closeup of car body frame; see 7853	7863	48029
J014852	Hopper	PS-3	1953	Ext. closeup of frame; see 7853	7864	48030
J014852	Hopper	PS-3	1953	Ext. closeup of frame; see 7853	7866	48031
J014852	Hopper	PS-3	1953	Closeup of body welds; see 7853	7867	48032
J014852	Hopper	PS-3	1953	Int. closeup of riveted section; see 7853	7868	48033
J014852	Hopper	PS-3	1953	Ext. closeup of air tank; see 7853	7869	48034

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
PULLMAN (continued)						
PULLMAN X-P5 & P5						
	Box	X-P5-1-1	1950	Car sides on flat car; see 6648	6646	46876
	Box	X-P5-1-1	1950	Car side on flat car; 6646, 6648-51 a series	6648	46878
	Box	X-P5-1-2	1950	See 6648	6649	46879
	Box	P5-2-1	1950	See 6648	6650	46880
	Box	P5-2-2	1950	See 6648	6651	46881
		P5-X-23	1950	Closeup of uncoupling rod; see 6831	6830	47047
		P5-X-23	1950	Closeup of uncoupling rod; see 6830	6831	47048
	Box	P5-X-26	1951	Int. end no floor; see 6922	6921	47134
	Box	P5-X-26	1951	Int. opposite of 6921	6922	47135
PULLMAN PSX-12						
	Hopper		1948	Ext. 3/4 end only	6133	46310
	Hopper		1948	Ext. 3/4 hand brake end	6134	46311
	Hopper		1948	Ext. 3/4 end only	6135	46312
PULLMAN PSX-19						
5955	Box	PSX19	1949	Ext. corner grab irons	6479	46645
	Box		1949	Int. floor frame (patent applied for); 6536-6563 a series	6536	46698
	Box		1949	Int. unfinished; see 6536	6537	46699
	Box		1949	Ext. closeup of underside; see 6536	6538	46700
	Box		1949	Ext. closeup of brake gear; see 6536	6539	46701
	Box		1949	Ext. closeup of brake gear; see 6536	6540	46702
	Box		1949	Ext. closeup of brake gear; see 6536	6541	46703
	Box		1949	Ext. closeup of brake gear; see 6536	6542	46704
	Box		1949	Ext. closeup of lower car end; see 6536	6543	46705
	Box		1949	Int. end unfinished; see 6536	6544	46706
	Box		1949	Ext. corner grab irons; see 6536	6545	46707



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
PULLMAN PSX-19 (continued)						
	Box		1949	Ext. closeup car end brake gear; see 6536	6546	46708
	Box		1949	Ext. underside closeup of brake gear; see 6536	6547	46709
	Box		1949	Ext. underside frame; see 6536	6548	46710
	Box		1949	Ext. underside frame; see 6536	6549	46711
	Box		1949	Int. unfinished; see 6536	6550	46712
	Box		1949	Ext. coupler; see 6536	6551	46713
	Box		1949	Ext. lower corner end; see 6536	6552	46714
	Box		1949	Ext. at truck; see 6536	6553	46715
	Box		1949	Ext. closeup of step; see 6536	6554	46716
	Box		1949	Ext. closeup of truck; see 6536	6555	46717
	Box		1949	Ext. 3/4 side no paint; see 6536	6556	46718
	Box		1949	Ext. side no paint; see 6536	6557	46719
	Box		1949	Ext. 3/4 side no paint; see 6536	6558	46720
	Box		1949	Ext. 3/4 end no paint; see 6536	6559	46721
	Box		1949	Ext. end; see 6536	6560	46722
	Box		1949	Ext. hand brake end; see 6536	6561	46723
	Box		1949	Ext. 3/4 hand brake end; see 6536	6562	46724
	Box		1949	Ext. end; see 6536	6563	46725
PULLMAN PSX-24						
	Box		1951	Ext. closeup of uncoupling rods; 7198-7209 series	7198	47398
	Box		1951	Ext. closeup of frame & bolster; see 7198	7199	47399
	Box		1951	Closeup of frame & truck; see 7198	7200	47400
	Box		1951	Closeup of frame & wheel; see 7198	7201	47401
	Box		1951	Int. end no floor or sheathing; see 7198	7202	47402
	Box		1951	Int. opposite of 7202	7203	47403
	Box		1951	Ext. closeup of uncoupling rod & truck; see 7198	7204	47404
	Box		1951	Closeup of truck & underframe; see 7198	7205	47405
	Box		1951	Int. frame at bolster no floor; see 7198	7206	47406
	Box		1951	Different view of 7206; see 7198	7207	47407
	Box		1951	Int. no floor	7254	47454
	Box		1951	Frame at bolster top	7255	47455
	Box		1951	Frame at bolster top	7256	47456

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
Pullman (continued)						
PULLMAN PSX-34						
	Box		1952	Int. hydraulic press straightening floor beams	7374	47566
	Box		1952	Int. bend in floor beams; see 7374	7375	47567
PULLMAN PSX-35						
JO7660	Hopper Covered		1952	Ext. 3/4 side	7400	47592
JO7660	Hopper Covered		1952	Ext. opposite of ;7400	7401	47593
JO7660	Hopper Covered		1952	Ext. 3/4 side	7402	47594
JO7660	Hopper Covered		1952	Details of lower body corner	7403	47595
JO7660	Hopper Covered		1952	Ext. closeup of hopper doors	7405	47596
JO7660	Hopper Covered		1952	Similar to 7405	7406	47597
JO7660	Hopper Covered		1952	Roof hatches; 7414-7421 a series of hatch photos	7414	47603
JO7660	Hopper Covered		1952	See ;7414	7415	47605
JO7660	Hopper Covered		1952	See 7414	7416	47604
JO7660	Hopper Covered		1952	See 7414	7417	47606
JO7660	Hopper Covered		1952	See 7414	7418	47607
JO7660	Hopper Covered		1952	See 7414	7419	47608
JO7660	Hopper Covered		1952	See 7414	7420	47609
JO7660	Hopper Covered		1952	See 7414	7421	47610
JO7660	Hopper Covered		1952	Detail of air pipe passage	7422	47611
JO7660	Hopper Covered		1952	Detail of roof hatch hinge	7423	47612
JO7660	Hopper Covered		1952	Roof hatches closed	7424	47613
JO7660	Hopper Covered		1952	Roof hatches open	7425	47614
JO7660	Hopper Covered		1952	Roof hatches open	7426	47615
JO7660	Hopper Covered		1952	Roof hatch hinge	7427	47616
JO7660	Hopper Covered		1952	Closeup of step & uncoupler rod	7428	47617
JO7660	Hopper Covered		1952	Ext. end	7429	47618
JO7660	Hopper Covered		1952	Ext. hand brake end	7430	47619
JO7660	Hopper Covered		1952	Ext. 3/4 side (end only)	7431	47620
JO7660	Hopper Covered		1952	Ext. 3/4 side (end only)	7432	47621
JO7660	Hopper Covered		1952	Ext. side end only	7433	47622



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
PULLMAN PSX-35 (continued)						
JO7660	Hopper Covered		1952	Ext. 3/4 end only	7460	47647
JO7660	Hopper Covered		1952	Ext. part of roof	7461	47648
JO7660	Hopper Covered		1952	Ext. part of roof	7462	47649
JO7660	Hopper Covered		1952	Roof hatch open	7676	47852
JO7660	Hopper Covered		1952	Roof hatch open	7677	47853
JO7660	Hopper Covered		1952	Roof hatch closed	7678	47854
JO7660	Hopper Covered		1952	Roof hatch closed	7679	47855
JO7660	Hopper Covered		1952	Roof hatch open	7680	47856
JO7660	Hopper Covered		1952	Roof hatch closed	7681	47857
JO7660	Hopper Covered		1952	Roof hatch closed	7682	47858
JO7660	Hopper Covered		1952	Roof hatch closed	7683	47859
JO7660	Hopper Covered		1952	Roof hatch open	7684	47860
JO7660	Hopper Covered		1952	Roof hatch closed	7685	47861
JO7660	Hopper Covered		1953	Roof hatch open	7686	47862
JO7660	Hopper Covered		1953	Broken grab iron	7687	47863
PSX-53						
8361	Trailer Flat		1956	Ext. 3/4 front in shop; 9159-9162 a series	9159	49086
8361	Trailer Flat		1956	3/4 side end only; see 9159	9160	49087
8361	Trailer Flat		1956	Frame inverted; see 9159	9161	49088
8361	Trailer Flat		1956	Frame inverted; see 9159	9162	49089
8361	Trailer Flat		1956	In train for test; 9163-9168 a series	9163	49090
8361	Trailer Flat		1956	In train for testg	9164	49091
8361	Trailer Flat		1956	See 9163	9165	49092
8361	Trailer Flat		1956	See 9163	9166	49093
8361	Trailer Flat		1956	See 9163	9167	49094
8361	Trailer Flat		1956	See 9163	9168	49095
8361	Trailer Flat		1956	Ext. 3/4 side	9178	49105
8361	Trailer Flat		1956	Ext/ 3/4 front	9179	49106
8361	Trailer Flat		1956	Ext. hand brake end	9180	49107

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
PULLMAN (continued)						
PULLMAN (TRAILMOBILE)						
	Single Axle Road Trailer		1940	Ext. rear	2855	44113
	Single Axle Road Trailer		1940	Rear doors open	2856	44114
	Single Axle Road Trailer		1940	3/4 left front roof	2857	44115
	Single Axle Road Trailer		1940	Int. from front	2858	44116
	Single Axle Road Trailer		1940	Int. from back	2859	44117
	Single Axle Road Trailer		1940	3/4 front of underside	2860	44118
PULLMAN (TROOP SLEEPERS)						
6704	Troop Sleeper	7040	1943	Ext. 3/4 side	3517	44591
6704	Troop Sleeper		1943	Scratch plates to check truck movement	3900	44651
6704	Troop Sleeper		1943	Shop scene assembling truck	3901	44652
6704	Troop Sleeper		1943	See 3901	3902	44653
6704	Troop Sleeper		1943	Ext. car end 3/4 side	3903	44654
6704	Troop Sleeper		1943	Shop scene erecting car side	3904	44655
6704	Troop Sleeper		1943	Shop scene frame inverted	3905	44656
6704	Troop Sleeper		1943	Shop scene building side	3906	44657
6704	Troop Sleeper		1943	See 3906	3907	44658
6704	Troop Sleeper		1943	Shop scene riveting side	3908	44659
6704	Troop Sleeper		1943	Int. workers installing floor beams	3909	44660
6704	Troop Sleeper		1943	See 3909	3910	44661
6704	Troop Sleeper		1943	See 3909	3911	44662
6704	Troop Sleeper		1943	Int. installing metal sheathing	3912	44663
6704	Troop Sleeper		1943	See 3912	3913	44664
6704	Troop Sleeper		1943	Ext. 3/4 end only	3914	44665
6704	Troop Sleeper		1943	Ext. end	3915	44666
6704	Troop Sleeper	7042	1943	Ext. 3/4 end	3916	44667
6704	Troop Sleeper	7044	1943	Ext. roof from end	3918	44668
6704	Troop Sleeper		1943	Ext. end door	3925	44675
6704	Troop Sleeper		1943	Corner of bed spring	3933	44683
6704	Troop Sleeper		1943	Bed springs	3934	44684



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
PULLMAN TROOP SLEEPERS (continued)						
6704	Troop Sleeper		1943	Bed springs	3935	44685
6704	Troop Sleeper		1943	Corner of bed spring	3936	44686
6704	Troop Sleeper		1943	Corner of bed spring	3937	44687
6704	Troop Sleeper		1943	Int. beds in day position	3938	44688
6704	Troop Sleeper		1943	Interior of washroom	3939	44689
6704	Troop Sleeper		1943	Int. washroom linen closet	3940	44690
6704	Troop Sleeper		1943	Int. ends of bunks	3941	44691
6704	Troop Sleeper		1943	Int. beds in night position	3942	44692
6704	Troop Sleeper		1943	Int. beds in night position	3943	44693
6704	Troop Sleeper		1943	Ext. closeup of lower section	3944	44694
6704	Troop Sleeper		1943	Worker checking step level	3952	44700
6704	Troop Sleeper		1943	Left and right side w/door closed	3955	44701
6704	Troop Sleeper		1943	Shop scene, frame	3993	44702
6704	Troop Sleeper		1943	Shop scene, frame inverted	3994	44703
6704	Troop Sleeper		1943	Frame 3/4 front end only	3995	44704
6704	Troop Sleeper		1943	Shop scene erecting side	3996	44705
6704	Troop Sleeper		1943	Car end sheet	3997	44706
6704	Troop Sleeper		1943	Int. no sheathing	3998	44707
6704	Troop Sleeper		1943	Int. insulation in place	3999	44708
6704	Troop Sleeper		1943	Int. sheathing partially installed	4000	44709
6704	Troop Sleeper		1943	Int. sheathing installed	4001	44710
6704	Troop Sleeper		1943	Int. see 4001	4002	44711
6704	Troop Sleeper		1943	Truck parts	4006	44712
6704	Troop Sleeper		1943	Journal box and parts	4007	44713
6704	Troop Sleeper		1943	Brake beam and parts	4009	44714
6704	Troop Sleeper		1943	Brake parts	4010	44715
6704	Troop Sleeper		1943	Truck, top view	4012	44716
6704	Troop Sleeper		1943	Truck 3/4 side	4013	44717
6704	Troop Sleeper		1943	Truck 3/4 side	4014	44718
6704	Troop Sleeper		1943	Truck underside	4015	44719
6704	Troop Sleeper		1943	Truck underside	4016	44720
6704	Troop Sleeper		1943	TRuck underside	4017	44721
6704	Troop Sleeper		1943	Step lifting parts	4020	44722
6704	Troop Sleeper		1943	Frame at bolster inverted	4029	44723

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
PULLMAN TROOP SLEEPERS (continued)						
6704	Troop Sleeper		1944	Int. unfinished end	4031	44724
6704	Troop Sleeper	8099	1944	Ext. end	4032	44725
6704	Troop Sleeper		1944	Ext. 3/4 side unfinished car	4095	44771
6704	Troop Sleeper		1944	Int. no floor or sheathing	4096	44772
6704	Troop Sleeper	7673	1944	Ext. 3/4 side	4097	44773
6704	Troop Sleeper	7673	1944	Ext. 3/4 side opposite of 4097	4098	44774
6704	Troop Sleeper		1944	Woman worker with nail gun; see 4124	4123	44792
6704	Troop Sleeper		1944	See 4123	4124	44793
6704	Troop Sleeper		1944	Train of cars	4140	44794
6704	Troop Sleeper		1944	Interior unfinished	4145	44795
6704	Troop Sleeper		1944	Int. installing batteries	4155	44796
6704	Troop Sleeper		1944	Int. workers installing ceiling & sides	4159	44797
6704	Troop Sleeper		1944	Ext. 3/4 end	4162	44798
6704	Troop Sleeper		1944	Train of cars	4171	44799
6704	Troop Sleeper		1943	Porter w/soldier retiring; 4258-4261 a series	4258	44833
6704	Troop Sleeper		1943	Similar to 4258	4259	44834
6704	Troop Sleeper		1943	See 4258	4260	44835
6704	Troop Sleeper		1943	See 4258	4261	44836
6753	Troop Sleeper		1945	Truck, side view	4693	45073
6753	Troop Sleeper		1945	Truck, 3/4 front	4694	45074
6753	Troop Sleeper		1945	Truck top view	4695	45075
6753	Troop Sleeper		1945	Frame 3/4 front, shop scene	4696	45076
6753	Troop Sleeper		1945	Frame 3/4 front inverted, shop scene	4697	45077
6753	Troop Sleeper		1945	Int. no floor or sheathing	4699	45078
6753	Troop Sleeper		1945	Int. carpenters installing sheathing	4701	45079
6753	Troop Sleeper		1945	Int. carpenters installing sheathing	4703	45080
6753	Troop Sleeper		1945	Int. carpenters installing sides	4706	45081
6753	Troop Sleeper		1945	Int. women workers installing window shades	4708	45082
6753	Troop Sleeper		1945	3/4 frt. shop scene, sides up	4709	45083
6753	Troop Sleeper		1945	Car end panel	4710	45084
6753	Troop Sleeper		1945	Shop scene fabricating car ends	4711	45085
6753	Troop Sleeper		1945	Train of cars	4735	45109
6753	Troop Sleeper	9153	1945	Ext. end	4751	45125
6753	Troop Sleeper	9153	1945	Ext. 3/4 side	4752	45126



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
PULLMAN TROOP SLEEPERS (continued)						
6753	Troop Sleeper	9153	1945	Ext. 3/4 side	4753	45127
6753	Troop Sleeper		1945	Roof 3/4 front	4755	45129
6753	Troop Sleeper		1945	Ext. 3/4 end	4756	45130
6753	Troop Sleeper		1945	Int. unfinished	4757	45131
6753	Troop Sleeper		1945	Parts of window frame	4758	45133
6753	Troop Sleeper		1945	Window frame assembly	4759	45134
6753	Troop Sleeper		1945	Int. window frames being installed	4760	45135
6753	Troop Sleeper		1945	Int. workman installing window frames	4761	45136
6753	Troop Sleeper		1945	Int. worker installing window frame	4762	45137
6753	Troop Sleeper		1945	Int. window frames	4763	45138
6753	Troop Sleeper		1945	Windows and screens	4764	45139
6753	Troop Sleeper		1945	Window shades	4765	45140
6753	Troop Sleeper		1945	Int. window shades	4766	45141
6753	Troop Sleeper		1945	Int. workman installing doors & window frames	4767	45142
6753	Troop Sleeper		1945	Int. electricians installing lights	4768	45143
6753	Troop Sleeper		1945	Workers building light bar	4769	45144
6753	Troop Sleeper		1945	Int. workers installing light bar	4770	45145
6753	Troop Sleeper		1945	Interior	4771	45146
6753	Troop Sleeper		1945	Interior same as 4771	4772	45147
6753	Troop Sleeper		1945	Int. worker spreading floor tile cement	4773	45148
6753	Troop Sleeper		1945	Int. worker installing floor	4774	45149
6753	Troop Sleeper		1945	Int. floor installed	4775	45150
6753	Troop Sleeper		1945	Clothes lockers	4776	45151
6753	Troop Sleeper		1945	Int. clothes lockers being installed	4777	45152
6753	Troop Sleeper		1945	Installing batteries	4778	45153
6753	Troop Sleeper		1945	Cart load of doors	4779	45154
6753	Troop Sleeper		1945	Int. bunks installed	4780	45155
6753	Troop Sleeper		1945	Worker assembling air line	4781	45156
6753	Troop Sleeper		1945	Ext. end door	4782	45157
6753	Troop Sleeper		1945	Ext. workers at end platform	4783	45158
6753	Troop Sleeper		1945	Ext. 3/4 end	4784	45159
6753	Troop Sleeper		1945	Ext. workers at end	4785	45160
6753	Troop Sleeper		1945	Ext. side door	4786	45161
6753	Troop Sleeper		1945	Int. side door	4787	45162

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
PULLMAN TROOP SLEEPERS (continued)						
6753	Troop Sleeper		1945	Door frame parts	4788	45163
6753	Troop Sleeper		1945	Worker with winch	4789	45164
6753	Troop Sleeper		1945	Interior window	4790	45165
6753	Troop Sleeper		1945	Int. end door	4791	45166
6753	Troop Sleeper		1945	Int. worker installing door sill	4792	45167
6753	Troop Sleeper		1945	Ext. worker installing end door sill	4793	45168
						& 45169
6753	Troop Sleeper		1945	Ext. closeup of trucks	4794	45170
6753	Troop Sleeper		1945	Truck frames in fixtures	4795	45171
6753	Troop Sleeper		1945	Int. wash room	4802	45178
6753	Troop Sleeper		1945	Group of lavatory sinks	4803	45179
6753	Troop Sleeper		1945	Int. wash room door	4804	45180
6753	Troop Sleeper		1945	Group of toilets	4805	45181
6753	Troop Sleeper		1945	Hot water tank with insulation (4806-09 a series)	4806	45182
6753	Troop Sleeper		1945	Same as 4806	4807	45183
6753	Troop Sleeper		1945	See 4807	4808	45184
6753	Troop Sleeper		1945	Workers with hot water tank	4809	45185
6753	Troop Sleeper		1945	Int. unfinished washroom floor	4810	45186
6753	Troop Sleeper		1945	Int. constructing washroom floor	4811	45187
6753	Troop Sleeper		1945	Clothes closets	4812	45188
6753	Troop Sleeper		1945	Installing clothes closets	4813	45189
6753	Troop Sleeper		1945	Finished clothes closet	4814	45191
6753	Troop Sleeper		1945	Metal clothes lockers; 4814-19 a series	4815	45192
6753	Troop Sleeper		1945	See 4815	4816	45193
6753	Troop Sleeper		1945	See 4815	4817	45194
6753	Troop Sleeper		1945	See 4815	4818	45195
6753	Troop Sleeper		1945	See 4815	4819	45196
6753	Troop Sleeper		1945	Int. water fountain	4820	45197
6753	Troop Sleeper		1945	Int. workers installing water fountain	4821	45198
6753	Troop Sleeper		1945	Ext. washroom door	4822	45199
6753	Troop Sleeper		1945	Ext. panel	4823	45200
6753	Troop Sleeper		1945	Ext. end panel	4824	45201
6753	Troop Sleeper		1945	Int. hall	4825	45209
6753	Troop Sleeper		1945	Int. end door	4826	45210



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
PULLMAN TROOP SLEEPERS (continued)						
6753	Troop Sleeper		1945	Int. overhead storage	4827	45211
6753	Troop Sleeper		1945	Int. upper bunks	4828	45212
6753	Troop Sleeper		1945	Int. bunks	4829	45213
6753	Troop Sleeper		1946	Int. bunks in day position	4854	45229
6753	Troop Sleeper		1946	Int. bunks made up	4855	45230
6753	Troop Sleeper		1946	Int. of side door	4856	45231
6753	Troop Sleeper		1946	Side door	4857	45232
6753	Troop Sleeper		1946	Side door	4858	45233
6753	Troop Sleeper		1946	Side door	4859	45234
6753	Troop Sleeper		1946	Int. bed in day position	4860	45235
6753	Troop Sleeper		1946	Int. beds in night position	4861	45236
PULLMAN (XYZ RAILROAD)						
	Box 40', Welded		1937	(Marked XYZ Railroad), ext. 3/4 side	2337	43693
5584	Box		1937	XYZ RR.) ext. 3/4 side	2337	43693
5584	Box		1937	(XYZ RR.) exterior 3/4 front roof	2339	43695
5584			1938	(XYZ RR.) center plate & filler assembly	2344	43698
5584			1938	(XYZ RR.) exterior side doors	2347	43699
5584	Box		1938	(XYZ RR.) exterior hand brake end	2350	43700
5584	Box		1938	(XYZ RR.) ext. opposite of 2350	2351	43701
5584	Box		1938	(XYZ RR.) truck front	2352	43702
5584	Box		1938	(XYZ RR.) truck side view	2353	43703
5584	Box		1938	(XYZ RR.) interior corner without sheathing	2354	43704
5584	Box		1938	(XYZ RR.) draft gear	2357	43705
5584	Box		1938	(XYZ Car) interior end of finished car	2358	43706
5584	Box		1938	(XYZ RR.) exhibit of welded sections	2360	43708
5584	Box		1938	(XYZ RR.) ext. several XYZ cars on exhibit	2361	43709
5584	Box		1938	(XYZ RR.) same as 2361, different view	2362	43710
5584	Box		1938	(XYZ Car) int. end view furring strips in place	2363	43711
5584	Box		1938	(XYZ RR.) side view frame on turnover machine	2364	43712
5584			1938	(XYZ RR.) Shop "A" exhibit of operations	2365	43713
5584	Box		1938	(XYZ RR.) 3/4 fr.t of underframe in welding jig	2366	43714

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
PULLMAN XYZ RR. (continued)						
5584	Box		1938	(XYZ RR.) Opposite of 2366	2367	43715
5584	Box		1938	(XYZ RR.) draft sill for rubber draft gear	2372	43716
5584	Box		1938	(XYZ RR.) front rubber draft gear	2375	43717
5584	Box		1938	(XYZ RR.) rear view rubber draft gear	2376	43718
5584	Box		1938	(XYZ RR.) bleachers, fixture for welding draft lugs to center sill	2377	43719
5584	Box		1938	(XYZ RR.) 3/4 side truck and end	2378	43720
5584	Box		1938	(XYZ RR.) 3/4 side truck & car, opposite of 2378	2379	43721
5584	Box		1938	(XYZ RR.) ext. underbody brake gear	2380	43722
5584	Box		1938	(XYZ RR.) shop scene welding fixture car sides	2381	43723
5584	Box		1938	(XYZ RR.) ext. door only Cresco fixtures	2383	43724
PULLMAN RAILROAD CO.						
5504	Box	500	1935	Exterior, frame corner detail	1943 & 1944	43476
5504	Box	500	1935	Exterior, side door	1945	43477
5504	Box	500	1934	Interior side door (43478-43495 leased to Calumet Harbor Route)	1946	43478
5504	Box	500	1935	Exterior end	1949	43479
5504	Box	500	1935	Exterior end (hand brake)	1950	43480
5504	Box	500	1935	Exterior side door	1952	43482
5504	Box	500	1935	Exterior side door lock	1953	43483
5504	Box	500		Steel beam	1959	43485
5504	Box	500	1935	665# wheels inside/outside	1961	43486
5504	Box	500	1935	700# wheels inside/outside	1965	43487
5504	Box	500	1935	Exterior side (extra bracing)	1975	43489
5504	Box	500	1935	Ext. 3/4 side door open car (extra ext. bracing)	1976	43489
5504	Box	500	1935	Interior floor (holes cut for bracing)	1977	43490
5504	Box	500	1935	Interior floor (holes cut for bracing)	1978	43491
5504	Box	500	1935	Exterior end (hand brake)	1979	43492
5504	Box	500	1935	Exterior, 3/4 end	1980	43493
5504	Box		1935	Interior loaded with bags of sugar	1981	43494



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
PULLMAN (RR.Co.-continued)						
5504	Box	500	1935	Interior loaded with bags of sugar	1982	43495
5504	Box	500	1935	Ext. 3/4 side being photographed	1996	43499
5504	Box	500	1937	Exterior side	1998	43502
5507	Pressed Steel Box	1500	1936	Exterior, 3/4 front	2016	43517
5507	Pressed Steel Box	1500	1936	Exterior end	2017	43518
5507	Pressed Steel Box	1500	1936	Exterior end (hand brake end)	2018	43519
5507	Pressed Steel Box	1500	1936	Exterior roof end hatches	2024	43520
	Box	500	1936	3/4 front being fitted with exterior bracing	2004	43507
	Box	500	1936	Same as 2005, different view	2005	43508
	Box	500	1936	Int. box car loaded, car has ext. bracing	2006	43509
	Box	500	1936	Same as 2006, other end	2007	43510
	Box	500	1936	Same as 2007	2008	43511
	Box	500	1936	Same as 2008	2009	43512
	Box	500	1936	Same as 2009	2010	43513
	Box	500	1936	Same as 2010	2011	43514
	Box	500	1936	Coupler	2012	43515
	Box	500	1936	2 views of "A" end with exterior bracing	2013	43516
	Box	500	1936	Interior end loaded	2043	43533
	Box	500	1936	Interior end with partial load	2044	43534
	Box	500	1936	Interior end nearly empty	2045	43535
	Box	500	1936	Exterior car dimensions	2049	43536
	Box	500	1936	Exterior right front corner and truck	2050	43537
	Box	500	1936	Exterior right side from rear	2051	43538
	Box	500	1936	Exterior 3/4 side closeup	2052	43539
	Box	500	1936	Exterior side door latches	2053	43540
	Box	500	1936	Exterior end view showing roof	2054	43541
	Box	500	1936	2 views exterior r/s end only; r/s end only coupler	2056	43542
	Box	500	1936	Interior end partially loaded	2057	43543
	Box	500	1936	Interior end partially loaded	2058	43544
	Box	500	1936	Interior end partial load	2060	43545
	Box	500	1936	Same as 2060	2061	43546
	Box	500	1936	Same as 2061	2062	43547
	Box	500	1936	Interior end framing exposed	2063	43548
	Box	500	1936	Interior end partially loaded	2064	43549

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
PULLMAN RAILROAD CO. (continued)						
	Box	500	1936	Exterior under carriage near "B" end	2065	43550
	Box	500	1936	Exterior closeup frame and support "B" end l/s	2066	43551
	Box	500	1936	Exterior under carriage brake system	2067	43552
	Box	500	1936	Exterior "A" end r/s closeup of frame	2068	43553
	Box	500	1936	Exterior "A" end right corner	2069	43554
	Box		1942	Ext. side door	3290	44375
RICHMOND FREDERICKSBURG & POTOMAC						
	Box		1946	Damaged side door latch; 5180-5185 a series	5180	45460
	Box		1946	Damaged side door latch; see 5180	5181	45461
	Box		1946	See 5180	5182	45462
	Box		1946	See 5180	5183	45463
	Box		1946	See 5180	5184	45464
	Box	2598	1946	Int. at side door; see 5180	5185	45465
8042	Box	2880	1952	Ext. 3/4 side	7668	47844
8042	Box	2880	1952	Ext. hand brake end	7669	47845
8042	Box	2897	1952	Int. end	7670	47846
8042	Box	2897	1952	Int. side door area	7671	47847
RUTLAND						
8175B	Box	104	1954	Ext. 3/4 side	8451	48409
8175B	Box	104	1954	Ext. hand brake end	8452	48410
8207	Box	125	1954	Ext. 3/4 side	8490	48448
8207	Box	125	1954	Ext. hand brake end	8491	48449
8225	Box	151	1955	Ext. 3/4 side	8541	48498
8225	Box	151	1955	Ext. hand brake end	8542	48499
8281	Box	281	1956	Ext. 3/4 side	9071	49000
8281	Box	281	1956	Ext. hand brake end	9072	49001
8300	Box	378	1956	Ext. 3/4 side	9184	49111
8300	Box	378	1956	Ext. hand brake end	9185	49112



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
SACRAMENTO NORTHERN						
8268	Box	2402	1955	Ext. 3/4 side	8983	48913
8268	Box	2402	1955	Ext. hand brake end	8984	48914
ST. LOUIS & SAN FRANCISCO						
5429	Hopper	88769	1928	Ext. 3/4 side	1574	49169
5429	Hopper	88769	1928	Ext. 3/4 side	9296	49169
5430	Box Automobile	151261	1928	Ext. side	9297	49170
5835	Box Automobile	154250	1946	Ext. 3/4 side	5153	45450
5835	Box Automobile	154250	1946	Ext. hand brake end	5154	45451
5835	Box Automobile	154250	1946	Int. auto carriers retracted	5155	45452
5835	Box Automobile	154250	1946	Int. auto carriers extended	5156	45453
5911	Box		1948	Construction at side door	5952	46132
5911	Box	17162	1948	Ext. 3/4 side	5983	46162
5911	Box	17162	1948	Duplicate of frame 46162	5983	46163
5911	Box	17162	1948	Ext. hand brake end	5984	46164
5912	Hopper	90249	1948	Ext. 3/4 side	5992	46172
5912	Hopper	90249	1948	Ext. hand brake end	5993	46173
5912	Hopper	90249	1948	Ext. 3/4 side	6064	46244
5937	Hopper	90899	1949	Ext. 3/4 side	6424	46599
5937	Hopper	90899	1949	Ext. hand brake end	6425	46600
5937	Hopper	90899	1949	Ext. end	6426	46601
5937	Hopper	90899	1949	Int. from above	6427	46602
5937	Hopper	90899	1949	Ext. 3/4 end from above	6428	46603
5937	Hopper		1949	Ext. closeup hopper door open	6429	46604
5937	Hopper		1949	Ext. closeup hopper door closed	6430	46605
5962D	Hopper Covered	83860	1950	Ext. 3/4 side	6683	46908
5962D	Hopper Covered	83860	1950	Ext. hand brake end	6684	46909
5995	Box	17549	1951	Ext. 3/4 side	7099	47306
5995	Box	17549	1951	Ext. hand brake end	7100	47307
8046	Box	17998	1952	Ext. 3/4 side	7661	47837
8046	Box	17998	1952	Ext. hand brake end	7662	47838

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
ST. LOUIS & SAN FRANCISCO (continued)						
8126	Hopper	80098	1954	Ext. 3/4 side	8270	48304
8126	Hopper	80098	1954	Ext. 3/4 front	8271	48305
8126	Hopper	80098	1954	Ext. hand brake end	8272	48306
8126	Hopper	80098	1954	Ext. side (end only)	8273	48307
8126	Hopper	80098	1954	Ext. end	8274	48308
8126	Hopper	80098	1954	Ext. side (1/2)	8275	48309
8126	Hopper	80098	1954	Ext. side closeup of hopper door	8276	48310
8154	Hopper	92399	1954	Ext. 3/4 side	8382	48353
8154	Hopper	92399	1954	Ext. hand brake end	8383	48354
8154	Hopper	92399	1954	Ext. 3/4 front from above	8384	48355
8154	Hopper	92399	1954	Ext. closeup of hopper door	8385	48356
8154	Hopper	92399	1954	Ext. 1/2 side	8386	48357
8178	Box	18299	1954	Ext. 3/4 side	8277	48311
8178	Box	18299	1954	Ext. end	8278	48312
8178	Box	18299	1954	Ext. hand brake end	8279	48313
8178	Box	18299	1954	Int.	8280	48314
8269	Box	7566	1956	Ext. 3/4 side	9028	48958
8269	Box	7566	1956	Ext. hand brake end	9029	48959
8269	Box	7547	1956	Int.	9030	48960
8269	Box		1956	Train of cars for delivery	9031	48961
8270	Box	19073	1956	Int.	9060	48989
8270	Box	19073	1956	Underside of car	9077	49004
8270	Box	19073	1956	Underside of car	9078	49005
8270	Box	19073	1956	Underside of car	9079	49006
8270	Box	19073	1956	Ext. 3/4 side	9114	49041
8270	Box	19073	1956	Ext. hand brake end	9115	49042
8270	Box	19073	1956	Int.	9116	49043
8270	Box	19073	1956	Car step closeup	9117	49044
8270	Box	19073	1956	Car step; different angle	9118	49045
8270	Box	19073	1956	Car step side	9119	49046
8270	Box	19073	1956	Car step	9120	49047
8270	Box	19073	1956	Car step	9121	49048
8270	Box	19073	1956	Car step	9122	49049
8270	Box		1956	Ext. side (end only)	9143	49070



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
ST. LOUIS BROWNSVILLE & MEXICO						
5823	Box	18399	1946	Ext. 3/4 side	4978	45294
5823	Box	18399	1946	Ext. hand brake end	4979	45295
ST. LOUIS SOUTHWESTERN						
8001A	Box	33899	1951	Ext. 3/4 side	7240	47440
8001A	Box	33899	1951	Ext. hand brake end	7241	47441
8026	Box	33974	1951	Ext. 3/4 side	7114	47319
8026	Box	33974	1951	Ext. hand brake end	7115	47320
8206	Box	20274	1954	Ext. 3/4 side	8484	48442
8206	Box	20274	1954	Ext. hand brake end	8485	48443
8208	Box	34091	1954	Ext. 3/4 side	8488	48446
8208	Box	34091	1954	Ext. hand brake end	8489	48447
8209	Box	20299	1954	Ext. 3/4 side	8486	48444
8209	Box	20299	1954	Ext. hand brake end	8487	48445
8227	Box	34324	1955	Ext. 3/4 side	8664	48618
8227	Box	34324	1955	Ext. 3/4 side opposite of 8664	8665	48619
8227	Box	34324	1955	Ext. end	8666	48620
8227	Box	34324	1955	Ext. hand brake end	8667	48621
8227	Box	34324	1955	Int.	8668	48622
8227	Box	34324	1955	Truck 3/4 side	8669	48623
8227	Box	34324	1955	Truck front view	8670	48624
8251A	Box	47254	1955	Ext. 3/4 side	8917	48848
8251A	Box	47254	1955	Ext. hand brake end	8918	48849
8252	Auto Box	47374	1955	Ext. 3/4 side	8906	48837
8252	Auto Box	47374	1955	Ext. hand brake end	8907	48838
8266	Box	34650	1955	Ext. 3/4 side	8934	48864
8266	Box	34650	1955	Ext. hand brake end	8935	48865
8298	Box	47815	1956	Ext. 3/4 side	9207	49129
8298	Box	47815	1956	Ext. 3/4 side	9207	49129
8298	Box	47815	1956	Ext. hand brake end	9208	49130
8299	Box	35057	1956	Ext. 3/4 side	9155	49082
8299	Box	35057	1956	Ext. hand brake end	9156	49083

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
SANTA FE REFRIGERATED DISPATCH						
5485	Refrigerator	31013	1931	Exterior side	1830	43425
5485	Refrigerator	31013	1931	Exterior end	1831	43426
5485	Refrigerator	31013	1931	Exterior end (hand brake end)	1832	43427
5485	Refrigerator	31013	1931	Exterior 3/4 side	1833	43428
	Refrigerator	38450	1942	Ext. 3/4 side	4631	45019
5856	Refrigerator	3500	1948	Ext. side (sample car)	5186	45466
5856	Refrigerator		1947	Int. unfinished; note 5275-5289 ser. finishing int.	5275	45541
5856	Refrigerator		1947	See 5275	5276	45542
5856	Refrigerator		1947	See 5275	5277	45543
5856	Refrigerator		1947	See 5275	5278	45544
5856	Refrigerator		1947	See 5275	5279	45545
5856	Refrigerator		1947	See 5275	5280	45546
5856	Refrigerator		1947	See 5275	5281	45547
5856	Refrigerator		1947	See 5275	5282	45548
5856	Refrigerator		1947	See 5275	5283	45549
5856	Refrigerator		1947	See 5275	5284	45550
5856	Refrigerator		1947	See 5275	5285	45551
5856	Refrigerator		1947	See 5275	5286	45552
5956	Refrigerator		1947	See 5275	5287	45553
5856	Refrigerator		1947	See 5275	5288	45554
5856	Refrigerator		1947	See 5275	5289	45555
5856	Refrigerator	3526	1947	Ext. 3/4 side	5290	45556
SAVANNAH & ATLANTA						
5896A	Box	8240	1948	Ext. 3/4 side	6117	46294
5896A	Box	8240	1948	Ext. hand brake end	6118	46295
5896A	Box		1948	Int. center section floor	6678	46903
5896A	Box		1948	Int. center section floor	6679	46905
8151	Box	699	1954	Ext. 3/4 side	8219	48256
8151	Box	699	1954	Ext. hand brake end	8220	48257
8284	Box	354	1956	Ext. 3/4 side	9141	49068
8284	Box	354	1956	Ext. hand brake end	9142	49069



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
SEABOARD AIR LINE						
5502	Box, Closed	17438	1934	Exterior side	2308	43671
5502	Box, Closed	17438	1934	Exterior hand brake end	2309	43672
5503	Closed Top Phosphate	58071	1935	Exterior side	2302	43665
5503	Closed Top Phosphate	58071	1935	Exterior hand brake end	2303	43666
5503	Closed Top Phosphate	58071	1935	Exterior top hatches open	2304	43667
5503	Closed Top Phosphate	58071	1935	Exterior top hatches closed	2305	43668
5503	Closed Top Phosphate	58071	1935	Interior roof	2306	43669
5503	Closed Top Phosphate	58071	1935	Exterior hopper doors	2307	43670
5525	Closed Top Phosphate	58103	1936	Exterior 3/4 side	2114	43574
5525	Closed Top Phosphate	58102	1936	Exterior end hand brake	2115	43575
5551	Steel Sheathed Box	18647	1937	Exterior hand brake end	2203	43614
5551	Steel Sheathed Box	18647	1937	Exterior side	2203	43615
5578	Box Auto/Furniture	10080	1938	Exterior side	2288	43655
5578	Box Auto/Furniture	10080	1938	Exterior hand brake end	2289	43657
5617	Box Auto/Furniture	11353	1940	Ext. side	2714	43997
5617	Box Auto/Furniture		1940	Ext. hand brake end	2715	43998
5617	Box Auto/Furniture	11081	1940	Coupler and air hose	2750	44025
5617	Box Auto/Furniture	11081	1940	Coupler pocket	2751	44026
5617	Box Auto/Furniture	11081	1940	Coupler pocket	2752	44027
5617	Box Auto/Furniture	11081	1940	Coupler pocket	2753	44028
5617	Box Auto/Furniture	11081	1940	Coupler	2754	44029
5617	Box Auto/Furniture	11081	1940	Coupler	2755	44030
5617	Box Auto/Furniture	11081	1940	Coupler	2756	44031
5617	Box Auto/Furniture	11081	1940	Coupler	2757	44032
5626A	Hopper, Cement	8049	1940	Ext. side	2839	44099
5626A	Hopper, Cement	8049	1940	Ext. hand brake end	2840	44100
5659	Box	19153	1941	Ext. side	3021	44238
5659	Box	19153	1941	Ext. hand brake end	3022	44239
5659	Box	19153	1941	Ext. roof from end	3023	44240
5702	Auto/Furniture	11850	1942	Ext. side	3355	44434
5702	Auto/Furniture	11850	1942	Ext. hand brake end	3356	44435
5768	Box	19599	1944	Ext. side	4420	44903
5768	Box	19599	1944	Ext. 3/4 side	4421	44904

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
SEABOARD AIR LINE (continued)						
5768	Box	19599	1944	Ext. hand brake end	4422	44905
5769	Hopper	37550	1944	Ext. side	4451	44928
5769	Hopper	37550	1944	Ext. 3/4 side	4452	44929
5769	Hopper	37550	1944	Ext. hand brake end	4453	44930
5803	Box	22449	1945	Ext. 3/4 side	4656	45042
5803	Box	22449	1945	Ext. hand brake end	4657	45043
5804	Box	19799	1945	Ext. 3/4 side	4689	45069
5804	Box	19799	1945	Ext. hand brake end	4690	45070
5806	Box	19950	1945	Ext. 3/4 side	4723	45097
5806	Box	19950	1945	Ext. hand brake end	4724	45097
5852	Hopper Covered	58275	1947	Ext. 3/4 side	5561	45818
5852	Hopper Covered	58275	1947	Ext. hand brake end	5562	45819
5852	Hopper Covered	58275	1947	Ext. roof	5563	45820
5863	Box Automobile	9149	1947	Ext. 3/4 side	5581	45838
5863	Box Automobile	9149	1947	Ext. hand brake end	5582	45839
5863	Box Automobile	9149	1947	Int. auto carriers retracted	5583	45840
5863	Box Automobile	9149	1947	Int. auto carriers extended	5584	45841
5919B	Box	24300	1948	Ext. 3/4 side	6125	46302
5919B	Box	24300	1948	Ext. opposite of 6125	6126	46303
5919B	Box	24300	1948	Ext. hand brake end	6165	46342
5968	Hopper Covered	58850	1950	Ext. 3/4 side	6874	47091
5968	Hopper Covered	58850	1950	Ext. hand brake end	6875	47092
5979B	Hopper Covered	8552	1951	Ext. 3/4 side	6957	47171
5979B	Hopper Covered	8552	1951	Ext. hand b rake end	6958	47172
5987	Hopper Covered	59273	1951	Ext. 3/4 side	7019	47233
5987	Hopper Covered	59273	1951	Ext. hand brake end	7020	47234
5994	Box	24910	1951	Ext. 3/4 side	7055	47269
5994	Box	24910	1951	Ext. hand brake end	7056	47270
8029	Box	25253	1952	Ext. 3/4 side	7494	47681
8029	Box	25253	1952	Ext. hand brake end	7495	47682
8077	Gondola	91900	1953	Ext. 3/4 side	7990	48083
8077	Gondola	91900	1953	Ext. hand brake end	7991	48084
8078	Gondola	90420	1953	Ext. 3/4 side	7994	48087
8078	Gondola	90420	1953	Ext. hand brake end	7995	48088



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
SEABOARD AIR LINE (continued)						
8079	Hopper Covered	7664	1952	Ext. roof hatch	7626	47807
8079	Hopper Covered	7664	1952	Ext. 3/4 side	7657	47833
8079	Hopper Covered	7664	1952	Ext. hand brake end	7658	47834
8079	Hopper Covered	7664	1952	Ext. roof	7659	47835
8079	Hopper Covered	7664	1952	Ext. roof	7660	47836
8079	Hopper Covered		1952	Car in paint sprayer	7665	47841
8221	Box	25778	1955	Ext. 3/4 side	8630	48587
8221	Box	25778	1955	Ext. hand brake end	8631	48588
8276	Box	26025	1956	Ext. 3/4 side	9073	49002
8276	Box	26025	1956	Ext. hand brake end	9074	49003
SOUTHERN PACIFIC						
5537	Steel Box	33135	1936	Exterior, 3/4 side	2126	43586
5537	Steel Box	33185	1936	Exterior end hand brake	2127	43587
5698	Box	27588	1942	Ext. 3/4 side	3460	44537
5698	Box		1942	3/4 side, frame	3461	44538
5698	Box		1942	Truck 3/4 side	3462	44539
5698	Box		1942	Truck 3/4 front	3463	44540
5701	Box	95652	1942	Ext. side	3453	44530
5701	Box	95652	1942	Ext. hand brake end	3454	44531
5838	Box	21622	1946	Ext. 3/4 side	5073	45387
5838	Box	21622	1946	Ext. hand brake end	5074	45388
5872	Box	22149	1947	Ext. 3/4 side	5830	46090
5872	Box	22149	1947	Ext. hand brake end	5831	46091
5872	Box (T&NO)	55424	1947	Ext. 3/4 side	5832	46092
5872	Box (T&NO)	55424	1947	Ext. hand brake end	5833	46093
5872	Box (T&NO)	55499	1947	Ext. 3/4 side	5834	46094
5924	Box (T&NO)	59208	1949	Ext. 3/4 side	6276	46451
5924	Box (T&NO)		1949	Ext. hand brake end	6277	46452
5924	Box	101399	1949	Ext. 3/4 side	6278	46453
5924	Box	101399	1949	Ext. hand brake end	6279	46454
5967	Box	102199	1950	Ext. 3/4 side	6860	47077

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
SOUTHERN PACIFIC (continued)						
5967	Box	102199	1950	Ext. hand brake end	6861	47078
5967	Box	102199	1950	Ext. end	6862	47079
5967	Box	102199	1950	int.	6863	47080
5967	Box	102199	1950	Int. center floor at door	6864	47081
5967	Box	102199	1950	Roof top view	6865	47082
5967	Box		1950	Frame top view	6866	47083
5967	Box		1950	Ext. 3/4 side no roof or ends	6867	47084
5967	Box		1950	Truck 3/4 side	6868	47085
5967	Box		1950	Ext. car end panel only	6869	47086
5982	Box	105054	1951	Ext. 3/4 side	7045	47259
5982	Box	105054	1951	Ext. end	7046	47260
5982	Box	105054	1951	Ext. hand brake end	7047	47261
5982	Box	105054	1951	Ext. end sheet	7048	47262
5982	Box	105054	1951	Int.	7049	47263
5982	Box	105054	1951	Int. closeup of center floor	7050	47264
5982	Box	105054	1951	Ext. roof only from above	7051	47265
5982	Box		1951	Frame 3/4 front	7052	47266
5982	Box		1951	Ext. 3/4 side with sides only constr. photo	7053	47267
5982	Box		1951	Truck 3/4 side	7054	47268
8001	Box		1951	Truck 3/4 side	7078	47285
8001	Box	105499	1951	Ext. 3/4 side	7079	47286
8001	Box	105499	1951	Ext. end	7080	47287
8001	Box	105499	1951	Ext. hand brake end	7081	47288
8001	Box	105499	1951	Ext. roof only	7082	47289
8001	Box		1951	Int.	7083	47290
8001	Box		1951	Frame top view	7084	47291
8001	Box		1951	Ext. car with sides only	7085	47292
8001	Box (T&NO)	60299	1951	Ext. 3/4 side	7086	47293
8001	Box (T&NO)	60299	1951	Ext. hand brake end	7087	47294
8001	Box (T&NO)		1951	Int.	7088	47295
8001	Box (T&NO)		1951	Ext. car end	7089	47296
8001	Box	105499	1951	Ext. 3/4 end	7090	47297
8043	Box		1953	Int. closeup of "Azee" strap anchor	7774	47951
8043	Box		1953	Int. "Azee" strap anchor	7775	47952



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
SOUTHERN PACIFIC (continued)						
8043	Box	107499	1953	Ext. 3/4 side	7802	47976
8043	Box	107499	1953	Ext. hand brake end	7803	47977
8043	Box	107499	1953	Ext. end	7804	47978
8043	Box	107499	1953	Int.	7805	47979
8043	Box	107499	1953	Ext. roof	7806	47980
8043	Box		1953	Ext. construction photo, no roof or ends	7807	47981
8043	Box		1953	Underside of frame	7808	47982
8043	Box		1953	Ext. partially assembled car end	7809	47983
8043	Box		1953	Truck 3/4 side	7810	47984
8043	Box (T&NO)	61735	1953	Ext. 3/4 side	7811	47985
8043	Box (T&NO)	61735	1953	Ext. hand brake end	7812	47986
8140	Hopper Covered	165266	1953	Ext. 3/4 side	8174	48213
8140	Hopper Covered	165266	1953	Ext. hand brake end	8175	48214
8140	Hopper Covered	165266	1953	Ext. end	8176	48215
8140	Hopper Covered	165266	1953	Ext. car top	8177	48216
8140	Hopper Covered		1953	Int.	8178	48217
8140	Hopper Covered	165266	1953	Truck 3/4 front	8179	48218
8251	Box	650000	1955	Ext. 3/4 side	8828	48769
8251	Box		1955	Frane 3/4 front	8854	48789
8251	Box		1955	Frame 3/4 front inverted	8856	48790
8251	Box		1955	Int. no floor or sheathing	8857	48791
8251	Box		1955	Int. partially finished	8858	48792
8251	Box	650071	1955	Ext. 3/4 side	8859	48793
8251	Box	650071	1955	Ext. 3/4 side opposite of 8859	8860	48794
8251	Box	650071	1955	Ext. hand brake end	8861	48795
8251	Box	650071	1955	Ext. hand brake end	8862	487996
8251	Box		1955	Shop scene frame shop	8863	48797
8251	Box		1955	Shop scene; see 8863	8864	48798

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
SOUTHERN RAILWAY SYSTEM						
5575	Box, Steel 40'	306870	1937	Exterior side	2258	43639
5575	Box, Steel 40'	306870	1937	Exterior end (hand brake)	2259	43640
5576	Gondola, Steel	316400	1937	Fixed End; exterior side	2286	43654
5576	Gondola, Steel	316400	1937	Fixed End; exterior hand brake end	2287	43655
5590	Box	10060	1938	Exterior side	2402	43735
5590	Box	10060	1938	Exterior hand brake end	2403	43736
5592	Box	13096	1939	Exterior side	2427	43752
5592	Box	13096	1939	Exterior side	2428	43753
5592	Box	13096	1939	Exterior hand brake end	2429	43754
5592	Box	13096	1939	Interior from end	2430	43755
5592	Box	13096	1939	Exterior end view of roof	2431	43756
5592	Box	13096	1939	Truck side	2432	43757
5592	Box	13096	1939	Truck 3/4 front	2433	43758
5626A	Hopper, Cement	319018	1940	Ext. side	2813	44074
5626A	Hopper, Cement	319018	1940	Ext. hand brake end	2814	44075
5626A	Hopper, Cement	319018	1940	Ext. top	2815	44078
5648	Box	14500	1941	Ext. side	2962	44187
5648	Box	14500	1941	Ext. hand brake end	2963	44188
5692	Box	22878	1942	Ext. side	3353	44432
5692	Box	22878	1942	Ext. hand brake end	3354	44433
5789	Gondola	119322	1945	Ext. 3/4 side	4598	45002
5789	Gondola	119322	1945	Ext. hand brake end	4599	45003
5839	Box Automobile	39199	1947	Ext. 3/4 side	5441	45694
5839	Box Automobile	39199	1947	Ext. hand brake end	5442	45695
5839	Box Automobile	39199	1947	Int.	5443	45696
5839	Box Automobile	39199	1947	Int. automobile lift in place	5444	45697
5839	Box	39808	1947	Ext. 3/4 side	5560	45817
5839A	Box	39996	1947	Duplicate shot of frame 45928	5670	45927
5839A	Box	39996	1947	Ext. 3/4 side	5669	45928
5839A	Box	39996	1947	Ext. hand brake end	5670	45929
5839A	Box	39985	1947	Int.	5671	45930
5839A	Box	39969	1947	Ext. 3/4 side	5672	45931
5839A	Box		1947	Int. loaded	5673	45932



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
SOUTHERN RAILWAY SYSTEM (continued)						
5839A	Box		1947	Int.	5674	45333
5839A	Box		1947	Int. loaded	5675	45934
5855	Box	330399	1946	Ext. 3/4 side	5148	45446
5855	Box	330399	1946	Ext. hand brake end	5149	45447
5855	Box	23399	1947	Ext. 3/4 side	5667	45923
5855	Box	23399	1947	Ext. hand brake end	5668	45924
5919A	Box	262053	1948	Ext. 3/4 side	6254	46429
5919A	Box	262053	1948	Ext. 3/4 hand brake end	6255	46430
5960	Hopper Covered	280172	1949	Ext. 3/4 side	6534	46696
5960	Hopper Covered	280172	1949	Ext. hand brake end	6535	46697
5962A	Hopper Covered	94162	1950	Ext. 3/4 side	6685	46910
5962A	Hopper Covered	94162	1950	Ext. hand brake end	6686	46911
5979A	Hopper Covered	319220	1951	Ext. 3/4 side	6951	47165
5979A	Hopper Covered	319220	1941	Ext. hand brake end	6952	47166
8003	Box	30827	1951	Ext. 3/4 side	7276	47470
8003	Box	30827	1951	Ext. hand brake end	7277	47471
8003			1952	Int. floor frame closeup; 8616-8623 a series	8616	48573
8003			1952	Int. floor frame	8617	48574
8003			1952	Int. floor partially installed	8618	48575
8003			1952	See 8616	8619	48576
8003			1952	Installing floor to frame clips' see ;8616	8620	48577
8003			1952	See 8616	8621	48578
8003			1952	See 8616	8622	48579
8003			1952	See 8616	8623	48580
8099	Gondola	61099	1953	Ext. 3/4 side	8139	48178
8099	Gondola	61099	1953	Ext. hand brake end	8140	48179
8229A	Box	35200	1955	Ext. 3/4 side	8734	48688
8229A	Box	35200	1955	Ext. hand brake end	8735	48689
8229A	Box	35200	1955	Int.	8736	48690
8229A	Box	35399	1955	Ext. 3/4 side	8751	48705
8229A	Box		1955	Int. compartmentizer latches & posts; 8799-8803 ser.	8799	48753
8229A	Box		1955	See 8799	8800	48754
8229A	Box		1955	See ;8799	8801	48755
8229A	Box		1955	See ;8799	8802	48756

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
SOUTHERN RAILWAY SYSTEM (continued)						
8229A	Box		1955	See 8799	8803	48757
8229B	Box		1955	Gondola load of coupler pockets; 8809-8811 seriesd	8809	48763
8229B	Box		1955	Int. gondola empty; see 8810	8810	48764
8229B	Box		1955	Gondola empty; see 8809	8811	48765
8229B	Box	35199	1955	Ext. 3/4 side	8850	48787
8229B	Box	35199	1955	Ext. hand brake end	8851	48788
8272	Hopper	73002	1955	Ext. 3/4 side	8985	48915
8272	Hopper	73002	1955	Ext. end	8986	48916
SPOKANE PORTLAND & SEATTLE						
5826	Box	11315	1946	Ext. 3/4 side	5041	45356
TENNESSEE CENTRAL						
5638	Gondola	3471	1941	Ext. end	3019	44236
5638	Gondola	3471	1941	Ext. side	3020	44237
5655	Box	7995	1941	Ext. side	2999	44214
5655	Box	7995	1941	Ext. hand brake end	3000	44218
8068	Hopper	8699	1953	Ext. 3/4 side	7800	47974
8068	Hopper	8699	1953	Ext. hand brake end	7801	47975
TENNESSEE COAL IRON & RR. CO.						
5488	Flat Steel, 140,000	564	1931	Exterior, 3/4 side	1939	43472
5488	Flat Steel, 140,000	564	1931	Exterior, end	1940	43473
5488	Flat Steel, 140,000	560	1934	Exterior side, same as 1941 except rails up	1941	43474
5488	Flat Steel, 140,000	560	1934	Exterior end, same as 1942 except rails up	1942	43475
5558	Coal Hopper	2950	1938	Exterior 3/4 side	2298	43661
5558	Coal Hopper	2950	1938	Exterior hand brake end	2299	43662
5559	Gondola Steel Underslung 3454		1938	Exterior side	2300	43663



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
TENNESSEE COAL IRON & RR. CO. (continued)						
5559	Gondola Steel Underslung	3454	1938	Exterior hand brake end	2301	43664
5602	Hopper	2986	1939	Ext. 3/4 side	2597	43901
5602	Hopper	2986	1939	Ext. hand brake end	2598	43902
5637	Flat	4161	1941	Ext.	2984	44209
5637	Flat	4161	1941	Ext. end	2985	44210
5669	Hopper, Coal	2500	1941	Ext. side	3297	44382
5669	Hopper, Coal	2500	1941	Ext. end	3298	44383
5670	Hopper	5011	1942	Ext. side	3451	44528
5670	Hopper	5011	1942	Ext. end	3452	44529
5843	Hopper	5252	1946	Ext. 3/4 side	5248	45514
5843	Hopper	5252	1946	Ext. hand brake end	5249	45515
5844	Hopper	3099	1946	Ext. 3/4 side	5250	45516
5844	Hopper	3099	1946	Ext. hand brake end	5251	45517
TEXAS & NEW ORLEANS (S.P.)						
5838	Box	55150	1946	Ext. 3/4 side	5127	45433
5838	Box	55150	1946	Ext. hand brake end	5128	45434
5872	Box	55424	1947	Ext. 3/4 side	5832	46092
5872	Box	55424	1947	Ext. hand brake end	5833	46093
5872	Box	55499	1947	Ext. 3/4 side	5834	46094
5924	Box	59208	1949	Ext. 3/4 side	6276	46451
5924	Box		1949	Ext. hand brake end	6277	46452
5967	Box	60047	1950	Ext. side	6870	47087
5967	Box	60047	1950	Ext. hand brake end	6871	47088
8001	Box	60299	1951	Ext. 3/4 side	7086	47293
8001	Box	60299	1951	Ext. hand brake end	7087	47294
8001	Box		1951	Int.	7088	47295
8001	Box		1951	Ext. car end	7089	47296
8043	Box	61735	1953	Ext. 3/4 side	7811	47985
8043	Box	61735	1953	Ext. hand brake end	7812	47986

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
TEXAS & PACIFIC						
5581	Box, Steel	40199	1937	Exterior 3/4 side	2276	43645
5581	Truck	40199	1937	Side	2280	43648
5581	Truck	40199	1937	3/4 front	2281	43649
TEXAS MEXICAN RLY. CO.						
8119	Gondola	902	1953	Ext. 3/4 side	8187	48226
8119	Gondola	902	1953	Ext. hand brake end	8188	48227
TIDEWATER SOUTHERN						
8240	Box	501	1955	Ext. 3/4 side	8829	48770
8240	Box	501	1955	Ext. hand brake end	8830	48771
TOLEDO PEORIA & WESTERN						
8124	Box	620	1953	Ext. 3/4 side	8117	48158
8124	Box	620	1953	Ext. hand brake end	8118	48159
UNION CARBIDE (ELECTRO METALLURGICAL CO.)						
8131	Hopper	201	1953	Ext. 3/4 side	8123	48164
8131	Hopper	201	1953	Ext. hand brake end	8124	48165
8162	Hopper Covered	585	1953	Ext. 3/4 side	8198	48235
8162	Hopper Covered	585	1953	Ext. hand brake end	8199	48236



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
UNION PACIFIC						
	Box	187500	1939	Exterior 3/4 end; this car UP-built	2492	43810
	Box	187500	1939	Exterior side	2493	43811
	Box	187500	1939	Exterior side repainted & relettered	2494	43812
	Box	187500	1939	Exterior roof, view of shops	2494	43813
	Box	187500	1939	Interior from end	2496	43814
	Box	187500	1939	Exterior end	2497	43815
	Box	187500	1939	Exterior hand brake end	2498	43816
5584	Box	186021	1938	Ext. 3/4 end roof	2396	43729
5584	Box	186021	1938	Exterior end	2397	43730
5584	Box	186021	1938	Ext. hand brake end	2398	43731
5584	Box	186028	1938	Interior end	2399	43732
5584	Box	186028	1938	Exterior end	2400	43733
5584	Box	186028	1938	Exterior hand brake end	2401	43734
5664	Flat	57059	1941	Ext. side	3056	44271
5664	Flat	57059	1941	3/4 frt. frame and trucks	3057	44272
5775	Caboose	3799	1944	Ext. 3/4 side; blt. by Mt. Vernon car, reb.H&B	4173	44800
5775	Caboose	3799	1944	Int.	4174	44801
5775	Caboose	3799	1944	Ext. 3/4 end	4177	44802
5775	Caboose	3799	1944	Int.	4178	44803
5775	Caboose	3799	1944	Truck front view	4181	44804
5775	Caboose	3799	1944	Truck side view	4182	44805
5775	Caboose	3799	1944	Ext. 3/4 side	4185	44806
5775	Caboose	3799	1944	Int.	4186	44807
5775	Caboose	3799	1944	Int. unfinished	4187	44808
5775	Caboose		1944	3/4 front frame	4345	44871
5775	Caboose		1944	3/4 front frame inverted	4346	44872
5775	Caboose		1944	Truck side view	4347	44873
5775	Caboose		1944	Truck 3/4 side	4348	44874
5775	Caboose		1944	Truck top view	4349	44875
5775	Caboose		1944	Int. installing ceiling	4351	44876
5775	Caboose		1944	Ext. 3/4 side no paint	4365	44878
5775	Caboose		1944	Int.	4366	44879
5775	Caboose		1944	Int.	4367	44880

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
UNION PACIFIC (continued)						
5775	Caboose		1944	Int.	4368	44881
5775	Caboose		1944	Int.	4369	44882
5775	Caboose		1944	Int.	4369A	44883
5775	Caboose	3824	1944	Int.	4385	44890
5775	Caboose	3824	1944	Int. stove	4394	44891
5775	Caboose	3824	1944	Int. stove	4394	44892
5775	Caboose	3824	1944	Ext. 3/4 side	4402	44893
5775	Caboose	3824	1944	Ext. 3/4 side	4403	44894
5775	Caboose	3824	1944	Ext. hand brake end	4404	44895
5775	Caboose	3824	1944	Int.	4405	44896
5775	Caboose	3824	1944	Int.	4406	44897
5775	Caboose	3824	1944	Int.	4412	44898
5775	Caboose		1944	Ext. 3/4 side no paint	4414	44899
5775	Caboose		1944	Number of cabooses in train for shipment	4415	44900
5775	Caboose		1944	Int.	4417	44901
5827	Box, Automobile	455949	1946	Ext. side	5069	45384
5827	Box	455835	1946	Ext. roof from end	5075	45389
5827	Box		1946	Truck, side view	5076	45390
5827	Box		1946	Truck, 3/4 front	5077	45391
5827	Box, Automobile		1946	Shop scene frame under construction	5078	45392
5827	Box, Automobile	455835	1946	Int.	5079	45393
5827	Box, Automobile		1946	Int. no floor or sheathing	5080	45394
5827	Box, Automobile		1946	Int. no side sheathing	5081	45395
5827	Box, Automobile	455838	1946	Ext. end	5082	45396
5827	Box, Automobile	455838	1946	Ext. hand brake end	5083	45397
5827	Box, Automobile	455835	1946	Ext. 3/4 side	5084	45398
5827	Box, Automobile	455949	1946	Ext. 3/4 side	5085	45399
5860	Box		1947	Frame 3/4 front inverted	5411	45664
5860	Box		1947	Frame end from rear	5412	45665
5860	Box		1947	Frame 3/4 rear	5413	45666
5860	Box		1947	Frame 3/4 side inverted	5414	45667
5860	Box		1947	Frame partial from rear	5415	45668
5860	Box		1947	Frame partial 3/4 rear inverted	5416	45669
5860	Box		1947	Frame partial 3/4 side inverted	5417	45670



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
UNION PACIFIC (continued)						
5860	Box		1947	Frame, coupler pocket	5418	45671
5860	Box		1947	Frame center section	5419	45672
5860	Box		1947	Frame details	5420	45673
5860	Box		1947	Frame, 3/4 side end only	5421	45674
5860	Box		1947	Frame, partial 3/4 end	5422	45675
5860	Box		1947	Coupler pocket inverted	5423	45676
5860	Box		1947	Frame 3/4 front inverted	5424	45677
5860	Box		1947	Frame partial 3/4 side	5425	45678
5860	Box		1947	Frame center section	5426	45679
5860	Box		1947	Train of cars for delivery	5515	45770
5860	Box		1947	Similar to 5515	5516	45771
5861	Box		1947	Shop scene frame under construction	5390	45644
5861	Box		1947	Frame 3/4 front inverted	5391	45645
5861	Box	197899	1947	Ext. 3/4 side	5435	45688
5861	Box		1947	Int.	5439	45692
5861	Box		1941	Ext. side door	5440	45693
5861	Box	197899	1947	Ext. 3/4 side	5465	45718
5861	Box	197899	1947	Ext. end	5466	45719
5861	Box	197899	1947	Ext. hand brake end	5467	45720
5861	Box		1947	Int. no floor or sheathing	5468	45721
5861	Box		1947	Truck, side view	5469	45722
5861	Box		1947	Truck, 3/4 front	5470	45723
5861	Box	197899	1947	Ext. 3/4 end from above	5471	45724
5861	Box		1947	Shop scene frame on edge	5472	45725
5861	Box		1947	Shop scene frame welding fixture; see 5474	5473	45726
5861	Box		1947	Shop scene frame in welding fixture; see 5473	5474	45727
5861	Box		1947	Ext. side door	5440	45693
5861	Box	198290	1947	Ext. hand brake detail	5481	45733
5861	Box	198290	1947	Ext. hand brake end	5482	45734
5908	Box		1948	Construction at side door	5951	46131
5908	Box	100675	1948	Ext. 3/4 side	5988	46168
5908	Box	100675	1948	Ext. hand brake end	5989	46169
5908	Box	100675	1948	Ext. 3/4 side	5990	46170
5908	Box	100675	1948	Ext. end	5991	46171

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
UNION PACIFIC (continued)						
5908	Box		1948	Ext. closeup of truck at bolster	6068	46248
5908	Box		1948	Ext. underside frame detail	6069	46249
5908	Box		1948	Int. from side door, no floor	6070	46250
5908	Box		1948	Parts of destroyed car Lot 5908; 6143-6156 series	6143	46320
5908	Box		1948	Similar to 6143	6144	46321
5908	Box		1948	See 6143	6145	46322
5908	Box		1948	Ext. car body; see 6143	6146	46323
5908	Box		1948	Ext. body and frame parts; see 6143	6147	46324
5908	Box		1948	Frame parts; see 6143	6148	46325
5908	Box		1948	End of frame; see 6143	6149	46326
5908	Box		1948	Frame details; see 6143	6150	46327
5908	Box		1948	Body parts; see 6143	6151	46328
5908	Box		1948	Body parts; see 6143	6152	46329
5908	Box		1948	Frame; see 6143	6153	46330
5908	Box		1948	Frame details; see 6143	6154	46331
5908	Box		1948	Frame details; see 6143	6155	46332
5908	Box		1948	Ext. 3/4 end destroyed car; see 6143	6156	46333
5908	Box	100001	1948	Int. side wall	6221	46397
5908	Box	100001	1948	Int. side wall lettering	6222	46398
5908	Box	100001	1948	Same as 6221	6223	46399
5908	Box	100001	1948	Int. same as 6222	6224	46400
5908	Box		1951	Cracks in frame; 6938-6940 a series	6938	47152
5908	Box		1951	See 6938	6939	47153
5908	Box		1951	See 6938	6940	47154
8204	Box		1954	Shop scene car body constr.; 8509-8514 series	8509	48467
8204	Box		1954	See 8509	8510	48468
8204	Box		1954	See 8509	8511	48469
8204	Box		1954	See 8509	8512	48470
8204	Box		1954	See 8509	8513	48471
8204	Box		1954	See 8509	8514	48472
8204	Box		1954	Truck side view	8515	48473
8204	Box		1954	Truck front view	8516	48474
8204	Box		1954	Frame 3/4 front	8517	48475
8204	Box		1954	Frame 3/4 front inverted	8518	48476



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
UNION PACIFIC (continued)						
8204	Box	162504	1954	Int.	8520	48477
8204	Box	162504	1954	Int.	8521	48478
8204	Box	162399	1954	Ext. 3/4 side	8522	48479
8204	Box	162399	1954	Ext. hand brake end	8523	48480
8204	Box		1954	Int. no sheathing	8524	48481
8205	Box		1954	Truck 3/4 side	8533	48490
8205	Box		1955	Truck 3/4 front	8534	48491
8205	Box		1955	Int. no floor or sheathing	8535	48492
8205	Box		1955	Frame 3/4 front	8536	48493
8205	Box		1955	Frame inverted	8537	48494
8205	Box		1955	Int.	8538	48495
8205	Box	500698	1955	Ext. 3/4 side	8539	48496
8205	Box	500698	1955	Ext. hand brake end	8540	48497
8205	Box		1955	Shop scene frame shop; 8554-8582 a series building frame for UP box car Lot 8205	8554	48511
8205	Box		1955	Shop scene frame shop; see 8554	8555	48512
8205	Box		1955	Shop scene frame shop; see 8554	8556	48513
8205	Box		1955	Shop scene frame shop; see 8554	8557	48514
8205	Box		1955	Shop scene frame shop; see 8554	8558	48515
8205	Box		1955	Shop scene frame shop; see 8554	8559	48516
8205	Box		1955	Shop scene frame shop; see 8554	8560	48517
8205	Box		1955	Shop scene frame shop; see 8554	8561	48518
8205	Box		1955	Shop scene frame shop; see 8554	8562	48519
8205	Box		1955	Shop scene frame shop; see 8554	8563	48520
8205	Box		1955	Shop scene frame shop; see 8554	8564	48521
8205	Box		1955	Shop scene frame shop; see 8554	8565	48522
8205	Box		1955	Shop scene frame shop; see 8554	8566	48523
8205	Box		1955	Shop scene frame shop; see 8554	8567	48524
8205	Box		1955	See 8554	8568	48525
8205	Box		1955	See 8554	8569	48526
8205	Box		1955	See 8554	8570	48527
8205	Box		1955	See 8554	8571	48528
8205	Box		1955	See 8554	8572	48529
8205	Box		1955	See 8554	8573	48530

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
UNION PACIFIC (continued)						
8205	Box		1955	See 8554	8574	48531
8205	Box		1955	See 8554	8575	48532
8205	Box		1955	See 8554	8576	48533
8205	Box		1955	See 8554	8577	48534
8205	Box		1955	See 8554	8578	48535
8205	Box		1955	See 8554	8579	48536
8205	Box		1955	See 8554	8580	48537
8205	Box		1955	See 8554	8581	48538
8205	Box		1955	See 8554	8582	48539
	Box	10559	1948	Int.; note 6139-6142 a series	6139	46316
	Box	10559	1948	Int.; see 6139	6140	46317
	Box	10559	1948	Int. ; see 6139	6141	46318
	Box	10559	1948	Int.; see 6139	6142	46319
	Hopper Covered	1900	1955	Int.; 8737-8743 a series	8737	48691
	Hopper Covered	1900	1955	Int. self-cleaning jets	8738	48692
	Hopper Covered	1900	1955	Int.	8739	48693
	Hopper Covered	1900	1955	Ext. closeup of hopper	8740	48694
	Hopper Covered	1900	1955	Ext. closeup of hopper doors	8741	48695
	Hopper Covered	1900	1955	Cleaning jets	8742	48696
	Hopper Covered	1900	1955	Ext. underside	8743	48697
UNION RAILROAD						
	Gondola	7313	1952	Ext. end	7413	47602
UNITED STATES AIR FORCE						
8061	Box	26905	1953	Ext. side	7747	47924
8061	Box	26905	1953	Ext. hand brake end	7748	47925
8061	Box	26905	1953	Ext. 3/4 side	7749	47926
8105B	Box	26685	1953	Ext. side	7996	48089
8105B	Box	26685	1953	Ext. 3/4 side	7997	48090
8105B	Box	26685	1953	Ext. end	7998	48091



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
UNITED STATES AIR FORCE (continued)						
8105B	Box	26685	1953	Ext. hand brake end	7999	48092
8105B	Box	26685	1953	Int.	8000	48093
UNITED STATES ARMY						
5980	Box		1950	Train of cars for delivery	6895	47108
5980	Box	26070	1950	Ext. 3/4 side	6896	47109
5980	Box	26070	1950	Ext. 3/4 side	6897	47110
5980	Box	26070	1950	Ext. hand brake end	6898	47111
5980	Box	26070	1950	Ext. 3/4 end	6899	47112
8008	Box	26218	1951	Ext. hand brake end	6970	47184
8008	Box	26218	1951	Ext. side	6971	47185
8008	Box	26218	1951	Ext. 3/4 side	6972	47186
8044	Box	26423	1951	Ext. 3/4 side	7120	47325
8044	Box	26423	1951	Ext. side	7121	47326
8044	Box	26423	1951	Ext. hand brake end	7122	47327
8044	Box	26320	1951	Ext. 3/4 side	7130	47335
8044	Box	26320	1951	Ext. side	7131	47336
8044	Box	26300	1951	Ext. hand brake end	7132	47337
8061	Box	26488	1953	Ext. side door	7722	47899
8061	Box	26488	1953	Ext. side door	7723	47900
8061	Box	26488	1953	Ext. side door	7724	47901
8061	Box	26488	1953	Int. side door	7725	47902
8061	Box	26488	1953	Ext. side door	7726	47903
8061	Box	26488	1953	Ext. side door	7727	47904
8061	Box	26488	1953	Ext. lower section side door	7728	47905
8061	Box	26488	1953	Ext. lower section side door	7729	47906
8061	BHox	26488	1953	Ext. lower section side door	7730	47907
8061	Box	26488	1953	Ext. lower section side door	7731	47908
8061	Box	26534	1953	Ext. side door	7734	47911
8061	Box	26534	1953	Ext. side door	7735	47912
8061	Box	26534	1953	Ext. side door	7736	47913
8061	Box	26534	1953	Ext. side door	7737	47914

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
UNITED STATES ARMY (continued)						
8061	Box	26534	1953	Ext. side	7741	47918
8061	Box	26534	1953	Ext. hand brake end	7742	47919
8061	Box	26534	1953	Ext. 3/4 side	7743	47920
8061	Box	26534	1953	Ext. 3/4 side	7744	47921
8179	Box	27127	1954	Corner of roof	8261	48295
8179	Box	27127	1954	Closeup of brake hanger	8262	48296
8179	Box	27127	1954	Closeup of pipe	8263	48297
8179	Box	27127	1954	Closeup of car end, lower	8264	48298
8179	Box	27127	1954	Ext. 3/4 side	8265	48299
8179	Box	27127	1954	Ext. side	8266	48300
8179	Box	27127	1954	Ext. hand brake end	8267	48301
8179	Box		1954	Ext. side door	8268	48302
8179	Box		1954	Ext. side door	8269	48303
	Box		1953	Ext. closeup of door latch; see 8454	8453	48411
	Box		1953	Ext. closeup of door latch; see 8453	8454	48412
UNITED STATES ARMY (EXPORT)						
5731	Caboose	90051	1942	Ext. side	3629	44643
5731	Caboose	90051	1942	Ext. end	3630	44644
5731	Caboose	90051	1942	Ext. roof front	3631	44645
5731	Caboose	90051	1942	Int.	3632	44646
5731	Caboose	90051	1942	Int.	3633	44647
5731	Caboose	90051	1942	Int.	3634	44648
5732	Box	228075	1942	Ext. side	3626	44640
5732	Box	228075	1942	Ext. end	3627	44641
5732	Box	228075	1942	Ext. roof front	3628	44642
5743	Caboose	90962	1943	Ext. side	3919	44669
5743	Caboose	90962	1943	Ext. end	3920	44670
5743	Box		1943	Crate	4043	44726
5743	Box		1943	Crate	4044	44727
5743	Box		1943	Wheel set	4045	44728



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
UNITED STATES ARMY [EXPORT] (continued)						
5743	Box		1943	Barbel; 4046-4087 preparing & crating spare parts for shipment overseas	4046	44729
5743	Box		1943	Wheel sets	4047	44730
5743	Box		1943	Crate	4048	44731
5743	Box		1943	Crate	4049	44732
5743	Box		1943	Car ends	4050	44733
5743	Box		1943	Crates	4051	44734
5743	Box		1943	Crate	4052	44735
5743	Box		1943	Wheel set	4053	44736
5743	Box		1943	Crate	4054	44737
5743	Box		1943	Crate	4055	44738
5743	Box		1943	Crate	4056	44739
5743	Box		1943	Brake parts	4057	44740
5743	Box		1943	Crate of brake rods	4058	44741
5743	Box		1943	Crate	4059	44742
5743	Box		1943	Crate	4060	44743
5743	Box		1943	Worker spray painting wood car body parts	4061	44744
5743	Box		1943	Crate	4062	44745
5743	Box		1943	Wheel sets	4063	44746
5743	Box		1943	Crate	4064	44747
5743	Box		1943	Crate	4065	44748
5743	Box		1943	Crates	4066	44749
5743	Box		1943	Wheel sets	4067	44750
5743	Box		1943	Crate	4068	44751
5743	Box		1943	Crate	4069	44752
5743	Box		1943	Crate	4070	44753
5743	Box		1943	Crate	4071	44754
5743	Box		1943	Crate	4072	44755
5743	Box		1943	Car side	4073	44756
5743	Box		1943	Crate	4074	44757
5743	Box		1943	Crate	4075	44758
5743	Box		1943	Car side	4076	44759
5743	Box		1943	Crated car side	4077	44760
5743	Box		1943	Crated car roof	4078	44761

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
UNITED STATES ARMY [EXPORT] (continued)						
5743	Box		1943	Crated car roof	4079	44762
5743	Box		1943	Car frame and floor	4080	44763
5743	Box		1943	Car frame and floor	4081	44764
5743	Box		1943	Crate	4082	44765
5743	Box		1943	Crates in gondola	4083	44766
5743	Box		1943	Crates and frames in gondola	4084	44767
5743	Box		1943	Crates in gondola	4085	44768
5743	Box		1943	Wheel sets in gondola	4086	44769
5743	Box		1943	Yard scene car parts for shipment	4087	44770
5757-	Box		1043	Plywood sheets; see 3928	3927	44677
58-59-60						
5757-60	Box		1943	See 3927	3928	44678
5757	Box (4-wheel)	2203600	1944	Ext. side	4120	44790
5757	Box (4-wheel)	2203600	1944	Ext. end	4121	44791
5757	Box (4-wheel)		1944	Axle sets for shipment	4284	44843
5757	Box (4-wheel)		1944	Wheel sets for shipment	4285	44844
5757	Box (4-wheel)		1944	Wheel set for shipment	4286	44845
5757	Box (4-wheel)		1944	Car end for shipment	4296	44846
5757	Box (4-wheel)		1944	Frames for shipment	4313	44847
5759	Gondola (4-wheel)	4200117	1944	Ext. side	4374	44888
5759	Gondola (4-wheel)	4200117	1944	Ext. end	4375	44889
5760	Gondola	444238	1944	Shop scene underframe on edge	4239	44829
5760	Gondola	444239	1944	3/4 side	4254	44830
5760	Gondola		1944	Line of trucks for shipment	4275	44841
5760	Gondola		1944	Carload of misc. parts	4278	44842
5760	Gondola		1944	4331-4340 a series of setps in building car bumpers	4331	44861
5760	Gondola		1944	See 4331	4332	44862
5760	Gondola		1944	See 4331	4333	44863
5760	Gondola		1944	See 4331	4334	44864
5760	Gondola		1944	See 4331	4335	44865
5760	Gondola		1944	See 4331	4336	44866
5760	Gondola		1944	See 4331	4337	44867
5760	Gondola		1944	See 4331	4338	44868
5760	Gondola		1944	See 4331	4339	44869



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
UNITED STATES ARMY [EXPORT] (continued)						
5760	Gondola		1944	See 4331	4340	44870
5786	Box	237799	1944	Ext. 3/4 end	4439	44919
5786	Box	237799	1944	Int.	4440	44920
5786	Box	237799	1944	Ext. 3/4 end	4441	44921
5786	Box	237799	1944	Ext. opposite of 4441	4442	44922
5786	Box	237799	1944	Ext. side	4443	44923
5786	Box		1945	Truck 3/4 front	4474	44937
5786	Box		1945	Wheel set	4477	44938
5786	Box		1945	Ext. 3/4 side loaded with parts	4478	44939
UNITED STATES MARINE CORPS.						
8044	Box	173227	1951	Ext. 3/4 side	7127	47332
8044	Box	173227	1951	Ext. side	7128	47333
8044	Box	173227	1951	Ext. hand brake end	7129	47334
UNITED STATES NAVY						
5726	Box		1942	Ext. side	3490	44567
5726	Box		1942	Ext. hand brake end	3491	44568
8044	Box	61-02455	1951	Ext. 3/4 side	7124	47329
8044	Box	61-02455	1951	Ext. side	7125	47330
8044	Box	61-02455	1951	Ext. hand brake end	7126	47331
8054	Box		1952	Shop "A" bldg. car sides for US Navy; 7381-7396 ser.	7381	47573
8054	Box		1952	Similar to 7381	7382	47574
8054	Box		1952	Similar to 7382; see 7381	7383	47575
8054	Box		1952	Shop "A" fabricating frame; see 7381	7384	47576
8054	Box		1952	Shop "A" installing sheet steel floor; see 7381	7385	47577
8054	Box		1952	Similar to 7385; see 7381	7386	47578
8054	Box		1952	Shop "A" fabricating frame; see 7381	7387	47579
8054	Box		1952	Shop "A"; see 7381	7388	47580
8054	Box		1952	Shop "A" frame on truck; see 7381	7389	47581

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
UNITED STATES NAVY (continued)						
8054	Box		1952	Shop "A" car sides up; see 7381	7390	47582
8054	Box		1952	Shop "A" frame on trucks; see 7381	7391	47583
8054	Box		1952	Shop "A" similar to 7391; see 7381	7392	47584
8054	Box		1952	Shop "A" fabricating frame main beam; see 7381	7393	47585
8054	Box		1952	Similar to 7393; see 7381	7394	47586
8054	Box		1952	Continuation of 7393; see 7381	7394	47587
8054	Box		1952	Shop "A" fabricating frame; see 7381	7395	47588
8054	Box	8570	1952	Ext. side	7397	47589
8054	Box	8570	1952	Ext. 3/4 side	7398	47590
8054	Box	8750	1952	Ext. hand brake end	7399	47591
8054	Box	8000	1952	Ext. lower half side door	7463	47650
8054	Box	8000	1952	Ext. lower half side door	7464	47651
8054	Box	8000	1952	Ext. closeup of coupler at pocket; 7520-7522 ser.	7520	47707
8054	Box	8000	1952	Opposite of 7520	7521	47708
8054	Box	8000	1952	See 7520	7522	47709
8054	Box	8000	1952	Int.	7523	47710
8061	Box	61-03420	1953	Ext. side	7750	47927
8061	Box	61-03420	1953	Ext. hand brake end	7741	47928
8061	Box	61-03420	1953	Ext. 3/4 side	7752	47929
8088	Gondola	61-03098	1953	Ext. 3/4 side	7988	48081
8088	Gondola	61-03098	1953	Ext. hand brake end	7989	48082
8170	Hopper	61-03894	1954	Ext. 3/4 side	8424	48390
8170	Hopper	61-03894	1954	Ext. 3/4 end	8425	48391
8170	Hopper	61-03894	1954	Ext. hand brake end	8426	48392
8170	Hopper	61-03894	1954	Ext. 3/4 end from above	8427	48393
8203	Box	61-04245	1954	Ext. 3/4 side	8501	
8203	Box	61-04245	1954	Ext. hand brake end	8502	
8233			1955	Top view of couplers on 154'R. damage to air line	8784	48738
8233			1955	Side view of 8784	8785	48739
8233			1955	Side view of 8784	8786	48740
8233	Box	61-04270	1955	Ext. 3/4 side	8791	48745
8233	Box	61-04270	1955	Ext. hand brake end	8792	48746



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
USCC						
5811	Flat, raised ends	40	1946	Ext. 3/4 side	4862	45237
5811	Flat, raised ends	40	1946	Ext. end	4863	45238
U.S. STEEL CORP.						
			1939	2 views of welded bolster	2454	43778
			1939	Closeup welded truck bolsters	2455	43779
VIRGINIAN						
5626B	Hopper, Cement	3800	1940	Ext. side	2841	44101
5626B	Hopper, Cement	3800	1940	Ext. hand brake end	2842	44102
WARRIOR RIVER TERMINAL						
5577	Box, Steel	900	1938	Exterior side	2296	43659
5577	Box, Steel	900	1938	Exterior hand brake end	2297	43660
WESTERN PACIFIC						
5098B for 8021	Box Compert.	21164	1953	Int. end; see 7698; 7697-7704 a series	7697	47874
5098B for 8021	Box Compert.		1953	Int. end; see 7697	7698	47875
5098B for 8021	Box Compert.,		1953	Int.; see 7697	7699	47876
5098B for 8021	Box Compert.		1953	Int.; see 7697	7700	47877

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
WESTERN PACIFIC (continued)						
5098B for 8021	Box Compart.		1953	Int.; see 7697	7701	47878
5098B for 8021	Box Compart.		1953	Int.; see 7697	7702	47879
5098B for 8021	Box Compart.		1953	Int.; see 7697	7703	47880
5098B for 8021	Box Compart.		1953	Int.; see 7697	7704	47881
5448	Auto/Furniture	13099		Exterior, closed end	1715	43381
5448	Auto/Furniture	13099	1929	Exterior door end	1716	43382
5448	Auto/Furniture	12148	1929	Exterior closed end	1718	43383
5448	Auto/Furniture	12148	1929	Exterior closed end	1719	43384
8027	Box	20845	1951	Int.	7191	47391
8027	Box	20845	1951	Int.	7192	47392
8027	Box	20845	1951	Int.	7193	47393
8027	Box	20850	1951	Ext. side	7194	47394
8027	Box		1951	Int. sub floor preparing to install a Plastinail floor; 7208-7215 & 7219-7226 & 7229-7230 a series	7208	47408
8027	Box		1951	Int. sub floor; see 7208	7209	47409
8027	Box		1951	Int. different view of 7209; see 7208	7210	47410
8027	Box		1951	Ext. side door lower half; see 7208	7211	47411
8027	Box		1951	Ext. side door sill; see 7208	7212	47412
8027	Box		1951	Int. sub floor at side door; see 7208	7213	47413
8027	Box		1951	Int. sub floor at side door; see 7208	7214	47414
8027	Box		1951	Int. worker troweling Plastinail floor; see 7208	7215	47415
8027	Box		1951	Int. floor partially poured; see 7208	7219	47419
8027	Box		1951	Int. similar to 7219; see 7208	7220	47420
8027	Box		1951	Int. troweling floor; see 7208	7221	47421
8027	Box		1951	Int. shoveling in Plastinail; see 7208	7222	47422
8027	Box		1951	Ext. shoveling in Plastinail; see 7208	7223	47423
8027	Box		1951	Ext. mixing & shoveling Plastinail in car; see 7208	7224	47424
8027	Box		1951	Int. finished car; see 7208	7225	47425
8027	Box	20845	1951	Int. bag of Plastinail in foreground; see 7208	7226	47426
8027	Box		1951	Truck 3/4 side	7227	42427



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
WESTERN PACIFIC (continued)						
8027	Box		1951	Truck front view	7228	47428
8027	Box		1951	Int. troweling Plastinail; see 7208	7229	47429
8027	Box		1951	Int. finished car; see 7208	7230	47430
8027	Box		1951	Ext. 3/4 side	7231	47431
8027	Box	20983	1951	Ext. end	7232	47432
8027	Box	20983	1951	Ext. hand brake end	7233	47433
8027	Box		1951	Int. undercoating of car structure; 7234-37 series	7234	47434
8027	Box		1951	int. see 7234	7235	47435
8027	Box		1951	Int. see ;7234	7236	47436
8027	Box		1951	Int. see 7234	7237	47437
8027	Box		1951	Int. end with compart. doors	7243	47443
8027	Box		1951	Int. roof door lock rail	7244	47444
8027	Box		1951	Int.	7245	47445
8027	Box		1951	Int. floor door lock rail	7246	47446
8027	Box		1951	Int.	7247	47447
8027	Box		1951	Int. corner	7248	47448
8027	Box		1951	Int. compartment doors	7257	47457
8027	Box		1951	Int. compartment doors	7258	47458
8027	Box	20807	1951	Ext. 3/4 side	7259	47459
8027	Box	20807	1951	Ext. hand brake end	7260	47461
8027	Box	20807	1951	Truck side view	7261	47461
8160	Box	1968	1954	Ext. 3/4 side	8286	48319
8160	Box	1969	1954	Ext. hand brake end	8287	48320
8183	Box	35001	1954	Ext. 3/4 side	8401	48372
8183	Box	35001	1954	Ext. hand brake end	8402	48373
8183	Box	35001	1954	Int.	8403	48374
8211	Box	3023	1955	Ext. 3/4 side	8543	48500
8211	Box	3023	1955	Ext. hand brake end	8544	48501
8213	Box	3812	1954	Ext. 3/4 side	8503	48461
8213	Box	35182	1954	Ext. 3/4 side	8527	48484
8213	Box	35182	1954	Ext. end	8528	48485
8213	Box	35182	1954	Ext. hand brake end	8529	48486
8213	Box	35182	1954	Int. no sheathing	8530	48487
8238	Auto Box		1955	Ext. side no paint	8681	48635

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
WESTERN PACIFIC (continued)						
8238			1955	Top view couplers on 154'R.; 8787-8789 a series	8787	48741
8238			1955	Side view of 8787	8788	48742
8238			1955	Side view of 8787	8789	48743
8238	Auto Box		1955	Ext. side no paint	8790	48744
8238	Auto Box	19330	1955	Ext. 3/4 side	8806	48760
8238	Auto Box	19330	1955	Ext. hand brake end	8807	48761
8238	Auto Box	19330	1955	Int.	8808	48762
8239	Box	35253	1955	Ext. 3/4 side	8804	48758
8239	Box	35253	1955	Ext. hand brake end	8805	48759
8241	Box Compartment.		1955	Int. no floor or sheathing; 8831-8845 series	8831	48772
8241	Box Compartment.		1955	Int. sub floor installed	8832	48773
8241	Box Compartment.		1955	Int. sub floor installed	8833	48774
8241	Box Compartment.		1955	Int. insulating floor	8834	48775
8241	Box Compartment.		1955	Int. insulation in floor	8835	48776
8241	Box Compartment.		1955	Int. insulating sidewalls	8836	48777
8241	Box Compartment.		1955	Int. installing side walls	8837	48778
8241	Box Compartment.		1955	Int. installing end walls	8838	48779
8241	Box Compartment.		1955	Int. finished	8839	48780
8241	Box Compartment.		1955	Int. installing roof	8840	48781
8241	Box Compartment.		1955	Int. installing floor	8841	48782
8241	Box Compartment.		1955	Ext. insulating roof	8842	48783
8241	Box Compartment.		1955	Ext. insulation on roof	8843	48784
8241	Box Compartment.		1955	Int. roof no insulation	8844	48785
8241	Box Compartment.		1955	Int. installing side wall insulation	8845	48786
8241	Box		1955	Insulated box car door; 8865-8870 a series	8865	48799
8241	Box		1955	Insulated box car door; see 8865	8866	48800
8241	Box		1955	See 8865	8867	48801
8241	Box		1955	See 8865	8868	48802
8241	Box		1955	See 8865	8869	48803
8241	Box		1955	See 8865	8870	48804
8241	Box		1955	Int.	8871	48805
8241	Box		1955	Int. end	8872	48806
8241	Box		1955	Closeup compartment door lock; 8873-8887 a series	8873	48807
8241	Box		1955	Closeup of compartment door lock; see 8873	8874	48808



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
WESTERN PACIFIC (continued)						
8241	Box		1955	Closeup of compartment door lock; see 8873	8875	48809
8241	Box		1955	Closeup of compartment door lock; see 8873	8876	48810
8241	Box		1955	Closeup of compartment door lock; see ;8873	8877	48811
8241	Box		1955	Closeup of compartment door lock; see ;8873	8878	48812
8241	Box		1955	Closeup of compartment door lock; see 8873	8879	48813
8241	Box		1955	Closeup of compartment door lock; see 8873	8880	48814
8241	Box		1955	Closeup compartment door lock; see 8873	8881	48815
8241	Box		1955	Closeup of compartment door lock	8882	48816
8241	Box		1955	Closeup of compartment door lock	8883	48817
8241	Box		1955	Closeup of compartment door lock	8884	48818
8241	Box		1955	Closeup of compartment door lock	8885	48819
8241	Box		1955	Closeup of compartment door lock	8886	48820
8241	Box		1955	Closeup of compartment door lock	8887	48821
8241	Box		1955	Int. end of compartment doors	8888	48822
8241	Box	Compartmentized 55906	1955	Ext. 3/4 side	8890	48824
8241	Box		1955	Int. end w/compart. doors	8903	48836
8241	Box	Insul. Compart. 55906	1955	Ext. hand brake end	8908	48839
8242	Flat	2001	1955	Ext. 3/4 end	8989	48919
8267			1955	Underside car end	8889	48823
8267	Box	35309	1955	Ext. 3/4 side	8936	48866
8267	Box	35309	1955	Ext. 3/4 front closeup of lower half	8937	48867
8267A	Box	3838	1955	Ext. 3/4 side	8938	48868
8267A	Box	3838	1955	Ext. hand brake end	8939	48868
8267A	Box		1955	Int.	8942	48872
8267B	Auto Box	19429	1955	Ext. 3/4 side	8940	48870
8267B	Auto Box	19429	1955	Ext. hand brake end	8941	48871
8268	Box	35423	1955	Ext. 3/4 side	8980	48911
8268	Box	35423	1955	Ext. hand brake end	8981	48912
JO36812	Box	1952	1952	Ext. side	7598	47779
JO36812	Box	1952	1952	Ext. side	7599	47780
JO36812	Box	1952	1952	Ext. end	7600	47781
JO36812	Box	1952	1952	Ext. hand brake end	7601	47782
JO36878	Box	1953	1952	Ext. side	7602	47783
JO36878	Box	1953	1952	Ext. side	7603	47784

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
WESTERN PACIFIC (continued)						
JO36878	Box	1953	1952	Ext. 3/4 side	7604	47785
JO36878	Box	1953	1952	Ext. end	7605	47786
JO36878	Box	1953	1952	Ext. hand brake end	7606	47787
JO36878	Box		1952	Int.	7607	47788
JO36878	& Box		1952	Train of cars for delivery	7608	47789
JO36812						
JO36878			1953	Uncoupling lever, closeup; see 7740	7739	47916
JO36878			1953	Uncoupling lever; see 7739	7740	47917
	Box	21394	1952	Int. end; car in for repair	7617	47798
	Box Automobile	13099	1929	Ext. side	9298	49171
WESTERN RY. OF ALABAMA						
5685	Box	17349	1941	Ext. side	3294	44380
5685	Box	17349	1941	Ext. hand brake end	3296	44381
5753	Box	17464	1944	Ext. side	4115	44785
5869	Box	17649	1947	Ext. 3/4 side	5708	45968
5869	Box	17649	1947	Ext. hand brake end	5709	45969
5902A	Hopper	11200	1948	Ext. 3/4 side	5966	46145
5902A	Hopper	11200	1948	Ext. hand brake end	5967	46146
8021	Box	18209	1952	Ext. 3/4 side	7370	47562
8021	Box	18209	1952	Ext. hand brake end	7371	47563
8032	Gondola	11800	1952	Ext. 3/4 side	7490	47677
8032	Gondola	11800	1952	Ext. hand brake end	7491	47678
8283	Box	17254	1956	Ext. 3/4 side	9104	49031
8283	Box	17254	1956	Ext. hand brake end	9105	49032
8284D	Box	18250	1956	Ext. 3/4 side	9139	49066
8284D	Box	18250	1956	Ext. hand brake end	9140	49067



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
WHEELING & LAKE ERIE						
5604C	Box	26000	1940	Ext. side	2610	43910
5604C	Box	26000	1940	Ext. end	2631	43925
5604C	Box	26000	1940	Ext. hand brake end	2632	43926
5604C	Box	26000	1940	Ext. side	9393	49182
5649	Box	24268	1941	Ext. side door	2940	44165
5649	Box	24268	1941	Int. side door	2941	44166
5649	Box	24268	1941	Ext. side door	2942	44167
5649	Box	24268	1941	Int. side door	2943	44168
5649	Box	24260	1941	Ext. 3/4 side	2952	44177
5649	Box	24260	1941	Int. end, no floor	2953	44178
5649	Box	24260	1941	Int. end	2954	44179
5649	Box	24253	1941	Int. end from side door	2955	44180
5649	Box	24260	1941	Ext. roof from end	2956	44181
5649	Box	24260	1941	Ext. hand brake end	2957	44182
WOODWARD						
8243	Hopper	2349	1955	Ext. 3/4 side	8891	48825
8243	Hopper	2349	1955	Ext. end	8892	48826

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
				HASKELL AND BARKER CAR CO.		
				Photographer recording cars	1998	43500
			1936	Shop scene, exterior bracing ready to be fitted to box car	2000	43503
			1936	Same as 2000, different view	2001	43504
			1936	New York Central box car being fitted with exterior bracing; see 2000 and 2001	2002	43505
			1936	Same as 2002, different view	2003	43506
			1936c.	Side door	2093	43559
			1936c.	Side door	2094	43560
			1936c.	Side door	2095	43561
			1936	Side door closeup	2096	43562
			1936c.	Bolster parts, no details	2099	43565
			1936c.	Bolster parts, no details	2100	43566
			1936c.	Bolster, no details	2101	43567
			1936c.	Bolster, no details	2102	43568
				Journal bearing wedges, 5-1/2 x 10 and 5 x 9	2128	43588
			1937	Shop scene, three workers repairing car	2310	43673
			1938	Spot welding machine	2328	43684
			1938	Roof spot welding machine in operation	2329	43685
			1938	Side spot welding machine in operation	2330	43686
			1938	Spot welding posts to side sheets	2331	43686
			1938	Spot welding side parts	2332	43688
			1938	Gang spot welder for side assembly	2359	43707
			1939	Nail test for comparative holding	2404	43737
			1939	1-4-39 testing side sheets	2409	43740
			1939	Testing side sheets	2410	43741
	Box		1939	Load testing car section	2417	43742
			1939	Load testing car section	2418	43743
			1939	Load testing bolster	2419	43744
			1939	Stamping press car parts	2420	43745
			1939	Shop fixture for assembly truck chafe plate	2421	43746
			1939	Same as 2421, different view	2422	43747
			1939	Same as 2422, different view	2423	43748



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1939	Same as 2422, different view	2424	43749
			1939	"Last Word" indicator in fixture close up	2425	43750
			1939	Same as 2424 overall view of fixture	2426	43751
				3/4 frt. fixture for welding truck chafe plates	2434	43759
				Same as 2434 different view	2435	43760
			1939	"Last Word" indicator in fixture	2438	43761
			1939	Front of bldg. #20 machine shop	2445	43769
			1939	3/4 side bldg. #24 carpenter shop	2446	43770
			1939	Heating plant	2447	43771
			1939	Buildings on West Sixth Street	2449	43772
			1939	3/4 front pattern shop	2449	43773
			1939	3/4 front building #25	2450	43774
			1939	3/4 side same as 2450 different view	2451	43775
			1939	3/4 front pattern storage building	2452	43776
			1939	Rear of carpenter shop	2453	43777
			1939	End view gondola with I beams	2456	43780
			1939	Same as 2456 from above	2457	43781
			1939	Welded?	2458	43782
			1939	Coupler pocket welded	2459	43783
			1939	Coupler pocket welded	2460	43784
			1939	Coupler pocket welded	2461	43785
			1939	Coupler pocket welded	2462	43786
			1939	Coupler pocket welded	2463	43787
			1939	3/4 side truck (note: 2464-2475 same truck)	2464	43788
			1939	Side truck	2465	43789
			1939	3/4 front truck	2466	43790
			1939	3/4 rear of truck	2467	43791
			1939	3/4 front from below truck frame	2468	43792
			1939	Reverse of 2468	2469	43793
			1939	End only truck frame	2470	43794
			1939	End only truck frame w/journal box	2472	43795
			1939	Truck frame w/brake gear	2473	43796
			1939	Side journal box wheel and spring	2475	43797
			1939	Weldments on coupler pocket	2476	43798

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1939	Front coupler pocket	2477	43799
			1939	Opposite of 2477	2478	43800
			1939	Rear of 2477	2479	43801
			1939	Seam welding jig camber adj. wedge	2481	43802
			1939	Seam welding jig draft gear housing gauge	2482	43803
			1939	Seam welding jig overall view	2483	43804
			1939	Seam welding jig w/sill in position for welding	2484	43805
			1939	Rear of coupling pocket	2486	43806
			1939	Different view of 2486	2487	43807
			1939	Exterior side door	2488	43808
			1939	Exterior side door	2489	43809
			1939	Center sill turnover fixture	2501	43817
			1939	Parts of fixturing in 2501	2502	43817
			1939	Center sill turnover fixture w/sill in place	2503	43819
			1939	Center sill turnover fixture in operation	2504	43820
			1939	2 views coupler pockets	2505	43821
			1939	Coupler pocket	2506	43822
			1939	Top of coupler pocket	2507	43823
			1939	Different view of 2507	2508	43824
			1939	Closeup, welds on coupler pocket	2509	43825
			1939	Closeup, welds on coupler pocket	2510	43826
			1939	Draft lugs on draft sill before test	2511	43827
			1939	Draft lugs on draft sill before test 979	2547	43859
			1939	Results of test 979	2548	43860
			1939	Results of test 979	2549	43861
			1939	Coupling pocket results of test 979	2550	43862
			1939	Coupling pocket results of test 979	2551	43863
			1939	Coupling pocket results of test 979	2552	43864
			1939	Coupling pocket results of test 979	2553	43865
			1939	Coupling pocket results of test 979	2554	43866
			1940	Rear view door welding machine	2613	43912
	B&LE Car		1940	Welding side door panel to door frame	2615	43913
			1940	Welded draft lug section before test; sent to Purdue Univ. for test negs. 2642-2650	2642	43934



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1940	See 2642	2643	43935
			1940	See 2642	2644	43936
			1940	See 2642	2645	43937
			1940	See 2642	2646	43938
			1940	See 2642	2647	43939
			1940	See 2642	2648	43940
			1940	See 2642	2649	43941
			1940	See 2642	2650	43942
			1940	Spot welders	2675	43958
Shop scenes			1940	End view lathe	2710	43993
			1940	Side lathe	2711	43994
			1940	End view lathe	2712	43995
			1940	Side lathe	2713	43996
			1940	Ext. r.s. door	2719	44001
			1940	Interior door	2720	44002
			1940	Ext. side door	2721	44003
			1940	Shop scene, two workers spot welding	2722	44004
			1940	Same as 2722 different view	2723	44005
			1950	Test plates, bolt shear	2801	44069
			1940	Pipe hanger	2845	44105
			1941	Int. paint shop men's room bldg. #49 SECB	2923	44152
			1941	Wood erection men's room	2924	44153
			1941	Steel plant men's room	2925	44154
			1941	Steel plant men's room	2926	44155
			1941	Wood mill men's room	2927	44156
			1941	Paint shop wash room	2928	44157
			1941	Wood erection men's room	2929	44158
			1941	Steel plant men's room	2930	44159
			1941	1500-ton car door press	2944	44169
			1941	Electrical panel for spot welder	2945	44170
			1941	Shop scene, rolling door jig	2964	44189
			1941	Shop scene, rolling door jig w/door	2965	44190
			1941	Shop scene, jig for welded sides, front	2966	44191
			1941	Shop scene, jig for welded sides, rear	2967	44192

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1941	Shop scene, door shop	2968	44193
			1941	Shop scene, door shop	2969	44194
			1941	Shop scene, door shop	2970	44195
			1941	Shop scene, door shop	2971	44196
			1941	Shop scene, door shop	2972	44197
			1941	Shop scene, door shop	2973	44198
			1941	Shop scene, door welding machine, rear	2974	44199
			1941	Shop scene, door welding machine, front	2975	44200
			1941	Shop scene, welding fixture	2976	44201
			1941	Welding fixture, same as 2976, different view	2977	44202
			1941	Metal corrosion test piece	2978	44203
			1941c.	Two workmen nailing sheathing inside car	3038	44253
			1941c.	Two workmen riveting frame	3039	44254
			1941	Shear test of rivets	3040	44255
			1941	Shear test of rivets	3041	44256
			1942	Boxes?	3042	44257
			1941	Weld tester	3043	44258
			1941	Worker using weld tester; see 3043	3044	44259
			1941	Electrical panel for welder	3045	44260
			1941c.	Workman machine sanding box car frame	3046	44261
			1941c.	Workman riveting car frame	3047	44262
			1941c.	Worker riveting car frame	3048	44263
			1941c.	Workman riveting car frame	3049	44264
			1941c.	Workman riveting car frame	3050	44265
			1941c.	Workman riveting car frame	3051	44266
			1941c.	Workman riveting car frame	3052	44267
			1941	Shop scene car ends	3058	44273
			1941	Shop scene car end stamping mill	3059	44274
			1941	Shop scene car end shop	3060	44275
			1941	Shop scene controls of stamping mill	3061	44276
			1941	Shop scene car end shop	3062	44277
			1941	Shop scene car end shop	3063	44278
			1941	Shop scene car end stamping mill	3064	44279
			1941	Series of brake rods	3197	44285



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1941	Side erecting fixture	3198	44286
			1941	Different view of 3198	3199	44288
			1941	Same as 3198	3200	44288
			1941	Test on forge weld	3203	44291
			1941	Same as 3203	3204	44292
			1941	Test on arc weld	3205	44293
			1941	Test on arc weld	3206	44294
			1942	Workman using gauge	3213	44301
			1941	Car door, ready for shipment	3228	44316
	Car door		1941	Outside before repairs	3229	44317
	Car door		1941	Closeup of damage	3230	44318
	Car door		1941	See 3230	3231	44319
	Car door		1941	Damaged portion cut out	3232	44320
	Car door		1941	Repair completed, not painted	3233	44321
	Car door		1941	Same as 3233	3234	44322
			1941c.	Workman cutting on frame	3235	44323
			1941	Workman arc welding on car frame	3236	44324
			1941	Workman working on car frame	3237	44325
			1941c.	Workman welding on car frame	3238	44326
			1941	Workman using gauge on coupler pocket	3239	44327
			1941	Workman using cutting torch on car frame	3240	44328
			1941	Similar to 3240	3241	44329
			1941	Similar to 3240	3242	44330
			1941	Workman setting gauge on frame	3243	44331
			1941	See 3243	3244	44332
			1941	Workman using gauge on coupler pocket	3245	44333
			1941	Frame parts in storage	3246	44334
	Shop scene		1941	Building center sill	3247	44335
	Shop scene		1941	Similar to 3247	3247A	44336
			1941c.	Workman setting gauge on center sill	3248	44337
			1941	Arc welder control panel	3249	44338
			1941	Int. of arc welding control panel	3240	44339
			1942	Workman using high pressure hose	3259	44346
			1942	Similar to 3259	3260	44347

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1941	Welding fixture 3268-3280 series	3268	44351
			1941	Workman w/welding fixture	3269	44352
			1941	Workman checking car frame	3270	44353
			1941	Worker welding; see 3269	3271	44354
			1941	See 3268	3272	44355
			1941	See 3268	3273	44356
			1941	See 3268	3274	44357
			1941	See 3268	3275	44358
			1941	See 3268	3276	44359
			1941	See 3268	3277	44360
			1941	See 3268	3278	44361
			1941	See 3268	3279	44362
			1941	See 3268	3280	44363
			1941	Gauge set in center sill	3281	44364
			1941	See 3281	3282	44365
			1942	Bolt test	3289	44374
			1942	Workman at grinding wheel	3344	44423
			1942	Different view of 3344	3345	44424
			1942	Workman installing ladder	3346	44425
			1942	Test results plate fracture	3408	44484
			1942	Same as 3408	3409	44485
			1942	Same as 3408	3410	44486
			1942	Rolled stock test	3411	44487
			1942	Test results	3412	44488
			1942	Rolled steel test	3413	44489
			1942	Rolled steel test	3414	44490
			1942	Weld test	3415	44491
			1942	Weld test	3416	44492
			1942	Truck top view	3417	44493
			1942	Weld test	3424	44500
			1942	Test results (frame 44569-55478 series)	3492	44569
			1942	See 3494	3493	44570
			1942	See 3492	3494	44571
			1942	See 3492	3495	44572



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1942	See 3492	3496	44573
			1942	See 3492	3497	44574
			1942	See 3492	3498	44575
			1942	See 3492	3499	44576
			1942	See 3492	3500	44577
			1942	See 3492	3501	44578
			1942	Motor of Bliss punch	3505	44582
			1942	Elec. control box open	3507	44583
			1943	Journal Box #1; see 3930	3929	44679
			1943	See 3929	3930	44680
			1943	Journal Box #2; see 3932	3931	44681
			1943	See 3931	3932	44682
			1943	Journal Box saide #2; see 3946	3945	44695
			1943	Journal side; see 3945	3946	44696
			1943	Journal box #2; see 3948	3947	44697
			1943	See 3947	3948	44698
			1943	Test pieces	3949	44699
			1943	Shop scene car side	4042	49166
			1944	Welding fixture for truck side frame; 4108-4110 ser.	4108	44779
			1944	See 4108	4109	44780
			1944	See 4108	4110	44781
			1944	Side frame fixture used on Lot 5756; see 4189	4188	44809
			1944	See 4188	4189	44810
			1944	Car wheel 705# outside; see 4194	4193	44811
			1944	See 4193	4194	44812
			1944	Car sides being loaded in gondola	4236	44828
			1944	Weld test bar	4456	44931
			1944	Crane unloading center sills	4459	44934
			1945	Shop scene heat treat section	4556	44973
			1945	Int. car side; note 4594-4597 a series	4594	44998
			1945	See 4594	4595	44999
			1945	See 4594	4596	45000
			1945	See 4594	4597	45001
			1945	Workman electric welding	4600	45004

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1945	Ext. paint shop, fire damaged 6-7-45	4621	45009
			1945	Different view of 4621 6-7-45	4622	45010
			1945	Int. ceiling of bldg. damaged by fire 6-7-45	4623	45011
			1945	Ext. 3/4 front load of T&G lumber	4626	45014
			1945	Ext. 3/4 front load of T&G lumber	4627	45015
			1945	Closeup of coupler	4666	45046
			1945	Shop scene operator at Bridgeport milling machine; note 4681-4683 a series	4681	45061
			1945	See 4681	4682	45062
			1945	See 4681	4683	45063
			1945	General outside view South Yard paint shop under construction; 4725-4727 a series	4725	45099
			1945	Gen. outside vw. South Yard paint shop under constr.	4726	45100
			1945	See 4725	4727	45101
			1945	Gen. vw. pipe bending shop; 4730-4732 a series	4730	45104
			1945	See 4730	4731	45105
			1945	See 4730	4732	45106
			1945	See 4734.	4733	45107
			1945	See 4733	4734	45108
			1945	Axle lathe	4736	45110
			1945	Different view of 4736	4737	45111
			1945	Another view of 4736	4738	45112
			1945	Machinist operating lathe shown in 4736	4739	45113
			1945	Punch press flange punching; 4740-4743 a series	4740	45114
			1945	See 4740	4741	45115
			1945	See 4740	4742	45116
			1945	See 4740	4743	45117
			1945	Ext. gen. vw. of South Yard paint shop	4744	45118
			1945	Int. of South Yard paint shop	4745	45119
			1945	Ext. of South Yard paint shop	4746	45120
			1945	Ext. gen. vw. South Yard paint shop	4747	45121
			1945	Ext. South Yard paint shop	4748	45122
			1945	Air brake coupler	4749	45123
			1945	Brake rod end	4750	45124



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1945	Axle lathe	4754	45128
			1945	Worker soldering air brake pipes	4796	45172
			1945	Air brake assembly	4797	45173
			1945	Air brake pipes	4798	45174
			1945	Air brake pipes	4799	45175
			1945	Air brake pipes; 4797-99-4800 a series	4800	45176
			1945	Plumbing for air compressor	4801	45177
			1946	Lot of doors	4831	45203
			1946	Lot of doors showing damage	4832	45202
			1946	See 4831	4833	
			1946	See 4832	4834	45204
			1946	Shop scene welding fixture	4849	45224
			1946	Shop scene, welding fixture	4850	45225
			1946	Different view of 4850	4851	45226
			1946	Different view of 4850	4852	45227
			1946	End panel stamping mill	4853	45228
			1946	Shop scene cleaning operation after press in shape 4088-4890 and 4902 a series	4888	45263
			1946	See 4888	4889	45264
			1946	Shop scene car end press; see 4888	4890	45265
			1946	Car end stamping mill	4891	45266
			1946	Different view of 4891	4892	45267
			1946	Different view of 4891	4893	45268
			1946	Different view of 4891	4894	45269
			1946	Closeup of 4891	4895	45270
			1946	Same as 4895	4896	45271
			1946	Closeup of 4891	4897	45272
			1946	Closeup of 4891	4898	45273
			1946	Roof panel stamping mill	4899	45274
			1946	Different view of 4899	4900A	45275
			1946	Different view of 4899	4900B	45276
			1946	See 4888	4902	45277
			1946	Ext. South Yard paint shop	4925	46825
			1946	North end of car spray booth	4926	46826

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1946	South end of car spray booth	4927	46827
			1946	3/4 front of south end of car spray booth	4928	46828
			1946	3/4 side car spray booth	4929	46829
			1946	Building center section of car spray booth	4930	46830
			1946	3/4 front car spray booth	4931	46831
			1946	Shot blast pit	4932	46832
			1946	Riveting process	4933	46833
			1946	Drill press	4934	46834
			1946	Weld repair to body of large press; note 4946-4949 a series	4946	46846
			1946	See 4946	4947	46847
			1946	See 4946	4948	46848
			1946	See 4946	4949	46849
			1946	Machinery control station; see 4960	4959	46854
			1946	See 4959	4960	46855
			1946	Center sill turnover used on lots 5800 and 5817; see 4962	4961	46856
			1946	See 4961	4962	46857
			1939	Union melt machine; note 4963-4971 a series	4963	46858
			1939	See 4963	4964	46859
			1939	See 4963	4965	46860
			1939	See 4963	4966	46861
			1939	See 4963	4967	46862
			1939	See 4963	4968	46863
			1939	See 4963	4969	46864
			1939	See 4963	4970	46865
			1939	See 4963	4971	46866
				Strap	4993	45309
			1946	Closeup of metal shear	4994	45310
			1946	Metal shear; see 4994	4995	45311
			1946	Closeup of metal shear; see 4994	4996	45312
			1946	See 4994	4997	45313
			1946	Coupler pocket welded	4999	45314
			1946	See 4999	5000	45315



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1946	See 4999	5001	45316
			1946	See 4999	5002	45317
			1946	See 4999	5003	45318
			1946	See 4999	5004	45319
			1946	See 4999	5005	45320
			1946	See 4999	5006	45321
			1946	See 4999	5007	45322
			1946	See 4999	5008	45323
			1946	See 4999	5009	45324
			1946	See 4999	5010	45325
			1946	Coupler pocket; 5011-5016 a series of draft gear lugs	5011	45326
			1946	See 5011	5012	45327
			1946	See 5011	5013	45328
			1946	See 5011	5014	45329
			1946	See 5011	5015	45330
			1946	See 5011	5016	45331
			1946	Shop scene electric welding fixture	5028	45343
			1946	Incorrect method of piling bulb angles; see 5032	5031	45346
			1946	See 5031	5032	45347
			1946	Correct method of piling bulb angles; see 5031	5033	45348
			1946	Incorrect method of piling "Z" bar; see 5035-5036	5034	45349
			1946	See 5035	5035	45350
			1946	Correct method of piling "Z" bar; see 5034	5036	45351
			1946	Broken brake rod	5068	45383
			1946	Bending & drilling brake rod shackles; 5093-5099 ser.	5093	45402
			1946	See 5093	5094	45403
			1946	See 5093	5095	45404
			1946	See 5093	5096	45405
			1946	See 5093	5097	45406
			1946	See 5093	5098	45407
			1946	See 5093	5099	45408
			1946	Drill press in operation; see 5102	5100	45409
			1946	See 5100	5102	45410
			1945	Int. employment office	5114	45422

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1946	Shop scene lathe	5116	45423
			1946	Shop scene repairing car floor; 5118-5122 a series	5118	45424
			1946	See 5118	5119	45425
			1946	See 5118	5120	45426
			1946	See 5118	5121	45427
			1946	See 5118	5122	45428
			1946	Shop scene machine for bending brake rod shackles	5123	45429
			1946	Boring machine with wheel in setup	5124	45430
			1946	High voltage line connectors	5125	45431
			1946	Brake rod shackles	5126	45432
			1946	Several types of levers; 5140-5143 a series	5140	45438
			1946	See 5140	5141	45439
			1946	See 5140	5142	45440
			1946	See 5140	5143	45441
			1946	Spot welder; 5144-5147 a series	5144	45442
			1946	See 5144	5145	45443
			1946	See 5144	5146	45444
			1946	See 5144	5147	45445
			1946	Trash can	5152	45449
			1946		5179	45459
			1946	Brake rod test Pos.	5187	45467
			1946	Car roof section; 5205-5209 a series	5205	45472
			1946	Detail of car roof; see 5205	5206	45473
			1946	Section of roof rib; see 5205	5207	45474
			1946	Section of roof rib support; see 5205	5208	45475
			1946	See 5205	5209	45476
			1946	Coupler pocket; 5210-5212 a series	5210	45477
			1946	See 5210	5211	45478
			1946	See 5210	5212	45479
			1946	Bolster and bearing plate; 5213-5127 a series	5213	45480
			1946	See 5213	5214	45481
			1946	See 5213	5215	45482
			1946	See 5213	5216	45483
			1946	See 5213	5217	45484



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1946	Coupler pocket; 5218-5228 a series	5218	45485
			1946	See 5218	5219	45486
			1946	See 5218	5220	45487
			1946	See 5218	5221	45488
			1946	See 5218	5222	45489
			1946	See 5218	5223	45490
			1946	See 5218	5224	45491
			1946	See 5218	5225	45492
			1946	See 5218	5226	45493
			1946	See 5218	5227	45494
			1946	See 5218	5228	45495
			1946	Murphy improved steel roof	5229	45496
			1946	Roof section	5230	45497
			1946	Roof section	5231	45498
			1946	Corrugated roof section	5232	45499
			1946	Roof test	5233	45500
			1946	Corrugated roof section	5234	45501
			1946	Int. of competitors auto parts car; 5235-5240 series	5235	45502
			1946	See 5235	5236	45503
			1946	See 5235	5237	45504
			1946	See 5237	5238	45505
			1946	See 5237	5239	45506
			1946	See 5237	5240	45507
			1946	Car roof section test	5241	45508
			1946	See 5241	5243	45509
			1946	See 5241	5244	45510
			1946	See 5241	5245	45511
			1946	See 5241	5246	45512
			1946	See 5241	5247	45513
			1947	Shop scene continuous welder	5254	45520
			1947	See 5254	5255	45521
			1947	See 5254	5256	45522
			1947	See 5254	5257	45523
			1947	Electrical control panel; see 5254	5258	45524

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1947	Electrical control panel; see 5254	5259	45525
			1947	Generator; see 5254	5260	45526
			1947	Test pieces steel rods	5261	45527
			1947	Roof tests by Armour Research Foundation; 5262-67 ser.	5262	45528
			1947	See 5262	5263	45529
			1947	See 5262	5264	45530
			1947	See 5262	5265	45531
			1947	See 5262	5266	45532
			1947	See 5262	5267	45533
			1947	Coupler pocket	5268	45534
			1947	Worker at metal press	5269	45535
			1947	Installing turbo in pump	5270	45536
			1947	Roof tests; 5271-5274 a series	5271	45537
			1947	See 5271	5272	45538
			1947	See 5271	5273	45539
			1947	See 5271	5274	45540
			1947	Welded roof section; 5296-98 a series	5296	45557
			1947	Welded roof section; see 5296	5297	45558
			1947	Welded roof section; see 5296	5298	45559
			1947	Section of bulb angle	5299	45560
			1947	Electric welder; see 5305-5306	5304	45565
			1947	See 5304	5305	45566
			1947	See 5304	5306	45567
			1947	Welded roof section	5307	45568
			1947	Welded roof section	5308	45569
			1947	Steel car end top half; see 5310	5309	45570
			1947	Steel car end lower half; see 5309	5310	45571
			1947	Coupler pocket end; 5311-5318 a series	5311	45572
			1947	See 5311	5312	45573
			1947	See 5311	5313	45574
			1947	See 5311	5314	45575
			1947	See 5311	5315	45576
			1947	See 5311	5316	45577
			1947	See 5311	5317	45578



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1947	See 5311	5318	45579
			1947	Closeup of defect in car floor	5325	45584
			1947	Samples of crooked decking before power squeeze	5326	45585
			1947	Samples of crooked deck after power squeeze see 5326	5327	45586
			1947	Samples of crooked deck before squeeze; see 5326	5328	45587
			1947	Test PC riveted roof Pullman; 5329-5334 a series	5329	45588
			1947	Black steel roof sheets test PC; see 5329	5330	45589
			1947	Roof test sheet galvanized; see 5329	5331	45590
			1947	Test of riveted roof; see 5329	5332	45591
			1947	Test of riveted roof; see 5329	5333	45592
			1947	Test of riveted roof; see 5329	5334	45593
			1947	Sections of Pullman car end; see 5336	5335	45594
			1947	See 5335	5336	45595
			1947	Coupler pocket test; 5337-5341 a series	5337	45596
			1947	See 5337	5338	45597
			1947	Coupler pocket side; see 5337	5339	45598
			1947	See 5337	5340	45599
			1947	Coupler pocket test; see 5337	5341	45600
			1947	Car end for test; see 5344	5342	45601
			1947	See 5342	5343	45602
			1947	Welded roof section for test; 5344-5347 a series	5344	45603
			1947	See 5344	5345	45604
			1947	See 5344	5346	45605
			1947	See 5344	5347	45606
			1947	Riveted roof section test; 5348-5351 a series	5348	45607
			1947	See 5348	5349	45608
			1947	See 5348	5350	45609
			1947	See 5348	5351	45610
			1945	Bronze bushing and bearing; see 5363	5362	45621
			1945	See 5362	5363	45622
			1947	Test of welded roof; see 5365	5364	45623
			1947	See 5364	5365	45624
			1947	Rail crossing side of town	5370	45625
			1947	Test of Murphy riveted roof; see 5372	5371	45626

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1947	See 5371	5372	45627
			1947	Coupler pocket before test side view; see 5374-75	5373	45628
			1947	Coupler pocket before test 3/4 frt.; see 5373	5374	45629
			1947	Bolster plate for test; see 5373	5375	45630
			1947	Roof section test	5378	45631
			1947	Underside of Murphy roof after test	5379	45632
			1947	Roof test; see 5381	5380	45633
			1947	Underside of riveted roof test; see 5380	5381	45634
			1947	Welded roof test; see 5383	5382	45635
			1947	Underside of roof in 5382	5383	45636
			1947	Multi spindle drilling machine	5384	45637
			1947	See 5384	5385	45638
			1947	Car end	5386	45639
			1947	Punch press; 5392-5397 & 5400 a series	5392	45646
			1947	See 5392	5393	45647
			1947	See 5392	5394	45648
			1947	See 5392	5395	45649
			1947	See 5392	5396	45650
			1947	See 5392	5397	45651
			1947	Roof panel	5398	45652
			1947	Roof panel	5399	45653
			1947	See 5392	5400	45654
			1941	Production fixture	5427	45680
			1947	Metal shaper; note 5428-5432 a series	5428	45681
			1947	See 5428	5429	45682
			1947	See 5428	5430	45683
			1947	See 5428	5431	45684
			1947	See 5428	5432	45685
			1947	Metal test sections	5433	45686
			1947	System for bolting floor to frame; see 5476	5475	45728
			1947	See 5475	5476	45729
			1947	Shop scene worker putting wheel set in lathe	5483	45735
			1947	Series of clamps for attaching floor to frame	5500	45755
			1947	Shop scene building car side; 5501-5503 a series	5501	45756



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1947	See 5501	5502	45757
			1947	See 5501	5503	45758
			1947	Shop scene frame in welding fixture	5504	45759
			1947	Shop scene frame on edge	5505	45760
	Box		1947	Ext. 3/4 end	5510	45765
	Box		1947	Ext. closeup of ladder	5511	45766
			1947	Wheel set; see 5521	5520	45775
			1947	See 5520	5521	45776
			1947	Punch press set up	5522	45777
			1947	Lot of wheels	5543	45799
			1947	Shop scene sheet metal shop making side and roof panels; 5544-5549 a series	5544	45800
			1947	See 5544	5545	45801
			1947	See 5544	5546	45802
			1947	See 5544	5547	45803
			1947	See 5544	5548	45804
			1947	See 5544	5549	45805
			1947	Car load of roof sections	5550	45806
			1947	Similar to 5550	5551	45807
			1947	Large sheet metal press	5552	45808
			1947	Worker jacking up car corner	5558	45814
			1947	Forging	5559	45816
			1947	Forming brake rod ends; 5564-5566 a series	5564	45821
			1947	See 5564	5565	45822
			1947	See 5564	5566	45823
			1947	Structural failures in American Car & Foundry pullman; 5568-5576 a series	5568	45825
			1947	See 5568	5569	45826
			1947	See 5568	5570	45827
			1947	See 5568	5571	45828
			1947	See 5568	5572	45829
			1947	See 5568	5573	45830
			1947	See 5568	5574	45831
			1947	See 5568	5575	45832

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1947	See 5568	5576	45833
			1947	Forgings, use unknown	5577	45834
			1947	Clips used to tie wood floor to metal frame	5578	45835
			1947	Closeup of couplers Std. Rly. Equip. Co. & Pullman	5579	45836
			1947	Section of bulb angle	5580	45837
			1947	Spot welder; see 5590	5589	45846
			1947	Spot welder; see 5589	5590	45847
			1947	Scaffolding interior of car	5592	45848
			pre-1947	Six men loading running boards on flat car	5606	45862
			pre-1947	Storage area between shop A & Bldg. 44	5607	45863
			pre-1947	Bldg. 44 die storage	5608	45864
			pre-1947	Bldg. 44 general yard condition	5609	45865
			pre-1947	Bldg. 6 general view int.	5610	45866
			pre-1947	Bldg. 6 int. general view	5611	45867
			pre-1947	Bldg. 6 int. gen. view	5612	45868
			pre-1947	Bldg. 6 int. loading air brake cylinder by hand	5613	45869
			pre-1947	Bldg. 44 loading running boards by hand	5614	45870
			pre-1947	Bldg. 44 unloading running boards	5615	45871
			pre-1947	Bldg. 44 welding rod storage	5616	45872
			pre-1947	Bldg. 44 welding rod storage	5617	45873
			pre-1947	Bldg. 49 new welding rod storage room	5618	45874
			1947	Bldg. 6 int. new concrete floor	5619	45875
			1947	Bldg. 6 int. after concrete floor	5620	45876
			1947	Bldg. 6 after concrete floor	5621	45877
			1947	Bldg. 6 after concrete floor	5622	45878
			1947	Bldg. 44 bolt storage before palletizing	5623	45879
			1947	Pipe shop storage before palletizing	5624	45880
			1947	Tin shop storage int.	5625	45881
			1947	Tin shop storage int.	5626	45882
			1947	Yard scene unloading car wheels	5627	45884
			1947	Rolling car wheels by hand from storage	5628	45883
			1947	Yard scene loading car wheels	5629	45886
			1947	Air brake storage area before palletizing	5630	45885
			1947	Triple valve storage area before palletizing	5631	45887



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			pre-1947	Axle yard storage area	5632	45888
			pre-1947	Depressed track, axle yard	5633	45889
			pre-1947	Wheel storage	5634	45890
			pre-1947	Wheels in a float	5635	45891
			1947 aft.	Palletized bolt delivery	5636	45892
			1947 aft.	Palletized welding rod delivery	5637	45893
			pre-1947	Hand cart delivery of welding rod	5638	45894
			1947 aft.	Welding rod storage area	5639	45895
			pre-1947	Hand cart bolt delivery	5640	45896
			pre-1947	Derrick loading wheels	5641	45897
			1947 aft.	Air brake storage area	5642	45898
			1947 aft.	Fork lift stacking air brake parts	5643	45899
			1947	Various ops. in machining a car axle;5649-5657 ser.	5649	45905
			1947	See 5649	5650	45906
			1947	See 5649	5651	45907
			1947	See 5649	5652	45908
			1947	See 5649	5653	45909
			1947	See 5649	5654	45910
			1947	See 5649	5655	45911
			1947	See 5649	5656	45912
			1947	See 5649	5657	45913
			1947	Die for pressing car end panels; 5658-5661 a series	5658	45914
			1947	See 5658	5659	45915
			1947	See 5658	5660	45916
			1947	See 5658	5661	45917
			1947	Var. operations in grinding car axle;5676-5680 ser.	5676	45935
			1947	See 5676	5677	45936
			1947	See 5676	5678	45937
			1947	See 5676	5679	45938
			1947	See 5676	5680	45939
			1947	Int. of car straightening w/comealong;5681-5684 ser	5681	45940
			1947	See 5681	5682	45941
			1947	See 5681	5683	45942
			1947	See 5681	5684	45943

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1947	Yd. scn. 2 men rolling car wheels on float; see 5686	5685	45944
			1947	Moving float; see 5685	5686	45945
			1947	Yard scene 3 men unloading bulkhead material by hand	5696	45955
			1947	Yd. scn. 4 men unloading sheet metal by hand	5697	45956
			1947	Yd. scn. unloading sheet metal with fork lift	5698	45957
			1947	See 5698	5699	45958
			1947	Fixture for fabricating center sill; 5700-5701 ser.	5700	45959
			1947	See 5700	5701	45960
			1947	Shop scene fabricating frame	5702	45961
			1947	Shop scene welders fabricating parts	5703	45962
			1947	Same shop as 5703 different view	5704	45964
			1947	See 5704	5705	45965
			1947	Gen. vw. roof fabricating shop storage area see 5718	5717	45976
			1947	See 5717	5718	45977
			1947	Shop scene stack of center sills; see 5720A	5720	45979
			1947	See 5720	5720A	45980
			1947	Unloading bolts from car w/fork lift	5725	45985
			1947	Air brake cylinder storage after renovation	5726	45986
			1947	Moving air brake cylinders w/ fork lift; 5730-33 ser.	5730	45988
			1947	See 5730	5731	45989
			1947	See 5730	5732	45990
			1947	See 5730	5733	45991
	Box		1947	Ext. side unpainted; 5738-5741 a series	5738	45996
	Box		1947	See 5738	5739	45997
	Box		1947	See 5738	5740	45998
	Box		1947	See 5738	5741	45999
			1947	No. 6 fdry. looking so. after renov.; 5742-5744 a ser.	5742	46000
			1947	No. 6 foundry looking north after renovation	5743	46001
			1947	No. 6 foundry storage looking SW after renovation	5744	46002
			1947	Shop "A" storage after renovation	5745	46003
			1947	Shop scene	5758	46016
			1947	Traveling crane from below; see 5764	5763	46021
			1947	Traveling crane; see 5763	5764	46022



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1947	Production line, fixture for building car sides, continuous seam welding, clamping, cutting, etc.; 5767-5799 a series	5767	46025
			1947	See 5767	5768	46026
			1947	See 5767	5769	46027
			1947	See 5767	5770	46028
			1947	See 5767	5771	46029
			1947	See 5767	5772	46030
			1947	See 5767	5773	46031
			1947	See 5767	5774	46032
			1947	See 5767	5775	46033
			1947	See 5767	5776	46034
			1947	See 5767	5777	46035
			1947	See 5767	5778	46036
			1947	See 5767	5779	46037
			1947	See 5767	5780	46038
			1947	See 5767	5781	46039
			1947	See 5767	5782	46040
			1947	See 5767	5783	46041
			1947	See 5767	5784	46042
			1947	See 5767	5785	46043
			1947	See 5767	5786	46044
			1947	See 5767	5787	46045
			1947	See 5767	5788	46046
			1947	See 5767	5789	46047
			1947	See 5767	5790	46048
			1947	See 5767	5791	46049
			1947	See 5767	5792	46050
			1947	See 5767	5793	46051
			1947	See 5767	5794	46052
			1947	See 5767	5795	46053
			1947	See 5767	5796	46054
			1947	See 5767	5797	46055
			1947	See 5767	5798	46056

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1947	See 5767	5799	46057
			1947	Production line, fixture for building car roofs, continuous seam welding, clamping, cutting, etc.; note 5800-5822 a series	5800	46058
			1947	See 5800	5801	46059
			1947	See 5800	5802	46060
			1947	See 5800	5803	46061
			1947	See 5800	5804	46062
			1947	See 5800	5805	46063
			1947	See 5800	5806	46064
			1947	See 5800	5807	46065
			1947	See 5800	5808	46066
			1947	See 5800	5809	46067
			1947	See 5800	5810	46068
			1947	See 5800	5811	46069
			1947	See 5800	5812	46070
			1947	See 5800	5813	46071
			1947	See 5800	5814	46072
			1947	See 5800	5815	46073
			1947	See 5800	5816	46074
			1947	See 5800	5817	46075
			1947	See 5800	5818	46076
			1947	See 5800	5819	46077
			1947	See 5800	5820	46078
			1947	See 5800	5821	46079
			1947	See 5800	5822	46080
			1947	Coupler pocket test; 5823-5826 a series	5823	46081
			1947	See 5823	5824	46082
			1947	See 5823	5825	46083
			1947	See 5823	5826	46084
			1948	Oxygen acetylene tank storage; see 5838	5837	46097
			1948	Different view of 5837	5838	46098
			1948	Section of boiler room	5840	46100
			1948	Power plant boiler room; 5841-5849 power plant ser.	5841	46101



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1948	See 5841	5842	46102
			1948	Control panel; see 5841	5843	46103
			1948	Control panel; see 5841	5844	46104
			1948	Electric control panel; see 5841	5845	46105
			1948	Electrical control panel; see 5841	5846	46106
			1948	Generator room; see 5841	5847	46107
			1948	Pump room; see 5841	5848	46108
			1948	Electrical control panel w/crew posing; see 5841	5849	46109
			1948	Air brake cylinder storage; 5857-5859 a series	5857	46117
			1948	See 5857	5858	46118
			1948	See 5857	5859	46119
			1948	Lumber storage	5860	46120
			1948	Tin shop after renovation	5861	46121
			1948	Unloading car	5862	46122
			1948	Unloading air brake cylinders	5863	46123
			1948	Unloading air brake cylinders before renovation	5864	46124
			1948	Unloading roof running doors w/fork lift	5865	46125
			1948	Electric welding frame sections; 5866-5868 series	5866	46126
			1948	See 5866	5867	46127
			1948	See 5866	5868	46128
			1948	?	5953	46133
			1948	Car axle on hoist; see 5955	5954	46134
			1948	Car axle on hoist; see 5954	5955	46135
			1948	Examples of car ladders	5956	46136
			1948	Examples of car ladders	5957	46137
					5958	
			1948	Shop scene, welding fixture	5959	46138
			1948	Doors; note 5960-5963 a series	5960	46139
			1948	See 5960	5961	46140
			1948	See 5960	5962	46141
			1948	See 5960	5963	46142
			1948	Car arrester	5970	46149
			1948	See 5972	5971	46150
			1948	Operator w/machine?; see 5971	5972	46151

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1948	Three types car axle ends	5973	46152
			1948	Rivet tests	5974	46153
			1948	Section of running board; see 5976	5975	46154
			1948	Section of running board; see 5975	5976	46155
			1948	Crane unloading car of brake hangers	5985	46165
			1948	See 5985	5986	46166
			1948	See 5985	5987	46167
			1948	Int. wheel foundry before renovation; see 6066	6065	46245
			1948	Int. wheel foundry after renovation; see 6065	6066	46246
			1948	Ext. wheel storage yard before renovation	6067	46247
			1948	Samples of roof running boards	6086	46266
	Box		1948	6089-6102 a series; preparing stencils and applying lettering to CRI&P car	6089	46269
	Box		1948	See 6089	6090	46270
	Box		1948	See 6089	6091	46271
	Box		1948	See 6089	6092	46272
	Box		1948	See 6089	6093	46273
	Box		1948	See 6089	6094	46274
	Box		1948	See 6089	6095	46275
	Box		1948	See 6089	6096	46276
	Box		1948	See 6089	6098	46277
	Box		1948	See 6089	6100	46278
	Box		1948	See 6089	6102	46279
			1948	4 different frames sectioned at bolster; see 6106	6105	46282
			1948	See 6105	6106	46283
			1948	Mockup of door latch; 6107-6112 a series	6107	46284
			1948	See 6107	6108	46285
			1948	See 6107	6109	46286
			1948	See 6107	6110	46287
			1948	See 6107	6111	46288
			1948	See 6107	6112	46289
			1948	Various operations in grinding car axle shop scenes; 6113-6116 a series	6113	46290
			1948	See 6113	6114	46291



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1948	See 6113	6115	46292
			1948	See 6113	6116	46293
			1948	Weld test	6127	46304
			1948	Weld test	6128	46305
			1948	4 different frame sections	6130	46307
Hopper			1948	Ext. 3/4 end only no markings	6132	46309
			1948	Yard scene unloading wheels for car	6136	46313
			1948	Car spring storage	6137	46314
			1948	Outside storage shed interior	6138	46315
			1948	Shop scene fixture for constructing car sides	6162	46339
			1948	See 6162	6163	46340
			1948	Stack of H beams, end view	6184	46360
			1948	Loading scrap into gondola w/fork lift; see 6190	6189	46365
			1948	See 6189	6190	46366
			1948	Unloading car of brake beams by hand	6191	46367
			1948	Rod tests	6192	46368
			1948	Welder fabricating part	6193	46369
			1948	Electric welding machine; see 6195	6194	46370
			1948	See 6194	6195	46371
			1948	Machinest operating axle lathe; see 6197	6196	46372
			1948	See 6196	6197	46373
			1948	Worker trimming hopper car sheets w/torch	6198	46374
			1948	Worker operating flame cutter	6199	46375
			1948	Worker operating flame cutter; 6203-6205 a series	6203	46379
			1948	Worker operating flame cutter; see 6203	6204	46380
			1948	Worker operating flame cutter; see 6203	6205	46381
			1948	Worker trimming sheets on hopper car w/torch	6207	46383
			1948	Worker brazing parts; see 6209	6208	46384
			1948	See 6208	6209	46385
			1948	Control panel & bank of oxygen cylinders; see 6212	6210	46386
			1948	See 6210	6212	46388
			1948	Plant engineer adjusting oxygen acetylene controls; note 6213-6217 a series	6213	46389
			1948	See 6213	6214	46390

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1948	See 6213	6215	46391
			1948	See 6213	6216	46392
			1948	See 6213	6217	46393
			1948	Shop scene production fixture for car sides; see 6228	6227	46402
			1948	See 6227	6228	46403
			1948	H beam w/lugs welded to web; see 6230	6229	46404
			1948	Closeup of 6229	6230	46405
			1949	Jack; see 6260	6259	46434
			1949	Jack disassembled; see 6259	6260	46435
			1949	Continuous seam welding fixture; 6261-6267 series	6261	46436
			1949	See 6261	6262	46437
			1949	See 6261	6263	46438
			1949	See 6261	6264	46439
			1949	See 6261	6265	46440
			1949	See 6261	6266	46441
			1949	See 6261	6267	46442
			1949	Mockup of brake mechanism; 6294-6297 series	6294	46469
			1949	See 6294	6295	46470
			1949	See 6294	6296	46471
			1949	See 6294	6297	46472
			1949	See 6294	6297A	46473
			1949	Worker with fixture?	6309	46485
			1949	Plant safety sign	6313	46488
			1949	Hydraulic press for straightening gondola sides; 6314-6323 a series of devices & operation	6314	46489
			1949	See 6314	6315	46490
			1949	See 6314	6316	46491
			1949	See 6314	6317	46492
			1949	See 6314	6318	46493
			1949	See 6314	6319	46494
			1949	See 6314	6320	46495
			1949	See 6314	6321	46496
			1949	See 6314	6322	46497
			1949	See 6314	6323	46498



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1949	Int. gondola load of wheels; 6333-6338 a series	6333	46508
			1949	See 6333	6334	46509
			1949	See 6333	6335	46510
			1949	See 6333	6336	46511
			1949	See 6333	6337	46512
			1949	See 6333	6338	46513
			1949	Shop scene Shop "A" frame fabricating; 6339-6378 and 6387-6408 a series building car in lot 5926	6339	46514
			1949	Unidentified photo	6382	46557
			1949	Punch press	6383	46558
			1949	Roof sheet	6384	46559
			1949	Broken center plate Hartwig design; see 6415	6414	46589
			1949	See 6414	6415	46590
			1949	Sectioned test pieces; 6464-6475 a series	6464	46639
			1949	See 6464	6474	46640
			1949	See 6464	6475	46641
			1949	Journal bearing box; see 6481	6480	46646
			1949	See 6480	6481	46647
			1949	Gondola load of wheels	6482	46648
			1949	Model of plant layout	6507	46670
			1949	Journal box failed part	6517	46680
			1949	Journal box see 6519	6518	46681
			1949	Journal box see 6518	6519	46682
			1949	Small forged parts all labeled; 6531-6533 a series	6531	46693
			1949	See 6531	6532	46694
			1949	See 6531	6533	46695
			1949	Model of shop layout for building PS-2; see 6595	6579	46741
			1949	Journal boxes	6586	46748
			1949	Model of plant layout for building PS-2; see 6579	6595	46757
			1949	Model of plant layout; 6597-6599 a series	6597/1	46758
			1949	See 6597-1	6597/2	46759
			1949	See 6597-1	6597/3	46760
			1949	See 6597-1	6597/4	46761
			1949	See 6597-1	6598/1	46762

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1949	See 6597-1	6598/2	46763
			1949	See 6597-1	6598/3	46764
			1949	See 6597-1	6599	46765
			1949	Mockup of coupler & bolster; 6600-6604 a series	6600	46766
			1949	See 6600	6602	46767
			1949	See 6600	6603	46768
			1949	See 6600	6604	46769
			1949	Closeup of coupler pocket; see 6610	6609	46773
			1949	See 6609	6610	46774
			1949	Shop scene car end press	6611	46777
			1949	Shop scene car end press	6612	46778
			1949	Car side test piece; 6613-6616 a series	6613	46779
			1949	Car side test piece; see 6613	6614	46780
			1949	Workman test car side; see 6613	6615	46781
			1949	See 6613	6616	46782
			1949	Paint test piece; 6617-6626 a series	6617	46783
			1949	See 6617	6618	46784
			1949	See 6617	6619	46785
			1949	See 6617	6620	46786
			1949	See 6617	6621	46787
			1949	See 6617	6622	46788
			1949	See 6617	6623	46789
			1949	See 6617	6624	46790
			1949	See 6617	6624A	46791
			1949	See 6617	6625	46792
			1949	See 6617	6626	46793
			1949	Steps in fabricating coupler yoke	6636	46803
			1949	Roof section	6637	46804
			1950	Car side, testing	6640	46807
			1950	Elec. weld repair; 6641-6644 a series	6641	46871
			1950	See 6641	6642	46872
			1950	See 6641	6643	46873
			1950	See 6641	6644	46874
			1950	Paint test panel	6645	46875



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1950	Coupler yoke	6647	46877
			1950	Car frame test pieces; 6652-6654 a series	6652	46882
			1950	See 6652	6653	46883
			1950	See 6652	6654	46884
			1950	Car side test panel	6655	46885
			1950	Int. lumber shed #57 looking north damaged by wind	6656	46887
			1950	Int. lumber shed #57 looking south damaged by wind	6657	46886
			1950	Ext. lumber shed #58 damaged by wind	6658	46888
		PS-2-1	1950	Car sides on flat car paint test; 6664-6671 series	6664	46889
			1950	See 6664	6665	46890
			1950	See 6664	6666	46891
			1950	See 6664	6667	46892
			1950	See 6664	6668	46893
			1950	See 6664	6669	46894
			1950	See 6664	6670	46895
			1950	See 6664	6671	46896
Box			1950	Int. Penna RR. car 174800 blt. 12-6-49; not Pullman	6672	46897
			1950	Group of workers repairing insulation	6677	46902
			1950	Gondola load of brake beams consigned to Harry Fleming	6680	46905
			1950	Welded car sides on flat car; 6691-6698 a series	6691	46916
			1950	See 6691	6692	46917
			1950	See 6691	6693	46918
			1950	See 6691	6694	46919
			1950	See 6691	6695	46920
			1950	See 6691	6696	46921
			1950	See 6691	6697	46922
			1950	See 6691	6698	46923
			1950	Test pieces, methods for sealing floor to side sill; 6705-6709 a series	6705	46930
			1950	See 6705	6706	46931
			1950	See 6705	6707	46932
			1950	See 6705	6708	46933
			1950	See 6705	6709	46934
			1950	Flooring test piece with "Flint Cote" 6719--6721 ser. 6719	6719	46944

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1950	See 6719	6720	46945
			1950	See 6719	6721	46946
			1950	Trigger mechanism of sheet metal press	6722	46947
			1950	Underside of stamping mill; 6723-6725 a series	6723	46948
			1950	See 6723	6724	46949
			1950	See 6723	6725	46950
			1950	Model room layout of H&B plant; group of school teachers looking on	6726	46951
			1950	Uncoupling rod bracket; 6727-6729 a series	6727	46952
			1950	See 6727	6728	46953
			1950	See 6727	6729	46954
			1950	Forklift unloading car	6779	47005
			1950	Int. closeup of patent frame member; see 6805	6804	47030
			1950	Int. bottom view of 6804	6805	47031
	Box		1950	Side door interior	6807	47033
	Box		1950	Side door exterior	6808	47034
	Box		1950	Side door interior	6809	47035
	Box		1950	Side door exterior	6810	47036
			1950	Electric power transformers; 6814-6818 a series	6814	47039
			1950	See 6814	6815	47040
			1950	See 6814	6816	47041
			1950	See 6814	6817	47042
			1950	See 6814	6818	47043
			1950	Shop scene car end press; see 6833	6832	47049
			1950	Shop scene car end press; see 6832	6833	47050
			1950	Int. of box car, damaged shipment of drums	6834	47051
			1950	Mockup of uncoupling rod; see 6841	6840	47057
			1950	Mockup of uncoupling rod bracket; see 6840	6841	47058
			1950	Damage to dunnage in car; see 6844	6843	47060
			1950	Damage to dunnage in car; see 6843	6844	47061
			1950	Automatic nailer shop scene 6845-6852 a ser. of ops.	6845	47062
			1950	See 6845	6846	47063
			1950	See 6845	6847	47064
			1950	See 6845	6848	47065



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1950	See 6845	6849	47066
			1950	See 6845	6850	47067
			1950	See 6845	6851	47068
			1950	See 6845	6852	47069
			1950	Loading strap anchors	6856	47073
			1950	Strap anchor	6872	47089
			1950	Roller, table extension	6873	47090
			1950	6881-6884 a series	6881	47098
			1950	See 6881	6882	47099
			1950	See 6881	6883	47100
			1950	See 6881	6884	47101
			1950	Int. PRR gondola load of axles; 6892-6894 series	6892	41105
			1950	See 6892	6893	47106
			1950	See 6892	6894	47107
			1950	Shop scene fabricating roof; 6910-6194 a series	6910	47123
			1950	See 6910	6911	47124
			1950	See 6910	6912	47125
			1950	See 6910	6913	47126
			1950	See 6910	6914	47127
			1950	Pile of hand brake parts	6915	47128
			1950	Pile of hand brake parts	6916	47129
			1951	Ends test pieces shown in 6924; 6923-6924 a series	6923	47137
			1951	See 6923	6924	47138
			1951	Shop scene sand blasting parts; 6929-6932 series	6929	47143
			1951	See 6929	6930	47144
			1951	See 6929	6931	47145
			1951	See 6929	6932	47146
			1951	End section of wood beam, metal supports	6933	47147
			1951	Closeup of brake gear & coupler 3/4 side; see 6935	6934	47148
			1951	Closeup of brake gear & coupler, end; see 6934	6935	47149
			1951	See 6933	6945	47159
			1951	See 6945	6949	47163
			1951	Test weld	6950	47164
			1951	Small parts press; see 6956	6955	47169

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1951	See 6955	6956	47170
			1951	Int. Erie gondola with damaged sheet steel load	6959	47173
			1951	Damaged sheet steel; see 6959	6960	47174
			1951	Automatic nailer; 6961-6963 & 6966-6969 a series	6961	47175
			1951	See 6961	6962	47176
			1951	See 6961	6963	47177
			1951	Electric spot welder on traveling crane; see 6965	6964	47178
			1951	See 6964	6965	47179
			1951	See 6961	6966	47180
			1951	See 6961	6967	47181
			1951	See 6961	6968	47182
			1951	See 6961	6969	47183
			1953	Side panel	7001	48094
			1951	Repair weld; 7021-7024 a series	7021	47235
			1951	See 7021	7022	47236
			1951	See 7021	7023	47237
			1951	See 7021	7024	47238
			1951	Int. end; 7025-7028 a series	7025	47239
			1951	See 7025	7026	47240
			1951	See 7025	7027	47241
			1951	See 7025	7028	47242
			1951	Repair weld; see 7044	7043	47257
			1951	See 7043	7044	47258
			1954	Bessemer steel test bars	7061	47275
			1951	?	7091	47298
			1951	Test weld	7101	47308
			1951	Closeup of roof joint	7104	47311
			1951	Closeup of riveted roof section	7105	47312
			1961	Shop scene welding jig; 7116-7119 a series	7116	47321
			1961	See 7116	7117	47322
			1961	See 7116	7118	47323
			1961	See 7116	7119	47324
			1951	Car body wedges	7123	47328
			1951	General view of frame shop; see 7134	7133	47338



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1951	See 7133	7134	47339
			1951	Elec. welding jig; 7145-7148 a series	7145	47345
			1951	See 7145	7146	47346
			1951	See 7145	7147	47347
			1951	See 7145	7148	47348
			1951	Paint spray equipment	7149	47349
			1951	Strap anchors in test piece	7150	47350
			1951	Closeup of strap anchor; see 7150	7151	47351
			1951	Back side of strap anchor; see 7150	7152	47352
			1951	Welding fixture; see 7154	7153	47353
			1951	See 7153	7154	47354
			1951	Closeup of car int. side	7155	47355
			1951	7249-7253 a series	7249	47449
			1951	See 7249	7250	47450
			1951	See 7249	7251	47451
			1951	See 7249	7252	47452
			1951	See 7249	7253	47453
			1951	Awards dinner; 7262-7267 a series	7262	47462
			1951	See 7262	7263	47463
			1951	See 7262	7264	47464
			1951	See 7262	7265	47465
			1951	See 7262	7266	47466
			1951	See 7262	7267	47467
			1952	Shop scn. fixture for chking. straight line of frame	7294	47487
			1952	Shop scene laminating press; 7297-7299 a series	7297	47490
			1952	See 7297	7298	47492
			1952	See 7279	7299	47491
			1952	Ext. side door	7302	47495
			1952	Int. side door; see 7302	7303	47496
Box			1952	Int. side wall; ;7304-7321 a series installing & demonstrating strap anchors	7304	47497
			1953	Int. side wall; see ;7304	7305	47498
			1952	Int.; see 7304	7306	47499
			1952	See 7304	7307	47500

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1952	Int.; see 7304	7308	47501
			1952	Anchor bars; see 7304	7309	47502
			1952	Int. finished installation; see 7304	7310	47503
			1952	Worker installing straps; see 7304	7311	47504
			1952	Int.; see 7304	7312	47505
			1952	Similar to 7311; see 7304	7313	47506
			1952	Detail of anchor & strap	7314	47507
			1952	Similar to 7311; see 7304	7315	47508
			1952	Similar to 7311; see 7304	7316	47509
			1952	Similar to 7311; see 7304	7317	47510
			1952	Similar to 7311; see 7304	7319	47511
			1952	Detail of anchor & strap; see 7304	7320	47512
			1952	Anchor bar; see 7304	7321	47513
			1952	Ext. door; see 7323	7322	47514
			1952	Int. door; see 7322	7323	47515
			1952	See 7325-26	7324	47516
			1952	See 7324-26	7325	47517
			1952	See 7324-25	7326	47518
			1952	Shop scene fabricating frames; 7327-7330 a series "A" Building west end	7327	47519
			1952	Shop scene; see 7327 "A" bldg. west end	7328	47520
			1952	Shop scene; see 7327 "A" bldg.	7329	47521
			1952	Shop scene; see 7327 "A" bldg. west end	7330	47522
			1952	Shop scene flame cutter; 7334-7337 a series	7334	47526
			1952	Shop scene flame cutter; see 7334	7335	47527
			1952	Shop scene flame cutter; see 7334	7336	47528
			1952	Shop scene flame cutter; see 7334	7337	47529
			1952	Frame member	7363	47555
			1952	Mockup of side door latch; 7364-7367 a series	7364	47556
			1952	See 7364	7365	47557
			1952	See 7364	7366	47558
			1952	See 7364	7367	47559
			1952	Test pieces forgings	7412	47601
			1952	Lumber & timber storage; 7465-7470 a series	7465	47652



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1952	See 7465	7466	47653
			1952	See 7465	7467	47654
			1952	Outside timber storage; see 7465	7468	47655
			1952	See 7465	7469	47656
			1952	See 7465	7470	47657
	Box		1952	Closeup of lower half end of car	7488	47675
	Box		1952	See 7488	7489	47676
			1952	Machine for roof beam sealing; 7524-7533 a series	7524	47711
			1952	See 7524	7525	47712
			1952	See 7524	7526	47713
			1952	See 7524	7527	47714
			1952	See 7524	7528	47715
			1952	See 7524	7529	47716
			1952	See 7524	7530	47717
			1952	See 7524	7531	47718
			1952	See 7524	7532	47719
			1952	See 7524	7533	47720
			1952	Mockup of center door latch; see 7538	7537	47724
			1952	See 7537	7538	47725
			1952	Details of coupler & uncoupling lever; 7539-7544 ser.	7539	47726
			1952	See 7539	7540	47727
			1952	See 7539	7541	47728
			1952	See 7539	7542	47729
			1952	See 7539	7543	47730
			1952	See 7539	7544	47731
			1952	Card Board	7557	47739
			1952	Demonstration of combination uncoupling lever & step; 7559-7562 a series	7559	47741
			1952	See 7559	7560	47742
			1952	See 7559	7561	47743
			1952	See 7559	7562	47744
			1952	Section of bolster beam	7563	47745
			1952	Pullman Company booth an open house at Michigan City; 7564-7583 a series	7564	47746

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1952	See 7564	7565	47747
			1952	See 7564	7566	47748
			1952	See 7564	7567	47749
			1952	See 7564	7568	47750
			1952	See 7564	7569	47751
			1952	See 7564	7570	47752
			1952	See 7564	7571	47753
			1952	See 7564	7572	47754
			1952	See 7564	7573	47755
			1952	See 7564	7574	47756
			1952	See 7564	7575	47757
			1952	See 7564	7576	47758
			1952	See 7564	7577	47759
			1952	See 7564	7578	47760
			1952	See 7564	7579	47761
			1952	See 7564	7580	47762
			1952	See 7564	7581	47763
			1952	See 7564	7582	47764
			1952	See 7564	7583	47765
			1952	Drilling template; see 7586	7585	47766
			1952	See 7585	7586	47767
			1952	See 7590	7589	47770
			1952	Adding bolster section to frame; 7590-7592 a series	7590	47771
			1952	See 7590	7591	47772
			1952	Ext. of side door mockup; see 7593	7592	47773
			1952	Similar to 7592	7593	47774
			1952	Side door mockup; 7594-7597 a series	7594	47775
			1952	See 7594	7595	47776
			1952	See 7594	7596	47777
			1952	See 7594	7597	47778
	Box		1952	Instruction diagram for Signode grain door	7609	47790
			1952	Ext. of side door; 7610-7613 a series	7610	47791
			1952	Int. of side door	7611	47792
			1952	Int. of side door; see 7610	7612	47793



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
	Box		1952	Ext. of side door; see 7610	7613	47794
			1952	Test pieces, steel	7614	47795
			1952	Int. Azee tie anchors	7618	47799
			1952	Automatic welder; see 7620	7619	47800
			1952	See 7619	7620	47801
			1952	Broken metal clip	7630	47811
			1952	Stacks of roof sheets	7687	47864
			1952	Similar to 7687	7688	47865
			1952	Mockup use unknown; 7689-7696 a series	7689	47866
			1952	See 7689	7690	47867
			1952	See 7689	7691	47868
			1952	See 7689	7692	47869
			1952	See 7689	7693	47870
			1952	See 7689	7694	47871
			1952	See 7689	7695	47872
			1952	See 7689	7696	47873
			1953	Unidentified	7705	47882
			1953	Fixture use unknown	7738	47915
			1953	Fixture for holding draft gear lugs for welding	7755	47932
			1953	Damage to shipment of roof sheets; 7767-7773 ser.	7767	47944
			1953	See 7767	7768	47945
			1953	See 7767	7769	47946
			1953	See 7767	7770	47947
			1953	See 7767	7771	47948
			1953	See 7767	7772	47949
			1953	See 7767	7773	47950
			1953	Strength test bar stock; see 7777	7776	479534
			1953	See 7776	7777	47954
			1953	Section of car roof repair; 7779-7783 a series	7779	47955
			1953	See 7779	7780	47956
			1953	See 7779	7782	47957
			1953	See 7779	7783	47958
			1953	Int. gen. view of frame shop; 7813-7820 a series	7813	47987
			1953	Int. gen. view frame shop; see 7813	7814	47988

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1953	Int. gen. view frame shop; see ;7813	7815	47989
			1953	Int. gen. view frame shop; see 7813	7816	47990
			1953	Int. car erecting shop; see 7813	7817	47991
			1953	Int. car erecting shop; see 7813	7818	47992
			1953	Int. car erecting shop; see 7813	7819	47993
			1953	Int. car erecting shop; see 7813	7820	47994
			1953	Ext. of shop, damage to walls	7842	48016
			1953c.	Journal box frame	7843	48017
			1953c.	See 7843	7844	48018
	Hopper Covered		1953	Roof; see 7978	7977	48070
	Hopper Covered		1953	Roof; see 7977	7978	48071
			1953	Ext. hopper doors; 8071-8077 a series	8071	48112
			1953	Ext. hopper doors; see 8071	8072	48113
			1953	Ext. hopper doors open; see 8071	8073	48114
			1953	Ext. hopper doors open; see 8071	8074	48115
			1953	Ext. hopper doors open; see 8071	8075	48116
			1953	Builders plate; see 8071	8076	48117
			1953	Frame detail; see 8071	8077	48118
			1953	Closeup of truck axles in gondola; 8132-36 series	8132	48171
			1953	See 8132	8133	48172
			1953	See 8132	8134	48173
			1953	See 8132	8135	48174
			1953	See 8132	8136	48175
			1953	Gen. views of scrapping yard; 8149-8157 a series	8149	48188
			1953	See 8149	8150	48189
			1953	See 8149	8151	48190
			1953	See 8149	8152	48191
			1953	See 8149	8153	48192
			1953	See 8149	8154	48193
			1953	See 8149	8155	48194
			1953	See 8149	8156	48195
			1953	See 8149	8157	48196
			1953	Load of grates in gondola	8160	48199
			1953	Similar to 8160	8161	48200



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
	Roller		1953	Carload of tongue & groove flooring	8182	48221
			1953	See 8182	8183	48222
			1953	See 8182	8184	48223
			1954	F. M. Hess multi ball bearing roller	8216	48253
			1954	Worker receiving award	8234	48268
			1954	Bar bending fixture	8247	48281
			1954	See 8247	8248	48282
			1954	See 8247	8249	48283
			1954	See 8247	8250	48284
			1954	See 8247	8251	48285
			1954	See 8247	8252	48286
			1954	Broken dunnage	8253	48287
			1954	Broken dunnage	8254	48288
			1954	Car door packed for shipment	8255	48289
			1954	Same as 8255	8256	48290
			1954	Repairing car end stamping mill	8259	48293
	Box		1954	Straight side car press	8260	48294
			1954	Corner caps	8298	48331
			1954	Damaged car section (see 8373-8375)	8373	48342
			1954	See 8371	8372	48343
			1954	See 8371	8383	48344
			1954	See 8371	8374	48345
			1954	See 8371	8375	48346
			1954	Shop scene, car end stamping	8376	48347
			1954	See 8376	8377	48348
			1954	See 8376	8378	48349
			1954	See 8376	8379	48350
			1954	Single axle road trailer on flat car	8387	48358
			1954	Tie down of trailer; see 8387	8388	48359
			1954	4 men posing w/line of box cars	8404	48375
			1954	Shop scene gang drill for wood beams	8405	48376
			1954	Shop scene cut off saw	8406	48377
			1954	Welds closeup	8407	48378
			1954	Welds closeup	8408	48379

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1954	Welds closeup	8409	48380
			1954	Welds closeup	8414	48381
			1954	Welds closeup	8415	48382
			1954	Welds closeup	8416	48383
			1954	Worker washing car; 8418-8423 a series	8418	48384
			1954	See 8418	8419	48385
			1954	See 8418	8420	48386
			1954	See 8418	8421	48387
			1954	See 8418	8422	48388
			1954	See 8418	8423	48389
			1954	Method of attaching T&G floor to frame	8437	48401
			1954	See 8437	8438	48402
			1954	Press	8439	48403
			1954	Press	8440	48404
			1954	Distant view of plant	8455	48413
			1954	Foliage near plant	8456	48414
			1954	Truck and houses?	8457	48415
			1954	1954 Chevy station wagon	8458	48416
			1954	1953 Chevy pickup truck	8459	48417
			1954	1954 Chevy dump truck	8460	48418
			1954	1954 Chevy stake body truck	8461	48419
			1954	Scrapping yard breaking up hopper car; 8462-81 ser.	8462	48420
			1954	See 8462	8463	48421
			1954	See 8462	8464	48422
			1954	See 8462	8465	48423
			1954	See 8462	8466	48424
			1954	See 8462	8467	48425
			1954	See 8462	8468	48426
			1954	See 8462	8469	48427
			1954	See 8462	8470	48428
			1954	See 8462	8471	48429
			1954	See 8462	8472	48430
			1954	See 8462	8473	48431
			1954	See 8462	8474	48432



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1954	See 8462	8475	48433
			1954	See 8462	8476	48434
			1954	See 8462	8477	48435
			1954	See 8462	8478	48436
			1954	See 8462	8479	48437
			1954	See 8462	8480	48438
			1954	See 8462	8481	48439
	Box		1954	Inspecting sample car; 8496-8500 a series	8496	48454
	Box		1954	See 8496	8497	48455
	Box		1954	See 8496	8498	48456
	Box		1954	See 8496	8499	48457
	Box		1954	See 8496	8500	48458
	Box		1954	Clamps for compartmentizer barriers	8526	48483
			1954	Workers welding truck frame	8552	48509
			1954	See 8552	8553	48510
			1955	Shop scn. assembly clearing panel press; 8593-8607 ser.	8593	48550
			1955	See 8593	8594	48551
			1955	See 8593	8595	48552
			1955	See 8593	8596	48553
			1955	See 8593	8597	48554
			1955	See 8593	8598	48555
			1955	See 8593	8599	48556
			1955	See 8593	8600	48557
			1955	See 8593	8601	48558
			1955	See 8593	8602	48559
			1955	See 8593	8603	48650
			1955	See 8593	8604	48561
			1955	See 8593	8605	48562
			1955	See 8593	8606	48563
			1955	See 8593	8607	48564
			1955	See 8593	8608	48565
			1955	Worker operating air power rivet machine	8610	48566
			1955	Unidentified (check Car Bldrs. Dict.)	8624	48581
			1955	Journal box packing; 8625-8628 a series	8625	48582

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1955	Working packing journal; see 8625	8626	48583
			1955	See 8625	8627	48584
			1955	See 8625	8628	48585
			1955	Parts of Shaw crane	8629	48586
			1955	Cement pump	8632	48589
			1955	Door for compartmentized car; 8633-8650 a series	8633	48590
			1955	Same as 8633	8634	48591
			1955	Door locking device; see 8633	8635	48592
			1955	See 8633	8636	48593
			1955	See 8633	8637	48594
			1955	See 8633	8638	48595
			1955	See 8633	8639	48596
			1955	See 8633	8640	48597
			1955	See 8633	8641	48598
			1955	See 8633	8642	48599
			1955	See 8633	8643	48600
			1955	See 8633	8644	48601
			1955	See 8633	8645	48602
			1955	See 8633	8646	48603
			1955	See 8633	8647	48604
			1955	See 8633	8648	48605
			1955	See 8633	8649	48606
			1955	See 8633	8650	48607
			1955	Int. compartmentizer locking device	8654	48609
			1955	See 8654	8655	48610
			1955	Oxweld unit; 8677-8680 a series	8677	48631
			1955	See 8677	8678	48632
			1955	See 8677	8679	48633
			1955	See 8677	8680	48634
			1955	8682-8715 a series details of piggyback cars	8682	48636
			1955	See 8682	8683	48637
			1955	See 8682	8684	48638
			1955	See 8682	8685	48639
			1955	See 8682	8686	48640



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1955	See 8682	8687	48641
			1955	See 8682	8688	48642
			1955	See 8682	8689	48643
			1955	See 8682	8690	48644
			1955	See 8682	8691	48645
			1955	See 8682	8692	48646
			1955	See 8682	8693	48647
			1955	See 8682	8694	48648
			1955	See 8682	8696	48650
			1955	See 8682	8697	48651
			1955	See 8682	8698	48652
			1955	See 8682	8699	48653
			1955	See 8682	8700	48654
			1955	See 8682	8701	48655
			1955	See 8682	8702	48656
			1955	See 8682	8703	48657
			1955	See 8682	8704	48658
			1955	See 8682	8705	48659
			1955	See 8682	8706	48660
			1955	See 8682	8707	48661
			1955	See 8682	8708	48662
			1955	See 8682	8709	48663
			1955	See 8682	8710	48664
			1955	See 8682	8711	48665
			1955	See 8682	8712	48666
			1955	See 8682	8713	48667
			1955	See 8682	8714	48668
			1955	See 8682	8715	48669
			1955	Gate for compartmentized car	8716	48670
			1955	See 8716	8717	48671
			1955	See 8716	8718	48672
			1955c.	Truck side bearing stuck; 8744-8749 a series	8744	48698
			1955c.	Truck side bearing stuck; see 8744	8745	48699
			1955c.	Truck side bearing stuck; see 8744	8746	48700

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1955c.	See 8744	8747	48701
			1955c.	See 8744	8748	48702
			1955c.	See 8744	8749	48703
			1955	Preparing & installing hopper door guide; 8766-77 ser.	8766	48720
			1955	See 8766	8767	48721
			1955	See 8766	8768	48722
			1955	See 8766	8769	48723
			1955	See 8766	8770	48724
			1955	See 8766	8771	48725
			1955	See 8766	8772	48726
			1955	See 8766	8773	48727
			1955	See 8766	8774	48728
			1955	See 8766	8775	48729
			1955	See 8766	8776	48730
			1955	See 8766	8777	48731
	Box		1955	Int. no floor or sheathing; 8913-8916 a series	8913	48844
			1955	See 8913	8914	48845
			1955	See 8913 int.	8915	48846
			1955	See 8913	8916	48847
			1955	Spot welding fixture	8919	48850
			1955	Spot welding fixture	8920	48851
			1955	Spot welder; 8921-8923 a series	8921	48852
			1955	See 8921	8922	48853
			1955	See 8921	8923	48854
			1955	Erecting scaffold in side car preparing to paint; 8924-8932 a series	8924	48855
			1955	See 8924	8925	48856
			1955	See 8924	8926	48857
			1955	See 8924	8927	48858
			1955	See 8924	8928	48859
			1955	See 8924	8929	48860
			1955	See 8924	8930	48861
			1955	See 8924	8931	48862
			1955	See 8924	8932	48863



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1955	Both sections of draft gear cut up; 8948-8951 series	8949	48879
						48880
			1955	See 8948	8950	48881
			1955	See 8948	8951	48882
			1955	Section of roof; 8953-8956 a series	8953	48884
			1955	See 8953	8954	48885
			1955	See 8953	8955	48886
			1955	See 8953	8956	48887
			1955	Mockup of brake system; see 8976	8975	48906
			1955	Mockup of brake system; see 8975	8976	48907
			1955	Battery charger; see 8988	8987	48917
			1955	Battery charger; see 8987	8988	48918
			1956	Closeup of 9010; see 9007; 9007-9010 a series	9007	48937
			1956	Closeup of 9010; see 9007	9008	48938
			1956	Closeup of 9010; see 9007	9009	48939
			1956	Side panel; see 9007	9010	48940
			1956	Model layout for shop structures; see 9012	9011	48941
			1956	See 9011	9012	48942
			1956	Portable fixture, use unknown; see 9014	9013	48943
			1956	See 9013	9014	48944
			1956	Test lab cutting weld for test	9015	48945
			1956	Bolster plates	9023	48953
			1956	Power drive for unidentified machine; 9032-9034 ser.	9032	48962
			1956	See 9032	9033	48963
			1956	See 9032	9034	48964
			1956	Paint test plates; 9035-9038 a series	9035	48965
			1956	See 9035	9036	48966
			1956	See 9035	9037	48967
			1956	See 9035	9038	48968
			1956	Running boards	9045	48975
			1956	Welding fixture; see 9057	9056	48985
			1956	Welding fixture; see 9056	9057	48986
			1956	Hydraulic car tilting jack; see 9059	9058	48987
			1956	See 9058	9059	48988

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1956	Car side panel; 9063-9068 a series	9063	48992
			1956	Car side panel; see 9063	9064	48993
			1956	Car side panel; see 9063	9065	48994
			1956	Car side panel; see 9063	9066	48995
			1956	Car side panel; see 9063	9067	48996
			1956	Car side panel; see 9063	9068	48997
			1956	Axle finishing shop gen. view int.; see 9081	9080	49007
			1956	Axle finishing shop; see 9080	9081	49008
			1956	Testing cement car hopper door, trouble with closing; 9082-9098 a series	9082	49009
			1956	See 9082	9083	49010
			1956	See 9082	9084	49011
			1956	See 9082	9085	49012
			1956	See 9082	9086	49013
			1956	See 9082	9087	49014
			1956	See 9082	9088	49015
			1956	See 9082	9089	49016
			1956	See 9082	9090	49017
			1956	See 9082	9091	49018
			1956	See 9082	9092	49019
			1956	See 9082	9093	49020
			1956	See 9082	9094	49021
			1956	See 9082	9095	49022
			1956	See 9082	9096	49023
			1956	See 9082	9097	49024
			1956	See 9082	9098	49025
			1956	Hopper door latch	9101	49028
			1956	Car moving electric winch	9144	49071
			1956	Hopper door frame; 9147-9154 a series	9147	49074
			1956	See 9147	9148	49075
			1956	See 9147	9149	49076
			1956	See 9147	9150	49077
			1956	See 9147	9151	49078
			1956	See 9147	1952	49079



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
			1956	See 9147	9153	49080
			1956	See 9147	9154	49081
			1956	Gen. view of wood shop; cut of machine for flooring; 9169-9173 a series	9169	49096
			1956	See 9169	9170	49097
			1956	See 9169	9171	49098
			1956	See 9169	9172	49099
			1956	See 9169	9173	49100
			1956	Sectioned test piece	9186	49113
			1956	Unloading lumber; this series shows preparing flooring from unloading to finished product; 9189-9198 a series	9189	49116
			1956	Unloading; see 9189	9190	49117
			1956	Feeding into 4-sided planer; see 9189	9191	49118
			1956	Cutoff saw; see 9189	9192	49119
			1956	Cutoff saw; see 9189	9193	49120
			1956	Tenon machine; see 9189	9194	49121
			1956	Tenon machine; see 9189	9195	49122
			1956	Tenon machine; see 9189	9196	49123
			1956	Feeding into & groove machine; see 9189	9197	49124
			1956	Adjustable cut feed table; see 9189	9198	49125
			1956	Machine? 9215-9217 a series	9215	49137
			1956	See 9215	9216	49138
			1956	See 9215	9217	49139
				Electric drill applied to device used in car bldg.	2265	43641
5276			1941	Close up of coupler	3261	44348
5276	Box		1941	See 3261	3262	44349
5276	Box		1941	Opp. of 3261	3263	44350
5452	Hopper Car		1929	Interior, end view	1691	43369
5452	Car truck		1929	End view	1692	43370
5452	Car truck		1929	Side view	1693	43371
5452	Hopper		1929	Side view under construction	1694	43372
5452	Hopper		1929	3/4 end under construction	1695	43373
5584	(B&LE, CGW & UP cars this lot)		1938	Welded draft lugs and sills	2294	43658
5584			1938	3/4 end welded frame bottom	2321	43680

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
5584			1938	Body bolster diaphragm	2324	43681
5584			1938	Interior side door	2325	43681
5584			1938	Exterior side door	2326	43683
5584			1938	Exterior side sheet at door	2333	43689
5584			1938	Exterior side sheet at door	2334	43690
5584			1938	Interior side sheet	2335	43691
5584			1938	Exterior side door only	2336	43692
5609	Flat		1940	Ext. hand brake end	2652	43943
5609	Flat		1940	Ext. end view	2740	44016
5609	Flat		1940	3/4 frame at end	2741	44017
5615	Box		1940	Int. no floor or side sheathing	2732	44008
5615	Box		1940	Int. opposite of 2732	2733	44009
5615	Box		1940	Int. corner, see 2732	2734	44010
5615	Box		1940	Int. finished, see 2732	2735	44011
5615			1940	Coupler pocket	2760	44035
5615			1940	Coupler pocket	2761	44036
5615			1940	Coupler pocket	2762	44037
5615	Box		1940	Ext. 3/4 frt. corner, deflection test, car loaded 202100 lbs.	2898	44127
5615	Box		1940	Same as 2898, different view	2899	44128
5629	Box		1940	Interior	2804	44070
5629			1940	Diagonal brace at corner	2903	44132
5629	Box		1940	Diagonal brace welds	2904	44133
5629	Box		1940	Diagonal side brace	2905	44134
5631	Box		1940	Interior	2822	44083
5632	Box		1940	Interior	2838	44098
5631	Shop scene		1940	Welding cross bearing diaphragms	2790	44059
5631			1940	Different view of 2790	2791	44060
5631			1940	Different view of 2790	2792	44061
5631			1940	Different view of 2790	2793	44062
5631-	Shop scene		1940	Welding body bolster	2809	44071
5632						
5631-5632			1940	Different view of 2809	2810	44072
5631-5632			1940	Different view of 2809	2811	44073



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
5652	Box	1	1941	3/4 end inverted frame s/s	3053	44268
5652	Box		1941	Int. no floor or sheathing	3054	44269
5652	Box		1941	3/4 side frame s/s	3055	44270
5679			1941	3/4 front, truck	3214	44302
5679			1941	Front, truck	3215	44303
5741			1943	Truck 3/4 front	3926	44676
5832			1946	Coupler pocket	5151	45448
5832	Box		1946	Int. patented hinged lining	5161	45459
5832			1946	Int. end patented; 5161-5165 a series	5162	45455
5832			1946	See 5162	5163	45456
5832			1946	See 5162	5164	45457
5832			1946	See 5162	5165	45458
5896			1953	Int. end repair work; 8146-8148 a series	8146	48185
5896			1953	See 8146	8147	48186
5896			1953	See 8146	8148	48187
5898	Refrigerator		1947	Ext. at side door	5449	45702
5898	Refrigerator		1947	Ext. side ladder	5452	45705
5898	Refrigerator		1947	Ext. 3/4 end	5453	45706
5943			1949	Test of hatch screen	6269	46444
5943			1949	See 6269	6270	46443
5943			1949	See 6269	6271	46446
5943			1949	See 6269	6272	46447
5943			1949	See 6269	6273	46448
5943			1949	See 6269	6274	46449
5950	Box (MKT, CP & LS&BC blt. on this lot)		1949	Side sheets test pieces welding techniques; 6499-6506 a series	6499	46662
5950	Box		1949	Ext. side; see 6499	6500	46663
5950	Box		1949	Side sheets; see 6499	6501	46664
5950	Box		1949	Ext. side; see 6499	6502	46665
5950	Box		1949	Side sheets; see 6499	6503	46666
5950	Box		1949	Ext. side; see 6499	6504	46667
5950	Box		1949	Ext. side sheets; see 6499	6505	46668
5950	Box		1949	Ext. side no markings	6506	46669
8036	Box		1952	Frame 3/4 front	7510	47697

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
8036	Box		1952	Frame 3/4 front inverted	7511	47698
8036	Box		1952	Ext. side door	7512	47699
8036	Box		1952	Ext. side door	7513	47700
8036	Box		1952	Ext. lower corner side door opening; 7516-7519 ser.	7516	47703
8036	Box		1952	Ext. lower corner side door opening; see 7516	7517	47704
8036	Box		1952	Int. lower corner side door opening; see 7516	7518	47705
8036	Box		1952	Int. lower corner side door opening; see 7516	7519	47706
8073	Hopper Covered		1952	Ext. 3/4 front roof	7625	47806
8098B & 8121	Box Compartment		1952	Int. unfinished	7631	47812
8098B & 8121	Box Compartment		1952	Int. unfinished	7632	47813
8098B & 8121	Box Compartment		1952	Int. end	7633	47814
8098B & 8121	Box Compartment		1952	Int.	7634	47815
8098B & 8121	Box Compartment		1952	Int.	7635	47816
8098B & 8121	Box Compartment		1952	Int.	7636	47817
8098B & 8121	Box Compartment		1952	Int.	7637	47818
8121	Box Compartment		1952	Compert. door side top latch closed; 7638-7645 ser.	7638	47819
8121	Box Compartment		1952	Compt. door side top latch open; see 7638	7639	47820
8121	Box Compartment		1952	See 7638	7640	47821
8121	Box Compartment		1952	See 7638	7641	47822
8121	Box Compartment		1952	See 7638	7642	47823
8121	Box Compartment		1952	See 7638	7643	47824
8121	Box Compartment		1952	See 7638	7644	47825
8121	Box Compartment		1952	See 7638	7645	47826
8121	Box Compartment		1952	Rail & trolley for sliding door	7646	47827
8121	Box Compartment		1952	Upper door pivot	7647	47828
8121	Box Compartment		1952	Lower door pivot	7648	47829
8121	Box Compartment		1952	Lower door latch	7649	47830



LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
8121	Box Compartment		1952	Similar to 7649	7650	57831
8098B & 8121	Box Compartment		1952	Int.	7651	47832
R.8166			1953	Damaged cross member Repair Order 8166	8180	48219
R.8166			1953	See 8180	8181	48220
R.8166			1953	Ext. 3/4 side no car body	8185	48224
8222			1955	Gondola load of car ends	8750	48704
JO14022	Box, Auto		1940	Job 14022, int. auto lift	2823	44084
JO14022	Box, Auto		1940	Different view of 2823	2824	44085
JO14022	Box, Auto		1940	Different view of 2823	2825	44086
JO14022	Box, Auto		1940	Different view of 2823	2826	44087
JO14022	Box, Auto		1940	Different view of 2823	2827	44088
JO14470			1946	Damaged car parts; note 5022-5027 a series	5022	45337
JO14470			1946	See 5022	5023	45338
JO14470			1946	See 5022	5024	45339
JO14470			1946	See 5022	5025	45340
JO14470			1946	See 5022	5026	45341
JO14470			1946	See 5022	5027	45342
JO14470			1946	See 5022	5034	45338
JO14470			1946	See 5022	5024	45339
JO14470			1946	See 5022	5025	45340
JO14470			1946	See 5022	5026	45341
JO14470			1946	See 5022	5027	45342
JO35989			1952	Frame 3/4 front	7292	47485
JO35989			1952	Frame 3/4 side	7293	47486
JO36935			1953	Frame 3/4 front; see 7754	7753	47930
JO36935			1953	Frame 3/4 front inverted; see 7713	7754	47931
JO37080			1953	Installing loading straps	7713	47890
JO37080	Box		1953	See 7713	7720	47897
JO37080	Box		1953	See 7713	7721	47898
JO38071	Hopper		1954	3/4 front being rebuilt	8361	48332
JO38071	Hopper		1954	Body frame 3/4 side	8362	48333
JO38071	Hopper		1954	Int. hopper doors	8363	48334
JO38071	Hopper		1954	Body frame 3/4 side	8364	48335

LOT NO.	TYPE	CAR NO.	DATE OF PHOTO	REMARKS	NEG. NO.	FRAME NO.
HASKELL AND BARKER CAR CO. (continued)						
JO38760	Box		1954	Car end for repair	8296	48329
JO38760	Box		1954	Same as 8296	8297	48330
JO40654			1957	Empty gondola; see 9284	9291	49144
JO40654			1957	Top view car sides in gondola; see 9284	9292	49145
JO40754			1957	Dunnage in empty gondola; see 9284	9289	49143
JO40755			1957	Car sides in gondola for JO40744; 9284-9292 ser.	9284	49142

## PORTRAITS

Carl Lochner			1947		5668A	45925
John Ingles			1947	At South Louisville Shops	5668B	45926





## KEY TO LOT NUMBERS

LOT NO.	ASSIGNED TO (railroad or other)	CAR NOS.	REMARKS	DATE
5098B for 8021	Western Pacific	21164	Box Compartment	1933
5276	Haskell & Barker		Unidentified	1941
5386	Northern Pacific			1926
5411	Illinois Central	401452	Gondola steel/wood	1926
5413	Illinois Central	16285	Auto Furniture	1926
5429	St. Louis & San Francisco	88769	Hopper	1928
5430	St. Louis & San Francisco	151261	Box Auto	1928
5431	Pacific Fruit Express	37034		1928
5434	Chicago St. Paul Minneapolis & Omaha	59759	Flat car 46'0"	1928
5436	ACME Fast Freight	1002	Container Car	1925
5438	Northern Refrigerator Car Co.	120		1929
5446	Chicago & North Western	50696	40'6" auto/furniture	1929
5447	Chicago & North Western	93799	Gondola Car	1929
5448	Western Pacific	13099		1929
5452	Haskell & Barker		Hopper Car (unident.)	1929
5453	Nacionales de Mexico	48496, 48458		1929
5459	Michigan Central	89999, 89150	Auto Furniture	1929
5468	Northern Refrigerator Car Co.	471	Refrig.	1929
5478	Pere Marquette	90991	Auto Furniture	1930
5481	Chicago & North Western	85000, 85998	Even numbers only	1929
5490	Pullman		PS1 Box, JO27604	
5483	Chicago Great Western		Hopper Car	1931
5485	Santa Fe Ref. Dispatch	31013	Ref.	1931
5488	Tennessee Coal Iron & RR. Co.	564, 560	Flat car steel frame	1934
5490	Chicago & Illinois Midland	68	Caboose	1931
5497	Commonwealth Cast Steel Underframe		P65X1000	1933
5498	Chicago Great Western	87886	Box, Flour/grain	1933
5499	New York Chicago & St. Louis	13399	Box	1934
5499	Chesapeake & Ohio	7299	Box	1934
5501	Central of Georgia	732	Hopper	1934
5502	Seaboard Air Line	17438	Box closed	1934
5503	Seaboard Air Line	58071	Closed Top Phosphate	1935
5504	Pullman Railroad Co.		Box Car	1935



LOT NO.	ASSIGNED TO (railroad or other)	CAR NOS.	REMARKS	DATE
5505	Nacionales de Mexico	60276	Box	1935
5507	Merchants Dispatch Ref. Line	2000		1936
5507	Pullman Co.	1500	Box	1936
5513	Norfolk Southern	25246	40' Box	1935
5514	Chesapeake & Ohio	6407	Automobile Car	1936
5525	Seaboard Air Line	58102	Phosphate Closed Top Hop	1936
5526	Pacific Fruit Express		Ref.	1936
5528	Chicago Great Western	3763	Flat Car	1936
5531	Chesapeake & Ohio	4526	Steel box	1936
5532	Chesapeake & Ohio	6384	Box Automobile	1936
5536	Minneapolis St. Paul & Sault Ste. Marie			
5537	Southern Pacific	33135	Steel Box	1936
5540	Central of Georgia	21640	Coal Steel double Hopper	1936
5541& 5544	Birmingham Southern	320	Steel sheathed 40' box	1936
5547	Atchison Topeka & Santa Fe			1937
5550	Northern Refrigerator Line	746, 779 (1942)	Refrig.	1938
5551	Seaboard Air Line	18647	Steel Sheathed Box	1937
5551	Louisiana & Arkansas	15073	Box 40'6"	1937
5554	Duluth Missabe & Northern	24711	Hopper Steel Ore	1937
5558	Tennessee Coal Iron & RR. Co.	2950	Hopper Coal	1938
5559	Tennessee Coal Iron & RR. Co.	3454		1938
5560	Illinois Central	166199	Automobile Box	1937
5561	Nashville Chattanooga & St.L.	18300	Box all steel	1937
5562	Chicago & Illinois Midland		Gondola	1937
5563	Chicago & Illinois Midland	6300	Hopper	1937
5564	Louisville & Nashville	61654	Hopper Steel Coal	1937
5565	Great Northern	50499	Box	1937
5567	New York Despatch Ref. Lines	8050	Refrig. ice bunker	1937
5568	Central of Georgia	4254	Box Steel	1937
5569	Minn. St. Paul & SSM	175098	Box Auto	1937
5570	Minn. St. Paul & SSM	66990	Gondola	1937
5572	Nacionales de Mexico	60891	Box Steel	1937
5575	Southern Rly.	306870	Box	1937
5576	Southern Rly.	316400	Gondola Steel fixed end	1937
5577	Warrior River Terminal	900	Box Steel	1937

iii.

LOT NO.	ASSIGNED TO (railroad or other)	CAR NOS.	REMARKS	DATE
5578	Seaboard Air Line	10080	Auto Furniture Box	1938
5581	Texas & Pacific	40199	Box Steel 41'	1937
5584	Pullman (XYZ RR.)		For exhibit	1938
5584	Chicago Great Western			1938
5584	Bessemer & Lake Erie	90171		1938
5584	Union Pacific	186021		1938
5585	Atchison Topeka & Santa Fe		Refrigerator	1938
5590	Southern	10060	Box	1938
5592	Southern	13096	Box	1939
5595	Birmingham Southern	1912	Hopper Steel	1939
5596	Birmingham Southern	250-259		1939
5598	New York Chicago & St. Louis	76007	Gondola (container)	1939
5599	Minn. St. Paul & SSM		Auto Box (Soo Lines)	1939
5600	Minn. St. Paul & SSM		Flat Car	1939
5601	Chesapeake & Ohio	134299	Hopper	1939
5602	Tennessee Coal Iron & RR. Co.	2986	Hopper	1939
5604	New York Chicago & St. Louis	20148		1940
5604A	New York Chicago & St. Louis	20080	Box	1940
5604B	Pere Marquette	84000	Box	1930
5604B	Pullman Railroad Co.	84000	Box	1940
5604C	Wheeling & Lake Erie	26000	Box	1940
5605	Erie	79134	Box	1940
5607	Illinois Central	71675	Hopper	1940
5608	Chicago & North Western	64347	Hopper	1940
5609	Haskell & Barker		Flat (unident.)	1940
5615	Haskell & Barker		(unident.)	
5616	Louisville & Nashville	63360	Hopper	1940
5617	Seaboard Air Line	11353	Auto/Furniture	1940
5621	Northern Pacific	15108	Box	1940
5621A	Detroit & Mackinac	2700	Box	1940
5624	New York Chicago & St. Louis	76010	Gondola	1940
5626	Central of Georgia	1314	Hopper Cement	1940
5626	Louisville & Nashville	38297	Hopper Cement	1940
5626	Nashville Chattanooga & St. Louis	49000	Hopper Cement	1940
5626A	Seaboard Air Line	319018	Hopper	1940



LOT NO.	ASSIGNED TO (railroad or other)	CAR NOS.	REMARKS	DATE
5626A	Southern Railway			1940
5626B	Virginian	3800	Hopper Cement	1940
5627	Chesapeake & Ohio	80497	Flat	1940
5629	Haskell & Barker			
5631	Haskell & Barker			1940
5632	Haskell & Barker			
5633	Gulf Mobile & Ohio	3200	Hopper Coal	1940
5634	New York Chicago & St. Louis	72483	Gondola	1940
5635	Chesapeake & Ohio	3542	Box	1940
5636	Illinois Central	20300	Box	1940
5637	Tennessee Coal Iron & RR. Co.	4161	Flat	1941
5638	Tennessee Central	3471	Gondola	1941
5639	Louisville & Nashville	99935	Box (end door)	1940
5641	Atlantic Coast Line	51637	Auto Box	1941
5645	Minn. St. Paul & SSM	17077	Box	1940
5645	Duluth South Shore & Atlantic			1940
5647	Pere Marquette	83735	Box	1941
5648	Southern Railway System	14500	Box	1941
5649	Wheeling & Lake Erie	24268	Box	1940
5650	Great Northern	47648	Box Steel Frame	1941
5652	Atchison Topeka & Santa Fe	143150		1941
5655	Tennessee Central	7995	Box	1941
5656	Louisville & Nashville	64535	Hopper	1941
5657	Louisville & Nashville	99815	Box staggered door	1941
5659	Seaboard Air Line	19153	Box	1941
5662	Northern Pacific	17177	Box	1941
5662A	Copper Range	4001	Box	1941
5664	Union Pacific	57059	Flat	1941
5668	Minn. St. Paul & SSM	5225	Flat	1941
5669	Tennessee Coal Iron & RR. Co.	2500	Hopper Coal	1941
5670	Tenn. Coal Iron & RR. Co.	5011	Hopper	1941
5675	Atchison Topeka & Santa Fe	143510	Box	1941
5676	Atchison Topeka & Santa Fe	10440	Box	1941
5679	Haskell & Barker			
5680	Louisiana & Arkansas	3854	Hopper	1941

v.

LOT NO.	ASSIGNED TO (railroad or other)	CAR NOS.	REMARKS	DATE
5681	Louisiana & Arkansas	36158	Box	1941
5682	Kansas City Southern	20899	Auto Box	1941
5684	Louisville & Nashville	99138	Box staggered door	1941
5685	Western RR. of Alabama	17349	Box	1941
5685	Atlanta & West Point			1941
5685	Louisville & Nashville	90350	Box	1941
5686	Louisville & Nashville	67200	Hopper	1941
5687	Atlantic Coast Line	21011	Box	1942
5688	Minn. St. Paul & SSM	44134	Box Auto	1941
5689	Minn. St. Paul & SSM	1764800	Box Auto	1942
5691	Chicago & North Western	71028	Box	1941
5692	Southern Rly.	22878	Box	1942
5694	Nashville Chattanooga & St. L.	18850	Box	1942
5696	Atchison Topeka & Santa Fe	145798		1941
5697	Great Northern	46477	Box	1942
5698	Northern Pacific	27635	Box	1942
5699	Central of Georgia	6149	Box	1942
5701	Southern Pacific	95652	Box	1942
5702	Seaboard Air Line	11850	Auto/Furniture	1942
5704	Chicago & North Western	77382	Box	1942
5707	Chic. Indianapolis & Louisv.	9427	Box	1942
5708	Chicago Great Western	52183	Box	1942
5710	Birmingham Southern	5500	Gondola Steel	1942
5714	Export		Gondola Highside	1942
5715	Export		Side Drop Gondola	1942
5717	Louisville & Nashville	91046	Box	1942
5719	Atlantic Coast Line	53450	Box Automobile	1944
5720	Chicago & North Western	45865	Flat	1942
5720A	New York Chicago & St. Louis	8038	Flat	1942
5723	Duluth Missabe & Iron Range	25561	Hopper Ore	1942
5726	U.S. Navy Ammo Depot			1942
5728	E.M. Co. #1		Plancor #571 Hopper	1942
5731	U.S. Army (Export)	90051	Caboose	1942
5732	U.S. Army (Export)	228075	Box	1942
5736	Chicago & Alton	51000	Box	1944



LOT NO.	ASSIGNED TO (railroad or other)	CAR NOS.	REMARKS	DATE
5736A	Central of Georgia	21700	Hopper	1943
5741	Haskell & Barker	3926		1943
5742	Louisville & Nashville	31472	Hopper	1943
5743	U.S. Army (Export)		Box	1943
5753	Georgia Railroad	19899	Box	1944
5753	Western Railroad of Alabama	17464	Box	1944
5753	Atlanta & West Point	37459	Box	1944
5754	Birmingham Southern	6599	Box	1944
5756	Chicago & Alton	51390	Box	1944
5757	U.S. Army (Export)	2203600	Box 4 wheel	1944
5759	U.S. Army (Export)	4200117	Gondola 4 wheel	1944
5760	U.S. Army	444238	Gondola	1944
5761	Central of Georgia	41193	Box	1944
5764	Atchison Topeka & Santa Fe	151191	Box	1944
5766	New York Chicago & St. Louis	8006	Box	1944
5768	Seaboard Air Line	19599	Box	1944
5769	Seaboard Air Line	37550	Hopper	1944
5770	Northern Pacific	28023	Box	1944
5771	Chicago Great Western	41900	Box	1944
5772	Chicago Great Western	69049	Hopper	1942
5775	Union Pacific	3799	Caboose	1944
5776	Nashville Chattanooga & St.L.	48498	Hopper	1944
5777	Central of Georgia	4560	Box	1945
5778	Central of Georgia	6670	Box	1945
5779	Central of Georgia	21899	Hopper	1945
5780	New York New Haven & Hartford	31700	Box	1944
5781	Chesapeake & Ohio	49099	Hopper	1944
5783	Central of Georgia	19950	Box	1945
5783A	Atlanta & West Point	37500	Box	1945
5784	Georgia Railroad	21151	Hopper	1945
5785	Chicago & North Western	80606	Box	1945
5786	U.S. Army (Export)	237799	Box	1944
5789	Southern Railway	119322	Gondola	1945
5793	Chicago & Alton	52147	Box	1945
5798	Merchants Despatch Trans. Corp.	23030	Refrig.	1945

vii.

LOT NO.	ASSIGNED TO (railroad or other)	CAR NOS.	REMARKS	DATE
5799	Atchison Topeka & Santa Fe	64575	Box	1945
5800	Chicago & North Western	65215	Hopper	1945
5801	Chesapeake & Ohio	14111	Box	1945
5802	Chicago & Eastern Illinois	97790	Hopper	1946
5803	Seaboard Air Line	22449	Box	1945
5804	Seaboard Air Line	19799	Box	1945
5805	Chicago Great Western	92000	Box	1945
5806	Seaboard Air Line	19950	Box	1945
5807	Northern Pacific	29168		1945
5808	Chicago & Eastern Illinois	1	Box	1945
5811	USCC	40	Flat Raised Ends	1946
5814	Export-Russia		Drop Side Flat	1945
5815	Kansas City Southern	29240	Hopper	1946
5817	Chicago Rock Island & Pacific	2500	Box	
5818	Kansas City Southern	29621	Hopper Covered	1946
5820	Burlington Refrigerator Express	75276	Ref.	1945
5823	St. Louis Brownsville & Mexico	18399	Box	1946
5823	Missouri Pacific	18899	Box	1946
5826	Spokane Portland & Seattle	11315	Box	1946
5827	Union Pacific	455949	Box Auto	1946
5833	Louisville & Nashville	68599	Hopper	1946
5832	Haskell & Barker			1946
5835	St. Louis & San Francisco	154250	Box Auto	1946
5837	Chicago & North West6ern	105758?		1946
5838	Southern Pacific	21622	Box	1946
5838	Texas & New Orleans	55150	Box	1946
5839	Southern Railway Syst.	39199	Box	1947
5839A	Southern Railway Syst.	39996	Box	1947
5840	New York Chicago & St. Louis	5151	Box	1946
5843	Tennessee Coal Iron & RR.	5252	Hopper	1946
5844	Tennessee Coal Iron & RR.	3099	Hopper	1946
5844A	Birmingham Slag Co.	OD-1	Hopper	1946
5846	Export-France		Box	1946
5847	Minneapolis & St. Louis	70131	Hopper Covered	1947
5850	Illinois Central	79795	Hopper Covered	1947



LOT NO.	ASSIGNED TO (railroad or other)	CAR NOS.	REMARKS	DATE
5851	Gulf Mobile & Ohio	80003	Hopper Covered	1947
5852	Seaboard Air Line	58275	Hopper Covered	1947
5853	Chicago Great Western	70025?	Hopper Covered	1947
5855	Southern Railway System	330399	Box	1946
5856	Santa Fe Refrigerator Dispatch	3526	Refrig.	1947
5857	Pacific Fruit Express	47754	Refrig.	1947
5858	Louisville & Nashville	69250	Hopper	1947
5860	Union Pacific	197899	Box	1947
5860	Chicago Indianapolis & Louisville (Monon)	1	Box	1947
5861	Union Pacific	177899?	Box	1947
5863	Seaboard Air Line	9149	Box	1947
5866	Nashville Chattanooga & St. Louis	19399	Box	1947
5868	Nashville Chattanooga & St. Louis	48500	Hopper	1947
5869	Western Railway of Alabama	17649	Box	1947
5869	Georgia Railroad	29049	Box	1947
5871	Norfolk Southern	27000	Box	1947
5872	Southern Pacific (T&NO)	22149	Box	1947
5873	Lehigh Valley	62000	Box	1947
5875	Chicago Great Western	93251	Box	1947
5876	GOC?		Box	1947
5877	Boston & Maine	74305	Box	1947
5877	Maine Central	6730	Box	1947
5878	American Refrig. Transit Co.	28136	Refrig.	1947
5879	Atchison Topeka & Santa Fe	276749	Box	1947
5882	New York New Haven & Hartford	33870	Box	1947
5883	Louisville & Nashville	80350	Hopper	1947
5885	Kansas City Southern	18549	Box	1948
5886	Chesapeake & Ohio	15000	Box	1947
5887	New York Chicago & St. Louis	6251	Box	1948
5896	Haskell & Barker			1953
5896A	Savannah & Atlanta	8240	Box	1948
5898	Haskell & Barker			1947
5902A	Georgia Railroad	21200	Hopper	1948
5902A	Western Rly. of Alabama	11200	Hopper	1948
5905	Birmingham Southern	7050	Hopper	1948

LOT NO.	ASSIGNED TO (railroad or other)	CAR NOS.	REMARKS	DATE
5908	Union Pacific		Box	1948
5908A	Copper Range	4010	Box	1948
5911	St. Louis & San Francisco	17162	Box	1948
5912	St. Louis & San Francisco	90247	Hopper	1948
5913	Louisiana & Arkansas	9000	Gondola	1948
5918	Illinois Central	90999	Hopper	1949
5918A	APX	57	Hopper	1949
5919	Chicago Rock Island & Pacific	25688	Box	1948
5919A	Southern Railway System	262053	Box	1948
5919A	Copper Range	4025	Box	1948
5919A	Chicago St. Paul Minn. & Omaha	39304	Box	1948
5919A	Pittsburgh & West Virginia	1310	Box	1948
5919A	Duluth S. Shore & Atlantic	15052	Box	1948
5919A	Chicago & North Western	88364	Box	1948
5919B	Seaboard Air Line	24300	Box	1948
5920	Chicago & North Western	86390	Box	1948
5924	Southern Pacific (T&NO)	59208	Box	1949
5925	Chicago & North Western	49703	Hopper	1949
5926	Louisville & Nashville	35499	Hopper	1949
5927	Louisville & Nashville	33199	Hopper	1949
5927A	Birmingham Slag Co.	OD-101	Hopper	1949
5929	New York Chicago & St. Louis	47541	Hopper	1949
5930	New York Chicago & St. Louis	44275	Gondola	1949
5931	Grand Trunk Western	595519	Box	1948
5932	Gulf Mobile & Ohio	32644	Hopper	1949
5936	Delaware Lackawanna & Western		Box	1948
5937	St. Louis & San Francisco	90899	Hopper	1949
5938	Illinois Central	92142	Hopper	1949
5938A	Kewaunee Green Bay & Western	406	Hopper	1949
5938B	Escanaba & Lake Superior	4032	Hopper	1949
5939	Duluth South Shore & Atlantic	4099	Gondola	1949
5939A	Escanaba & Lake Superior	5033	Gondola	1949
5942	Mississippi Central		Box	1949
5942A	Chicago Indianapolis & Louisville (Monon)	502	Box	1949
5943	Haskell & Barker			



x.

LOT NO.	ASSIGNED TO (railroad or other)	CAR NOS.	REMARKS	DATE
5950	Missouri Kansas Texas	90024	Box	1949
5950	Canadian Pacific	269960	Box	1949
5950	LaSalle & Bureau County	1105	Box	1949
5955	Chicago & North Western	106982	Box	1949
5955	Pullman	PSX19	Box	1949
5957	Chicago & North Western	57694	Box	1949
5960	Southern Railway System	280172	Hopper Covered	1949
5961	Louisville & Nashville	38174	Hopper Covered	1950
5962A	New York Chicago & St. Louis	49083	Hopper Covered	1950
5962A	Southern Railway System	94162	Hopper Covered	1950
5962B	Chicago & Eastern Illinois	80025	Hopper Covered	1950
5962D	St. Louis & San Francisco	83860	Hopper Covered	1950
5964	Atchison Topeka & Santa Fe	31374	Box	1950
5964	New York Central?		Box	1950
5965	New York Central	169000	Box	1950
5965A	Lake Superior & Ishpeming	2266	Box	1950
5965B	New York Central	169982	Box	1950
5966	Louisville & Nashville	16938	Box	1950
5967	Southern Pacific		Box	1950
5967	Texas & New Orleans	60049	Box	1950
5968	Seaboard Air Line	58850	Hopper Covered	1950
5970	Lehigh Valley	62738	Box	1950
5971	Atlantic Coast Line	85346	Hopper	1950
5973	Delaware & Hudson	18570	Box	1950
5977	Green Bay & Western	799	Box	1950
5979A	Southern Railway System	319220	Hopper Covered	1951
5979C	Chicago & North Western	69467	Hopper Covered	1951
5979C	North American Car Corp.	30030	Hopper Covered	1951
5980	U.S. Army		Box	1950
5982	Southern Pacific	105054	Box	1951
5983	Chesapeake & Ohio	16249	Box	1950
5987	Seaboard Air Line	59273	Hopper Covered	1951
5988	Louisville & Nashville	17946	Box	1951
5993	New York Central	170750	Box	1951
5994	Seaboard Air Line	24910	Box	1951

LOT NO.	ASSIGNED TO (railroad or other)	CAR NOS.	REMARKS	DATE
5995	St. Louis & San Francisco	17549	Box	1951
5996	Chicago & Eastern Illinois	65596	Box	1951
5997	New York Central	171799	Box	1951
5998	Delaware & Hudson	19099	Box	1951
5999	Boston & Maine	75249	Box	1951
5999	Maine Central	8199	Box	1951
6704	Pullman	7040	Troop Sleeper	1943
6743	U.S. Army	90962	Caboose	1943
6753	Pullman		Troop Sleeper	1945
7764	Great Northern	71188	Hopper Covered	1953
8001	Southern Pacific (T&NO)	105497	Box	1951
8001A	St. Louis Southwestern	33899	Box	1951
8002	Norfolk & Western	44324	Box	1951
8003	Southern Railway System	30827	Box	1951
8003A	Lancaster & Chester	1019	Box	1952
8004	Akron Canton & Youngstown	750	Box	1951
8006	Nashville Chatta. & St. Louis	49111	Hopper	1950
8007	Chicago & North Western	6838	Box	1951
8008	U.S. Army	26218	Box	1951
8009	Birmingham Southern	6799	Box	1952
8013	Atlantic Coast Line	72899	Pulp Wood	1952
8015	New York Chicago & St. Louis	22145	Box	1952
8016	Chicago & North Western	5800's	Box	1951
8016	Chicago Great Western	5000's	Box	1951
8017	Chesapeake & Ohio	17246	Box	1951
8021	Georgia RR.	39518	Box	1952
8021	Western Rly. of Alabama	18209	Box	1952
8021	Western Pacific (see 5089B)	21164	Box Compartment	1953
8025	Chi. Milw. St. Paul & Pacific	35003	Box	1951
8026	St. Louis Southwestern	33974	Box	1951
8027	Western Pacific	20845	Box	1951
8028	Chicago Rock Island & Pacific	21499	Box	1951
8029	Seaboard Air Line	25253	Box	1952
8030	Central of Georgia	7086	Box	1952
8031	Central of Georgia	18572	Gondola	1952



LOT NO.	ASSIGNED TO (railroad or other)	CAR NOS.	REMARKS	DATE
8032	Columbus & Greenville	9339	Gondola	1952
8032	Western Rly. of Alabama	11800	Gondola	1952
8032	Gulf Mobile & Ohio	14143	Gondola	1952
8035	Norfolk & Western	44500	Box	1952
8036	Haskell & Barker		Box	1952
8036A	New York Central	180199	Box	1952
8036B	Fort Dodge Des Moines & Sou.	12300	Box	1952
8036C	Canadian Pacific	268899	Box	1952
8037	Chesapeake & Ohio	18499	Box	1952
8038	Buffalo Creek & Gauley	1001	Box	1952
8039	Louisville & Nashville	5000	Box	1952
8039	Atlanta & West Point		Box	1952
8040	Louisville & Nashville	82200	Hopper	1952
8040	Georgia Railroad	21350	Hopper	1953
8040	APX	69	Hopper	1953
8041	Duluth Missabe & Iron Range	21016	Hopper Ore	1952
8042	Richmond Fredricksburg & Potomac 2880	Box	1952	
8043	Southern Pacific (Texas & N.O.)	61735	Box	1953
8044	U.S. Army	26423		1951
8044	U.S. Navy			1951
8044	U.S. Marine Corps			1951
8046	St. Louis & San Francisco	17998	Box	1952
8047	Lake Superior & Ishpeming	2422	Box	1952
8049	Delaware & Hudson	19600	Box	1952
8050	Minneapolis Northfield & Sou.	1050	Box	1952
8054	U.S. Navy	8000	Box	1952
8055	Clinchfield	52499	Hopper	1953
8060	Chi. Ind. & Louisv. (Monon)	726	Box	1952
8061	U.S. Army	26488	Box	1953
8061	U.S. Air Force	26905	Box	1953
8061	U.S. Navy	6103420	Box	1953
8068	Tennessee Central	8699	Hopper	1953
8069	American Smelting & Refining	768	Box	1952
8072	Illinois Central	79010	Hopper Covered	1953
8072	McMillen Feed Mills		Hopper Covered	1953

## xiii.

LOT NO.	ASSIGNED TO (railroad or other)	CAR NOS.	REMARKS	DATE
8073	Haskell & Barker		Hopper Covered	1952
8077	Seaboard Air Line	91900	Gondola	1953
8078	Seaboard Air Line	90420	Gondola	1953
8079	Seaboard Air Line	7664	Hopper Covered	1952
8080	New York Susquehanna & Western	400's	Box	1952
8081	Chicago Rock Island & Pacific	100	Hopper Covered	1953
8087	Canadian Pacific	269349	Box	1953
8088	U.S. Navy	6103098	Gondola	1953
8089	Florida East Coast	12200	Gondola	1953
8091	International Minerals & Chem.	30098	Hopper Covered	1953
8094	New York Central	882050	Covered Hopper	
8095	Nashville Chatta. & St. L.	46699	Hopper	1953
8098B	Western Pacific		Box	1952
8099	Southern Railway	61099	Gondola	1953
8100	Norfolk & Western	53495	Box	1953
8105	U.S. Air Force	81053	Box	1953
8105	Chicago & North Western	84288	Box	1953
8105	Chi. Milw. St. Paul & Pacific	35061	Box	1953
8105	F.C. Del Pacifico	3300	Box	1953
8105	Chi. Ind. & Louisv. (Monon)	861	Box	1953
8105	Chi. St. Paul Minn. & Omaha	22440	Box	1953
8108	Chi. Ind. & Louisv. (Monon)	4331	Hopper Covered	1953
8109	Chi. St. Paul Minn. & Omaha	22418	Box	1953
8111	Appalachicola & Northern	AN117	Pulp Wood	1953
8112	Detroit Toledo & Ironton	15299	Box	1953
8115	NMSX		Box	1952
8119	Texas Mexican Ry. Co.	902	Gondola	1953
8121	(see 8098B) H&B?		Box Compartment	1952
8122	Illinois Central	79373	Hopper Covered	1953
8123	ARMCO	2205	Gondola	1953
8124	Toledo Peoria & Western	620	Box	1953
8125	Duluth Missabe & Iron Range		Ore Hopper	1953
8126	St. Louis & San Francisco	80098	Hopper	1954
8129	Chi. Ind. & Louisv. (Monon)	1481	Box	1953
8131	Union Carbide	201	Hopper	1953



LOT NO.	ASSIGNED TO (railroad or other)	CAR NOS.	REMARKS	DATE
8132	Atlantic Coast Line	82329	Hopper Covered	1953
8134	Central of Georgia	1444	Hopper Covered	1953
8135	Gulf Mobile & Ohio	80121	Hopper Covered	1953
8139	Delaware & Hudson	2935	Hopper Covered	1953
8140	Southern Pacific	165266	Hopper Covered	1953
8142	F.C. Del Pacifico	3319	Box	1953
8143	Duluth South Shore & Atlantic	15186	Box	1953
8144	Chicago & North Western	1	Box	1953
8145	Denver & Rio Grande Western	18450	Hopper Covered	1953
8150	Central of Georgia	8199	Box	1953
8151	Savannah & Atlanta	690	Box	1954
8152	Olympic Portland Cement Co.	H-4	Hopper Covered	1953
8154	St. Louis & San Francisco	92399	Hopper	1954
8156	F.C. Del Pacifico	3557	Box	1953
8159	Norfolk & Western	53542	Box	1953
8160	Chesapeake & Ohio	2990		1954
8160	Erie	84009		1954
8160	Great Northern	21961		1954
8160	Western Pacific	1968		1954
8160	Pennsylvania Railroad	47009		1954
8160	New York Central	175008		1954
8160	Bangor & Aroostook	4500		1954
8160	Norfolk & Western	53996		1954
8161	Delaware & Hudson	2900	Hopper Covered	1953
8162	Union Carbide	585	Hopper Covered	1953
8165	Birmingham Southern	6010	Hopper Covered	1953
8166	Elgin Joliet & Eastern	70988	Hopper	1953
8168	Chi. Ind. & Louisv. (Monon)		Hopper	1954
8170	U.S. Navy	6103894	Hopper	1954
8175	Erie	86767	Box	1954
8175A	Chicago & North Western		Box	1954
8175B	Rutland	104	Box	1954
8177	Chicago & North Western	155	Box	1954
8178	St. Louis & San Francisco	18299	Box	1954
8179	U.S. Army	27127	Box	1954

LOT NO.	ASSIGNED TO (railroad or other)	CAR NOS.	REMARKS	DATE
8180	Minneapolis Northfield & Sou.	1103	Box	1954
8183	Western Pacific	35001	Box	1954
8191	Chicago & Illinois Midland	16100	Box	1954
8192	Chicago & Eastern Illinois	3734	Box	1954
8196	Kansas City Southern	24269	Pulp Wood	1954
8198	Central of Georgia	5751	Box	1954
8202	Chicago & North Western		Box	1954
8203	U.S. Navy	6104245	Box	1954
8204	Union Pacific		Box 50'	1954
8205	Union Pacific	500698	Box	1955
8206	St. Louis Southwestern	20274	Box	1954
8207	Rutland	125	Box	1954
8207A	Central of Georgia	6200	Box Compartmentizer	1954
8208	St. Louis Southwestern	34091	Box	1954
8209	St. Louis Southwestern	20299	Box	1954
8210	Chicago Rock Island & Pacific	5159	Box	1954
8211	Western Pacific	3023	Box	1955
8213	Western Pacific	3812	Box	1954
8214	Denver & Rio Grande Western	60500	Box	1954
8215	Missouri Kansas & Texas		Box	1954
8216	Missouri Kansas & Texas		Box	1955
8216A	Central of Georgia	6208	Box	1954
8216B	Chicago & North Western	2256	Box	1955
8218	Atchison Topeka & Santa Fe	11434	Box Compartmentized	1955
8219	Atchison Topeka & Santa Fe	6047	Refrigerator	1955
8221	Seaboard Air Line	25778	Box	1955
8222	Haskell & Barker			1955
8224	Chi. Milw. St. Paul & Pacific	8741	Box Compartmented	1955
8225	Rutland	121	Box	1955
8227	St. Louis & Southwestern	3432-4	Box	1955
8228	Chicago & North Western	3109	Box	1955
8229	Haskell & Barker			
8229A	Southern Railway System	35200	Box	1955
8229B	Southern Railway System	35199	Box	1955
8232	E.F. Amapa	215	Box	1955



LOT NO.	ASSIGNED TO (railroad or other)	CAR NOS.	REMARKS	DATE
8233	U.S. Navy	5104270	Box	1955
8238	Western Pacific	19330	Auto Box	1955
8239	Western Pacific	35253	Box	1955
8240	Tidewater Southern	501	Box	1955
8241	Western Pacific		Box Compartmentized Insu.1955	
8242	Western Pacific	2001	Flat	1955
8243	Woodward	2349	Hopper	1955
8245	Akron Canton & Youngstown	3600	Box	1955
8247	Chesapeake & Ohio	28199	Box	1955
8251	Southern Pacific	650000	Box	1955
8251A	St. Louis Southwestern	47254	Box	1955
8252	St. Louis Southwestern	47374	Auto Box	1955
8260	Norfolk & Western	52749	Box	1955
8261	Norfolk & Western	42099	Box	1955
8262	Chicago & North Western	4516	Box	1955
8266	St. Louis Southwestern		Box	1955
8267	Western Pacific	35309	Box	1955
8267A	Western Pacific	3838	Box	1955
8267B	Western Pacific	19429	Box Automobile	1955
8268	Western Pacific	35423	Box	1955
8268	Sacramento Northern	2402	Box	1955
8269	St. Louis & San Francisco	7566	Box	1956
8270	St. Louis & San Francisco	19073		1956
8272	Southern Railway System	73002	Hopper	1955
8273	Missouri Kansas & Texas	99530	Box	1955
8274	Missouri Kansas & Texas	92002	Box	1955
8275	Missouri Kansas & Texas	90135	Box	1955
8276	Seaboard Air Line	26025	Box	1956
8280	Chicago & North Western	7851	Box	1955
8281	Rutland	281	Box	1956
8282	Ann Arbor	371	Box	1956
8283	Central of Georgia	1781	Box	1956
8283	Atlanta & West Point	39004	Box	1956
8283	Western Rly. of Alabama		Box	1956
8284	Savannah & Atlanta	354	Box	1956

LOT NO.	ASSIGNED TO (railroad or other)	CAR NOS.	REMARKS	DATE
8284C	Atlanta & West Point	38009	Box	1956
8284D	Western Rly. of Alabama	18250	Box	1956
8287	Lehigh & New England	8927	Box	1956
8288	Boston & Maine	77399	Box	1956
8289	Chesapeake & Ohio	21142	Box	1956
8292	Buffalo Creek	2170	Box	1956
8294	Delaware & Hudson	20010	Box	1956
8295	Delaware & Hudson	22164	Box	1956
8295A	Clinchfield	5655	Box	1956
8295B	Chi. Milw. St. Paul & Pacific	39056	Box	1956
8298	St. Louis Southwestern	47815	Box	1956
8299	St. Louis Southwestern	35057	Box	1956
8300	Rutland	378	Box	1956
8305	Norfolk & Western	52799	Box	1956
8307	Chicago & North Western	23099	Box	1956
8340	New York New Haven & Hartford	40506	Box	1956
8361	Pullman	PSX 53	Trailer Flat	1956
8425	Akron Canton & Youngstown	3600	Box	1955
JOK7660	Pullman		Hopper Covered	1952
JO9408	AT&SF		Refrig (car sides in gondola)	1938
JO13773	NY Chi. & St. Louis	20081	Box	
JO14022	H&B		Box Auto	1940
JO14470	H&B			1946
JO14852	Pullman	PS-3	Hopper (exhib. car)	1953
JO24999	AT&SF		Box (car side repair)	1946
JO27406	Pullman	PS1	Box	1947
JO27604	Pullman (L.5490?)	PS-1	Box	
JO30777	NY Chi. & St. Louis		Box Repair	1948
JO33080	Missouri Kansas & Texas		Box	1949
JO33991	Chi. Ind. & Louisv. (MONON)			
JO34869	Pullman	171400	Compartmentizedr	1951
JO35989	H&B			
JO36935	Pullman	PS1?	Box	1953
JO37080	H&B			
JO38071	H&B			



xviii.

LOT NO.	ASSIGNED TO (railroad or other)	CAR NOS.	REMARKS	DATE
JO38760	H&B			
JO40654	H&B			
JO40754 &	H&B			
JO40755				

END

